

Table of Contents

I. Introduction	1
II. Overall Response to Witness Richard Polich	3
III. Mr. Polich’s Mischaracterization of the State of Industry Guidance in November 2011	18
IV. Turbine Inspections and Xcel Energy’s General Practices	25
V. Xcel Energy’s Decisions With Respect to Turbine Inspections up to 2011 and Consistency with Industry Practices	30
VI. Conclusion	33

Schedules

DOC Response to Xcel Energy Information Request No. 25	Schedule 1
DOC Response to Xcel Energy Information Request Nos. 2, 3 and 4	Schedule 2
DOC Response to Xcel Energy Information Request No. 10	Schedule 3
GE Knowledge Bulletin (GEK) 111680	Schedule 4
MQS Inspection, Inc. Turbine Inspection Report	Schedule 5
DOC Response to Xcel Energy Information Request No. 30	Schedule 6
Rebuttal to Expert Witness Report of James D. Schultz	Schedule 7

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

I. INTRODUCTION

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25

Q. PLEASE STATE YOUR NAME AND EMPLOYER.

A. My name is Herbert J. Sirois. I am an independent turbomachinery consultant and previously the founder of the now dissolved Foster Cove Engineering, Inc.

Q. HAVE YOU PREVIOUSLY PROVIDED TESTIMONY IN THIS PROCEEDING?

A. Yes. On June 16, 2023, I filed my Direct Testimony on behalf of Northern States Power Company (Xcel Energy or the Company).

Q. WHAT IS THE PURPOSE OF YOUR REBUTTAL TESTIMONY?

A. My Rebuttal Testimony responds to the testimony filed by Mr. Richard Polich, of GDS Associates, Inc., on behalf of the Minnesota Department of Commerce (Department). In particular, I respond to Mr. Polich’s claim that Xcel Energy did not follow “good utility practice” at Sherco Unit 3.

Q. BEFORE TURNING TO THE SUBSTANCE OF MR. POLICH’S TESTIMONY, DO YOU AGREE WITH MR. POLICH’S USE OF THE TERM “GOOD UTILITY PRACTICE”?

A. I agree only to a point. I agree with Mr. Polich that any analysis of “good utility practices” should consider whether a utility has exercised “reasonable judgment in light of the facts known at the time the decision was made.”¹ That description is consistent with Company witness Mr. Allen D. Krug’s testimony which discusses the standard to be applied in this proceeding—the prudence standard—which recognizes that a range of actions may be reasonable and that hindsight has no place in a prudence analysis.

¹ Polich Direct, p. 7.

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 I disagree with the implication throughout Mr. Polich’s testimony that there is
2 some established “good utility practice” standard or standards on the issues he
3 discusses. As Mr. Polich acknowledges, other than his offered definition, there
4 are no other documents that support the definition he provides in his testimony.
5 (*See* the Department of Commerce’s (DOC’s) Response to Xcel Energy
6 Information Request (IR) No. 25, included as Exhibit___(HJS-2), Schedule 1.)
7 Ultimately, it comes down to reliability, efficiency, and the overall cost to
8 operate the power plant and a range of actions can fall within the realm of “good
9 utility practices,” as the prudence standard recognizes. Every utility or plant
10 operator the size of Xcel Energy has the goal of maximizing reliability and
11 thermal and operational efficiency while controlling risks associated with high
12 pressure steam, oil, and rotating equipment, including steam turbine generators,
13 boiler-feed pumps and turbines, fans, complicated hydrogen and lubrication
14 systems, and coal and ash systems.

15
16 Finally, I strongly disagree with Mr. Polich’s suggestion that *any* reasonable
17 definition of “good utility practice” or prudent utility operation would require
18 major inspections of the steam turbine generator every 3 to 5 years, and that
19 those would routinely and without justification (*i.e.*, abnormal events or
20 operational anomalies) include a blades-off, magnetic particle inspection of the
21 turbine finger dovetails. I have worked with many steam turbine
22 owner/operators and several insurance companies over the course of my 53-
23 year career, and I am not aware of a single operator, equipment manufacturer,
24 or insurance company that would agree with Mr. Polich’s assertion that “good
25 utility practice” requires his suggested major inspection frequency of every 3 to
26 5 years. To the contrary, Xcel Energy and the majority of power plant operators

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 around the world utilize a 9 to 10 year major inspection cycle, with some large
2 utilities using an 18 to 20 year major inspection cycle for low pressure turbines.

3
4 **II. OVERALL RESPONSE TO WITNESS RICHARD POLICH**

5
6 Q. WHAT OVERARCHING OBSERVATIONS DO YOU HAVE REGARDING MR. POLICH'S
7 TESTIMONY?

8 A. As an initial matter, Mr. Polich does not appear to be knowledgeable on the
9 subjects he testifies to. This includes a lack of knowledge of and experience
10 with: (1) a 900 megawatt (MW) steam turbine generator and its steam supply;
11 (2) stress corrosion and stress corrosion cracking of a highly engineered steam
12 turbine steam path; (3) steam quality, including the treatment of feedwater in a
13 subcritical drum boiler and the operational differences between drum and once-
14 through boilers; and (4) the decision-making processes at a large power plant
15 and within the central engineering group of a large utility such as Xcel Energy.
16 Given this lack of knowledge and experience, Mr. Polich misread,
17 misunderstood, and misinterpreted technical guidelines from General Electric
18 (GE), the Sherco 3 steam turbine designer and manufacturer, and the highly
19 technical root-cause analysis of the Sherco 3 L-1 finger dovetail failure
20 completed by Thielsch Engineering (Thielsch Report or Report).

21
22 Q. WHAT LEADS YOU TO THESE CONCLUSIONS?

23 A. A review of Mr. Polich's experience, as set forth in Schedules 1 and 2 to his
24 Direct Testimony, and his responses to discovery in this matter, show that his
25 experience and focus has largely been providing testimony on rates, cost of
26 service, and engineering problems to state regulatory commissions and the
27 Federal Energy Regulatory Commission. (*See* the DOC's Responses to Xcel

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 Energy IRs 2, 3, and 4, included as Exhibit___(HJS-2), Schedule 2.) While I
2 have no opinions about his suitability to offer testimony in those areas, his
3 education and experience—and, more importantly, his Direct Testimony—
4 demonstrate that he lacks an understanding of highly technical subjects such as
5 water and steam chemistry at a large fossil plant (further discussed by Company
6 expert and witness Mr. David G. Daniels), metallurgical engineering and its role
7 in a proper root cause analysis (further discussed by Company expert and
8 witness Mr. Anthony A. Tipton) or the decision-making processes for fossil
9 turbine outage planning and the risk management exercised by Xcel Energy and
10 the Sherco 3 responsible staff (further discussed by Company experts and
11 witnesses Mr. Timothy P. Murray and Mr. Mark W. Kolb). For example, Mr.
12 Polich has not designed a steam turbine—or any steam path component in any
13 large utility steam turbine—particularly a 900 MW subcritical unit, and appears
14 to have little if any hands on experience operating, maintaining or repairing such
15 a facility.² Further, Mr. Polich misstates the conclusion of the Thielsch Report,
16 as discussed by Mr. Tipton, and fails to even mention the Report’s *actual*
17 conclusion—that GE’s equipment design was the primary causal factor
18 responsible for the November 2011 failure³ (after analyzing and ruling out
19 maintenance and operations,⁴ which included an analysis of water chemistry⁵).
20 Mr. Polich has never been employed by any company to develop inspection
21 techniques—nor has he offered any meaningful review of the inspection

² In response to Xcel Energy Information Request No. 4, Mr. Polich stated: “Mr. Polich (sic) work in Consumers Energy’s Engineering Department in 1979 involved coal and natural gas plants.” Mr. Polich has identified no other hands on work at such plants.

³ Thielsch Report, Tipton Direct Exhibit___(AAT-1), Schedule 2 pp. 95-96 (pp. 93-94 of the Report).

⁴ Thielsch Report, Tipton Direct Exhibit___(AAT-1), Schedule 2 pp. 67-78, 95-96 (pp. 65-76, 93-94 of the Report).

⁵ Thielsch Report, Tipton Direct Exhibit___(AAT-1), Schedule 2 pp. 79-84, 95-96 (pp. 77-82, 93-94 of the Report).

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 protocol developed by interested parties associated with the failure of the
2 Sherco 3 low-pressure turbine. And Mr. Polich has never worked in a power
3 plant as a water treatment specialist or systems engineer. Simply put, Mr. Polich
4 renders conclusory opinions on issues such as water chemistry and the root
5 cause of the Event, although his testimony reveals that he does not have the
6 qualifications, knowledge, or understanding to make those opinions
7 meaningful.

8
9 Q. DO YOU HAVE ANY SPECIFIC EXAMPLES THAT DEMONSTRATE MR. POLICH'S
10 LACK OF STEAM TURBINE EXPERTISE?

11 A. Yes. Mr. Polich suggests that his opinions are based on his steam turbine
12 expertise, however his testimony is riddled with incorrect information. For
13 example, he represents that Figure 7 in his Direct Testimony (reproduced
14 below), represents the “Sherco LP bucket⁶ Attachment Types”—including a
15 tangential entry dovetail:⁷




Figure 7 -Sherco LP bucket Attachment Types

⁶ The use of the term “buckets” throughout the parties’ testimony is a common industry reference to the turbine “blades.” For simplicity, and to minimize industry jargon, I use the term blades throughout my testimony, but the terms are interchangeable.

⁷ Polich Direct, p.12.

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 November 19, 2011 catastrophic failure at Sherco 3.” (Polich Direct, p. 6.) Yet
2 this type of general assertion either ignores or fails to understand critical facts,
3 in an effort to blame Xcel Energy for the failure of Unit 3. What Mr. Polich
4 conveniently ignores is that, while there was *general* industry knowledge about
5 the potential for stress corrosion cracking (among other risks) in low pressure
6 turbines, it is important to understand and make distinctions about: (1) in what
7 type of boilers these issues were largely manifesting (*i.e.*, once-through boilers
8 as opposed to the drum boiler in Sherco 3); (2) which types of dovetails had
9 largely been affected (*i.e.*, tangential dovetails versus finger dovetails such as
10 those in the L-0 and L-1 rows of Sherco 3), and—importantly—(3) the type of
11 “inspections” that could be performed to detect *latent* stress corrosion cracking
12 in the L-1 finger dovetails (*e.g.*, a magnetic particle inspection that requires the
13 removal of the turbine blades).

14
15 The Sherco 3 failure on November 19, 2011 was the first utility steam turbine
16 generator in a large plant with a *drum boiler* to fail catastrophically when the L-1
17 blades liberated due to latent stress corrosion cracking in the turbine wheel *finger*
18 *dovetails*. There was no “industry knowledge” in 2011 that would inform an
19 owner/operator such as Xcel Energy that a blades-off, magnetic particle
20 inspection of the L-1 wheel finger dovetails was warranted *in the absence of*
21 *abnormal events or operational anomalies*. Mr. Polich appears to utilize 20/20
22 hindsight—and the fact that something, unfortunately, did go wrong—to
23 impugn the Company for failing to perform a blades-off, magnetic particle
24 inspection of the finger dovetails when there were no abnormal events or
25 operational anomalies (as described in GE’s Technical Information Letter (TIL)
26 1121-3AR1) that justified the added maintenance, duration of outage, expense,

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 and risk to the equipment that performing such an inspection would have
2 entailed.

3
4 Q. HOW DO YOU RESPOND TO MR. POLICH’S SUGGESTION THAT A “NON-
5 INVASIVE” INSPECTION DURING THE 2011 MAINTENANCE OUTAGE WOULD
6 HAVE REVEALED THE STRESS CORROSION CRACKING PRESENT IN THE L-1
7 BLADES (POLICH DIRECT, PP. 25-26)?

8 A. Mr. Polich is simply wrong once again. With the benefit of hindsight and the
9 post-failure analysis, we know that there was stress corrosion cracking on the
10 internal fingers of the L-1 finger dovetails. Arguably, such cracking would have
11 been visible *if* the blades had been removed. But any suggestion that evidence
12 of the cracking could have been discovered *without* the blades being removed
13 (*i.e.*, a “non-invasive inspection”) is flat-out wrong. It is worth emphasizing here
14 that it is not the actual inspection (*i.e.*, the magnetic particle inspection of the
15 finger dovetails) that is an onerous process that must be judiciously performed.
16 As is thoroughly detailed in Mr. Murray’s testimony, it is the process of
17 *removing the blades* and then *re-attaching the blades* that is time-
18 consuming, labor-intensive, and potentially jeopardizes the useful life of the
19 equipment. And unless the blades are being replaced, or there is manufacturer
20 guidance or justification to perform a magnetic particle inspection of the finger
21 dovetails, a prudent utility would not capriciously remove the blades as part of
22 a minor or major inspection. In other words, a prudent utility would never
23 remove the blades from any row on the turbine rotors without justification, and
24 no justification existed here.

25
26 As such, the quoted comment in Mr. Polich’s Direct Testimony that “cracks in
27 the LP rotors would’ve been large enough at the time of the 2011 planned

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 outage to be visible with the naked eye, had the buckets been removed”¹⁰ is
2 meaningless. The 2011 planned outage did not include (and did not have
3 justification for) a plan to access the two low-pressure rotors by removing the
4 upper half casing and removing the rotors by disassembling the couplings and
5 then removing the turbine blades, all of which would have been necessary to
6 make those “naked eye” observations referenced by Mr. Polich. And a prudent
7 operator would not undertake the rigorous blade-removal process without
8 manufacturer guidance or the presence of abnormal events or operational
9 anomalies—neither of which was present in 2011. As such, speculations about
10 what might (or might not) have been visible had Xcel Energy removed the
11 blades is irrelevant. Since there was no reasonable basis to remove the blades in
12 2011, hypothetical scenarios/outcomes do not inform this prudence analysis.

13
14 What is relevant, however, is what actually *did* happen during the 2011
15 inspection. As addressed in Mr. Murray’s Rebuttal Testimony, Xcel Energy
16 engaged a qualified contractor, Alstom, to perform this inspection. Notably,
17 Alstom completed a visual inspection of the low pressure turbine rotor last-
18 stage blades—*i.e.*, a non-invasive inspection, the very thing that Mr. Polich
19 opines would have revealed the stress corrosion cracking.¹¹ Alstom’s inspection
20 report confirms that “[n]o corrosion, pitting, cracks, or indications were noted
21 during [sic] in the inspection.”¹² In other words, Alstom’s inspection
22 demonstrates that—contrary to Mr. Polich’s speculation—the stress corrosion

¹⁰ Polich Direct, p. 26.

¹¹ Polich Direct, pp. 25-26 (“the cracking was prevalent throughout the LP turbine rotor disk that attach the L-1 buckets to the LP turbine rotor, and would have been found if Xcel had performed non-invasive inspection [sic] during the 2011 maintenance outage.”).

¹² Murray Rebuttal, Exhibit____(TPM-2) Schedule 3.

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 cracking on the L-1 finger dovetails was *not* observable to the naked eye in a
2 non-invasive inspection.

3
4 Q. WHAT ELSE DOES MR. POLICH GET WRONG?

5 A. Mr. Polich suggests throughout his testimony that there was guidance available
6 in 2011 “that identified the potential for steam turbine failure and provided
7 recommended plant maintenance and inspection practices to avoid such a
8 failure.” (Polich Direct, p. 5.) Again, if speaking only in *generalities*, this is true:
9 yes, there was guidance available to operators about how to maintain and
10 inspect steam turbines to prevent failures. But the critical and necessary follow-
11 up question is whether there was guidance available in 2011 that was specific to
12 the type of unit present at Sherco 3 that warned and advised about how to
13 prevent the type of failure that occurred on November 19, 2011 in the turbine
14 finger dovetails. The answer to that question is a resounding “no.”

15
16 Despite the lack of specific advice from GE in the form of a unit-specific,
17 Technical Information Letter (other than TIL 1121-3AR1 which is discussed
18 further in this testimony), Xcel Energy was nevertheless diligent in monitoring
19 for issues and performing necessary maintenance—in addition to scheduling
20 appropriate outages for more detailed inspection/repair work. And as
21 confirmed by Timothy Murray and Mark Kolb, the Company *repeatedly*
22 requested guidance from GE as early as January 15, 2008 for Sherco 3, including
23 seeking unit-specific recommendations associated with the turbine finger
24 dovetails and, as was their practice, constantly engaged with GE to review and
25 discuss planned maintenance decisions. (*See* email included as Schedule 1 in
26 Murray Rebuttal, Exhibit___(TPM-2), Schedule 1.) There is simply no
27 justification for Mr. Polich’s claim that Xcel Energy knowingly and

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 unreasonably delayed inspections with the knowledge that such delays would
2 increase the risk of failure. (See Polich Direct, p. 6.) The mere suggestion that
3 Xcel Energy knowingly put its employees and the Sherco 3 turbine, the most
4 substantial unit in its fleet, at risk is absurd.

5
6 Q. DOES MR. POLICH ACCURATELY SUMMARIZE GE’S GUIDANCE ON LP TURBINE
7 INSPECTION AND TESTING?

8 A. No. First, Mr. Polich identifies two Technical Information Letters (TILs) that
9 he indicates “pertain to the Sherco 3 LP turbine failure”: TIL 1121-3AR1 and
10 TIL 1277-2.¹³ While there is no dispute that TIL 1121-3AR1 is relevant to this
11 inquiry, Mr. Polich is mistaken that TIL 1277-2 relates to this discussion. TIL
12 1277-2, which—notably—was never issued to Sherco 3, applies to fossil steam
13 turbines with steam supplied by *once-through boilers* (as opposed to Sherco 3’s
14 drum boilers). TIL 1277-2, therefore, is not applicable to Sherco 3.

15
16 Further, Mr. Polich refers to two General Electric Knowledge bulletins (GEKs)
17 that were issued in the 1970s that purportedly address inspection requirements
18 relevant to this matter: GEK 63355 and GEK 46354.¹⁴ While these GEKs do
19 apply to Sherco 3 and reflect GE’s inceptive 3- to 5-year inspection-interval
20 recommendations, these over 40-year old GEKs are outdated and fail to reflect
21 GE’s most up-to-date inspection guidance (and industry practices) as of 2011.

¹³ As explained in Mr. Kolb’s Direct Testimony, GE, as the Original Equipment Manufacturer, would from time-to-time issue Technical Information Letters (TILs). When GE issued a TIL, it was issued with specific serial numbers and would be applicable *only* to turbines with those serial numbers. For example, Sherco Unit 3’s low-pressure B turbine had a serial number of 170X819, and only TILs issued with that serial number would apply to Unit 3’s low pressure B turbine. If GE issued a TIL that did not include any Xcel Energy serial numbers, then the Company would not have access to that TIL and it would not apply to any Company turbines.

¹⁴ Polich Direct, pp. 38-39.

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 As will be discussed further below, Mr. Polich fails to include any reference to
2 or discussion about GEK 111680, which was issued in 2007, applies to Sherco
3 3, and effectively supplanted the prior GE guidance as it relates to inspection-
4 interval recommendations. GEK 111680 reflects the industry trending towards
5 longer inspection intervals as it recommended *6-year or longer* inspection
6 intervals—directly refuting Mr. Polich’s opinion that “GE recommends three-
7 to-five year service interval[sic] for major turbine inspections.”¹⁵

8
9 Q. ARE THERE ANY OTHER MISSTATEMENTS IN MR. POLICH’S TESTIMONY THAT
10 WOULD AFFECT THE OUTCOME OF THIS HEARING?

11 A. Yes. Mr. Polich not only claims that GE recommends a 3 to 5 year “major”
12 inspection cycle for the steam turbine generator, but he further implies that
13 these every-3-to-5 year major inspections should include a blades-off, magnetic
14 particle inspection of the turbine wheel finger dovetails.¹⁶ Whether Mr. Polich
15 is arguing that GE recommends a major inspection every 3 to 5 years, or that
16 GE recommends a major inspection that includes a blades-off, magnetic
17 particle inspection of the finger dovetails every 3 to 5 years, he is wrong on both
18 accounts. First, as will be addressed further below, GE’s formal (and informal)
19 written guidance belies Mr. Polich’s “every three to five year” inspection
20 suppositions. And GE’s involvement in the 1993, 1996, and 2005 major
21 inspections of Sherco Unit 3 debunks Mr. Polich’s opinion that GE intended

¹⁵ Polich Direct, p. 39.

¹⁶ Polich Direct, p. 54: “GE recommends inspection [sic] of the turbine rotor for problems like SCC should be performed every three to five years. The inspection for SCC induced cracks in the LP rotor disk requires removal of the buckets from the rotor. Xcel did not perform this type of inspection within the recommended time period. GE specifically states the buckets need to be removed from the rotor to test for SCC.”

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 all major inspections to include a blades-off, magnetic particle inspection of the
2 turbine wheel finger dovetails.

3
4 GE was contracted to perform major inspections on the Sherco 3 LP turbine
5 in 1993 (GE removed and replaced several L-1 blades due to tenon failures but
6 did not perform a full blades-off magnetic particle inspection) and 1996 (GE
7 removed a few blades from each L-1 wheel for thorough inspection of tie wire
8 holes and tenons for cracking but did not perform a full blades-off magnetic
9 particle inspection). And in 2005, Xcel Energy consulted with GE about the
10 scope of the planned major inspection. Further, GE submitted a bid for the
11 work and, while not selected, GE representatives were on-site for the major
12 overhaul/inspection where Mechanical Dynamics & Analysis (MD&A)
13 replaced the turbine end and generator end last stage blade covers. Yet, GE—
14 as the Original Equipment Manufacturer (OEM) and issuer of TIL 1121-
15 3AR1—neither submitted a bid for nor recommended a blades-off, magnetic
16 particle inspection of the turbine finger dovetails during the 2005 major
17 inspection. Why wouldn't GE have pushed for (or suggested/proposed) a
18 blades-off, magnetic particle inspection of the turbine finger dovetails as part of
19 the 1993, 1996, or 2005 major overhauls/inspections if GE's guidance was, as
20 Mr. Polich asserts, to routinely perform such an inspection as part of a major
21 overhaul/inspection? This was not an oversight on GE's part. Such an
22 inspection simply was not viewed as necessary for the Sherco 3 low pressure
23 turbines, given Unit 3's operating history.

24
25 Today, even with the benefit of hindsight and knowledge of the Sherco 3 event,
26 GE has not issued any guidance recommending either: (1) a major inspection
27 every 3 to 5 years; or (2) a major inspection with the additional blades-off,

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 magnetic particle inspection of the turbine finger dovetails every 3 to 5 years.
2 Mr. Polich’s claims to the contrary are not supported by GE guidance and lack
3 merit.

4
5 Q. TO CLARIFY, IS A “MAJOR” OVERHAUL/INSPECTION THE SAME THING AS A TIL
6 1121-3AR1 BLADES-OFF, MAGNETIC PARTICLE INSPECTION OF THE FINGER
7 DOVETAIL ATTACHMENTS?

8 A. No, these are two entirely separate categories of inspections. GE’s manufacturer
9 guidance is instructive to understanding the scope of a major
10 overhaul/inspection. In GEK 111680: Creating an Effective Steam Turbine
11 Maintenance Program (2007), GE explains that a major inspection consists of
12 “[a]ll inspections completed as part of a minor outage/overhaul with exception
13 of borescope inspections.”¹⁷ The GEK proceeds to list nine additional
14 recommended scheduled activities, such as “clean[ing] and inspect[ing]
15 stationary and rotating components” and “appropriate non-destructive testing
16 and examinations.”¹⁸ Notably, according to this 2007 guidance, the scope of a
17 major overhaul/inspection does *not* include a blades-off, magnetic particle
18 inspection of the finger dovetail attachments.

19
20 Put differently, the TIL 1121-3AR1 inspection (*i.e.*, blades-off, magnetic particle
21 inspection of the finger dovetail attachments) is a separate, *additional* layer on
22 top of a major inspection that, pursuant to the TIL’s recommendations, should
23 only be performed whenever all of the turbine blades are being removed (for

¹⁷ See Sirois Rebuttal, Exhibit___(HJS-2), Schedule 4.

¹⁸ See Sirois Rebuttal, Exhibit___(HJS-2), Schedule 4, pp. 14-15.

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 whatever purpose) *or* if there are abnormal events or operational anomalies that
2 cause concern for the long-term reliability of the unit.

3
4 Q. AS OF TODAY, ARE YOU AWARE OF ANY CHANGES GE IMPLEMENTED IN THE
5 DESIGN OF THE FINGER DOVETAIL ATTACHMENT AREAS IN ITS LOW-PRESSURE
6 TURBINE PRODUCTS?

7 A. Yes. On June 17, 2008, GE was granted United States patent US 7,387,494 B2
8 titled “Finger Dovetail Attachment Between A Turbine Rotor Wheel and
9 Bucket For Stress Reduction,” Yehle et. al. (2008 Patent).¹⁹ The essence of the
10 2008 Patent is the incorporation of compound radii in the two transition areas
11 (ledges) between varying thicknesses of the wheel fingers and at the bottom
12 radius between adjacent wheel fingers. This design detail is similar to the design
13 process for contouring the side surfaces of steam and gas turbine wheels to
14 produce “constant” or nearly constant stress profile from the hub of the wheel
15 toward outer radius of the wheel but not including the rim of the wheel. The
16 2008 Patent abstract clearly states: “The fillets on the wheel fingers and slot
17 bottoms have a blend of different radii with the larger radii outward of the
18 smaller radii to reduce stress concentrations and to avoid stress corrosion
19 cracking in steam turbine applications.”

20
21 Q. AND DOES THIS DESIGN CHANGE FURTHER SUPPORT THE THIELSCH REPORT
22 CONCLUSION REGARDING THE PRIMARY CAUSAL FACTOR BEHIND THE EVENT?

23 A. Yes. As previously mentioned, Mr. Polich failed to even mention the Thielsch
24 Report’s actual conclusion of the root cause of the Event. The Report

¹⁹ Tipton Direct, Exhibit____(AAT-1), Schedule 3, pp. 450-456.

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 determined that GE’s equipment design was the primary causal factor
2 responsible for stress corrosion cracking and that the design stresses at the LP
3 L-1 finger-pinned blade attachment area of the LP L-1 rotor disks were
4 sufficiently high to render the Sherco 3 low pressure steam turbine rotor
5 material susceptible to stress corrosion cracking *under normal operating conditions*.
6 GE’s work on the 2008 Patent confirms the existence of this fundamental
7 design issue.

8
9 Q. WHY IS THAT SIGNIFICANT?

10 A. This is important because prior to the November 2011 Sherco 3 failure event
11 involving the L-1 wheel finger dovetail attachment, and unbeknownst to Xcel
12 Energy, GE sought to improve the design of the finger dovetail attachment to
13 reduce the susceptibility to stress corrosion cracking and applied for and was
14 granted a patent for an improved design. This patent application process was
15 ongoing while Xcel Energy key employees sought guidance from GE in early
16 2008 about inspections for its low-pressure turbines in the drum boiler plants.
17 GE, however, never disclosed that it had re-designed the finger dovetail
18 attachment to reduce susceptibility for stress corrosion cracking—which would
19 have informed Xcel Energy that its existing design was, in fact, susceptible to
20 such issues.

21
22 Q. CAN YOU SUMMARIZE YOUR OVERALL CONCERNS WITH MR. POLICH’S
23 TESTIMONY?

24 A. Mr. Polich’s testimony is based upon his reading of several documents,
25 including the Thielsch Report and various GE technical guidelines, but he has
26 not demonstrated the knowledge or experience to understand them. As I will
27 discuss in greater detail below, Mr. Polich gratuitously “cherry-picks” from

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 those documents and then selectively uses general testimony from the GE trial
2 (where the Company was not a party) to suggest that Xcel Energy knew about
3 the risks, but nevertheless chose not to perform the necessary inspection that
4 could have prevented the 2011 failure. Simply put, it is apparent *only* to Mr.
5 Polich, and *only* with the benefit of 20/20 hindsight, that this accident should
6 have been prevented by performing a blades-off, magnetic particle inspection
7 of the finger dovetails without any recommendation from GE or other cause to
8 do so.

9
10 It does not appear that Mr. Polich clearly understands that a major inspection
11 of a utility-size steam turbine generator involves literally thousands of
12 components and an equal number of repair-replace or use “as is” decisions
13 associated with the steam and feedwater systems, instrumentation, and balance
14 of plant equipment. Tellingly, Mr. Polich ignores (or fails to understand) the
15 difference between an ordinary “major” inspection, such as the one originally
16 planned for 2011 and then deferred to 2014, and a major inspection that would
17 have also included removing the blades to perform a magnetic particle
18 inspection of the finger dovetails as described in TIL 1121-3AR1.

19
20 Mr. Polich also *admits* (as he must) that the blades-off, magnetic particle
21 inspection in full accordance with TIL 1121-3AR1 is the required inspection to
22 detect latent stress corrosion cracking in the finger dovetails. (See DOC
23 response to XE IR 10 included as Exhibit____(HJS-2, Schedule 3 and Polich
24 Direct, pp. 40-41.) Yet the planned 2011 inspection—the same inspection that
25 Mr. Polich says “would have discovered the extent of the SCC in the LP turbine

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 L-1”²⁰ and for which “Xcel’s decision to delay that inspection ... was directly
2 responsible for the accident”²¹—*did not include, and had no reason to include, a*
3 *blades-off, magnetic particle inspection of the turbine finger dovetails. This is*
4 *why precision is so important when describing what “inspections” occurred—*
5 *or, as Mr. Polich suggests, should have occurred.*

6
7 In sum, if we take Mr. Polich’s generalized opinions and reasoning to their
8 conclusion, he opines that the “buckets off” (*i.e.*, blades off) magnetic particle
9 inspection described in TIL 1121-3AR1 (indisputably, the inspection needed to
10 detect latent stress corrosion cracking) should be performed every 3 to 5
11 years—without reasonable consideration of the additional outage times, costs,
12 and risk to equipment. There is no guidance from GE (or any industry practice)
13 that in 2011—or even today—supports Mr. Polich’s suggestion that the blades-
14 off, magnetic particle inspection should be routinely performed every 3 to 5
15 years as part of a major inspection.

16
17 **III. MR. POLICH’S MISCHARACTERIZATION OF THE STATE OF**
18 **INDUSTRY GUIDANCE IN NOVEMBER 2011**
19

20 Q. PRIOR TO NOVEMBER 2011, HAD GE PROVIDED GUIDANCE ON LP TURBINE
21 INSPECTION AND TESTING APPLICABLE TO SHERCO 3?

22 A. Yes. As I discussed in my direct testimony, GE issues technical information
23 letters (TILs) and General Electric Knowledge bulletins (GEKs) to its
24 customers to provide technical advice and guidance for inspecting and
25 maintaining GE-designed and manufactured power plant equipment, including

²⁰ Polich Direct, p. 58.

²¹ Polich Direct, p. 58.

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 steam turbines. As it relates to inspection of the LP turbine blades, GE issued
2 two TILs: TIL 1121-3AR1 (1993) and TIL 1277-2 (1999). But of those two, *only*
3 TIL 1121-3AR1 applies to Sherco Unit 3 and would only have applied when the
4 L-1 and L-0 blades with finger dovetails were removed from the rotor. TIL
5 1277-2, which GE did not provide to Xcel Energy for Sherco 3, expressly
6 applies to fossil steam turbines with once-through boilers (as opposed to all the
7 Sherco units' drum boilers) and therefore is not applicable.

8
9 As it relates to inspection frequency recommendations, GE issued GEK 63355
10 and GEK 46354 in the 1970s. However, in 2007, GE issued updated inspection
11 recommendations in GEK 111680: Creating an Effective Steam Turbine
12 Maintenance Program.²²

13
14 Q. DO ANY OF GE'S GEKS OR TILS—INCLUDING TIL 1277-2, WHICH EXPRESSLY
15 APPLIES TO ONCE-THROUGH BOILERS (AS OPPOSED TO SHERCO 3'S DRUM
16 BOILERS)—PRESCRIBE A 3 TO 5 YEAR MAJOR INSPECTION INTERVAL?

17 A. Neither TIL 1121-3AR1 nor TIL 1277-2 recommend a 3- to 5-year major
18 inspection interval. When GE issued GEK 63355 and GEK 46354, over forty
19 years ago, GE recommended that major inspections should take place every 3
20 to 5 years. Over time, however, both GE's recommendations and industry
21 practice related to those inspection intervals has changed, to reflect longer
22 intervals.

23
24 As noted above, GE issued updated inspection recommendations in 2007 when
25 it issued GEK 111680. This GEK identified a 6-year or longer major inspection

²² See Sirois Rebuttal, Exhibit____(HJS-2), Schedule 4.

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 interval, recognizing that inspection intervals could be extended beyond 6 years
2 depending on “fleet experience, testing results, and operational assessment[.]”²³
3 Notably, GEK 111680 expressly recognized that: “Many of the factors related
4 to the exact timing of inspections are determinable by the owner/operator;
5 other factors draw from empirical knowledge and fleet experience.”

6
7 In other words, GE’s own guidance refutes Mr. Polich’s 3 to 5 year major
8 inspection interval opinions. Rather than prescribing specific inspection
9 intervals, GE acknowledged that the owner/operator is in the best position to
10 determine inspection intervals based on numerous factors, including fleet
11 experience. And I am aware that GE gave a PowerPoint presentation in 2006
12 to Xcel Energy key personnel that confirmed that the industry trend for major
13 inspection intervals had increased from “5 to 7 years” to “10-12” years.²⁴ In
14 sum, GE’s guidance confirms that Mr. Polich is mistaken that there is a “one
15 size fits all” major inspection interval for steam turbines.

16
17 Q. DOES MR. POLICH ADDRESS GEK 111680 IN HIS TESTIMONY?

18 A. No, Mr. Polich does not address GEK 111680, which GE issued in 2007. The
19 only GEKs referenced by Mr. Polich regarding the topic of inspection intervals
20 were GEK 63355 and GEK 46354, which were both issued in the 1970s.
21 Therefore, Mr. Polich ignored the most current GE guidance during the time
22 period prior to the Event.

²³ See Sirois Rebuttal, Exhibit____(HJS-2), Schedule 4.

²⁴ Murray Rebuttal, Exhibit____(TPM-2), Schedule 2, p. 34.

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 Q. DO ANY OF GE'S GEKS OR TILS PRESCRIBE A 3 TO 5 YEAR MAJOR INSPECTION
2 INTERVAL THAT WOULD INCLUDE A BLADES-OFF, MAGNETIC PARTICLE
3 INSPECTION OF THE FINGER DOVETAILS?

4 A. No – not prior to 2011 and not today.

5

6 Q. IS GENERAL KNOWLEDGE THAT STRESS CORROSION CRACKING CAN OCCUR IN
7 LP TURBINES THE SAME THING AS HAVING OBJECTIVE FACTS/INFORMATION
8 JUSTIFYING A TIL 1121-3AR1 BLADES-OFF, MAGNETIC PARTICLE INSPECTION
9 OF THE FINGER DOVETAILS FOR A SPECIFIC LP TURBINE?

10 A. No. Large utility steam turbines such as those installed at Sherco are not
11 standardized within the power generation industry. There are significant design
12 differences between steam turbines operating with similar or even the same
13 conditions but from different manufacturers.

14

15 For example, as I stated above, the process for removing and replacing all of
16 the pins and blades from each of the four L-1 finger-dovetail rows (as required
17 to inspect for stress corrosion cracking) is extremely onerous on GE blades. In
18 contrast, while a Westinghouse or Alstom straight or curved axial entry blade is
19 also susceptible to stress corrosion cracking, the inspections for such cracking
20 are less onerous because the blades can easily be removed and the wheel rim
21 can then be inspected using magnetic particle inspection or ultra-sonic
22 inspection techniques.

23

24 Similarly, design differences in steam turbines can lead different turbines to be
25 more or less susceptible to stress corrosion cracking. To be sure, no one is
26 disputing that—generally—the power generation industry was fully aware of
27 and appreciated that stress corrosion cracking could occur in low pressure

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 turbines. But because of the differences in operating conditions (steam pressure
2 and temperature, operating speed, duty cycle (load following, base load, cycling),
3 frequency of overspeed trips and many others), differences in design features
4 (such as axial, tangential entry, and finger dovetails), differences in rotor and
5 blade mechanical and chemical properties, and many other factors, the extent
6 and frequency of stress corrosion cracking will vary.

7
8 Unfortunately, in the case of Sherco 3—based solely on hindsight and all of the
9 information learned as a result of the 2011 Event—we now know that the GE
10 low pressure turbine L-1 finger dovetail stage was more susceptible to stress
11 corrosion cracking due to its design. Compounding the issue, GE’s design of
12 the finger dovetail made inspections difficult. And as explained by Mr. Tipton
13 in both his Direct and Rebuttal Testimony, the GE finger dovetail was also
14 designed in such a way that the as-designed operating stresses were sufficient to
15 result in stress corrosion cracking even in “pure” laboratory water.

16
17 In summary, Xcel Energy’s general knowledge in 2011 that stress corrosion
18 cracking *may occur* in steam turbines was not—by itself—sufficient to warrant
19 an invasive, costly, and time-consuming blades-off, magnetic particle inspection
20 of the L-1 finger wheel dovetails in the Sherco 3 unit. Prior to the Event, there
21 was no general knowledge or industry guidance suggesting that the specific
22 design features and properties of Sherco 3 was more susceptible to stress
23 corrosion cracking.

24
25 Q. WOULD IT BE REASONABLE FOR XCEL ENERGY TO SIMPLY “ERR ON THE SIDE
26 OF CAUTION” AND PERFORM A TIL 1121-3AR1 BLADES-OFF, MAGNETIC
27 PARTICLE INSPECTION OF THE FINGER DOVETAILS AS PART OF EVERY MAJOR

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 OUTAGE EVEN IN THE ABSENCE OF ABNORMAL EVENTS/OPERATIONAL
2 ANOMALIES?

3 A. No. The TIL 1121-3AR1 magnetic particle inspection is a time consuming,
4 labor intensive, and expensive process that causes long-term wear on the
5 machine and therefore should only be performed in accordance with GE's
6 technical guidance.

7
8 As described in more detail in Mr. Murray's Rebuttal Testimony, it is Xcel
9 Energy's experience that such an inspection would add 2 to 4 weeks to a
10 planned major outage, possibly longer depending on the amount of repairs
11 needed to the retaining pin holes in the turbine wheel that were damaged during
12 removal of the pins—and add approximately \$1-\$2 million to the overall cost
13 of the major outage. Also, as set forth in my Direct Testimony, the repair of
14 retaining pin holes eventually requires a major weld repair of the rotor because
15 the pin holes can only be "oversized" so many times. Accordingly, it would be
16 patently *unreasonable* for an operator to routinely perform a blades-off, TIL
17 1121-3AR1 magnetic particle inspection without the required justification.

18
19 Q. ARE YOU AWARE OF ANY STEAM TURBINE OPERATORS THAT, PRIOR TO THE
20 EVENT, ROUTINELY PERFORMED BLADES-OFF, MAGNETIC PARTICLE
21 INSPECTIONS OF THE TURBINE FINGER DOVETAILS TO DETECT LATENT STRESS
22 CORROSION CRACKING IN THE ABSENCE OF ABNORMAL EVENTS/OPERATIONAL
23 ANOMALIES?

24 A. No.

25

26 Q. CAN YOU PLEASE SUMMARIZE THE STATE OF INDUSTRY KNOWLEDGE IN
27 NOVEMBER 2011 REGARDING THE POTENTIAL THAT STRESS CORROSION

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 CRACKING COULD LEAD TO THE KIND OF CATASTROPHIC FAILURE THAT WAS
2 EXPERIENCED AT SHERCO 3 THAT WOULD HAVE WARRANTED A BLADES-OFF,
3 MAGNETIC PARTICLE INSPECTION OF THE TURBINE WHEEL FINGER DOVETAIL
4 ATTACHMENTS?

5 A. The power generation industry where steam is generated with fossil and nuclear
6 fuel has generally been aware of stress corrosion cracking since the 1960s. The
7 Thielsch Report provides a detailed review of “Industry Experience,” including
8 an EPRI study conducted in 1997.²⁵ However, the fact remains that *general*
9 knowledge of the potential for stress corrosion cracking is not a substitute for
10 *specific* knowledge as it relates to a specific steam turbine design operating with
11 conditions outlined previously in this report. The November 2011 Sherco 3 L-
12 1 failure, where the blades liberated from the wheel, was the first in the industry.
13 This event substantially contributed to industry knowledge about the potential
14 of latent stress corrosion cracking in wheel finger dovetails and prompted GE
15 to subsequently issue TIL 1886, technical guidance specific to low pressure
16 turbines with L-1 finger dovetails and operating with steam generated by a drum
17 boiler—*i.e.*, the same type of low pressure turbine and blade attachments
18 present in Sherco 3.

19
20 As of November 2011, however, there was no GE guidance recommending a
21 time-based, magnetic particle inspection of the L-1 wheel finger dovetails for
22 power generating plants with drum boilers (in the absence of abnormal events
23 or operational anomalies as set forth in TIL 1121-3AR1).

²⁵ Thielsch Report, Tipton Direct Exhibit____(AAT-1), Schedule 2, pp. 85-86 (pp. 83-84 of the Report).

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 turbines if their recommendation of time between major outages was 3 to 5
2 years, since GE's competitors recommend time between outages that are more
3 in line with Xcel Energy's and other owner/operators' practices of
4 approximately every 10 years (or longer).

5
6 Q. WOULD A BLADES-OFF, MAGNETIC PARTICLE INSPECTION OF THE FINGER
7 DOVETAILS EVERY 3 TO 5 YEARS—AS SUGGESTED BY MR. POLICH—BE
8 PRUDENT OPERATION IN THE ABSENCE OF ANY OBJECTIVE FACTS SUPPORTING
9 SUCH AN INSPECTION?

10 A. No. Performing a blades-off, magnetic particle inspection of the finger dovetails
11 on a routine, *i.e.*, every three to five years, basis on a large unit such as Sherco 3
12 would not be prudent for any utility. The cost of the inspection, lost generation
13 revenue (during the 6- to 8-week—or longer—outage) and cost of replacement
14 power for such frequent inspections would certainly be questioned by the
15 regulator. As previously discussed, based on the design of the turbine, the act
16 of removing the finger dovetailed blades consumes some of the life of the low-
17 pressure rotor since many of the blade retaining pins must be drilled out for
18 removal and the corresponding hole must be oversized by drilling and reaming
19 for the fitting of replacement blade retaining pins. In TIL 1886, which was
20 issued approximately two years *after* the Sherco 3 failure, GE confirmed that the
21 wheel finger dovetails should be inspected by removing the blades and
22 performing a magnetic particle inspection in accordance with TIL 1121-3AR1
23 after **22 years** of operation or prior to that whenever the blades are otherwise
24 removed for replacement or inspection. In other words, even with the benefit
25 of hindsight of the 2011 Event, GE's updated (*i.e.*, post-Event) guidance
26 prescribes only three circumstances that would warrant a TIL 1121-3AR1
27 magnetic particle inspection: (1) the presence of abnormal events or operational

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 anomalies (which I will address below); (2) if the steam turbine has been
2 operational for 22 years; and (3) whenever the blades are otherwise removed for
3 replacement or inspection.

4
5 Q. IS THIS CONSISTENT WITH THE COMPANY DID IN 1999?

6 A. Yes. In 1999, the planned Sherco 3 outage included the removal and
7 replacement of the L-1 blades with an upgraded design. Even though Sherco 3
8 had only been operational for 12 years, and there were no abnormal events or
9 operational anomalies, Xcel Energy followed the guidance of TIL 1121-3AR1
10 and contracted with GE to perform a magnetic particle inspection of the turbine
11 finger dovetails as part of that planned major maintenance overhaul because the
12 blades had already been removed. Notably, no issues were detected during this
13 inspection. The inspection report is included as Exhibit___(HJS-2), Schedule 5)

14
15 Q. THE IMPLICATION OF MR. POLICH'S TESTIMONY IS THAT XCEL ENERGY DID
16 THE BARE MINIMUM (OR LESS) MAINTENANCE ON ITS LOW PRESSURE STEAM
17 TURBINES—HOW DO YOU RESPOND?

18 A. I disagree with that assertion (and what it incorrectly implies) as my experience
19 and the evidence does not support Mr. Polich's testimony. Aside from his non-
20 specific castigations that the Company failed to follow (outdated) industry
21 guidance (*i.e.*, the over 40-year old GEKs, issued in the 1970s), or apply
22 Technical Information Letters (*i.e.*, TIL 1277-2), that had not been issued to
23 Sherco 3's low pressure turbines, Mr. Polich has not pointed to any maintenance
24 failure by the Company. In addition, there are numerous examples of the
25 Company using available information to make the prudent decisions as to its
26 maintenance program for Unit 3 (and all the Sherco units).

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 For example, as explained by Mr. Murray in his Rebuttal Testimony, in 2001, at
2 a GE-sponsored conference in Atlanta, a GE representative shared with Xcel
3 Energy representatives (including Murray) that the manufacturer was starting to
4 see *tangential entry dovetail* cracking in low-pressure turbines with drum boilers—
5 in addition to the cracking issues observed with tangential entry dovetails in
6 once-through boilers that was the basis for GE’s issuance of TIL 1277-2.
7 Accordingly, despite the absence of written guidance in the form of a Technical
8 Information Letter, GE recommended that utilities with drum boilers (in
9 addition to the utilities that had previously received written guidance specific to
10 units with once-through boilers) conduct phased array ultrasonic inspections of
11 all tangential entry dovetails to look for cracking. The first major overhaul that
12 arose after this conference was the 2005 major overhaul on Sherco Unit 3.
13 Although GE had still not issued any written guidance incorporating their
14 recommendations from the 2001 conference to units with drum boilers, Xcel
15 Energy nevertheless performed a phased array ultrasonic inspection of the L-2
16 and L-3 tangential entry dovetails on Unit 3.

17
18 Next, in 2007, the Company planned a major outage for Sherco Unit 1, which
19 also has a drum boiler. As part of the inspection process for Unit 1, the
20 Company once again performed phased array ultrasonic testing of the tangential
21 entry wheel dovetails even though GE had still not issued any updated written
22 guidance incorporating their informal recommendations conveyed during the
23 2001 Atlanta conference to units with drum boilers. For Unit 1, this included
24 the L-1 tangential entry dovetail row, in addition to the L-2 and L-3 tangential
25 entry dovetail rows. The vendor performing this inspection detected cracking
26 on the L-1 tangential entry wheel dovetails, which then required machining of

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 the wheel rims followed by a major repair weld. The four L-1 wheels were
2 repaired by Alstom in Richmond, VA and Unit 1 was returned to service.

3
4 Based on the issues discovered in Unit 1, Xcel Energy took an unplanned outage
5 in 2008 to also inspect Sherco 2 for L-1 stress corrosion cracking using phased
6 array ultrasonic testing of the tangential entry dovetails. Notably, GE had still
7 not issued any updated written guidance incorporating their recommendations
8 relating to phased array ultrasonic testing of the tangential entry dovetails on
9 units with drum boilers (as first addressed by GE in the 2001 Atlanta
10 conference). The decision to take the unplanned outage to inspect Sherco 2 was
11 based upon reasonable information and evidence at that time: both Unit 1 and
12 Unit 2 had been in service since the 1970s (in contrast to Unit 3, which was put
13 in service in 1987); both Unit 1 and Unit 2 had tangential entry dovetails on the
14 L-1 stage (in contrast to Unit 3, which had *finger* dovetails on the L-1 stage); and
15 Unit 1 and Unit 2 were operated in the exact same fashion—same equipment,
16 same monitoring, and same chemistry team (in contrast, Unit 3 had its own
17 dedicated monitoring and chemistry team). The Company determined that,
18 based upon all these similarities and the findings of stress corrosion cracking on
19 the Unit 1 tangential entry dovetails, it was prudent to inspect Unit 2 to confirm
20 that there was no similar cracking (there wasn't). The 2008 unplanned outage
21 and inspection of Unit 2 was completed without specific guidance from GE,
22 but clearly demonstrates that Xcel Energy was making reasonable, informed,
23 and prudent maintenance decisions based on available data and the training and
24 experience of its key personnel.

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

**V. XCEL ENERGY'S DECISIONS WITH RESPECT TO TURBINE
INSPECTIONS UP TO 2011 AND CONSISTENCY WITH INDUSTRY
PRACTICES**

1 **V. XCEL ENERGY'S DECISIONS WITH RESPECT TO TURBINE**
2 **INSPECTIONS UP TO 2011 AND CONSISTENCY WITH INDUSTRY**
3 **PRACTICES**
4
5 Q. DO YOU AGREE WITH MR. POLICH'S SUGGESTION THAT XCEL ENERGY
6 "DELAYED" OR "DEFERRED" INSPECTION OF THE LOW PRESSURE TURBINE
7 ROTOR DISK WHEEL DOVETAIL?

8 A. No. Mr. Polich misconstrues or misunderstands Xcel Energy's decisions as they
9 relate to the 2011 planned inspection of the low-pressure turbine. While Xcel
10 Energy did defer the major inspection of the low-pressure turbine originally
11 planned for 2011 until 2014, at no time did the planned major inspection include
12 a "blades off" TIL 1121-3AR1 magnetic particle inspection of the turbine L-1
13 and L-0 wheel finger dovetails—a decision based on the fact that there were no
14 objective facts (*i.e.*, abnormal events or operational anomalies) or GE / industry
15 guidance that would have supported such an invasive inspection at that time.
16 At most, during the originally planned 2011 inspection of the low-pressure
17 turbine, Xcel Energy may have inspected the L-2 and L-3 tangential entry
18 dovetails using the phased array ultrasonic inspection technique since this
19 inspection method does not require removal of the blades. But this inspection
20 (or anything less than an inspection that would have removed the blades) would
21 not have detected the latent stress corrosion cracking that was later discovered
22 in the L-1 finger dovetails, an important fact which has not been considered in
23 Mr. Polich's testimony. As discussed by Mr. Murray in his Rebuttal Testimony,
24 Xcel Energy's contractor (Alstom) completed a visual inspection of the low-
25 pressure turbine rotor last-stage blades in 2011 and observed that "[n]o

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 corrosion, pitting, cracks, or indications were noted during [sic] in the
2 inspection.”²⁶

3
4 This is why it is important for witnesses to be precise about what types of
5 inspections they are talking about in their testimony. Here, based upon
6 information that Xcel Energy had in 2011, there was no reason to include a
7 blades-off, TIL 1121-3AR1 magnetic particle inspection of the L-1 and L-0
8 turbine wheel finger dovetails in either the originally planned 2011 inspection
9 or the “deferred” 2014 inspection.

10
11 Q. DO YOU AGREE WITH MR. POLICH’S CONCLUSION THAT XCEL ENERGY’S
12 DECISION TO DELAY OR DEFER INSPECTION OF THE LOW PRESSURE TURBINE
13 ROTOR DISK DOVETAIL WAS THE TRUE ROOT CAUSE OF THE NOVEMBER 19,
14 2011 ACCIDENT?

15 A. No. There was no evidence to indicate that the Sherco 3 L-1 finger dovetail had
16 been subjected to operational anomalies or otherwise experienced abnormal
17 events as defined by GE. Also, there was no guidance from GE that would
18 reasonably lead Xcel Energy, or any utility owner/operator for that matter, to
19 perform this invasive and costly TIL 1121-3AR1 inspection.

20
21 Instead, I agree with the root cause determinations stated in the Thielsch
22 Report:

23
24 The primary causal factor responsible for the stress corrosion
25 cracking of LP “B” disk was the high static stresses generated

²⁶ Murray Rebuttal, Exhibit____(TPM-2), Schedule 3

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 during normal operation at the pin holes, ledges and at the base
2 of the fingers of the finger pinned blade attachments in the low
3 pressure turbine L-1 stage disks. These stresses in the finger
4 pinned blade attachments are solely a function of the original
5 design and operation at design conditions.²⁷
6

7 My over 50 years of experience in the industry, combined with my interviews
8 with key Xcel Energy personnel in January 2016, reviews of their depositions
9 and trial testimony, my review of key documents such as the Thielsch Report,
10 GE documentation such as the TILs, GEKs, and GE internal communications,
11 leads me to conclude that the Company acted in a reasonable and prudent
12 manner in the operation and maintenance of Sherco Unit 3 and its two LP
13 turbines.

14
15 Importantly, Xcel Energy is in the business of producing power; as such, it
16 operates large utility-size steam turbine generators. Xcel Energy is not a steam
17 turbine designer and does not have the GE fleet data necessary to understand
18 the nuances of the GE-designed steam turbines. Owners and operators such as
19 Xcel Energy rely on manufacturers—here, GE—for unit-specific guidance
20 about which inspections should be performed on specific design features. And
21 contrary to Mr. Polich’s suggestions, GE did not provide any guidance that
22 would have justified the blades-off, TIL 1121-3AR1 magnetic particle
23 inspection of the finger dovetails in the absence of abnormal events or
24 operational anomalies—*i.e.*, the *only* inspection that would have detected the
25 latent stress corrosion cracking of the L-1 finger dovetail in 2011.

²⁷ Thielsch Report, Tipton Direct Exhibit____(AAT-1), Schedule 2, pp. 95-96 (pp.93-94 of the Report).

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 Q. BUT DOESN'T MR. POLICH CLAIM THAT SHERCO UNIT 3 *DID* EXPERIENCE
2 ABNORMAL EVENTS OR OPERATIONAL ANOMALIES THAT SHOULD HAVE
3 PROMPTED A TIL 1121-3AR1 MAGNETIC PARTICLE INSPECTION?

4 A. Mr. Polich did make that claim, generally, and he is simply wrong once again.
5 Mr. Polich did not present any testimony defining or explaining what might
6 have constituted “abnormal events” or “operational anomalies” that would
7 have triggered a TIL 1121-3AR1 magnetic particle inspection. Instead, in
8 response to an Information Request,²⁸ he pointed to a report from Mr. James
9 Schultz, an expert for GE in the *GE Litigation*, who I understand is not
10 presenting testimony in this case and whose report in the GE Litigation was
11 thoroughly addressed and rebutted by both me and Company witness David
12 Daniels.²⁹ Despite this direct and specific request for information from the
13 Company, Mr. Polich did not (or could not) identify any specific “abnormal
14 events or operational anomalies.”

VI. CONCLUSION

16
17
18 Q. DOES THE FACT THAT A FAILURE HAPPENED DEMONSTRATE THAT THERE WAS
19 IMPRUDENT MAINTENANCE?

20 A. No, and it would be improper to draw such conclusions based solely on the fact
21 that something did, unfortunately, go wrong (*i.e.*, 20/20 hindsight). The failure
22 happened for the reasons stated in the Thielsch Report (and summarized in Mr.

²⁸ See DOC's Response to XE Information Request No. 30, included as Exhibit____(HJS-2), Schedule 6.

²⁹ For example, regarding the condenser tube leaks discussed by Mr. Schultz and included in the passage relied on by Mr. Polich, I addressed this issue in my rebuttal report “Rebuttal to Expert Witness Report of James D. Schultz” dated April 25, 2016 at paragraph 23. My rebuttal report is included as Exhibit____(HJS-2), Schedule 7.

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 Tipton’s Direct and Rebuttal testimony). But as to prudence, and as explained
2 in this Rebuttal (with evidentiary support), Xcel Energy made prudent,
3 considered, and well-reasoned maintenance decisions related to Unit 3 that were
4 well within the range of reasonable utility practices. Not only were those
5 maintenance decisions reasonable and aligned with industry trends, they were
6 consistent with GE’s applicable guidance existing at that time (*i.e.*, GEK 111680
7 and GE’s 2006 PowerPoint confirming industry trend for inspection intervals
8 had increased to “10-12” years).

9
10 Q. WAS IT COMMON INDUSTRY PRACTICE IN 2011 TO DO A BLADES-OFF, MAGNETIC
11 PARTICLE INSPECTION OF THE FINGER DOVETAILS TO DETECT LATENT STRESS
12 CORROSION CRACKING IN THE ABSENCE OF ABNORMAL EVENTS/OPERATIONAL
13 ANOMALIES?

14 A. No, not to my knowledge and based on my 53-years of industry experience. It
15 would be imprudent to perform such an invasive, costly inspection without
16 justification—especially, as Mr. Polich suggests, every 3 to 5 years. At the plant
17 level, the engineering manager and plant manager would likely question this
18 recommendation (and the associated expenditure, as they did for the unplanned
19 outage to inspect the L-1 tangential entry wheel dovetails on Sherco 2 in 2008)
20 without any indication of abnormal events or operational anomalies or
21 manufacturer guidance that the risk would be too great if the steam turbine
22 generator was allowed to continue to operate. The applicable regulators would
23 also likely take issue with such expensive outages that were not required by
24 manufacturer guidance. It is important to keep in mind that the Sherco 3 L-1
25 finger dovetail failure was the first in the industry. Prior to this event, there was
26 no history of a similar failure where blades were liberated from the rotor, so it

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 would have been uncommon for a plant to perform this inspection in the
2 absence of an abnormal event or operational anomaly.

3
4 Q. WHEN THE COMPANY MADE ITS OUTAGE PLAN IN 2011, DID THE COMPANY
5 MAKE REASONABLE DECISIONS BASED ON THE INFORMATION AND
6 MANUFACTURER GUIDANCE THAT THE COMPANY HAD AT THE TIME?

7 A. Yes. In 2011, there was no specific guidance from GE that would necessitated
8 Xcel Energy to schedule a major inspection of the low pressure turbine—let
9 alone a major inspection that would have included removing the blades to
10 perform a magnetic particle inspection of the L-1 and L-0 finger dovetails.
11 Further, contrary to Mr. Polich’s testimony, GE—as the Original Equipment
12 Manufacturer—confirmed in GEK 111680 that owners/operators are in the
13 best position to determine inspection intervals based on numerous factors,
14 including fleet experience. And in a 2006 PowerPoint presentation to Xcel
15 Energy key personnel, GE further confirmed that the industry was trending to
16 “10-12” years between major inspections. This directly disproves Mr. Polich’s
17 opinion that “GE recommends three to five year service interval [sic] for major
18 turbine inspections.”³⁰

19
20 Q. IN YOUR EXPERT OPINION, BASED ON YOUR 53-YEARS OF STEAM TURBINE
21 INDUSTRY EXPERIENCE AND REVIEW OF SHERCO 3 MAINTENANCE AND
22 OPERATIONS PRACTICES, DID THE COMPANY PRUDENTLY OPERATE AND
23 MAINTAIN SHERCO 3?

24 A. Yes. The Company’s actions operating and maintaining Sherco 3 were well
25 within the range of reasonable utility actions, based on information available to

³⁰ Polich Direct, p. 39.

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 the Company at the time. Further, the Company's actions operating and
2 maintaining Sherco 3 were well within common industry practice as they existed
3 at the time of the November 2011 event.

4

5 Q. DOES THIS CONCLUDE YOUR REBUTTAL TESTIMONY?

6 A. Yes, it does.

**Northern States Power Company, doing business as Xcel Energy
Information Request**

Docket No.: E002/GR-12-961, E002/GR-13-868; E999/AA-13-599;
E999/AA-14-579; E999/AA-16-523; E999/AA-17-492;
E999/AA-18-373; OAH 65-2500-38476
Sherco 3

Requestor: Xcel Energy - Tara R. Duginske, Assistant General Counsel, Xcel Energy
Requestor email: Tara.R.Duginske@xcelenergy.com
Requested from: Minnesota Department of Commerce
Date of Request: August 14, 2023 Information Request No. 25
Response Due: August 24, 2023

Reference: Direct Testimony of Mr. Richard Polich

Question:

For each of the following uses of the term “good utility practice,” please identify all documents relied on by Mr. Polich to describe or define “good utility practice” as used in the identified testimony:

- a. Page 5, Line 12
- b. Page 6, Line 8
- c. Page 55, Line 15
- d. Page 56, line 8
- e. Page 56, Line 11

Response:

The term good utility is defined on pages 6 & 7 of Mr. Polich’s testimony and no other documents were used to describe or define the term.

Preparer: Richard A. Polich
Title: Managing Director
Department: Power Supply
Telephone: 501-316-9805
Date: August 24, 2023

27005479v1

**Northern States Power Company, doing business as Xcel Energy
Information Request**

Docket No.: E002/GR-12-961, E002/GR-13-868; E999/AA-13-599;
E999/AA-14-579; E999/AA-16-523; E999/AA-17-492;
E999/AA-18-373; OAH 65-2500-38476
Sherco 3

Requestor: Xcel Energy - Tara R. Duginske, Assistant General Counsel, Xcel Energy
Requestor email: Tara.R.Duginske@xcelenergy.com
Requested from: Minnesota Department of Commerce
Date of Request: August 9, 2023 Information Request No. 2
Response Due: August 21, 2023

Question:

State all experience Mr. Polich has with operating or maintaining fossil steam turbines, including but not limited to, and separately identifying, experience with GE manufactured turbine-trains like Sherco Units 1 and 2 (with tangential entry dovetails on the L-1) and experience with GE manufactured turbine-trains like Sherco Unit 3 (with finger dovetails on the L-1).

Response:

Mr. Polich has over 43 years of experience with fossil power plants with steam turbines. In addition, Mr. Polich also has experience with nuclear power plant steam turbines whose low pressure steam turbine has similar operating characteristics to Sherco 3's low pressure steam turbine. Mr. Polich cannot recall which of the units he worked on were GE or other turbine manufacturers. While at Consumers Energy, Mr. Polich worked on all the company's steam turbines during his career. Mr. Polich was also responsible for thermal cycle design of the Midland Cogeneration Venture combined cycle plant. This design required developing a steam cycle that matched the existing steam turbine designed to be used in the Midland Nuclear Plant based on a B&W nuclear steam supply system. Since leaving Consumers Energy, MR. Polich has continued to provide engineering support for coal and natural gas plants support of his clients. This includes coal and natural gas cogeneration facilities, all with steam turbines. Recent plants with steam turbines in which Mr. Polich has worked include Independence Power Plant Unit 2, RS Nelson Power Station Unit 6, Plum Point, John W. Turk, Bartow Combined Cycle Project, and Harrison County. Mr. Polich does not know which of the steam turbines have tangential entry dovetails or finger dovetails.

Preparer: Richard A. Polich
Title: Managing Director
Department: Power Supply
Telephone: 501-316-9805
Date: August 21, 2023

26979707v1

**Northern States Power Company, doing business as Xcel Energy
Information Request**

Docket No.: E002/GR-12-961, E002/GR-13-868; E999/AA-13-599;
E999/AA-14-579; E999/AA-16-523; E999/AA-17-492;
E999/AA-18-373; OAH 65-2500-38476
Sherco 3

Requestor: Xcel Energy - Tara R. Duginske, Assistant General Counsel, Xcel Energy
Requestor email: Tara.R.Duginske@xcelenergy.com
Requested from: Minnesota Department of Commerce – Richard A. Polich
Date of Request: August 9, 2023 Information Request No. 3
Response Due: August 21, 2023

Reference: Direct Testimony of Mr. Richard Polich

Question:

- a) State all education, degrees, coursework, memberships, etc. Mr. Polich has in the area of water chemistry.
- b) State all experience Mr. Polich has in operating, monitoring, evaluating, or analyzing water chemistry.
- c) State all experience Mr. Polich has in analyzing historical water chemistry data.
- d) Provide a list of all matters or cases in which Mr. Polich been offered as an expert in water chemistry.
 - i. Indicate if any of these matters or cases in which Mr. Polich has been offered as an expert in water chemistry involved the steam path in a fossil unit.
- e) Produce all reports, testimony, opinions and conclusions reached for each matter or case in which Mr. Polich has been offered as an expert in water chemistry.

Response:

- a) Mr. Polich does not have any degrees or specific course work in the area of water chemistry. Mr. Polich has taken college courses in chemistry, understands

- the fundamentals of proper water chemistry, and how it affects materials in the steam turbine. Mr. Polich does not have any memberships in water chemistry.
- b) Mr. Polich's experience with steam turbines are discussed in response to Xcel's Information Request No. 2. Some of that experience includes review of water chemistry impacts on plant operations and damage to plant equipment.
 - c) During the startup of Consumers Energy Campbell 3 power plant, Mr. Polich was part of the team assigned to determine the root cause of the super heater failure. Mr. Polich reviewed the water chemistry data as well as the boiler operational data. The final cause of the super heater failure, which had only been subject to steam conditions for three months, was boiler drum carryover during a power increase and subsequent plant shutdown shortly afterwards. Sodium in the boiler drum was carried over into the super heater and left deposits on the tubes. During the subsequent cooldown and the plant being idle for three days after the carryover, the boiler tubes experienced stress corrosion cracking in the weld areas. Upon startup, the welds failed resulting in the replacement of the superheater. Mr. Polich also analyzed water chemistry data for Plum Point power station as part of assessment of weld failure in the boiler economizer. In assessing the low pressure steam turbine last stage blade failure of Duke Energy Florida's Bartow combined cycle plant, Mr. Polich reviewed historical plant water chemistry data. Mr. Polich has also had discussions with plant personnel at a variety of power plants on water chemistry as it relates to various plant problems.
 - d) Mr. Polich has not provided direct testimony on water chemistry in regulatory proceedings because the equipment failure presented in his testimony was not related directly to water chemistry. As part of his investigation into equipment failures, Mr. Polich has reviewed water chemistry because of its potential to impact material failure.
 - e) Not applicable.

Preparer: Richard A. Polich
Title: Managing Director
Department: Power Supply
Telephone: 501-316-9805
Date: August 21, 2023

**Northern States Power Company, doing business as Xcel Energy
Information Request**

Docket No.: E002/GR-12-961, E002/GR-13-868; E999/AA-13-599;
E999/AA-14-579; E999/AA-16-523; E999/AA-17-492;
E999/AA-18-373; OAH 65-2500-38476
Sherco 3

Requestor: Xcel Energy - Tara R. Duginske, Assistant General Counsel, Xcel Energy
Requestor email: Tara.R.Duginske@xcelenergy.com
Requested from: Minnesota Department of Commerce – Richard A. Polich
Date of Request: August 9, 2023 Information Request No. 4
Response Due: August 21, 2023

Reference: Direct Testimony of Richard A. Polich, pp. 2-3

Question:

- a) What type of power generation equipment was involved when you “provided plant engineering design, project oversight and engineering trouble shooting on [Consumer Powers Inc.’s] existing and new construction power generation fleet” in 1979?
- b) Identify each “fossil generation project” for which you provided project development work and state the nature of your work on each project.
- c) Identify all instances of assessing, evaluating, or analyzing operations, management, equipment failure or maintenance and repair practices for power generating units with GE turbine-trains in fossil units.

Response:

- a) Mr. Polich partially discussed this issue in Discovery Response 2 and 3. Mr. Polich work in Consumers Energy’s Engineering Department in 1979 involved coal and natural gas plants. Mr. Polich was responsible for oversight of Midland Nuclear steam cycles system design between during 1980 – 1984. Mr. Polich also was assigned to Palisades Nuclear plant in 1985 as part of a team overseeing design and construction of systems overhaul.
- b) Mr. Polich provided project development work on coal plants in Georgia, Michigan and Indiana, none of which were ever built.
- c) See DOC’s response to XE-002 and Schedule 1 to Mr. Polich’s Direct Testimony (RAP-D-1).

Preparer: Richard A. Polich
Title: Managing Director
Department: Power Supply
Telephone: 501-316-9805
Date: August 21, 2023

26979709v1

**Northern States Power Company, doing business as Xcel Energy
Information Request**

Docket No.: E002/GR-12-961, E002/GR-13-868; E999/AA-13-599;
E999/AA-14-579; E999/AA-16-523; E999/AA-17-492;
E999/AA-18-373; OAH 65-2500-38476
Sherco 3

Requestor: Xcel Energy - Tara R. Duginske, Assistant General Counsel, Xcel Energy
Requestor email: Tara.R.Duginske@xcelenergy.com
Requested from: Minnesota Department of Commerce – Richard A. Polich
Date of Request: August 9, 2023 Information Request No. 10
Response Due: August 21, 2023

Reference: Direct Testimony of Richard A. Polich – “Ultrasonic testing provides the ability to detect flaws in parts below the surface due to the penetration of the ultrasonic waves deep into the part and the reflection off cracks in the material. It is often used to detect SCC deep within a part.”

Question:

Is it your opinion that the stress corrosion cracking (“SCC”) on the internal fingers of finger dovetail rotors can be detected using ultrasonic (“UT”) examination?

If yes, provide all documents supporting this contention.

Response:

The portion of Mr. Polich’s testimony being quoted was a description of ultrasonic testing. GE’s recommendation for finger dovetail rotors inspection was to perform Magnetic Particle Inspection. GE specified in TIL 1121-3AR1

Preparer: Richard A. Polich
Title: Managing Director
Department: Power Supply
Telephone: 501-316-9805
Date: August 21, 2023

PUBLIC DOCUMENT
DISREGARD CONFIDENTIAL MARKING IN FOOTER



GEK 111680
May 2007

GE Energy

Creating an Effective Steam Turbine Maintenance Program

NSP, et al v GE

EX 724

Date: 7-19-16

Richard G. Stirewalt
Stirewalt & Associates

These instructions do not purport to cover all details or variations in equipment nor to provide for every possible contingency to be met in connection with installation, operation or maintenance. Should further information be desired or should particular problems arise which are not covered sufficiently for the purchaser's purposes the matter should be referred to the GE Company.

© 2007 General Electric Company

PUBLIC DOCUMENT
DISREGARD CONFIDENTIAL MARKING IN FOOTER

GEK 111680

Creating an Effective Steam Turbine Maintenance Program

The below will be found throughout this publication. It is important that the significance of each is thoroughly understand by those using this document. The definitions are as follows:

NOTE

Highlights an essential element of a procedure to assure correctness.

CAUTION

Indicates a potentially hazardous situation, which, if not avoided, could result in minor or moderate injury or equipment damage.

WARNING

INDICATES A POTENTIALLY HAZARDOUS SITUATION, WHICH, IF NOT AVOIDED, COULD RESULT IN DEATH OR SERIOUS INJURY

*****DANGER*****

INDICATES AN IMMINENTLY HAZARDOUS SITUATION, WHICH, IF NOT AVOIDED WILL RESULT IN DEATH OR SERIOUS INJURY.

PUBLIC DOCUMENT
DISREGARD CONFIDENTIAL MARKING IN FOOTER

Creating an Effective Steam Turbine Maintenance Program

GEK 111680

TABLE OF CONTENTS

I. BACKGROUND..... 4

II. MONITORING & DIAGNOSTICS 4

 A. Vibration Level 5

 B. Thermodynamic Performance & Efficiency 6

III. INSPECTION & TESTING 7

 A. Visual Examination 7

 B. Nondestructive Testing 9

 C. Last Stage Buckets Inspections 10

 D. Borescope Inspections 11

IV. MAINTENANCE SCOPE & FREQUENCY..... 12

 A. Factors 13

 B. Scope 13

 C. Intervals 15

 D. Interval Extensions 16

LIST OF TABLES

Table 1. Visual Inspection Areas 12

Table 2. Periphery Maintenance 14

Table 3. Inspection Interval Matrix 15

PUBLIC DOCUMENT
DISREGARD CONFIDENTIAL MARKING IN FOOTER

GEK 111680***Creating an Effective Steam Turbine Maintenance Program*****I. BACKGROUND**

GE steam turbines have significant differences in the design, application, steam conditions, and output. However, the major components and supporting systems experience similar degradation mechanisms. While it is not possible to exactly forecast the rate of deterioration due to the many unforeseen conditions that a unit may be subjected to during its life (number of start-ups, variation in loading and steam conditions, rubbing of rotating and stationary components, chemical attack, solid particle erosion, water erosion, and water induction etc.), it is understood that proper operation and adherence to starting and loading instructions are vital to sustained performance. Implementing a thorough maintenance and monitoring program is the most effective way to retain reliability, performance and avoid major expenses due to failure of components. As such, GE recommends a comprehensive maintenance management system that incorporates the following elements:

- Monitoring and Diagnostics
- Inspection and Testing
- Maintenance Scope & Frequency

Since the frequency of inspection is dependent upon service duty, system demands, age of the unit, and many other plant requirements, the owner must ultimately determine the exact time intervals between inspections to balance performance, reliability and cost. It is the intent of this instruction to provide information on each of these elements, which will aid the owner/operator to establish a thorough and cost effective maintenance program.

II. MONITORING & DIAGNOSTICS

Between periods of normal maintenance, there are a number of parameters an operator can monitor to detect changes in operating conditions. This facilitates diagnostics in deviation from design conditions to understand the overall condition of the unit and gives capability to predict possible equipment failures in advance.

NOTE

Several parameters have associated alarm and trip settings based on unit configuration and application. An alarm condition represents any condition exceeding a specified threshold and provides indication of abnormal operating conditions to be investigated. Actions should be taken to remove or clear the condition. A trip condition represents any condition that exceeds a specified threshold and provides automatic action to protect equipment from potential failure. Proper actions are critical to ensure unit longevity and prevent potential component failure, if alarm and trip conditions exist.

The following list of parameters is, as a minimum, recommended to effectively manage the health and performance of a steam turbine.

- Speed (RPM) & Power (MW)
- Bearing vibration – seismic, shaft rider, or shaft x-and-y proximity probes (as applicable)
- Journal bearing and thrust bearing metal temperatures
- Condensate and steam chemistry
- Steam turbine inlet pressure & temperature

PUBLIC DOCUMENT
DISREGARD CONFIDENTIAL MARKING IN FOOTER***Creating an Effective Steam Turbine Maintenance Program*****GEK 111680**

- Steam turbine 1st stage pressure & temperature (as applicable)
- HP turbine exhaust pressure & temperature
- IP turbine inlet pressure & temperature
- LP turbine inlet pressures & temperature
- Steam turbine rotor/shell differential expansions (as applicable)
- Steam turbine shell and steam chest temperatures/differentials (as applicable)
- Admission and extraction pressures and temperatures (as applicable)
- Extraction line thermocouples to detect water induction (as applicable)
- Sealing steam and exhauster pressures (as applicable)
- Lube oil and hydraulic fluid supply pressures and temperatures

In addition to the turbine and plant control system capabilities, various systems and software packages are available to compile trends, perform diagnostics, and perform overall condition monitoring. This allows effective analysis of data with the intent of detecting and addressing potential issues in a timely and cost effective manner. It is recommended that employment of one of these systems be considered as part of a comprehensive monitoring program.

A. Vibration Level

The continuous monitoring system for GE steam turbines is referred to as the Turbine Supervisory Instrumentation (TSI) System and includes the typical radial displacement vibration and axial position measurements used for GE steam turbines. Vibration monitoring capability and evaluation is one of the most important portions of the TSI system for trending and predicting changes in turbine health and thermodynamic performance. Overall, vibration monitoring provides the following capabilities:

1. A means of detecting bearing problems. A change in vibration level or erratic vibration reading can be indicative of a wiped bearing and scored journal, as can an increase in bearing metal or oil drain temperature.
2. A means of detecting problems in the rotating parts. Any circumferential variation in weight in the rotating parts will result in an unbalance, which will be reflected in the vibration level at the bearings. Examples are: loss of bucket covers, loss of part or all of a bucket. Step changes in vibration level are indicative of this condition in many cases.
3. A means of detecting bowed rotors. Rubbing of steam path components due to insufficient clearance, created by mis-assembly or mis-operation can create a bow due to uneven heating or cooling of the rotor surfaces. This shift in center of rotation further compounds the rub and increases distortion. Packing, spill strips and bucket covers are the most frequently damaged parts in a bowed rotor event, but permanently bowed rotors may also occur if the localized heating or cooling is sufficient to change material properties of the rotor body. A bow in the rotor of even a few mils will cause a shift in the axis of rotation sufficient to produce a change in vibration level at the bearings. In the low-pressure element of the unit, which contains longer buckets, severe mechanical damage can be caused by water induction and this may be reflected by a change in the vibration level at the bearings. Where applicable, water detection thermocouples can be used to better identify if there is a water induction problem and to help identify the source of the water.

GEK 111680***Creating an Effective Steam Turbine Maintenance Program***

4. A means of detecting a water induction incident. Water backing up from extraction lines and cold reheat lines will cause contraction of the shell lower half, giving a humping effect that can lift the diaphragm packing against the rotor, causing radial rubs and subsequent bowing of the rotor. Another consequence is potential for quenching and localized cooling of the rotor surface. As this occurs the rotor bows away from the area and yields in tension. Dependent on the severity and location, after temperatures equalize, the quenched area may have compressive surface residual stresses resulting in a permanent bow. Where applicable, water detection thermocouples can be used to better identify if there is a water induction problem and to help identify the source of the water. Depending upon the specific characteristics of the unit, including whether water detection thermocouples are installed, additional information on water induction is available either in separate turbine instruction book articles or upon request from General Electric.
5. A means of detecting a cracked rotor. A rotor may crack from repeated excessive thermal stresses or in rare cases, from high cycle fatigue. Thermal cracking (low cycle fatigue) can result from a few incidents of extremely high thermal stresses (such as water induction) or from repeated thermal stresses of lesser but still dangerous magnitude (as in repeated startup and shutdown beyond the recommended starting and loading limits). High cycle fatigue of a shaft or rotor may be produced by periods of operation with adjacent bearings misaligned. As a crack develops, it will change the flexibility of the rotor and hence the vibration level. It may also cause the rotor to react in an erratic manner to normal attempts to balance. Balancing of cracked rotors to achieve operating speed and load is not recommended and should not be attempted.

B. Thermodynamic Performance & Efficiency

An increase in operating pressure within any section of a unit can be indicative of:

- A change in cycle operation
 - Internal deposits within the steam path
 - Internal damage within the steam path
1. A reduction in operating pressure could be indicative of mechanical damage in which the failed part is digested to the point of not restricting steam flow, but the loss of the part increases the flow capacity of the steam path. Example - loss of or erosion on buckets or partitions.
 2. A loss of efficiency in any section of the unit can be indicative of internal deposits or internal damage the same as described above. It should be noted that internal damage, even to the extent of bucket loss might not necessarily be reflected as increased vibration level if the loss occurs in a symmetrical manner.

PUBLIC DOCUMENT
DISREGARD CONFIDENTIAL MARKING IN FOOTER***Creating an Effective Steam Turbine Maintenance Program*****GEK 111680****III. INSPECTION & TESTING**

Two methods of inspection are available for better understanding the overall health and performance of a steam turbine, visual and nondestructive testing. Each method can provide enormous amount of information and should be employed at different times during the life of the unit. A good visual examination will quite often reveal the majority of problems that might be encountered, and will generally reveal areas that should be more thoroughly examined by nondestructive testing. Visual examinations should be completed early in an outage or shutdown period, regardless of type, to help recognize priorities and facilitate acquisition of any replacement materials should they be needed, thus helping to assure completion of necessary action within the planned outage time span.

A. Visual Examination

1. *Rubbing* - Rubbing can occur both in the radial and axial direction. Look for rubbing on the covers, packing, wheels and dovetails. Significant rubbing in any of these areas can be critical because of the effect of localized heating. Cover and bucket material, especially in the high temperature stages, is subject to cracking when severely rubbed. On the wheels and rotors, the heat-affected zone may be more significant than the amount of metal removed by rubbing.
2. *Erosion* - Erosion of steam path components can occur due to various sources and in some cases require implementation of extensive repair programs to restore steam path condition to nominal. Proper management of these sources is key to minimizing erosion of the steam path and the effects on lifecycle cost. While a majority of the initiating events that cause erosion conditions are one-time events that can be prevented, sometimes balance of plant equipment operation permits inadequate steam quality to be applied to the steam turbine.
 - a. **Water Erosion** - Excessive water erosion can be caused by mis-operation or misdirection of water sprays, running for extended periods with lower than normal reheat temperature, or because of water induction into the steam path from an extraction connection.
 - b. **Foreign Particle Erosion** - Excessive foreign particle erosion usually is noted on the governing stage or first stage of the reheat section. The source of particles is an oxide carryover from the boiler and steam pipes or shot peen material left in the steam leads after welding. Photographs and/or casts (R.T.V. rubber, dental compound) can be an invaluable tool for comparison at a future outage.
3. *Cracks* - Close scrutiny can also reveal cracks in covers, vanes, dovetails, or rotors. These cracks can be the results of rubbing, impact damage, fatigue, thermal stresses, or stress corrosion. Early discovery, visually, can lead to proper nondestructive testing and analysis to determine the cause and recommendations for correction.
4. *Stress Corrosion* - Materials and stress levels required to build a unit make various components subject to stress corrosion cracking (SCC) if caustic sulfides or chlorides are introduced. Erosion shields, dovetail pins, buckets, wheels, rotors and shafts are all subject to stress corrosion cracking in the presence of these contaminants. Proper chemistry control is critical to minimizing this effect and is covered in a separate instruction book article. To minimize the possibilities of stress corrosion cracking, proper procedures must be followed when cleaning main steam piping to avoid introducing chemical contaminants into the turbine. The recommended procedures are covered in a separate instruction book article. During operation, chemicals in the boiler may also be carried over by entrainment or in the vapor phase to deposit in specific temperature and pressure regions of the turbine. Even low proportional carryover into the turbine, because of the concentrating mechanism, which exists in the machine, can lead to damaging concentrations of contaminants. Both caustic and chlorides can be carried over in the vapor phase. In plants where

GEK 111680***Creating an Effective Steam Turbine Maintenance Program***

demineralizers are employed, if resins become depleted or regeneration is carried out incorrectly, it is possible for sodium ions or chloride ions to be introduced into the feedwater. Thus, close attention is required in this area.

5. *Deposits* - Deposits that have built up on or in the steam path, should be removed. It is advisable that samples of deposits be taken from the steam path and rotor for laboratory analysis. This analysis can indicate whether contaminants are entering the unit, the possible source of contamination, and result in a recommendation to eliminate, or at least reduce the source of contamination.
6. *Removal of Deposits* - Removal of insoluble deposits from rotors and buckets by blast cleaning has come to be an accepted practice. Tests indicate that the use of 220-mesh aluminum oxide is satisfactory. It produces a soft gray satin finish and slightly increases the fatigue strength of the material. In addition to the relatively pure nature of the product, it also contains a corrosion inhibitor.

While inherent sturdiness of General Electric turbine buckets has been long recognized, carelessness in cleaning operations may seriously affect the mechanical strength of the part. Hand cleaning with files, scrapers, etc. often produces heavy transverse scratches, which can cause greatly reduced fatigue strength in turbine buckets. Blast cleaning in general is far superior to hand cleaning methods and results in a much quicker, less expensive, and superior job. It reaches fillets and crevices that cannot be reached by hand cleaning methods. Blast cleaning should be done after a complete visual inspection and prior to any nondestructive testing.

CAUTION

Special cleaning instructions and requirements exist for High Velocity Oxygen Fuel (HVOF) or plasma coated diaphragm partitions or buckets. Improper cleaning can result in inadequate removal of deposits or damage to equipment.

For soluble deposits, various methods are available but the only conclusive way to determine all deposits have been removed from the interior dovetail surfaces is complete removal of buckets with subsequent cleaning, inspection, and testing. Contact your local GE Service Office if more information is required on methods and requirements of cleaning soluble deposits is needed.

It is important to emphasize that under circumstances of severe contamination with corrosive deposits such as caustic, additional actions are generally required to assess if stress corrosion cracks have initiated, especially in more highly stressed regions such as dovetails or keyways in shrunk on wheels. Ultrasonic examinations can be used effectively in many cases to inspect internal regions without disassembly. However, removal of partial or full rows of buckets may be required in cases where the potential for cracking is particularly high, or where ultrasonic inspections cannot be used effectively due to geometry concerns. For built-up rotors, disassembly of wheels may be required in some cases to inspect wheel bore and keyway surfaces.

7. *Steampath Inspections* – Several visual inspections of both stationary and rotating components are recommended. While some of these can be done through non-intrusive means using a borescope the entire steam path is only viewable during a major outage overhaul and provides the best access to complete these critical checks. Your local GE Service Office can provide detailed process and acceptable measurement criteria. In general the following items should be inspected:

PUBLIC DOCUMENT
DISREGARD CONFIDENTIAL MARKING IN FOOTER***Creating an Effective Steam Turbine Maintenance Program*****GEK 111680**

- Visual inspection of the buckets to verify that there are no gaps between adjacent bucket cover shrouds and dovetails as well as no bucket lifting between bucket and wheel
- Inspection for solid particle impingement, with close attention to the first few stages of the HP & IP rows as well as inspection for tenon corrosion
- Visual inspection for diaphragm partition damage and contour
- Detailed inspection of sites that indicates rubbing of stationary and rotating components. Localized rubbing can be a precursor to inadequate clearance control during operation and should be investigated prior to re-assembly
- Visual inspection of the buckets should also be performed to verify that the grub screw retention feature at the closure bucket is properly installed. (as applicable)
- For the rotor strip seals a visual inspection should be performed per GEK 110920.

B. Nondestructive Testing

There are several means available to test the soundness of the turbine rotor and buckets; X-ray, ultrasonic test, magnetic particle test, and red-dye penetrant test or Zyglo-test. Each of these tests has its limitations and is more applicable to certain areas.

1. *X-Ray* - X-ray testing is most applicable during manufacture of buckets and has not had widespread usage as an inspection tool for an in service unit, primarily because the defects being tested for are not internal to the part. However, X-ray testing can be used to check the erosion shields on last stage buckets.
2. *Ultrasonic Testing* - The use of ultrasonic testing is widespread. Areas that can be inspected by ultrasonic means are: bucket dovetail pins, bucket and rotor dovetails, integral rotor bodies, and shrunk-on wheels. Special tests have been developed by General Electric to detect cracked dovetail pins, cracked bucket dovetails and wheel dovetails, and to determine the depth of a crack in a rotor surface.

Ultrasonic testing is available as a test and should be routinely applied to integral (no shrunk-on wheels) rotors during major inspections. It is recommended that all integral rotors have an inspection conducted after 10 years of service. Based on results of the testing performed by GE will specify re-inspection intervals. The details of the inspection depend upon whether the rotor has a bore. On boreless rotors, an ultrasonic inspection is performed from the rotor peripheral surfaces. The extent of coverage is limited by the external geometry of the rotor. A more detailed examination is possible on rotors with a bore. In these cases, the inspection would also include a visual and magnetic particle inspection of the bore surface and an ultrasonic inspection from the rotor bore. Inspection recommendations for nuclear units (1500 and 1800 RPM) differ slightly, and are described in GEK 72178. It is recommended that specially trained General Electric personnel be utilized for these tests.

3. *Magnetic Particle Testing* - Magnetic particle testing has long been established as a reliable and quick means of testing the entire assembled rotor; however, care must be exercised in testing the high temperature stages. The high strength materials can be magnetic particle tested though it is a little more difficult and time consuming than on the more readily magnetized materials used in the lower temperature regions.

GEK 111680***Creating an Effective Steam Turbine Maintenance Program*****CAUTION**

Erosion shields are of non-magnetic materials and must be tested by a dye-penetrant or fluorescent penetrant.

4. *Red-Dye Penetrant or Zyglo* - Red-dye penetrant or Zyglo must be utilized in testing non-magnetic materials such as those used in erosion shields. It is also useful in verifying magnetic particle test results. Trained personnel should be used for this test due to the possibilities of mis-interpretation of results.

Properly applied and interpreted nondestructive testing can do much to eliminate the possibility of a future forced outage. The above discussion, by necessity, is not intended to be a detailed instruction for inspections. The local GE Service Office can supply technical direction and trained personnel to make a complete and thorough inspection. GE will provide repair and operating recommendations upon reporting of the results of any inspection. Upon receipt of a complete description of the problem, GE engineers will describe the repair options available, considering the design parameters on the stage, service experience with other similar designs, and experience obtained with various kinds of repair procedures

C. Last Stage Buckets Inspections

1. A turbine is occasionally shutdown for short durations due to issues with other plant components. At that time, an inspection of the last stage exhaust region can be made with little difficulty through the access manholes. This method of inspection can reveal a number of operational problems, last stage difficulties, or problems related to the internal condition in the machine upstream of the last stage. The following can all be detected by means of last stage inspection
 - a. *Last Stage Erosion* - Excess erosion on the trailing or leading edge of the last stage buckets can be caused by mis-operation or mis-direction of water sprays, running for extended periods with a lower-than-normal reheat temperature, or water induction into the steam path from an extraction connection upstream of the last stage. Erosion measurements should be taken & trended to determine abnormal indications.
 - b. *Water Induction* - Serious mechanical damage to the latter stages may result from water induction. Visual inspection of the last stage may reveal if such a problem exists in the unit.
 - c. *Stress Corrosion Cracking* - As discussed, stress corrosion cracking is intergranular cracking of components at stress concentrations in the presence of a corrosive agent. The most common corrosive agents are caustic, chlorides, and sulfides that can be introduced into the steam path by carryover in steam, or as a residue left from a cleaning agent. Another factor required for such cracking is a warm, moist atmosphere, which is exactly the condition found in the latter stages of a steam turbine.
 - d. *Mechanical Failure* - Mechanical failures of vanes, covers, or tie-wires would be discovered during inspection.
 - e. *Foreign Material Damage* - Mechanical damage to vanes, covers, or tie-wires would indicate possible action to prevent failure and loss of efficiency.
2. Considering the value of the information which can be obtained by such an inspection, the ease with which it can be obtained, and the severe consequences that may result from failure of last

PUBLIC DOCUMENT
DISREGARD CONFIDENTIAL MARKING IN FOOTER***Creating an Effective Steam Turbine Maintenance Program*****GEK 111680**

stage and/or other low pressure section components, it is recommended that the last stage buckets of all units be inspected at the customer's convenience on an annual basis. As a minimum, the inspection should consist of a thorough visual inspection of parts visible from inside the exhaust hood. Additional non-destructive testing should be considered based on unit history and/or unit age. The following areas should be inspected:

- a. *Tie-Wires* - Brazed or welded tie-wires should be visually inspected for cracks in the tie wire, the fillet between tie wire and vane, or in the vane adjacent to the tie wire. Loose tie wires should be inspected for evidence of tie wire cracks. Fretting or other damage in the area of the tie wire hole should also be looked for.
- b. *Loose Tie Wire Sleeves* - Some buckets utilize tie wire sleeves held on by bosses. These should be visually inspected for cracks, for missing sleeves, and for sleeves, which may be cocked between adjacent buckets.
- c. *Erosion Shields* - Erosion shields, if installed, should be visually and red-dye inspected to uncover evidence of cracking. Visual inspection can also reveal cases of severe erosion or failure of brazed joints.
- d. *Bucket Vane* - The vane should be visually inspected for evidence of cracking or pitting, as well as trailing edge erosion. Non-destructive testing is also available.
- e. *Peened Covers* - The covers should be inspected for indication of lifting or severe erosion of the covers or tenons. In addition, any missing covers can be discovered.
- f. *Inserted Covers* - Several longer buckets employ an inserted cover. Such covers should be inspected for erosion, cracks in the tenon, or cocking of the cover between adjacent buckets. Missing covers would also be detected.
- g. *Dovetail* - The accessible area of the bucket dovetail should be inspected for any sign of distress, pitting of the wheel or dovetail pins, or loose pins.
- h. *Spill Strips* - The radial spill strips should be inspected for severe rubbing. In the case of a honeycomb spill strip, missing filler material would be discovered.
- i. *Mechanical Damage* - All accessible rotating and stationary parts should be inspected for evidence of mechanical (impact) damage. Problems in any of the areas described above can possibly lead to future last stage failure, with the possibility of a forced outage. In addition, they may also be symptomatic of other troubles upstream in the machine.

D. Borescope Inspections

An experienced individual performing proper visual inspections will enable detection and disclosure of unit conditions not detected by monitoring equipment or operational analysis. Visual inspections are limited to areas that can be accessed for view, directly or with mirrors, borescope, cameras, etc. In cases where there is a suspicion of internal damage or a build-up of deposits, selected parts may be examined during a short shutdown by means of a borescope. These inspections should be combined with testing to give a more accurate picture of unit health and condition and should include the following areas as a minimum:

GEK 111680

Creating an Effective Steam Turbine Maintenance Program

Table 1. Visual Inspection Areas

		Foreign Material Damage	Foreign Material Contamination	Cleanliness	Loose or Displaced Parts	Abnormal Movement	Surface Condition	Cracks	Abnormal Wear/Worn Parts	Flow Obstruction	Erosion/Corrosion
Rotor	All Components	X	X	X			X	X			X
	Periphery & Dovetails					X					
	Buckets				X		X		X	X	
	Covers				X	X			X		
Diaphragm	All Components	X	X	X				X			X
	Airfoil						X			X	
	Shell Fit				X	X		X	X		
	Web							X	X		
Valves/Casings	All Components	X	X	X				X			X
	Disc				X	X	X				
	Body						X				
	Drain Lines			X		X				X	
Shell Connections	Weld Connections		X	X			X	X			X
	Drain Lines			X		X				X	

IV. MAINTENANCE SCOPE & FREQUENCY

As detailed in previous sections the purposes of inspections include looking for, minimizing the causes of, and correcting items that occur as the unit ages. Specifically, these include items such as wear, erosion, deposits, distortion, misalignment, mechanical damage, and contamination.

For the purposes of discussion, scheduled outages will be referred to as (1) Minor Maintenance Overhauls and (2) Major Maintenance Overhauls. The difference in these inspections is the magnitude of disassembly and testing performed. Minor outages primarily consist of bearing, valve, and minor steam path inspections with the unit assembled while a major outage primarily consists of complete unit disassembly and inspection. Additionally, GE recommends a detailed steam path audit be completed during major outage overhauls to help understand performance degradation characteristics as well as any potential reliability concerns for planning of next major outage.

There are a number of auxiliary and support systems, which require routine maintenance or inspection between scheduled outages. The owner/operator will find these recommendations in various operating instructions within the O&M manual and should also include additional maintenance tasks as operating experience and inspections indicates. Results of this routine maintenance should be retained in well-organized files readily available for reference. These routine maintenance records coupled with the information from the monitored operating data are a good indicator of pending service or operating problems that should be addressed at the next scheduled outage.

PUBLIC DOCUMENT
DISREGARD CONFIDENTIAL MARKING IN FOOTER

Creating an Effective Steam Turbine Maintenance Program***GEK 111680*****A. Factors**

While many items need to be considered when determining exact outage frequency, unit specific influence factors should be one of the major considerations. In general the factors that should be considered when determining exact timing of your scheduled outage are:

- Performance and health trend monitoring results
- Operational compliance & maintenance practices, procedures, and personnel
- Inspections and testing completed between major overhaul outages
- Previous NDE inspection results completed during scheduled outages
- Operational events/incidents since last scheduled outage
- General problems based on empirical data and specific fleet issues
- Past history of problems
- Water and steam purity monitoring capability & compliance
- Service Duty – starts/hours per year (base-load, mid-range, cyclic)
- Unit age and design life concerns

Many of the factors related to the exact timing of inspections are determinable by the owner/operator; other factors draw from empirical knowledge and fleet experience. GE monitors operating experience, inspection results, and in-service operating issues of the installed base to the degree that the information is available. This is used to analyze and identify potential issues specific to similar units across the fleet with subsequent recommendations to owners on specific matters forwarded by means of Technical Information Letters (TIL) so applicable action can be taken to obtain maximum reliability, availability, and maintainability.

B. Scope

During an outage, the full scope of maintenance activities varies based on operational assessment as well as previous inspection and testing results. In addition scheduled maintenance activities are recommended to ensure the highest reliability and availability. The following guidelines are recommended scheduled activities for steam turbine maintenance.

GEK 111680

Creating an Effective Steam Turbine Maintenance Program

Table 2. Periphery Maintenance

TEST / INSPECTION	Daily	Weekly	Monthly	Annually
Visual inspection of unit and auxiliary equipment for leaks and abnormal noise	X			
Unit performance & health trend with Turbine Supervisory Instrumentation		X		
Visual inspection and greasing of all sliding surfaces		X	X	
Testing of turbine protection systems & devices per GEK requirements		X	X	X
Analyze lube & hydraulic oil per GEK requirements			X	
Visual inspection of Stop and Control Valve operation			X	
Functional testing of emergency lube oil systems per GEK requirements		X	X	X
Visual inspection of pipe hangers and piping support systems			X	
Visual inspection of all leak off lines and drain valves for proper operation			X	
Visual inspection of lube oil system and components				X
Low Pressure section last stage inspection				X
Mechanical & electrical checkout of instrumentation, protection & control systems				X
Test mechanical over-speed (as applicable)				X

1. Minor Maintenance Overhaul

- Borescope inspection of accessible parts of the steam path and shell connections
- Actuator & steam side inspection of all stop, control, and bypass valves
- Checkout/Calibrate all alarms, trips, and protective devices and/or instrumentation
- Inspect all journal and thrust bearing for wear and clearances
- Remove and inspect steam strainers
- Inspect spray water systems including bypass systems and condenser interior
- Visual inspection of all drain system piping, fitting, and traps
- Visual inspection of filters and fluid pipes for damage including functional testing of lubrication and drain system piping and components
- If installed, visual examination of condensing and feed-heating systems
- Inspections of foundation slide surfaces and anchor locations
- Additional checks based on unit history and individual operational observations

2. Major Maintenance Overhaul

- All inspections completed as part of a minor outage/overhaul with exception of borescope inspections
- Opening of turbine casings and steam path inspection

PUBLIC DOCUMENT
DISREGARD CONFIDENTIAL MARKING IN FOOTER

Creating an Effective Steam Turbine Maintenance Program

GEK 111680

- Opening clearance and alignment
- Clean and inspect stationary and rotating components
- Complete examination of couplings, including axial run-out test
- Close consideration should be made for performance of a steam path audit to best understand performance degradation and definition of recoverable and unrecoverable losses
- Appropriate non-destructive testing and examinations
- Inspection of all shell/casing piping connections
- As appropriate, NDE of all parts should be done to checks for both surface and sub-surface cracking and/or indications
- Detailed inspection of lubrication and drain system piping and components

C. Intervals

While the exact timing of inspections depends on the factors mentioned above, they can be made to correspond to periods of shutdown for work on, or inspection of, other power plant components. Scheduled maintenance outages should be planned well in advance of the actual outage date, and preparation for the outage should begin early. An important part of that is to review operational logs, previous inspection reports for any indication of work needed, and review recommendations from GE communicated by letter or TIL to integrate those items into your scope in addition to that described above.

In general, it is recommended that turbine-generators that have been operated in accordance with the Company's specific operating instructions or, in the absence thereof, in accordance with generally accepted operating practices of the electric power producing industry, be inspected in accordance with the approximate timelines defined in Table 2.

Table 3. Inspection Interval Matrix

	Interval (Service Years)	Comments
Minor Maintenance Overhaul	3 years*	Inspections may be required more or less frequent depending on fleet experience, testing results, and operational assessment completed as part of comprehensive maintenance management program.
Major Maintenance Overhaul	6 years*	Inspections may be required more or less frequent depending on fleet experience, testing results, and operational assessment completed as part of comprehensive maintenance management program.
*Influence factors are unit specific and need to be considered when determining exact outage interval. Timing should also consider balance of plant and other power generation equipment outage requirements.		

GEK 111680***Creating an Effective Steam Turbine Maintenance Program***

Materials expected during an outage, should be ordered such that they are available at the start of the outage to avoid risk of costly delays waiting for material. A sound maintenance program should reflect the level of acceptable risk for the unit. This will vary from unit to unit and plant to plant, and will change over time as the economic importance of the unit changes. In addition, new technologies are constantly being developed to improve unit reliability, performance, monitoring and inspection equipment, and otherwise provide more cost effective means for maintaining your unit. The owner/operator should be aware of the developments and modify the maintenance program accordingly. While this should be a continuous process, the maintenance outage planning review is an appropriate checkpoint.

D. Interval Extensions

The previous discussions are general guidance and recommendations and do not purport to cover all details nor to provide for every possible contingency to be met in connection with maintenance. Should further information be desired or should particular problems arise which are not covered sufficiently for the owner/operators purposes the matter should be referred to your local GE Service Office.

A maintenance program should reflect the level of acceptable risk for the unit, which will vary from unit to unit, plant to plant and fleet to fleet and will probably change over time as the importance of the unit to the power system changes. In addition, new technologies are constantly being developed to improve unit reliability, performance, monitoring and inspections, and otherwise provide more cost effective means for maintaining the unit

It is recognized that some customers desire to have longer or shorter intervals where it makes sense. GE has unique capability to help assist in this evaluation and analysis on a single unit or an entire fleet in the form of a customized reliability analysis to optimize unit availability and lifecycle cost. This type of engineering assessment is completed for units that are serviced under a Long Term Service Agreement managed by GE. For other customers, your local GE Service Office can assist you in your maintenance planning, and review of your overall maintenance program, incorporating any appropriate new maintenance, repair and upgrade technologies available.

**GE Energy**

General Electric Company

www.gepower.com

Still
11-22-80

COPY

Form No: 27.300

MOS INSPECTION, INC.

TURBINE INSPECTION REPORT

OWNER: Northern States Power CLIENT: Northern States Power

LOCATION: Sherco Plant CONTACT: Lanny Dahlman
Becker, MN

TURBINE:

Manufacturer: General Electric Serial Number: 170X819

Unit Number: 3 Rating: 850 MW RPM: 3600

INSPECTION:

Date Inspected: 3-4-99 thru 3-18-99 Technician: Mike Christensen
Technician: Doug Gertner

P.O. #: PN4205MT

W/O#: 07F3389

Report Date: 3-15-99

Complete () Partial Inspection

Auxl. Comp. Inspected:

This report details the conditions noted during our inspection of the above unit. The disposition of all deficiencies noted shall be the responsibility of the owner.

MQS INSPECTION, INC.

Form: 27.302

Turbine #: 170X819

Work Order #: 07F3389

HIGH PRESSURE (H.P.) SECTIONS

Component	Insp. Req'd		Method Cleaned	Deficiency Noted							
	Yes	No		MT	UT	PT	VT	ET	RT	Yes	No
Outer Shell/Cylinders											
Inlet Sleeve Trepan(Westinghouse)	()	(✓)	NA	()	()	()	()	()	()	()	()
Positioning Grooves	(✓)	()	sandblast	(✓)	()	()	(✓)	()	()	()	(✓)
Horizontal Joint	(✓)	()	"	(✓)	()	()	(✓)	()	()	()	(✓)
Studs/Bolts	(✓)	()	NA	()	(✓)	()	(✓)	()	()	()	(✓)
Inlet Steam Flanges	(✓)	()	sandblast	(✓)	()	()	(✓)	()	()	()	(✓)
Bell Seals (Westinghouse)	()	(✓)	NA	()	()	()	()	()	()	()	()
Steam Chest											
Steam Flange Bolts	()	(✓)	NA	()	()	()	()	()	()	()	()
Chest Seats	(✓)	()	solvent	()	()	(✓)	(✓)	()	()	()	(✓)
Studs	(✓)	()	stoned	()	(✓)	()	(✓)	()	()	()	(✓)
Covers	()	(✓)	NA	()	()	()	()	()	()	()	()
Cover Studs	()	(✓)	"	()	()	()	()	()	()	()	()
Body	(✓)	()	"	()	()	()	(✓)	()	()	()	(✓)
Rotor/Spindle											
Shaft	(✓)	()	sandblasted	(✓)	()	()	(✓)	()	()	()	(✓)
Buckets/Blades	(✓)	()	"	(✓)	()	()	(✓)	()	()	()	(✓)
Covers/Shroud Bands	(✓)	()	"	(✓)	()	()	(✓)	()	()	()	(✓)
Wheels/Discs	(✓)	()	"	(✓)	()	()	(✓)	()	()	()	(✓)
Coupling	(✓)	()	solvent	(✓)	()	()	(✓)	()	()	()	(✓)
Coupling Bolts	(✓)	()	NA	()	(✓)	()	(✓)	()	()	()	(✓)
Thrust Collar....(IP rotor)	(✓)	()	solvent	(✓)	()	()	(✓)	()	()	()	(✓)
Bearing Journal	(✓)	()	"	(✓)	()	()	(✓)	()	()	()	(✓)
Babbitt Bearing Bond	(✓)	()	"	()	(✓)	()	(✓)	()	()	()	(✓)
Thrust bearing Bond (Babbitt)	(✓)	()	"	()	(✓)	()	(✓)	()	()	()	(✓)
Diaphragms/Stationary Blade Rings											
Partitions/Blades	(✓)	()	sandblasted	(✓)	()	()	(✓)	()	()	()	(✓)
I.D. Rings/Sets	(✓)	()	"	(✓)	()	()	(✓)	()	()	()	(✓)
O.D. Rings/Sets	(✓)	()	"	(✓)	()	()	(✓)	()	()	()	(✓)
Inner Shells/Cylinders											
Nozzle Block	(✓)	()	sandblasted	(✓)	()	()	(✓)	()	()	()	(✓)
Port Way	()	(✓)	NA	()	()	()	()	()	()	()	()
Nozzle Row (Row of Partitions)	(✓)	()	sandblasted	(✓)	()	()	(✓)	()	()	()	(✓)
Steam Shield/Steam Deflector	()	(✓)	NA	()	()	()	()	()	()	()	()
Horizontal Joints	(✓)	()	sandblasted	(✓)	()	()	(✓)	()	()	()	(✓)
Positioning Grooves	(✓)	()	"	(✓)	()	()	(✓)	()	()	()	(✓)
Studs/Bolts	(✓)	()	stoned	()	(✓)	()	(✓)	()	()	()	(✓)
Other Components											
_____	()	()	_____	()	()	()	()	()	()	()	()
_____	()	()	_____	()	()	()	()	()	()	()	()
_____	()	()	_____	()	()	()	()	()	()	()	()
_____	()	()	_____	()	()	()	()	()	()	()	()
_____	()	()	_____	()	()	()	()	()	()	()	()
_____	()	()	_____	()	()	()	()	()	()	()	()

MQS INSPECTION, INC.

Form: 27.304

Turbine #: 170X819

Work Order #: 07F3389

INTERMEDIATE PRESSURE (L.P.) SECTIONS

Component	Insp. Req'd		Method Cleaned	Efficiency Noted									
	Yes	No		MT	UT	PT	VT	ET	RT	Yes	No		
Outer Shell/Cylinders													
Positioning Grooves.....	(✓)	()	<u>sandblasted</u>	(✓)	()	()	(✓)	()	()	()	()	(✓)	()
Horizontal Joint.....	(✓)	()	"	(✓)	()	()	(✓)	()	()	()	()	()	(✓)
Studs/Bolts.....	(✓)	()	<u>NA</u>	()	(✓)	()	(✓)	()	()	()	()	()	(✓)
Inlet Steam Flanges.....	()	(✓)	"	()	()	()	()	()	()	()	()	()	(✓)
Rotor/Spindle													
Shaft.....	(✓)	()	<u>sandblasted</u>	(✓)	()	()	(✓)	()	()	()	()	()	(✓)
Buckets/Blades.....	(✓)	()	"	(✓)	()	()	(✓)	()	()	()	()	()	(✓)
Covers/Shroud Bands.....	(✓)	()	"	(✓)	()	()	(✓)	()	()	()	()	()	(✓)
Wheels/Discs.....	(✓)	()	"	(✓)	()	()	(✓)	()	()	()	()	()	(✓)
Couplings.....	(✓)	()	<u>solvent</u>	(✓)	()	()	(✓)	()	()	()	()	()	(✓)
Bearing Journal.....	(✓)	()	"	()	(✓)	(✓)	(✓)	()	()	()	()	()	(✓)
Babbitt Bearing Bond.....	(✓)	()	"	()	(✓)	(✓)	(✓)	()	()	()	()	()	(✓)
Diaphragms/Stationary Blade Rings													
Partitions/Blades.....	(✓)	()	<u>sandblasted</u>	(✓)	()	()	(✓)	()	()	()	()	()	(✓)
I.D. rings/Sets	(✓)	()	"	(✓)	()	()	(✓)	()	()	()	()	()	(✓)
O.D. Rings/Sets.....	(✓)	()	<u>NA</u>	(✓)	()	()	(✓)	()	()	()	()	()	(✓)
Inner Shells/Cylinders													
Horizontal Joints.....	(✓)	()	_____	()	()	()	()	()	()	()	()	()	(✓)
Positioning Grooves.....	(✓)	()	_____	()	()	()	()	()	()	()	()	()	(✓)
Studs/Bolts.....	()	()	_____	()	()	()	()	()	()	()	()	()	()
Other Components													
_____	()	()	_____	()	()	()	()	()	()	()	()	()	()
_____	()	()	_____	()	()	()	()	()	()	()	()	()	()
_____	()	()	_____	()	()	()	()	()	()	()	()	()	()
_____	()	()	_____	()	()	()	()	()	()	()	()	()	()

MQS INSPECTION, INC.

27.303

Turbine #: 170X819

Work Order #: 07F3389

LOW PRESSURE (L.P.) SECTIONS

Component	Insp. Req'd		Method Cleaned	Deficiency Noted								
	Yes	No		MT	UT	PT	VT	ET	RT	Yes	No	
Rotor/Spindle												
Buckets/Blades.....	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>sandblasted</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Covers/Shroud Bands.....	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>"</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Wheels/Disc.....	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>"</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Shaft.....	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>"</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Bearing Journal.....	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>solvent</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Tie Wires/Lashing Wire Lugs.....	<input type="checkbox"/>	<input type="checkbox"/>	<u>NA</u>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Couplings.....	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>solvent</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Bucket Pins/Steeple.....	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>sandblasted</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Erosion Strips/Stellite Strips.....	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>"</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Babbitt Bearing Bond.....	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>solvent</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Shells/Cylinders												
Positioning Grooves.....	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>sandblasted</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Horizontal Joint.....	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>"</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Support Tube Welds.....	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>"</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Bridge Supports.....	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>"</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Studs/Bolts.....	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<u>NA</u>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Crossover Pipe System												
Crossover Studs and Bolts.....	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<u>NA</u>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Crossover Diaphragm.....	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<u>NA</u>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Expansion Diaphragm.....	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<u>NA</u>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Steam Deflectors.....	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<u>NA</u>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Support Welds.....	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<u>NA</u>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Other Components												
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MQS INSPECTION, INC.

27.306

Turbine #: 170X819

Work Order #: 07F3389

GENERATOR SECTION

Component	Insp. Req'd		Method Cleaned									Deficiency Noted	
	Yes	No		MT	UT	PT	VT	ET	RT	Yes	No		
Rotating Field													
Retaining Rings.....ID only.....	<input checked="" type="checkbox"/>	<input type="checkbox"/>	solvent	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Fan Blades.....	<input checked="" type="checkbox"/>	<input type="checkbox"/>	"	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Fan Blade Bolts.....	<input type="checkbox"/>	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Shaft (Exposed Areas).....	<input type="checkbox"/>	<input checked="" type="checkbox"/>	"	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Couplings.....	<input type="checkbox"/>	<input checked="" type="checkbox"/>	"	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Bearing (Babbitt Bond).....	<input checked="" type="checkbox"/>	<input type="checkbox"/>	solvent	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

(Note: Plugging and sealing of the generator shall be the responsibility of the client)

Other Components

_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
_____	<input type="checkbox"/>	<input type="checkbox"/>	_____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

MQS INSPECTION, INC.

27.301

Turbine #: 170X819

Work Order #: 07F3389

VALVES

Component	Insp. Req'd		Method Cleaned	D efficiency Noted							
	Yes	No		MT	UT	PT	VT	ET	RT	Yes	No
Stop Valves											
H.P. Seal Head.....	()	(✓)	NA	()	()	()	()	()	()	()	()
Bonnet.....	()	(✓)	NA	()	()	()	()	()	()	()	()
H.P. Seal Head Seat.....	()	(✓)	NA	()	()	()	()	()	()	()	()
Disc/Plug.....	()	(✓)	NA	()	()	()	()	()	()	()	()
Anti-Rotation Pins.....	()	(✓)	NA	()	()	()	()	()	()	()	()
Screen/Strainer.....	()	(✓)	NA	()	()	()	()	()	()	()	()
Valve Body.....	(✓)	()	NA	()	()	()	(✓)	()	()	()	(✓)
Valve Body Seat.....	(✓)	()	solvent	()	()	(✓)	(✓)	()	()	()	(✓)
Head.....	()	(✓)	NA	()	()	()	()	()	()	()	()
Support Yoke.....	()	(✓)	NA	()	()	()	()	()	()	()	()
Studs.....	(✓)	()	wire brush	()	(✓)	()	(✓)	()	()	()	(✓)
Disc Seat/Plug Seat.....	()	(✓)	NA	()	()	()	()	()	()	()	()
Studs.....	()	(✓)	NA	()	()	()	()	()	()	()	()
Control Valve/Governing Valves											
Stem.....	()	(✓)	NA	()	()	()	()	()	()	()	()
Bonnet.....	()	(✓)	NA	()	()	()	()	()	()	()	()
Disc/Plug.....	()	(✓)	NA	()	()	()	()	()	()	()	()
Disc Seat/Plug Seat.....	()	(✓)	NA	()	()	()	()	()	()	()	()
Valve Body.....	(✓)	()	NA	(✓)	()	()	()	()	()	()	(✓)
Valve Body Seat.....	(✓)	()	solvent	()	()	(✓)	(✓)	()	()	()	(✓)
Studs.....	(✓)	()	wire brush	()	(✓)	()	(✓)	()	()	()	(✓)
Intercept Valves or Combination Intercept/Reheat Valves											
Stems.....	()	()	NA	()	()	()	()	()	()	()	()
Discs/Plugs.....	()	()	NA	()	()	()	()	()	()	()	()
Disc Seat/Plug Seat.....	()	()	NA	()	()	()	()	()	()	()	()
Screen.....	()	()	NA	(✓)	()	()	(✓)	()	()	()	(✓)
Valve Body...& seat.....	()	()	NA	()	()	(✓)	(✓)	()	()	()	(✓)
H.P. Seal Head.....	()	()	solvent	()	()	()	()	()	()	()	()
Studs.....	()	()	wire brush	()	(✓)	()	(✓)	()	()	()	(✓)
Equalizer Valve											
Stem.....	()	()	solvent	(✓)	()	()	(✓)	()	()	()	(✓)
Disc.....	()	()	solvent	(✓)	()	()	(✓)	()	()	()	(✓)
Disc Seat.....	()	()	solvent	()	()	(✓)	(✓)	()	()	()	(✓)
Valve Body.....	()	()	NA	()	()	()	()	()	()	()	()
Valve Body Seat.....	()	()	solvent	()	()	(✓)	(✓)	()	()	()	(✓)
Studs.....	()	()	NA	()	()	()	()	()	()	()	()

Confidential

MQS INSPECTION, INC.												Record of Turbine Blade or Bucket Inspection		
Date: <u>3-15-99</u>		Unit No.: <u>3</u>												Form No. 27.308
Station <u>Sherco</u>		Turbine No.: <u>170X819</u>				HIGH PRESSURE ROTOR								
Stage No.	Total No. Blades	No. Groups	Blades / Group	Blade Length	Notch Plugs	Blade / Bucket No.	Inspection Method	Distance from Shroud	Defect Length	Defect Entirely thru (Y or N)	Entrance or Dischg. Side (E or D)	Remarks		
Gov-1	80	20	4	6-1/4"	1	NA	mt/vt					Light erosion & pitting to blading		
Turb-1	80	20	4	6-1/4"	1	"	"					Light erosion & pitting to blading		
2	92	23	4	7"	1	"	"					Light erosion & pitting to blading		
3	88	22	4	7-3/4"	1	"	"					Light erosion & pitting to blading		
4	84	21	4	8-3/4"	1	"	"					No defects noted		
5	76	19	4	9-1/4"	1	"	"					No defects noted		
6	68	17	4	19"	1	"	"					No defects noted		
7	62	15	4/5	11-1/4"	1	"	"					No defects noted		

XCEL_Sherco_05_0122488

Confidential

MQS		INSPECTION, INC.		Record of Turbine Blade or Bucket Inspection										
Date: 3-15-99		Unit No.: 3										Form No. 27.308		
Station Sherco		Turbine No.: 170X819						INTERMEDIATE PRESSURE ROTOR						
Stage No.	Total No. Blades	No. Groups	Blades / Group	Blade Length	Notch Plugs	Blade / Bucket No.	Inspection Method	Distances from Shroud	Defect Length	Defect Entirely thru (Y or N)	Entrance or Dischg. Side (E or D)	Remarks		
8	100	25	4	9-3/4	1	NA	mt/vt					Light foreign object damage with heavy erosion to blading. Foreign material wedged on ID of covers.		
9	108	27	4	9"	1	"	"					Light foreign object damage with heavy erosion to blading. Foreign material wedged on ID of covers.		
10	104	26	4	9-3/4	1	"	"					Light erosion with sporadic foreign material wedged on the ID of the covers.		
11	104	26	4	10.5"	1	"	"					Sporadic foreign material wedged on the ID of the covers.		
12	80	20	4		1	"	"					No defects noted		
13	72	18	4	14"	1	"	"					No defects noted		

XCEL_Sherco_05_0122489

PUBLIC DOCUMENT
 DISREGARD CONFIDENTIAL MARKING IN FOOTER

Confidential

MQS INSPECTION, INC. Record of Turbine Blade or Bucket Inspection														
Date: 3-15-99		Unit No.: 3		Station Sherco Turbine No.: 170X819							LOW PRESSURE ROTOR "B"			
Stage No.	Total No. Blades	No. Groups	Blades / Group	Blade Length	Notch Plugs	Blade / Bucket No.	Inspection Method	Distance from Shroud	Defect Length	Defect Entirely thru (Y or N)	Entrance or Dischg. Side (E or D)	Remarks		
14	198	40	4/5	6-1/8"	1	NA	mt/vt					Light pitting on blading both the generator and turbine ends		
15	200	40	5	7.5"	1	"	"					Light pitting on blading both the generator and turbine ends		
16	128	32	4	10-5/8"	1	"	"					Light pitting on blading both the generator and turbine ends		
17	94	13	4/5	16-5/8"	1	"	"					Light pitting on blading both the generator and turbine ends		
L-1 18												Blading removed to be replaced		
L-0 19	94	NA	NA	39-3/4"	1	"	"					Moderate erosion to the erosion strips, blade area, adjacent to strips and insert blocks 56 bucket pins found to be rejected one pin on the turbine end and 55 pins on the generator end.		
												NOTE: Stage #17 notch plug blade is a titanium blade. (non-magnetic)		

XCEL_Sherco_05_0122491

Confidential

MQS

Form 27.309

Inspection, Inc. 1920 Oakerest Avenue, Roseville, MN 55113

IDENTIFICATION OF DIAPHRAGM BLADING DEFECTS

Sketch is looking at steam inlet side of diaphragm.
First blade on left side would be No. 1-T on top half and
No. 1-B on bottom half. Also, show total number of
blades as their total number in either top or bottom,
not total number in top and bottom.

NB= Nozzle Block
FOD = Foreign object damage

Since the defects are found in about the same location
on either the inside diameter or outside diameter, and
usually on the discharge side we only need to indicate
with "X" where the crack or defect occurred, in proper
column and the length of the defect.

Date: 3-15-99 Station: Sherco WO# 07-F3389

Turbine #: 170X819 Unit No. 3 Technician: Michael T. Christensen, Level II, Doug Gertner, Level II

Gen	Total # of Blades	# of Defects	Inspect. Method	Block	From O-Ring	From ID-Ring	Inside	Discharge Side	Length of Defect	Type Defects
Gen										
NB-T	84		Vt/mt	All			X	X		Light FOD severe erosion
"	"	9	"	--	X			X		1-4, 41,44,81-83 missing part of blade due to erosion
"	"	2	"	--	X			X		29, 64 have cracks
"	"	25	"	--		X		X		5,7,8,15,16,18,19,22,24,26-28,31,35,39,42,48,50,69,73,75-77,80,81 have cracks
Gen.										
NB-B	84		Vt/mt	All			X	X		Light FOD, severe erosion
"	"	8	"	--	X			X		2-4, 44, 80-83 are missing part of blade due to erosion
"	"	4	"	--		X		X		4,6,14,15,17,26,29,46,56,60 have cracks
Turb										
NB-T	84		Vt/mt	All			X	X		Light FOD severe erosion
"	"	12	"	--	X			X		1-5, 40-42,44,81-83 are missing part of blade due to erosion
"	"	21	"	--		X		X		1,3,4,6,13,14,19,21,39,41,42,44,48,51,53,55,56,60,65,71,79 have cracks
Turb										
NB-B	84		Vt/mt	All			X	X		Light FOD severe erosion
"	"	10	"	--	X			X		1-4, 44, 78, 80-84 are missing part of blade due to erosion
"	"	2	"	--	X			X		59,77 have cracks
"	"	11	"	--		X		X		1,38,39,45,47,71,72,74,81-83 have cracks
2-T	36		"	All			X	X		Heavy FOD light erosion
"	"	1	"	5	X			X		Has tear

XCEL_Sherco_05_0122492

Confidential

MQS

Inspection, Inc. 1920 Oakcrest Avenue, Roseville, MN 55113

Form 27.309

IDENTIFICATION OF DIAPHRAGM BLADING DEFECTS

Sketch is looking at steam inlet side of diaphragm.
First blade on left side would be No. 1-T on top half and
No. 1-B on bottom half. Also, show total number of
blades as their total number in either top or bottom,
not total number in top and bottom.

NB = Nozzle Block
FOD = Foreign Object Damage

Since the defects are found in about the same location
on either the inside diameter or outside diameter, and
usually on the discharge side we only need to indicate
with "X" where the crack or defect occurred, in proper
column and the length of the defect.

Date: 3-15-99 Station: Sherco WO# 07-F3389

Turbine #: 170X819 Unit No. 3 Technician: Michael T. Christensen, Level II, Doug Gertner, Level II

Spec	Total # of Blades	# of Defects	Inspection Method	Blades	From FOD Ring	From ID Ring	Inlet Side	Discharge Side	Length of defect	Type Defects
2-T	36	1	V/mt	11	X			X		Has hole
"	"	1	"	21	X			X		Has crack
"	"	1	"	22		X		X		Has crack
2B	36		"	All			X	X		FOD and light erosion
"	"	4	"	--	X	X		X		Previous weld repair area cracked on 1,4,19,20
"	"	1	"	18	X			X		Has crack
3-T	60		"	All			X	X		Light FOD light erosion
"	"		"	--		X	X			Weld cracked on brace between blades 59 and 60
"	"	4	"	--		X		X		47,53,57,58 have cracks
"	"	1	"	49	X			X		Has crack
3-B	60		"	All			X	X		Light erosion FOD
"	"	8	"	--	X			X		3-5,8,9,14,52,60 have cracks
"	"	4	"	--	X			X		33,48,55,57 are missing piece of blade due to FOD
4-T	50		"	All			X	X		Light erosion light FOD
"	"	2	"	--		X		X		3, 25 have cracks
4-B	50		"	All			X	X		Light FOD erosion
"	"	1	"	--		X	X			Crack on brace which is between blades 49 and 50
"	"	2	"	--	X			X		11, 13 have cracks
"	"	1	"	--		X		X		23 has crack
5-T	47		"	All			X	X		Light erosion
"	"	2	"	--	X		X			8, 27 have cracks

XCEL_Sherco_05_0122493

Confidential

MQS Inspection, Inc. 1920 Oakcrest Avenue, Roseville, MN 55113

Form 27.309

**IDENTIFICATION OF
DIAPHRAGM BLADING DEFECTS**

Sketch is looking at steam inlet side of diaphragm.
First blade on left side would be No. 1-T on top half and
No. 1-B on bottom half. Also, show total number of
blades as their total number in either top or bottom,
not total number in top and bottom.

NB= Nozzle Block
FOD = Foreign object damage

Since the defects are found in about the same location
on either the inside diameter or outside diameter, and
usually on the discharge side we only need to indicate
with "X" where the crack or defect occurred, in proper
column and the length of the defect.

Date: 3-15-99 Station: Sherco WO# 07-F3389

Turbine #: 170X819 Unit No. 3 Technician: Michael T. Christensen, Level II, Doug Gertner, Level II

Blade #	Total # of Blades	# of Defects	Inspection Method	Blade #	OD	ID	Inlet Side	Discharge Side	Length of Defect	Type Defects
5-T	47	1	Vt/mt	--	X			X		24 has crack
"	"	1	"	--		X		X		35 is separating in the weld repair area
"	"	3	"	--		X		X		39, 44, 46 have cracks
5-B	47		"	All			X	X		Light erosion
"	"	1	"	--		X		X		44 has crack
6-T	57		"	All			X	X		Light erosion
"	"	1	"	--	X	X		X		57 has crack
"	"	2	"	--		X		X		11, 13 have cracks
6-B	57		"	All			X	X		Light erosion
"	"	10	"	--		X		X		2,12,32,33,39,41,47,50,51,53 have cracks
"	"	3	"	--	X			X		9,11,13 have cracks
7-T	39	4	"	--	X			X		13, 16, 18, 26 have cracks
"	"	2	"	--	X	X	X			Weld cracked on braces which are between blades 38 and 39
7-B	39	1	"	--	X			X		#1 has crack
Gen										
8-T	61		Vt/mt	All			X	X		Severe erosion, FOD
"	"	14	"	--		X		X		1,14,19,21,22,24,28,31-33,46,48,50,52 have cracks
"	"	1	"	--		X	X			Weld cracks on brace which is between blades 60 and 61

XCEL_Sherco_05_0122494

PUBLIC DOCUMENT
DISREGARD CONFIDENTIAL MARKING IN FOOTER

Confidential

MQS Inspection, Inc. 1920 Oakcrest Avenue, Roseville, MN 55113

Form 27.309

IDENTIFICATION OF
DIAPHRAGM BLADING DEFECTS

Sketch is looking at steam inlet side of diaphragm.
First blade on left side would be No. 1-T on top half and
No. 1-B on bottom half. Also, show total number of
blades as their total number in either top or bottom,
not total number in top and bottom.

NB = Nozzle Block
FOD = Foreign Object Damage

Since the defects are found in about the same location
on either the inside diameter or outside diameter, and
usually on the discharge side we only need to indicate
with "X" where the crack or defect occurred, in proper
column and the length of the defect.

Date: 3-15-99 Station: Sherco WO# 07-F3389

Turbine #: 170X819 Unit No. 3 Technician: Michael T. Christensen, Level II, Doug Gertner, Level II

Stage	Total # of Blades	# of Defects	Inspection Method	Blade Condition	FOD	From Inlet Side	From Discharge Side	Length of Defect	Defect Description
Gen	61		V/mt	All			X	X	Erosion FOD
"	"	12	"	--		X	X		2,6,13,15,23,27,28,32,39,40,47,50 have cracks
"	"	1	"	--	X		X		Weld cracked on brace which is between blading 60 and 61
Turb.									
8-T	61		"	All			X	X	Heavy FOD, severe erosion
"	"	3	"	--	X			X	3,8,15 are missing part of blade due to erosion
"	"	20	"	--		X		X	6,8,11,14,17,19,20,24-29,36,49-53,55 have cracks
"	"	3	"	--	X			X	30,31,58 have cracks
Turb									
8-B	61		"	All			X	X	Erosion FOD
"	"	23	"	--		X		X	1-5,8,10,11,13,27,28,30-34,36,39,40,57-60 have cracks
"	"	1	"	--	X			X	46 has crack
Gen									
9-T	43		"	All			X	X	FOD erosion
"	"	2	"	--	X		X		5,38 have cracks
"	"	1	"	--		X	X		32 has crack
"	"	3	"	--		X		X	3,19,27 have tears
"	"	4	"	--		X		X	5,11,36,40 have cracks
"	"	2	"	--	X			X	9,12 have cracks

XCEL_Sherco_05_0122495

Confidential

MQS Inspection, Inc. 1920 Oakcrest Avenue, Roseville, MN 55113

Form 27.309

**IDENTIFICATION OF
DIAPHRAGM BLADING DEFECTS**

Sketch is looking at steam inlet side of diaphragm.
First blade on left side would be No. 1-T on top half and
No. 1-B on bottom half. Also, show total number of
blades as their total number in either top or bottom,
not total number in top and bottom.

NB= Nozzle Block
FOD = Foreign object damage

Since the defects are found in about the same location
on either the inside diameter or outside diameter, and
usually on the discharge side we only need to indicate
with "X" where the crack or defect occurred, in proper
column and the length of the defect.

Date: 3-15-99 Station: Sherco WO# 07-F3389

Turbine #: 170X819 Unit No. 3 Technician: Michael T. Christensen, Level II, Doug Gertner, Level II

Gen./Turb.	Total # of Blades	# of Defects	Inspection Method	Inlet Side	From Inlet Ring	From Inlet Blade	Discharge Side	Length of Defect	Type Defects
Gen.	43		Vt/m	All			X	X	FOD erosion
"	"	4	"	--	X			X	4,11,12,25 have cracks
"	"	1	"	--		X		X	15 has crack
"	"	1	"	--		X	X		Web cracked in previous weld repair area at blade #32
Turb.	43		"	All			X	X	Light erosion, FOD
"	"	2	"	--	X			X	19, 21 have holes
"	"	7	"	--		X		X	2,5,17,25,34,33,38 have cracks
"	"	6	"	--	X			X	13,19,29,33,40,42 have cracks
"	"	2	"	--	X	X	X		Welds cracked on braces between blades 42 and 43
Turb.	43		"	All			X	X	Erosion FOD
"	"	1	"	--		X		X	14 has crack
"	"	1	"	--	X			X	36 has crack
"	"	3	"	--				X	7,9,13,22 previous repair areas cracked
"	"	1	"	--			X		Inner web cracking between blades
Gen.	37		"	All			X	X	Light FOD
"	"	1	"	--	X		X		Weld on brace has severe erosion between blades 36,37

XCEL_Sherco_05_0122496

Confidential

MQS Inspection, Inc. 1920 Oakcrest Avenue, Roseville, MN 55113

Form 27.309

IDENTIFICATION OF DIAPHRAGM BLADING DEFECTS

Sketch is looking at steam inlet side of diaphragm.
First blade on left side would be No. 1-T on top half and No. 1-B on bottom half. Also, show total number of blades as their total number in either top or bottom, not total number in top and bottom.

NB = Nozzle Block
FOD = Foreign Object Damage

Since the defects are found in about the same location on either the inside diameter or outside diameter, and usually on the discharge side we only need to indicate with "X" where the crack or defect occurred, in proper column and the length of the defect.

Date: 3-15-99 Station: Sherco WO# 07-F3389

Turbine #: 170X819 Unit No. 3 Technician: Michael T. Christensen, Level II, Doug Gertner, Level II

Stage	Total # of Blades	# of Defects	Inspector Method	Blade	From FOD Ring	From Inlet Ring	Discharge Side	Length of defect	Notes
Gen.	37		Vt/mt	All			X	X	Light FOD
"	"	6	"	--		X	X		3,28,30,31,34,36 have cracks
Turb.	37		"	All			X	X	Erosion light FOD
"	"	2	"	--		X	X		1, 16 have holes
Turb.	37		"	All			X	X	FOD
"	"	1	"	--		X	X		1 has crack
"	"	2	"	--			X		11, 35 have holes in blade
Gen.	63		"	All			X	X	Light erosion
"	"	2	"	--	X	X	X		63 has cracks
Gen.	63		"	All			X	X	Light erosion
"	"	1	"	--	X		X		5 has crack
"	"	1	"	--		X	X		11 has crack
Turb.	63		"	All			X	X	Light erosion, FOD
"	"	1	"	--	X		X		#52 has crack

XCEL_Sherco_05_0122497

Confidential

MQS Inspection, Inc. 1920 Oakcrest Avenue, Roseville, MN 55113

Form 27.309

IDENTIFICATION OF DIAPHRAGM BLADING DEFECTS

Sketch is looking at steam inlet side of diaphragm.
First blade on left side would be No. 1-T on top half and
No. 1-B on bottom half. Also, show total number of
blades as their total number in either top or bottom,
not total number in top and bottom.

NB = Nozzle Block
FOD = Foreign Object Damage

Since the defects are found in about the same location
on either the inside diameter or outside diameter, and
usually on the discharge side we only need to indicate
with "X" where the crack or defect occurred, in proper
column and the length of the defect.

Date: 3-15-99 Station: Sherco WO# 07-F3389

Turbine #: 170X819 Unit No. 3 Technician: Michael T. Christensen, Level II, Doug Gertner, Level II

Stage	Total # of Blades	# of Defects	Inspection Method	Blade	From Ring	Com ID	Inlet Side	Discharge Side	Length of Defect	Description
Turb.										
11-T	63	1	Vt/mt	--			X			63 weld is separating from brace
11-B	63			All			X	X		FOD light erosion
"	"	2	"	--				X		1, 63 have holes in blade
Gen.										
12-T	52		"	All			X	X		Light erosion
12-B	"	1	"	--	X			X		23 has holes
"	"	1	"	--		X		X		42 has crack
Turb.										
12-T	52		"	All			X	X		Light erosion
"	"	1	"	--		X		X		1 has hole
12-B	52		"	All			X	X		Light erosion
"	"	2	"	--				X		16, 40 have holes
"	"	1	"	--	X			X		42 has crack
Gen.										
13-T	60		"	All						Good
13-B	"	2	"	--	X			X		5,7 have cracks
"	"	1	"	--						Outer web cracked at blade #41
Turb										
13-T	60		"	All			X	X		Light erosion, light FOD
13-B	"	1	"	--		X		X		26 has crack

XCCEL_Sherco_05_0122498

PUBLIC DOCUMENT
DISREGARD CONFIDENTIAL MARKING IN FOOTER

Confidential

MQS

Inspection, Inc. 1920 Oakcrest Avenue, Roseville, MN 55113

Form 27.309

IDENTIFICATION OF DIAPHRAGM BLADING DEFECTS

Sketch is looking at steam inlet side of diaphragm.
First blade on left side would be No. 1-T on top half and
No. 1-B on bottom half. Also, show total number of
blades as their total number in either top or bottom,
not total number in top and bottom.

NB= Nozzle Block
FOD = Foreign object damage

Since the defects are found in about the same location
on either the inside diameter or outside diameter, and
usually on the discharge side we only need to indicate
with "X" where the crack or defect occurred, in proper
column and the length of the defect.

Date: 3-15-99 Station: Sherco WO# 07-F3389

Turbine #: 170X819 Unit No. 3 Technician: Michael T. Christensen, Level II, Doug Gertner, Level II

Unit	Total # of Blades	# of Defects	Inspection Method	Blade	From OD	From ID	Inlet	Discharge	Length of defect	Type Defects
Turb.										
13-B	60	1	Vt/mt	All	X			X		Web cracked at #3 blade
LPA	GEN									
14-T	71		"	All			X	X		Light erosion
14-B	71		"	"			X	X		Light erosion
LPA	TURB									
14-T	71		"	All			X	X		Light erosion
"	71	1	"	--	X			X		17 has tear
"	"	1	"	--	X			X		18 has crack
LPA	TURB									
14-B	71		"	All			X	X		Light erosion
"	"	1	"	--		X		X		71 has crack
"	"	1	"	--	X			X		70 has crack
LPA	GEN									
15-T	79	2	"	--	X			X		68, 79 have cracks
15-B	"	1	"	--		X		X		19 has crack
"	"	1	"	--	X			X		44 has crack
LPA	TURB									
15-T	79		"	All			X	X		FOD
"	"	1	"	--	X			X		79 has tear

XCEL_Sherco_05_0122499

Confidential

MQS Inspection, Inc. 1920 Oakerest Avenue, Roseville, MN 55113

Form 27.309

IDENTIFICATION OF DIAPHRAGM BLADING DEFECTS

Sketch is looking at steam inlet side of diaphragm.
First blade on left side would be No. 1-T on top half and
No. 1-B on bottom half. Also, show total number of
blades as their total number in either top or bottom,
not total number in top and bottom.

NB = Nozzle Block
FOD = Foreign Object Damage

Since the defects are found in about the same location
on either the inside diameter or outside diameter, and
usually on the discharge side we only need to indicate
with "X" where the crack or defect occurred, in proper
column and the length of the defect.

Date: 3-15-99 Station: Sherco WO# 07-F3389

Turbine #: 170X819 Unit No. 3 Technician: Michael T. Christensen, Level II, Doug Gertner, Level II

Station	Total # of Blades	# of Defects	Blade #	Blade Method	From FOD Ring	From Imp Ring	Inlet Side	Discharge Side	Length of defect	Notes
LPA TURB	79			Vt/mt	All		X	X		FOD
"	"	5	"	--	X			X		Previous weld repair area cracked
LPA GEN	36			"	All		X	X		Light pitting
16-T	36	1	"	--	X			X		36 has crack
LPA GEN	36			"	All		X	X		Light pitting
16-B	36			"	All		X	X		Light pitting
LPA TURB	36			"	All		X	X		Light pitting
16-T	36	1	"	--		X		X		29 has crack
16-B	36	1	"	--		X		X		29 has crack
LPA GEN	40			"	All					Good
17-T	40	1	"	--	X			X		14 has crack
17-B	40	1	"	--	X			X		22 has crack
LPA TURB	40			"	All					
17-T	40	1	"	--	X			X		1 has crack
"	"	4	"	--		X		X		24,25,26,27 have cracks
17-B	40			"	--	X		X		Good

XCEL_Sherco_05_0122500

Confidential

MQS Inspection, Inc. 1920 Oakcrest Avenue, Roseville, MN 55113

Form 27.309

IDENTIFICATION OF DIAPHRAGM BLADING DEFECTS

Sketch is looking at steam inlet side of diaphragm.
First blade on left side would be No. 1-T on top half and
No. 1-B on bottom half. Also, show total number of
blades as their total number in either top or bottom,
not total number in top and bottom.

NB= Nozzle Block
FOD = Foreign object damage

Since the defects are found in about the same location
on either the inside diameter or outside diameter, and
usually on the discharge side we only need to indicate
with "X" where the crack or defect occurred, in proper
column and the length of the defect.

Date: 3-15-99 Station: Sherco WO# 07-F3389

Turbine #: 170X819 Unit No. 3 Technician: Michael T. Christensen, Level II, Doug Gertner, Level II

Stage	Total # of Blades	# of Defects	Inspect. Method	Blade	From OD	From ID	Inter Side	Discharge Side	Length of Defect	Type Defects
LPA	GEN									
18-T	40	1	Vt/mt	--		X		X		22 has crack
"	"	1	"	--	X			X		32 has crack
"	"	1	"	--	X					Right side horizontal joint cracked in weld area
18-B	40	1	"	--	X			X		37 previous repair area separating
"	"	1	"	--	X					Left side horizontal joint cracked in weld area
LPA	TURB									
18-T	40	1	"	--	X			X		Web cracked at blade #40
"	"	1	"	--	X					Right side horizontal joint cracked in weld area
18-B	40	1	"	--	X			X		18 has crack
"	"	1	"	--		X		X		35 has crack
"	"	1	"	--	X					Left side horizontal joint cracked in weld area
"	"	1	"	--		X				Left side fit key racked
LPA	GEN									
19-T	30	7	"	--		X	X			16,17,19,20,23-25 welds cracked
"	"	3	"	--	X		X			6,7,29 welds cracked
19-B	30	1	"	--	X			X		1 weld cracked
"	30	4	"	--		X		X		23-25, 27 welds cracked
LPA	TURB									
19-T	30	2	"	--		X		X		17,24 welds cracked
"	"	2	"	--	X			X		19,23 welds cracked

XCEL_Sherco_05_0122501

Confidential

MQS Inspection, Inc. 1920 Oakcrest Avenue, Roseville, MN 55113

Form 27.309

IDENTIFICATION OF DIAPHRAGM BLADING DEFECTS

Sketch is looking at steam inlet side of diaphragm.
First blade on left side would be No. 1-T on top half and
No. 1-B on bottom half. Also, show total number of
blades as their total number in either top or bottom,
not total number in top and bottom.

NB = Nozzle Block
FOD = Foreign Object Damage

Since the defects are found in about the same location
on either the inside diameter or outside diameter, and
usually on the discharge side we only need to indicate
with "X" where the crack or defect occurred, in proper
column and the length of the defect.

Date: 3-15-99 Station: Sherco WO# 07-F3389

Turbine #: 170X819 Unit No. 3 Technician: Michael T. Christensen, Level II, Doug Gertner, Level II

Stage	Total # of Blades	# of Defects	Inspection Method	Blade	From ID	From OD	Hold Side	Disch. Side	Length of defect	Remarks
LPA	TURB									
19-T	30	4	Vt/mi	--	X		X			10,14,22,25 welds cracked
19-B	30	3	"	--	X		X			2,3,5 welds cracked
LPB	GEN									
14-T	71		"	All			X	X		Light erosion, light FOD
14-B	71		"	All			X	X		Light erosion, light FOD
"	"	1	"	--	X			X		Previous weld repair separately at 57
LPB	TURB									
14-T	71		"	All			X	X		Light erosion, light FOD
"	"	1	"	--	X			X		63 has crack
14-B	71		"	All			X	X		Light FOD light erosion
LPB	GEN									
15-T	79		"	All			X	X		FOD erosion
"	79		"	--				X		Previous weld repair areas bending and rolling over
15-B	79	2	"	--				X		2, 76 have holes
"	"	1	"	--	X			X		74 has crack
"	"	1	"	--		X		X		52 has crack
LPB	TURB									
15-T	79		"	--						Good
15-B	79		"	--						Good

XCEL_Sherco_05_0122502

PUBLIC DOCUMENT
DISREGARD CONFIDENTIAL MARKING IN FOOTER

Confidential

MQS Inspection, Inc. 1920 Oakcrest Avenue, Roseville, MN 55113

Form 27.309

IDENTIFICATION OF
DIAPHRAGM BLADING DEFECTS

Sketch is looking at steam inlet side of diaphragm.
First blade on left side would be No. 1-T on top half and
No. 1-B on bottom half. Also, show total number of
blades as their total number in either top or bottom,
not total number in top and bottom.

NB= Nozzle Block
FOD = Foreign object damage

Since the defects are found in about the same location
on either the inside diameter or outside diameter, and
usually on the discharge side we only need to indicate
with "X" where the crack or defect occurred, in proper
column and the length of the defect.

Date: 3-15-99 Station: Sherco WO# 07-F3389

Turbine #: 170X819 Unit No. 3 Technician: Michael T. Christensen, Level II, Doug Gertner, Level II

Stage	Total # of Blades	# of Defects	Inspection Method	Blade	From OD Ring	From ID Ring	Inlet Side	Discharge Side	Length of Defect	Type Defects
LPB	GEN									
16-T	36		Vt/mt	All			X	X		Light pitting
16-B	36		"	"			X	X		Light pitting
LPB	TURB									
16-T	36		"	All			X	X		Light pitting
16-B	36		"	All			X	X		Light pitting
17-T	40		"	--						Good
17-B	40	1	"	--	X					Lift side horizontal joint cracked in weld area
"	"	1	"	--	X		X			Web cracked at blade #13
LPB	TURB									
17-T	40	1	"	--	X			X		33 has crack
17-B	40	1	"	--	X			X		10 has crack
LPB	GEN									
18-T	40	1	"	--	X					Right side horizontal joint cracked in weld area
18-B	40	1	"	--	X					Left side horizontal joint cracked in weld area
"	"	1	"	--		X		X		Repair area separating at Blade #1
LPB	TURB									
18-T	40	1	"	--	X					Right side horizontal joint cracked in weld area
18-B	40	1	"	--	X					Left side horizontal joint cracked in weld area

XCEL_Sherco_05_0122503

Confidential

MQS Inspection, Inc. 1920 Oakerest Avenue, Roseville, MN 55113

Form 27.309

IDENTIFICATION OF DIAPHRAGM BLADING DEFECTS

Sketch is looking at steam inlet side of diaphragm.
First blade on left side would be No. 1-T on top half and
No. 1-B on bottom half. Also, show total number of
blades as their total number in either top or bottom,
not total number in top and bottom.

NB = Nozzle Block
FOD = Foreign Object Damage

Since the defects are found in about the same location
on either the inside diameter or outside diameter, and
usually on the discharge side we only need to indicate
with "X" where the crack or defect occurred, in proper
column and the length of the defect.

Date: 3-15-99 Station: Sherco WO# 07-F3389

Turbine #: 170X819 Unit No. 3 Technician: Michael T. Christensen, Level II, Doug Gertner, Level II

Stage	Total # of Blades	# of Defects	Inspection Method	# Blades	From OD Ring	From ID Ring	Inlet Side	Discharge Side	Length of defect	Defect Description
LPA GEN										
19-T	30	1	Vt/mt	--	X			X		2 weld cracked
"	"	8	"	--	X		X			3,8,11,12,14,26-28 welds cracked
"	"	5	"	--		X	X			3,21,8,24,26 welds cracked
19-B	30	2	"	--	X			X		25,27 have cracks
"	"	1	"	--		X		X		26 weld cracked
"	"	20	"	--	X		X			1,2,4-7,9-11,14,16-18,21,22,26-30 welds cracked
"	"	8	"	--		X	X			6,8-11,23,24,29 welds cracked
LPB TURB										
19-T	30	9	"	--	X		X			1,6,10,16,18,20,21,27,28 welds cracked
"	"	1	"	--		X	X			11 weld cracked
19-B	30	5	"	--	X	X	X			4,9,21,26,29 welds cracked
"	"	8	"	--	X		X			1,2,10,11,16,19,27,30 welds cracked
"	"	1	"	--		X	X			24 weld cracked
"	"	5	"	--		X		X		10,11,19,20,30 welds cracked
"	"	11	"	--	X			X		3,5,13,14,16,17,22-24, 26,28 welds cracked
"	"	4	"	--	X	X		X		9,12,15,19 welds cracked

XCEL_Sherco_05_0122504

Confidential

MQS Inspection, Inc.

Form: 27.311

TURBINE COMPONENT REPORT

Client: NSP Turbine # 170X819 Unit #: 3 Item: Packing Glands
Station: Sherco Date: 3-15-99 Technician: Michael T. Christensen, Level II

Description/Area	AVL	IML	BT	TO	Damage	Location/Comments
N-1	X	X				Both halves inner & outer revealed no recordable indications
N-2	X	X				Both halves inner & outer revealed no recordable indications
N-3	X	X				Both halves revealed no recordable indications.
N-4	X	X				Both halves revealed no recordable indications.
N-5	X	X				Both halves revealed no recordable indications.
N-6	X	X				Both halves revealed no recordable indications.
N-7	X	X				Both halves revealed no recordable indications.
N-8	X	X				Both halves revealed no recordable indications.

XCEL_Sherco_05_0122505

Confidential

MQS Inspection, Inc.

Form: 27.311

TURBINE COMPONENT REPORT

Client: NSP Turbine # 170X819 Unit #: 3 Item: Casings
Station: Sherco Date: 3-15-99 Technician: Michael T. Christensen, Level II

Description of Area	YTD	MD	BD	UT	Damage	Location/Comments
H.P. Outer casing	X	X				Upper & lower casing halves revealed no recordable indications.
I.P. outer casing	X	X				Lower casing half revealed no recordable indications, upper half #2 Fit on gen. End has a 2-1/8" long crack at 61" from right side horz. Joint
L.P.-A casings	X	X				Diaphragm fits show physical damage (rubbing)
L.P.-B casings	X	X				Diaphragm fits show physical damage. (rubbing) inner (upper half) #2 access cover weld is cracked in base metal. 5.25" on the turbine End, 13.5" long crack at 61" from access cover described previously, Crack is in base metal on the turbine end. Lower half revealed no Indications
H.P. Inner casing	X	X	X			No recordable indications noted.
I.P. #1 Inner casing	X	X				Lower halves for the turbine and generator ends revealed no recordable Indications. Upper halves for the turbine and generator ends have Cracking on the left and right hand horizontal joints.
I.P. #2 Inner casing	X	X				Lower halves for the turbine & generator ends revealed no recordable Indications Upper half generator end revealed cracking on the left And right hand side horizontal joints, upper half turbine end revealed No recordable indications.

XCCEL_Sherco_05_0122506

Confidential

MQS Inspection, Inc.

Form: 27.311

TURBINE COMPONENT REPORT

Client: NSP Turbine # 170X819 Unit #: 3 Item: Misc.
 Station: Sherco Date: 3-15-99 Technician: Michael T. Christensen, Level II

Description of Area	WV	MD	FR	SD	Damage	Location/Comments
Gen. For blades (60)	X		X			No defects noted.
Misc. turning gear pieces	X		X			No defects noted.
Generator retaining rings	X		X			No defects noted.

Confidential

MQS Inspection, Inc.

Form: 27.311

TURBINE COMPONENT REPORT

Client: NSP Turbine # 170X819 Unit #: 3 Item: Exciter
Station: Sherco Date: 3-15-99 Technician: Michael T. Christensen, Level II

Description or Area	AVL	MMB	EDT	DDI	Damage	Location/Comments
Exciter retaining rings	X		X			O.D. of rings examined, no defects noted.
Bearing	X		X	X		Collector end (lwr.) - excessive rubbing.
	X		X	X		Collector end (upper) - excessive rubbing with a 1/4" long crack on the Bottom of the inboard side.
"	X		X	X		Turbine end (lwr.) - light sporadic disbond around edges.
						Turbine end (upper) - light sporadic disbond around edges, with a crack 7/16" long, 4-3/8" from left horizontal joint and 1-1/4" from inboard
						Side, another crack 3/8" long, 1/16" from right side horizontal joint 1/4" From inboard side and a 3/8" long crack, 7/8" from right horizontal Joint at the outboard side.
Seal assemblies (4) (boiler feed pump port)	X	X				3 assemblies NDE'd acceptable, #33 inboard has a 2-3/4" long crack In the webbing.
Rings (4) (boiler feed pump port)	X	X				NDE acceptable
Exciter shaft	X	X				No defects noted on excisable shaft, journals & coupling

XCCEL_Sherco_05_0122509

Confidential

MQS Inspection, Inc.

Form: 27.311

TURBINE COMPONENT REPORT

Client: NSP Turbine # 170X819 Unit #: 3 Item: Bearings
Station: Sherco Date: 3-15-99 Technician: Michael T. Christensen, Level II

Description or Area	WLD	MIL	PIV	PUW	Damage	Location/Comments
Thrust Bearings	X		X	X		Light sporadic disbond around edges of bearings, light pitting.
#1 Bearing	X		X	X		Upper half bearing has randomly isolated 1/8" diameter areas of disbond #4 pad one area and #5 pad twelve areas.
"	X		X	X		Lower half bearing has light sporadic disbond around edges of bearing Pad #6L has a 1.5" diameter area of disbond and pads 7 and 6R have Cracks in babbit, see attached sketch for locations.
#2 Bearing	X		X	X		Upper half bearing has light sporadic disbond around edges of bearing Pads. Pads #3, #4 and #5 have disbond see attached sketch for Locations. #3 and #4 pads have cuts in babbit near the governor end
"	X		X	X		Lower half bearing has light sporadic disbond around edges of bearing Pads. Pads #6L, #7 and #6R have disbond. See attached sketch.
#3 Bearing	X		X	X		Upper half bearing #3 pad missing a 1/2"X1/4" piece of material on the Generator end.
"	X		X	X		Lower half bearing #6L pad and #7 pad have light sporadic disbond Around edges

XCEL_Sherco_05_0122510

Confidential

MQS Inspection, Inc.

Form: 27.311

TURBINE COMPONENT REPORT

Client: NSP Turbine # 170X819 Unit #: 3 Item: Bearings (contd.)
 Station: Sherco Date: 3-15-99 Technician: Michael T. Christensen, Level II

Description/Location	MD	MT	ED	DD	Damage	Location/Comments
#4 Bearing	X		X	X		Upper half bearing #3 & #5 pad have light sporadic disbond around Edges, light pitting on governor end of the #5 pad.
"	X		X	X		Lower half bearing #6L & #7 have disbond on the governor end See attached sketch.
#5 Bearing	X		X	X		Upper half bearing has light sporadic disbond around the edges with light Pitting in the middle of the pad. Pad also has disbond and cracking See attached sketch.
"	X		X	X		Lower half bearing has light sporadic disbond around the edges with Cracking and disbond, see attached sketch.
#6 Bearing	X		X	X		Upper ;half bearing hs light sporadic disbond around the edges of the Generator and governor ends only. Bearing also has one area of disbond See attached sketch.
"	X		X	X		Lower half bearing has light sporadic disbond on the left and right Horizontal joints, with other areas of disbond in center of pad, See attached sketch.

XCEL_Sherco_05_0122511

Confidential

MQS Inspection, Inc.

Form: 27.311

TURBINE COMPONENT REPORT

Client: NSP Turbine # 170X819 Unit #: 3 Item: Bearings (contd.)
Station: Sherco Date: 3-15-99 Technician: Michael T. Christensen, Level II

Description/Area	W	M	D	U	Damage	Location/Comments
#4 Bearing	X		X	X		Upper half bearing #3 & #5 pad have light sporadic disbond around Edges, light pitting on governor end of the #5 pad.
"	X		X	X		Lower half bearing #6L & #7 have disbond on the governor end See attached sketch.
#5 Bearing	X		X	X		Upper half bearing has light sporadic disbond around the edges with light Pitting in the middle of the pad. Pad also has disbond and cracking See attached sketch.
"	X		X	X		Lower half bearing has light sporadic disbond around the edges with Cracking and disbond, see attached sketch.
#6 Bearing	X		X	X		Upper ;half bearing hs light sporadic disbond around the edges of the Generator and governor ends only. Bearing also has one area of disbond See attached sketch.
"	X		X	X		Lower half bearing has light sporadic disbond on the left and right Horizontal joints, with other areas of disbond in center of pad, See attached sketch.

XCCEL_Sherco_05_0122512

Confidential

VIQO Turbine Inspection Program

Form 27.319.0, Rev.0

Turbine Component Report

Client: NSP
Station: Sherco


Unit: 3

MQS Work Order No. 07F3389


Sheet 1 of 10

Date: 3-15-99


#1 Bearing Pads (Lower)



6L



7



6R

Technician: Mark J. Chrus Level I Date: 3-15-99
Technician: Doug Cretz Level II Date: 3-15-99

Confidential

VIWO Turbine Inspection Program

Form 27.319.0, Rev.0

Turbine Component Report

Client: NSP MQS Work Order No. 07F3389 Sheet 2 of 10
 Station: Sherco Unit: 3 Date: 3-15-99

#2 Bearing Pads (Upper)

↑ Dovetails Gov End #3 Pad
 ↑ Dovetails Gov End #5 Pad
 ↑ Dovetails Gen End #4 Pad

Technician: M. J. Chung Level II Date: 3-15-99
 Technician: Long Carter Level II Date: 3-15-99

XCEL_Sherco_05_0122514

Confidential

VIQS Turbine Inspection Program

Form 27.319.0, Rev.0

Turbine Component Report

Client: <u>NSP</u>	MQS Work Order No. <u>07F3389</u>	Sheet <u>3</u> of <u>10</u>
Station: <u>Sherco</u>	Unit: <u>3</u>	Date: <u>3-15-99</u>

#2 Bearing Pads (Lower)

Gov end
#6L Pad

Gov end
#7 Pad

Gov end
#6R Pad

Technician: [Signature] Level II Date: 3-15-99
 Technician: [Signature] Level II Date: 3-15-99

XCEL_Sherco_05_0122515

Confidential


MQS Turbine Inspection Program

Form 27.319.0, Rev.0

Turbine Component Report


Client: <u>MSP</u>	MQS Work Order No. <u>07F3389</u>	Sheet <u>4</u> of <u>10</u>
Station: <u>Sberco</u>	Unit: <u>3</u>	Date: <u>3-15-99</u>

4 LOWER



#6L

Gov.
END



#7

Gov.
END

Disbonded 1/8" wide

Technician: <u>Mick T. Glynos</u>	Level <u>II</u>	Date: <u>3-15-99</u>
Technician: <u>Paul J. O'Brien</u>	Level <u>I</u>	Date: <u>3-15-99</u>

XCEL_Sherco_05_0122516

Confidential

MQS Turbine Inspection Program

Form 27.319.0, Rev.0

Turbine Component Report

Client: NSP Station: Sherco Unit: 3 MQS Work Order No. 07F3389 Sheet 5 of 10
Date: 3-15-99

#5 LWR.

LEFT side

#5 upp.

LEFT side

XXXX - represents heavily pitted areas.

XCEL_Sherco_05_0122517

Technician: [Signature] Level II Date: 3-15-99
 Technician: [Signature] Level II Date: 3-15-99

Confidential

VIQO Turbine Inspection Program

Form 27.319.0, Rev.0

Turbine Component Report

Client: NSP MQS Work Order No. 07F5389 Sheet 6 of 10
 Station: Sherco Unit: 3 Date: 3-15-99

#6 upper

#6 Lower

Technician: Mark F. Christ Level II Date: 3-15-99
 Technician: Doug Becker Level II Date: 3-15-99

XCEL_Sherco_05_0122518

Confidential

MIQS Turbine Inspection Program

Form 27.319.0, Rev.0

Turbine Component Report

Client: NSP Unit: 3 MQS Work Order No. 07F3389 Sheet 7 of 10
 Station: Sherco Date: 3-15-99

Left side

GEN. END

#7 upper

Disbonded 1/8" wide

Left side

GEN. END

#7 Lower

Disbonded 1/8" wide


Technician: Matt T. Clark Level III Date: 3-15-99
 Technician: Doug Beckman Level II Date: 3-15-99

XCEL_Sherco_05_0122519

Confidential

MQS Turbine Inspection Program

Form 27.319.0, Rev.0



Technician: [Signature] Level II Date: 3-15-99
 Technician: [Signature] Level II Date: 3-15-99

XCBL_Sherco_05_0122520

Confidential

IVIGS Turbine Inspection Program

Form 27.319.0, Rev.0

Turbine Component Report

Client: NSP Station: Sherco Unit: 3 MQS Work Order No. 07F3387 Sheet 9 of 10 Date: 3-15-99

#9 Bearing (Top)

Gou End

Technician: M. L. Chu Level II Date: 3-15-99
 Technician: Doug Coitner Level I Date: 3-15-99

XCEL_Sherco_05_0122521

Confidential

VIQS Turbine Inspection Program

Form 27.319.0, Rev.0

Turbine Component Report


Client: NSP
Station: Shocco

Unit: 3

MQS Work Order No. 07F3389

Sheet 10 of 10
Date: 3-15-99

#10 Bearing (bottom)



Gov End

Technician: Mike Christ Level TD Date: 3-15-99
 Technician: Doug Barber Level II Date: 3-15-99

XCEL_Sherco_05_0122522

MQS Inspection, Inc. 1920 Oakcrest Avenue, Roseville, MN 55113

FORM 27.315

TURBINE INSPECTION PROGRAM
Ultrasonic Examination of Bolts & Studs

Client: Northern States Power MQS Work Order #: 07F3389
Station: Sherco Unit 3 Turbine No. 170X819 Date: 3-15-99

Component	Total # of Items	# Inspected	# Accept	# Reject	Dimensions (B, A, C, D)	In-Place	Defect Locations
HP Outer							
Cyl. Studs	44	44	0			No	
IP Outer							
Cyl. Studs	64	64	0			No	
CRV Studs	72	72	0			Yes	
Control							
Valve Studs	48	48	0			Yes/No	
Stop Valve Studs	48	48	0			Yes/No	
A Coupling							
Bolts	16	16	0			No	
B Coupling							
Bolts	16	16	0			No	
C Coupling							
Bolts	16	16	0			No	
D Coupling							
Bolts	16	16	0			No	
Ventilation							
Valve	18	18	0			Yes	
HP Inner							
Cylinder	26	16	0			No	

Technician: Michael T. Christensen, Level II, Douglas Gertner, Level II Date: 3-15-99

MQS		INSPECTION, INC.		TURBINE INSPECTION PROGRAM	
NDE TECHNIQUE RECORD / MAGNETIC PARTICLE				Form: 21.07A Rev. Org.	
DATE:	<u>3-15-99</u>	PAGE		of	
CLIENT:	<u>Northern States Power</u>	WORK ORDER No	<u>07F3389</u>		
STATION:	<u>Sherco</u>	UNIT	<u>3</u>		
TURBINE No	<u>170X819</u>				
SPECIFICATION:	<u>MQS INSPECTION, INC.</u>	PROCEDURE:	<u>27.D.300 Rev.0 - Section 4</u>		
PRECLEAN:					
MATERIAL:	<u>NA</u>	METHOD	<u>NA</u>	BATCH No:	<u>NA</u>
EQUIPMENT:	<u>MAGNAFLUX</u>	<u>M500</u>	<u>P500</u>	S/N:	<u>78108</u>
		(CIRCLE ONE)			
AMPS:	CURRENT:				
	Head Shot	<u>NA</u>	Coil Shot:	<u>1500 amps</u>	Other Info:
	Contact Material:	<u>COPPER</u>	4/0 Cable		
	RATED MAXIMUM AMPERAGE:		<u>4,000</u>	METHOD: <u>CONTINUOUS</u>	
	YOKE:	<u>PARKER</u>	<u>MAGNAFLUX</u>	S/N:	<u>6007-Y9</u>
	CURRENT:	<u>AC</u>	<u>DC</u>	FIXED AMPERAGE	
	MAGNETIC FIELDS ARE VERIFIED WITH A MAGNETIC FIELD INDICATOR (PIE GAUGE)				
MATERIAL:	<u>MAGNAFLUX 14A</u>	BATCH No:	<u>98C074</u>	APPLICATION:	<u>Spray</u>
	(Redi-Bath)	<u>CARRIER II</u>	BATCH No:	<u>NA</u>	
	<u>14AM</u>	BATCH No:	<u>97F09K</u>		
	GREY DRY POWDER:	TYPE:	<u>#1 Grey</u>	BATCH No:	<u>91F050</u>
	RED DRY POWDER:	TYPE:	<u>8A Red</u>	BATCH No:	<u>95D009</u>
DEMAG:	METHOD:	<u>AUTOMATIC REOSTAT DEMAG with INFINITE CONTROL</u>		RESIDUAL:	<u>+/- 2 GAUS</u>
	METHOD:	<u>Withdrawal</u>		RESIDUAL:	<u>+/- 2 GAUSS</u>
POSTCLEAN:					
MATERIAL:	<u>NA</u>	METHOD	<u>NA</u>	BATCH No:	<u>NA</u>
	NOTE: If any of the above parameters change make note of them below.				
Record results on appropriate Turbine Inspection form.			Attach sketches or additional information as applicable.		
LEVEL III APPROVAL:	TECHNICIAN / Level:		DATE:		
<u>Kenneth J. Olson</u>	<u>Michael T. Christensen, Doug Gertner</u>		<u>3-15-99</u>		

MQS		INSPECTION, INC.		TURBINE INSPECTION PROGRAM	
NDE TECHNIQUE RECORD/LIQUID PENETRANT				Form: 23.08A Rev. Org.	
DATE:	<u>3-15-99</u>	PAGE		of	
CLIENT:	<u>Northern States Power</u>	WORK ORDER No:	<u>07F3389</u>		
STATION:	<u>Sherco</u>	UNIT	<u>3</u>		
TURBINE No	<u>170X819</u>				
SPECIFICATION:	<u>MQS INSPECTION</u>	PROCEDURE:	<u>27.D.300 Rev.0 - Section 9</u>		
PRECLEAN:					
MATERIAL:	<u>NA</u>	METHOD	<u>NA</u>	BATCH No:	<u>NA</u>
				DRYING TIME:	<u>NA</u>
PENETRANT:					
MATERIAL:	<u>SKL-SP</u>	BATCH No:	<u>98M02K</u>	APPLIED BY:	<u>Spray/brush</u>
				DWELL:	<u> </u>
MATERIAL:	<u>ZL-60D</u>	BATCH No:	<u>98L108</u>	APPLIED BY:	<u>Spray</u>
				DWELL:	<u>30 min.</u>
EXCESS PENETRANT REMOVAL:					
MATERIAL:	<u>SKC-S</u>	METHOD:	<u>Wipe</u>	BATCH No:	<u>98L08K</u>
				DRYING TIME:	<u>5 min.</u>
	<u>Denatured Alcohol</u>	METHOD:	<u>wipe</u>	BATCH No:	<u>NA</u>
				DRYING TIME:	<u>5 min.</u>
DEVELOPER:					
MATERIAL:	<u>SKD-S2</u>	BATCH No:	<u>98B04K</u>	APPLIED BY:	<u>Spray</u>
				DEV. TIME	<u>10 min.</u>
POSTCLEAN:					
MATERIAL:	<u>NA</u>	METHOD	<u> </u>	BATCH No:	<u> </u>
NOTE: If any of the above parameters change make note of them below.					
Record results on appropriate Turbine Inspection form.			Attach sketches or additional information as applicable.		
LEVEL III APPROVAL: Kenenth J. Olson		TECHNICIAN / Level: Michael T. Christensen, Doug Gertner		DATE: 3-15-99	

MQS		INSPECTION, INC.		TURBINE INSPECTION PROGRAM	
NDE TECHNIQUE RECORD / ULTRASONIC				Form: 22.15A Rev. Org.	
DATE:	<u>3-15-99</u>	PAGE		of	
CLIENT:	<u>Northern States Power</u>	WORK ORDER No:	<u>07-F3389</u>		
STATION:	<u>Sherco</u>	UNIT:	<u>3</u>		
TURBINE No	<u>170X819</u>				
SPECIFICATION:					
BABBIT BEARINGS	MQS INSPECTION, INC.	PROCEDURE:	27.D.300 Rev.0 - Section 7		
STUDS / BOLTING	MQS INSPECTION, INC.	PROCEDURE:	27.D.300 Rev.0 - Section 8		
EQUIPMENT					
Unit Mfg.:	<u>Krautkramer</u>	Model:	<u>USK-7B</u>	S/N:	<u>2732</u>
Transducer Mfg.:	<u>Panametrics</u>	Model:	<u>contact</u>	S/N:	<u>191046</u>
Frequency:	<u>5.0 mhz</u>	Angle:	<u>0 degrees</u>	Size:	<u>.25" dia.</u>
Type:	<u>contact</u>				
Transducer Mfg.:	<u>Panametrics</u>	Model:	<u>contact</u>	S/N:	<u>126536</u>
Frequency:	<u>2.25 mhz</u>	Angle:	<u>0 degrees</u>	Size:	<u>.50" dia.</u>
Type:	<u>contact</u>				
CABLE:	LENGTH:	<u>6 ft</u>	TYPE:	<u>BNC / BNC</u>	<u>BNC / MD</u> * (CIRCLE ONE)
Calibration Block:	<u>IIV Block</u>	S/N:	<u>A01515</u>		
	<u>Babbit bearing cal. Std.</u>	S/N:	<u>GTM-31</u>		
Couplant:	<u>Aquasonic 100</u>	Batch No.:	<u>H-386</u>		
	<u>Turbine Oil</u>	Batch No.:	<u>NA</u>		
PROCESS					
Method:	<u>CONTACT</u>	Scanning:	<u>MANUAL</u>	Inches / Second:	<u>< 6"/sec.</u>
				Overlap	<u>25%</u>
Special Instructions:					
Record results on appropriate Turbine Inspection form. Attach sketches or additional information as applicable.					
LEVEL III APPROVAL:	TECHNICIAN / Level:		<u>Doug Gertner, Lv II</u>	DATE:	<u>3-15-99</u>
<u>Patrick J. Haggemiller</u>	<u>Michael T. Christensen, Level II</u>				



MQS Inspection, Inc.

1920 Oakcrest Avenue
Roseville, MN 55113

Phone (612)633-7616
Fax (612)633-4928

CERTIFICATION OF INSPECTION

Northern States Power
ATTN: Accounts Payable
P.O. Box 9366
Minneapolis, MN 55440

(612) 520-6896

CERTIFICATION # 07-F3389
Customer # 073310
Lab # 07
Customer Job#
Shipping Doc #
Customer PO #
Date Completed 03/19/99

Description of Parts:
Their Our

Count Count Part Number Description

Count	Count	Part Number	Description
1	1	FWO	GENERAL ELECTRIC TURBINE UNIT #3 AT SHERCO STATION, BECKER, MN

Method MAGNETIC PARTICLE, LIQUID PENETRANT

Specification MQS INSPECTION

Procedure 27.D.300 REV 0

Acceptance Criteria REPORT ALL FINDINGS TO CLIENT

Remarks:
See report.

Kenneth G. ...
MQS Inspection, Inc.

...
Title

**Northern States Power Company, doing business as Xcel Energy
Information Request**

Docket No.: E002/GR-12-961, E002/GR-13-868; E999/AA-13-599;
E999/AA-14-579; E999/AA-16-523; E999/AA-17-492;
E999/AA-18-373; OAH 65-2500-38476
Sherco 3

Requestor: Xcel Energy - Tara R. Duginske, Assistant General Counsel, Xcel Energy
Requestor email: Tara.R.Duginske@xcelenergy.com
Requested from: Minnesota Department of Commerce
Date of Request: August 29, 2023 Information Request No. 30
Response Due: September 11, 2023

Reference: DOC Response to Xcel Energy Information Request 21 (a) states:

“TIL 1121-3AR1 does not prescribe a specific interval for performing inspection of the finger dovetails but it does identify abnormal events or operational anomalies that should trigger the inspection and Sherco 3 did experience these events.” (emphasis added)

Question:

Identify with specificity the “events” referred to in this response, including the date of any such events.

Response:

The Sherco 3 operating abnormalities referred to in my testimony can be found in GE’s expert witness James D. Schultz’s “Expert Witness Report”, pages 13 – 15. See GE Litigation Deposition Exhibit 686.

Preparer:
Title:
Department:
Telephone:
Date:

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

Northern States Power Company

MPUC Docket No. E999/AA-18-373, et al.
OAH Docket No. 65-2500-38476
Exhibit____(HJS-2), Schedule 7

Schedule 7

Exhibit____(HJS-2), Schedule 7 has been marked Not-Public in its entirety. This Schedule was prepared by Mr. Herb Sirois directly in response to a report prepared by Mr. James D. Schultz (Schultz Report) on behalf of General Electric (GE), and provided to Xcel Energy by GE, subject to a confidentiality agreement. GE considers the Schultz Report to include confidential and proprietary information to GE. Therefore, the Company considers this Schedule to be trade secret data as defined by Minn. Stat. § 13.37(1)(b) and Xcel Energy maintains this information as a trade secret pursuant to Minn. Rule 7829.0500, subp 3.

Pursuant to Minn. R. 7829.0500, subp. 3, the Company provides the following description of the excised material:

1. **Nature of the Material:** Expert Report – Rebuttal to Expert Witness Report of James D. Schultz
2. **Authors:** Herbert J. Sirois, PE, Foster Cove Engineering, Inc.
3. **Importance:** Includes confidential and proprietary information of GE that is subject to a confidentiality agreement between the Company and GE.
4. **Date the Information was Prepared:** April 25, 2016