

20

4-5-00	changed cation resin on U3 CPD, #32 & #33 polisher
4-6-00	changed cation resin on U2 Boiler & Econ; U1 #11 polisher
4-10-00	removed and cleaned in-line filter on U3 Boiler silica analyzer
4-12-00	changed cation resin @ LPI
4-17-00	changed cation resin on U1 Econ, CPD and #12 polisher
	new cal standard on U3 CPD silica analyzer
	changed in-line filter on U3 Boiler Nat analyzer
	changed cation resin on U3 Main Steam
4-19-00	checked on LPI
4-21-00	New Reagents U3 Boiler SiO <sub>2</sub> Analyzer
4-25-00	Calibrated U1 and U2 Sodium Analyzers U1 Boiler slope → 90%      U2 Boiler slope → 92% U1 CPD slope → 99%      U2 CPD slope → 105%
4-26-00	Calibrated U3 Sodium Analyzers Boiler slope → 102% CPD slope → 101%
	replaced in-line filter on U3 Boiler Nat analyzer again
	changed cation resin @ LPI & Bryan J. removed and cleaned the sample filter

Wold 000174

- 5-1-00 Fresh reagents in U-3 boiler  $\text{SiO}_2$  analyzer.  
RLM
- 5-3-00 Changed reagent + tubing, etched Na electrode on Demin sodium analyzer.
- 5-4-00 New Cal Std on LPI WQP  $\text{SiO}_2$  analyzer.
- 5-5-00 New Resin in C-column, U-3 Econ Inlet.
- 5-5-00 Demin Na Analyzer: Etched electrode, new reagent + tubing. Slope  $\rightarrow$  57.9
- 5-8-00 Replaced cation resin on the various columns:  
- U1 Boiler Water  
- U2 CPD  
- 21 Polisher  
- 22 Polisher
- 5-9-00 Fresh reagents in - U1 CPD  $\text{SiO}_2$  analyzer  
- Demin  $\text{SiO}_2$  analyzer
- 5-11-00 LPI WQP - changed cation resin.
- 5-10+11-00 Calibration of ORP Monitor in U-3 lab.
- 5-15-00 - Replaced Cal Std. - U-3 Boiler  $\text{SiO}_2$  analyzer.  
- Replaced reagents - LPI  $\text{SiO}_2$  analyzer.
- 5-16-00 Rebuilt U-2  $\text{DO}_2$  probe.
- 5-18-00 Replaced colorimeter lamp - U2 Boiler  $\text{SiO}_2$  analyzer.
- 5-19-00 Cation resin changes: 11 + 12 Polishers  
U1 - Econ Inlet  
U2 - Econ Inlet

22

5-23-00	Calibration of U-3 Na analyzers: CPD - 101 % slope Boiler - 102 % slope
5-24-00	Cation Resin changed at LPI.
5-25-00	Fresh Reagents in U-2 CPD Silica analyzer.
5-31-00	Fresh Reagents in U-2 Boiler Silica analyzer
6-1-00	Fresh cation resin - U-2 Boiler cation column.
6-7-00	Cation Resin changed at LPI. Silica reagent levels at 64 %.
6-13-00	New Cal Stds on U1 - CPD Silica analyzer U2 - Boiler Silica analyzer
6-13-00	DEMIN Na analyzer - New reagent + tubing - etched Na electrode - Calibration: Slope → 57.0
6-15-00	Rebuilt the U-1 DO <sub>2</sub> sensor. (Portable)
6-15-00	Changed cation resin in the following columns: - U-1 CPD - U-2 CPD, U-2 Econ Inlet, 21 + 22 polishers
6-21-00	Cation resin changed on LPI cation conductivity. Silica reagent levels ~ 45 %
6-21-00	Cation resin changed on - U-1 Econ Inlet cation cond. - U-1 Boiler Water cation cond.

6-22-00	Calibration of U-2 Na analyzers: RLM CPD Slope → 105% Boiler Slope → 92%
	Calibration of U-1 Na analyzers: CPD Slope → 99% Boiler Slope → 90%
6-30-00	Changed cation resin on 11 + 12 Polishers C. Conductivity.
7-6-00	Replaced Std in Unit 2 CPD silica analyzer. Replaced resin in Unit 3 Boiler & B1 31 cation columns.
7-7-00	Replaced cation resin @ LPI W&P. Silica reagents tipped - level to 30%.
7-11-00	Replaced Demin Silica analyzer reagents.
7-13-00	Replaced Silica analyzer reagents at LPI.
7-14-00	W&P enunciator on Unit 1 doesn't work. Wrote MWR for electricians They replaced the fuse, but there is a transmit card that needs replacement. Refrigeration system comp #2 is continually tripping. Called Lloyd, he recharged both comp. on Unit 1.
7-20-00	LPI W&P in old lab: Silica analyzer placed in-service today.
7-21-00	changed resin in LPI Cat. column. Replaced reagents on Unit 2 CPD SiO <sub>2</sub> analyzer

24

7-26-00	Replaced reagents on Boiler U-1 & U-2 SiO <sub>2</sub> analyzers.
	Replaced resin on Econ Unit 1 Cation Col.
	Replaced pH/ref. electrodes on Unit 1 Boiler & Econ.
8-2-00	U3 CPD, 33, 32 pol CATION columns - replaced Resin
8-3-00	Replaced Resin and SiO <sub>2</sub> STD LPI Buffered pH probe at LPI pH 9.3
8-7-00	Replaced Cal std U3 BIR + Demin SiO <sub>2</sub> analyzers
8-10-00	Replaced Reagents U3 CPD SiO <sub>2</sub> analyzer
8-10-00	Replaced Resin 11 pol, 12 pol, Boiler CATION Columns U1
8-16-00	Replaced Resin U3 Steam CAT. Columns
8-16-00	- Installed (B.J.) New Dissolved Oxygen Analyzer U3 - Calibrated U3 Dissolved O <sub>2</sub> Analyzer
8-17-00	changed Reagents U3 BLR SiO <sub>2</sub> Analyzer
8-28-00	Replaced SiO <sub>2</sub> STD U1 CPD
8-29-00	Rebuilt U1 D.O. probe
8-23-00	Rebuilt Portable D.O. probe
8-30-00	Replaced Resin LPI CAT. column
8-31-00	Replaced SiO <sub>2</sub> Reagents LPI
8-31-00	Replaced SiO <sub>2</sub> Reagents Demin Analyzer

Wold 000178

- 8-31-00 Replaced Resin U3 ECON CAT. Cond.
- 9-5-00 soaked new  $\text{N}_2\text{H}_4$  cell in 2%  $\text{NaOH}$  overnight
- 9-6-00 gelled and installed  $\text{N}_2\text{H}_4$  cell into U1 Analyzer <sup>new in-line filter too</sup>  
 new tubing, o-rings, solution and etched electrode on  
 1811 EK Nat analyzer.  
 Calibrated with a slope of 58.1 and  $E_0$  of -33.1
- 9-7-00 new resin U1 Econ & U2 Econ & CPD  
 weekly LPI check
- 9-11-00 replaced cal standard on U2 Boiler silica analyzer  
 Calibrated U1 & U2 Sodium Analyzers  
 Unit 1 Boiler  $\rightarrow$  90%      Unit 2 Boiler  $\rightarrow$  109%  
 Unit 1 CPD  $\rightarrow$  84%      Unit 2 CPD  $\rightarrow$  110%
- Calibrated U3 Nat analyzers  
 Boiler  $\rightarrow$  106%  
 CPD  $\rightarrow$  108%
- 9-13-00 changed cation resin @ LPI  
 replaced reagents on U1 & U2 Boiler Silica analyzers
- 9-14-00 changed cation resin on U1 CPD and U2 #21 & #22 polisher
- 9-21-00 checked on LPI
- 9-25-00 new cal standard on U1 Boiler and U2, CPD silica analyzers
- 9-27-00 new cation resin #2 Boiler & #11/#12 polisher  
 new cation resin @ LPI

26

10-4-00	etched electrode and calibrated demin Nat analyzer slope $\rightarrow$ 58.4 $E_0 \rightarrow$ -37.3
10-4-00	new reagents on U2 CPD analyzer (silica)
10-5-00	new reagents on U3 CPD silica analyzer
	new cation resin on U2 Econ and LPI cation column in the old lab
10-11-00	new resin @ LPI
10-12-00	new reagents on U3 Boiler silica analyzer
10-16-00	new reagents on U1 CPD silica analyzer
	new cal standard on U3 CPD silica analyzer
10-17-00	calibrated U3 Nat analyzers Boiler Slope $\rightarrow$ 92% CPD Slope $\rightarrow$ 82%
10-18-00	new cation resin U2 Boiler, #21 polisher and #22 polisher
10-19-00	new cation resin on U2 CPD
	calibrated U1 & U2 Nat analyzers U1 Boiler Slope $\rightarrow$ 97% U1 CPD Slope $\rightarrow$ 89% U2 Boiler Slope $\rightarrow$ 98% U2 CPD Slope $\rightarrow$ 110%
	replaced in-line filters on U2 Boiler & CPD Nat analyzers
10-24-00	new reagents and cal standard on Demin silica analyzer
10-25-00	new cation resin @ LPI - replaced reagent valve for molybdate on Series 5000 silica analyzer @ LPI

Wold 000180

- 10-26-00 new reagents & standard for LPI silica analyzer (@LPI)
- 11-1-00 new reagents on U1 Boiler silica analyzer  
 new reagent tubing, o-rings and etched electrode on  
 1811 EL Nat analyzer.  
 ALSO calibrated Slope  $\rightarrow$  58.8  $E_0 \rightarrow$  -35.3
- 11-2-00 new cation resin for #12 polisher
- 11-6-00 BLS + RLM replaced measuring pH at LPI and buffered.
- 11-13-00 - New cation resin for LPI WQP.  
 - New Cal Std for U-1 CPD Silica analyzer.
- 11-14-00 New reagents - LPI WQP Silica in backroom - Old Chem Lab
- 11-15-00 New cation resin for  
 U-1 polisher  
 U-1 CPD  
 U-2 Econ Inlet } Cation Cond.
- 11-28-00 New cation resin for  
 21 Polisher  
 22 Polisher } Cation Cond.  
 U-2 CPD  
 New Cal Std. for U-2 Boiler  $SiO_2$  analyzer.  
 Calibration of U-3 Boiler + CPD sodium analyzers.
- 11-29-00 New cation resin at LPI WQP.
- 12-1-00 New reagents - U-2 CPD Silica analyzer.
- 12-7-00 New cation column resin for U-3 Main Steam.  
 New reagents for U-3 CPD Silica analyzer.  
 New reagents for U-1 CPD Silica analyzer.



28

12-11-00	New pH + ref. electrodes on Unit 2 Econ. Inlet.
12-14-00	New resin for U-1 Boiler Cation Cond. column.
12-18-00	-New resin for LPI WQP cation cond. * (At LPI and here at Sherco)
	-New resin for U-2 Boiler Cation + Econ Inlet.
	-New reagents for Demin. Silica analyzer.
12-19-00	New reagents for LPI WQP SiO <sub>2</sub> analyzer.
12-28-00	New reagents U1 Boiler SiO <sub>2</sub> analyzer.
	* 2001 *
1-2-01	new tubing, solution, o-rings, reference solution and etching of electrode on the demin Na <sup>+</sup> analyzer (181 EL) also calibrated * slope → 56.7 E <sub>0</sub> → -37.3
	replaced cation resin on #32 & #33 cation columns
	removed & cleaned in-line filter on dissolved oxygen sample line
1-4-01	new cation resin @ LPI
	new cation resin U1 Econ & 11 polisher
	new cation resin U2 #21 & #22 polisher
1-9-01	calibrated U2 Boiler Na <sup>+</sup> analyzer; slope → 97%
	calibrated U2 CPD Na <sup>+</sup> analyzer; slope → 105%
	installed new in-line-filters on U1 Boiler & CPD Na <sup>+</sup> analyzers

Wold 000182

1-10-01 replaced cal standard @ LPI on silica analyzer  
buffered LPI pH electrodes with 7 & 10 & collected sample  
lab → 8.8 monitor @ LPI → 9.0

1-11-01 new resin U2 CPD & Econ cation columns  
replaced reagents on U2 Boiler silica analyzer

new resin U1 CPD cation column  
calibrated U1 Nat analyzers; Boiler slope → 88%  
CPD slope → 87%

1-16-01 calibrated U3 CPD Nat analyzer; slope of 82%

replaced fitting under the molybdate reagent valve on  
U3 Boiler silica analyzer, it was leaking badly

calibrated U3 Boiler Nat analyzer; slope of 86%

1-17-01 new cal standard on Demin silica analyzer  
new cal standard on U3 CPD silica analyzer

1-18-01 new cation resin for U1 Boiler column

1-24-01 new reagents for U3 CPD silica analyzer

new resin in LPI cation column @ LPI

1-29-01 new cal standard U1 CPD silica analyzer

1-25-01 new reagents for LPI silica analyzer in 1/2 Chem lab  
new reagents for U2 CPD silica analyzer

1-30-01 calibrated Demin Nat analyzer  
slope → 56.1  $E_0$  → -38.8

1-31-01 new resin in #12 polisher cation column

30

2-6-01	replaced reagents and cal standard in U3 Boiler silica analyzer
	replaced reagents in the Demin silica analyzer
2-8-01	new reagents in silica analyzer @ LPI new cation resin in column @ LPI
2-14-01	new cation resin for: Unit 1 Economizer Unit 2 Boiler, #21 & #22 polisher LPI cation in old chem lab
2-15-01	new reagents for U1 CPD silica analyzer
2-20-01	new cal standard for U2 Boiler silica analyzer replaced pH electrodes @ LPI and buffered with 7 & 10
2-21-01	calibrated U1 nat analyzers U1 Boiler → 86% U1 CPD → 87% calibrated U2 nat analyzers U2 Boiler → 97% U2 CPD → 108%
2-22-01	calibrated U3 nat analyzers U3 Boiler → 85% U3 CPD → 82%
	new resin in U1 #11 polisher cation column new resin in U2 Econ & CPD cation columns
2-27-01	calibrated Demin nat analyzer: slope → 58.7, $E_0$ → -35.7 also replaced reagent, tubing and etched electrode
2-28-01	new resin @ LPI
3-7-01	cleaned up U1 silica analyzers and flushed all lines with DI water overnight

Wold 000184

- 3-20-01 replaced rented U3 DO sensor and calibrated  
sent old probe back through stockroom
- 3-21-01 calibrated U3 Nat analyzers: CPD slope  $\rightarrow$  90%  
Boiler slope  $\rightarrow$  91%
- replaced reagents on U3 CPD silica analyzer
- replaced cation resin on WQP @ LPI
- 3-27-01 new resin for U3 Main steam and U3 CPD cation columns
- calibrated U2 Nat analyzers: Boiler slope  $\rightarrow$  99%  
CPD slope  $\rightarrow$  109%
- new reagents for U2 CPD SiO<sub>2</sub> analyzer
- new reagents & cal standard for demin SiO<sub>2</sub> analyzer
- 3-28-01 calibrated Demin Nat analyzer: slope  $\rightarrow$  57.1 E<sub>0</sub>  $\rightarrow$  -29.6  
also etched electrode
- 3-29-01 new reagents for U3 Boiler SiO<sub>2</sub> analyzer
- 3-31-01 Replaced <sup>CATION</sup> RESIN LPI WQP (SHERCO)
- 4-5-01 Replaced ALL CATION RESINS U1
- 4-6-01 Replaced 21 + 22 polisher - cation Resin
- 4-6-01 Replaced SiO<sub>2</sub> reagents + std @ LPI
- 4-6-01 - Calibrated U1 Nat Analyzers  
- New Reagents + Std U1 CPD analyzer

32

4-11-01	- Replaced cal std U2 BLR SiO <sub>2</sub> Analyzer - Replaced reagent shutoff valve U2 Boiler SiO <sub>2</sub> analyzer
4-12-01	- Replaced Cation Resin U3 Econ + 31 polisher
4-18-01	- Replaced U1 CPD + 11 polisher cation Resin
4-18-01	Replaced Resin LPI cond @ LPI
4-19-01	Replaced Lamp U3 CPD SiO <sub>2</sub> analyzer
4-20-01	Replaced in-line filters U3 CPD + Boiler Na <sup>+</sup> Analyzers
4-20-01	Calibrated U3 Na <sup>+</sup> Analyzers Boiler - 90% CPD - <del>90%</del> 103%
4-20-01	Replaced U3 SiO <sub>2</sub> analyzer LAMP
4-25-01	Calibrated U2 Na Analyzers Boiler Slope → 92% CPD Slope → 104%
4-25-01	Calibrated Domin Na Analyzers Slope 61.5 E <sub>0</sub> -23.8
4-27-01	Changed Resin U2 BLR Cation Column
5-2-01	- Replaced U3 SiO <sub>2</sub> standard on Boiler Analyzer - Replaced U2 Econormer cation Resin
5-4-01	- Replaced U1 BLR Cation Resin - Replaced in-line filter U1 Boiler Na <sup>+</sup> Analyzer

Wold 000186

- 5-8-01 Replaced Resin in 32 pd, U3 Boiler, U2 CPD
- 5-10-01 Calibrated U1 Na Analyzers CPD 82%  
Boiler 86%
- 5-11-01 Changed Resin Column @ LPI
- 5-15-01 - Replaced SiO<sub>2</sub> stds + Reagents U3 CPD  
- Replaced Lamp in LPI SiO<sub>2</sub> analyzer in old Chem LAB
- 5-16-01 - Changed SiO<sub>2</sub> Reagents Demin SiO<sub>2</sub> analyzer  
- Changed Resin in LPI C.C. in old Chem LAB
- 5-18-01 Changed Reagents U2 CPD SiO<sub>2</sub> analyzer  
Changed Reagents U3 BLR SiO<sub>2</sub> analyzer
- 5-22-01 - Calibrated U3 CPD Na<sup>+</sup> Analyzer 102% slope  
- Calibrated U3 Boiler Na<sup>+</sup> Analyzer 109% slope  
- Replaced SiO<sub>2</sub> std U2 CPD SiO<sub>2</sub> analyzer  
- Replaced line filter U2 CPD SiO<sub>2</sub> analyzer  
- Replaced reagent valve U2 CPD SiO<sub>2</sub> analyzer #4 line
- 5-23-01 - Calibrated U2 BLR Na<sup>+</sup> Analyzer Slope → 97% 401 mV  
- Calibrated U2 CPD Na<sup>+</sup> Analyzer Slope → 103% 434 mV  
- Calibrated 1811EL Demin Na<sup>+</sup> Analyzer Slope → 60.6 -28.5 mV
- 5-25-01 Replaced Resin U3 survey Cation Cond analyzer  
Replaced SiO<sub>2</sub> Reagents U1 CPD SiO<sub>2</sub> analyzer
- 6-7-01 Replaced Reagents @ LPI SiO<sub>2</sub> analyzer
- 6-8-01 Changed Resin U1 CPD + U2 economizer C.C. Columns
- 6-14-01 Rebuilt boiler throttle valve. - Unit 1  
RLM

34

6-15-01	- Replaced $\text{SiO}_2$ std on U1 CPD - Replaced $\text{SiO}_2$ std at LPI $\text{SiO}_2$ analyzer - Replaced $\text{SiO}_2$ Reagents LPI $\text{SiO}_2$ analyzer @ OLD LAB - Replaced $\text{SiO}_2$ Reagents U1 B/R $\text{SiO}_2$ analyzer
6-21-01	Replaced Resin @ LPI C.C. monitor
6-27-01	Calibrated U3 B/R $\text{Na}^+$ Analyzer 96% slope Calibrated U3 CPD $\text{Na}$ Analyzer 113% slope Calibrated U2 B/R $\text{Na}^+$ Analyzer 94% slope Calibrated U2 CPD $\text{Na}^+$ Analyzer 102% slope Calibrated U1 CPD $\text{Na}^+$ Analyzer 83% slope Calibrated U1 B/R $\text{Na}^+$ Analyzer 90% slope Rebuilt U1 $\text{Aox. O}_2$ probe Rebuilt U2 Dissolved $\text{O}_2$ probe
6-28-01	Rebuilt Demin $\text{Na}^+$ analyzer IRIEL Spc 61.5
6-29-01	Changed resin in 12 pol, U1 B/R, C.C. column
7-5-01	Changed resin in all columns U2
7-5-01	- New Reagents Demin $\text{SiO}_2$ analyzer - New Electrodes OLD LAB pH analyzer
7-11-01	New $\text{SiO}_2$ std LPI Analyzer @ SHERCO New $\text{SiO}_2$ std U1 B/R analyzer New Resin U3 MAIN steam C.C. analyzer New Resin U3 31 pol C.C. analyzer
7-13-01	New Reagents U3 B/R & CPD $\text{SiO}_2$ analyzers New Resin U1 ECON C.C. analyzer New Reagents U1 CPD $\text{SiO}_2$ analyzer New Reagents U2 CPD $\text{SiO}_2$ analyzer
7-17-01	New Resin @ LPI C.C. analyzer

Wold 000188

7-19-01 CHANGED Resin 11 gal. Cat. Cond. analyzer

7-26-01 - Changed Reagents @ LPI SiO<sub>2</sub> Analyzer  
 - Changed Reagents U2 CPD SiO<sub>2</sub> analyzer  
 - Changed LAMP Demin SiO<sub>2</sub> analyzer

7-31-01 - Changed Resin Column U3 CPD C.C. analyzer  
 - Calibrated U3 CPD Na<sup>+</sup> Analyzer Slope 86 %  
 - Calibrated U3 BLR Na<sup>+</sup> Analyzer Slope 101 %

8-1-01 - Calibrated U1 BLR Na<sup>+</sup> Analyzer Slope 83 %  
 - Calibrated U1 CPD Na<sup>+</sup> Analyzer Slope 90 %  
 - Calibrated U2 BLR Na<sup>+</sup> Analyzer Slope 105 %  
 - Calibrated U2 CPD Na<sup>+</sup> Analyzer Slope 102 %  
 - Calibrated 1811EL Na<sup>+</sup> Analyzer and etched electrode slope 60.9 E<sub>0</sub> -28.8  
 - Replaced Resin Unit 1 CPD Cat. Cond. analyzer  
 - Replaced Leaky Fittings U2 CPD SiO<sub>2</sub> analyzer (molybdate)

8-3-01 Replaced SiO<sub>2</sub> stds U1 + U2 BLR SiO<sub>2</sub> analyzers

8-7-01 Changed Reagents LPI SiO<sub>2</sub> analyzer @ SHERCO

8-9-01 new resin @ LPI for cation column

8-15-01 new resin for U1 Econ and #12 polisher cation columns  
 new resin for U2 Econ and #21 & #22 polisher cation columns  
 new resin for U3 Econ cation column

8-20-01 new cal standard for U3 Boiler silica analyzer  
 new cal standard for Demin silica analyzer



36

8-23-01	Replaced resin 32 polisher CAT. COND. Analyzer Replaced resin 33 polisher CAT. COND. Analyzer
8-24-01	changed resin U1 Boiler CAT. COND. analyzer
8-28-01	Replaced Cal std U2 BLR SiO <sub>2</sub> analyzer Replaced Cal std U2 CPD SiO <sub>2</sub> analyzer Replaced Cal std U1 CPD SiO <sub>2</sub> analyzer
8-29-01	- Replaced in-Line filters U1 CPD + BLR Nat Analyzers - Changed resin @ LPI in Cat. Cond. Analyzer - Replaced resin 31 polisher cat. Cond. Analyzer - Changed Cal Std U3 CPD SiO <sub>2</sub> analyzer
8-30-01	- Changed Reagents U1 SiO <sub>2</sub> analyzer (CPD) - Changed Reagents U3 CPD SiO <sub>2</sub> analyzer
9-4-01	- Replaced resin U3 As O <sub>2</sub> treatment Cat Columns
9-6-01	- Calibrated U1 Nat Analyzers CPD - 90% slope Boiler 87% slope - Calibrated 1811 EL Demin Nat Analyzer 59.2 slope E <sub>o</sub> 25.1
9-11-01	- Calibrated U2 Nat Analyzers CPD - 84% slope Boiler - 100% slope
9-12-01	Changed Resin in U1 BLR CAT. COND. Analyzer
9-13-01	Changed Reagents Demin SiO <sub>2</sub> analyzer. Calibrated U3 CPD Nat Analyzers Slope 120% U3 BLR Nat Analyzers Slope 101%
9-20-01	CHANGED Resin U1 Econ, CPD, 12 pol C.C. Analyzers Changed Resin U2 Boiler Cat. Cond. Analyzers Changed Reagents U2 CPD + BLR SiO <sub>2</sub> analyzers

Wold 000190

9-21-01	Replaced Electrodes U3 CPD Nat Analyzer
9-25-01	- Calibrated U3 CPD Nat Analyzer Slope $\rightarrow$ 94 % - Changed SiO <sub>2</sub> Std U2 CPD SiO <sub>2</sub> analyzer
9-27-01	Replaced Reagents LPI (SHERCO LAB) SiO <sub>2</sub> analyzer Replaced Resin U2 Econ Cat Cond analyzer Replaced Resin 21, 22 polisher Cat Cond analyzer
10-3-01	etched electrode & calibrated Demin Nat analyzer slope $\rightarrow$ 58.3 $E_0 \rightarrow$ -31.0
10-4-01	calibrated and installed new DO probes for OT system Boiler Downcomer Serial # 43524 Econ Inlet Serial # 45136
	reinstalled DO probe # 33826 in U3 WQP & calibrated
10-9-01	new cation resin for 7 <sup>th</sup> Floor OT WQP new cation resin for LPI WQP at LPI
10-10-01	new cation resin for LPI WQP in old lab new reagents for U1 Boiler silica analyzer
10-16-01	calibrated U1 Boiler Nat analyzer; slope $\rightarrow$ 80% U1 CPD; slope $\rightarrow$ 90% U2 Boiler; slope $\rightarrow$ 90% U2 CPD; slope $\rightarrow$ 82%
	replaced cation resin on U1 Boiler, # 11 & # 12 polisher columns
	replaced cation resin on U3 Main Steam cation column
10-18-01	new reagents in U1 CPD silica analyzer

38

10-18-01	calibrated U3 Nat analyzers Boiler slope $\rightarrow$ 97% CPD slope $\rightarrow$ 97%
10-19-01	INSTALLED NEW LAMP U3 CPD S.U <sub>2</sub> analyzer
10-23-01	new reagents for U3 CPD silica analyzer
10-24-01	new resin for U1 Econ cation column new resin for U2 CPD cation column
10-31-01	new solution, tubing and etched electrode on Demin Nat analyzer. Also calibrated; slope $\rightarrow$ 54.8 E <sub>0</sub> $\rightarrow$ -37.7 new cation resin @ LPI
11-6-01	new <sup>reagents</sup> <del>standards</del> for U3 Boiler silica analyzer
11-7-01	replaced in-line filter on U3 Nat analyzer new reagents for U2 Boiler SiO <sub>2</sub> analyzer new reagents for Demin SiO <sub>2</sub> analyzer
	new cation resin for U1 CPD; new cation resin U2 Econ and #21 polisher
	new reagents and standard for LPI SiO <sub>2</sub> analyzer @ LPI
	new cation resin for OT Panel East & West Downcomer on 2 1/2 new cation resin for OT Panel Econ Inlet 7 <sup>th</sup> Floor
11-12-01	replaced cal standard in U1 Boiler & CPD silica analyzers replaced cal standard in U2 Boiler & CPD silica analyzers
11-17-01	new cation resin for U2 Boiler and #22 polisher new cation resin for U3 Boiler

Wold 000192

11-15-01 replaced cation resin @ LPI

11-26-01 new reagents for U2 CPD silica analyzer  
new reagents for LPI silica analyzer in lab

calibrated U1 Nat analyzers

Boiler slope  $\rightarrow$  80% CPD slope  $\rightarrow$  90%

calibrated U2 Nat analyzers

Boiler slope  $\rightarrow$  90% CPD slope  $\rightarrow$  82%

replaced cal standards on U3 Boiler & CPD silica analyzers

11-27-01 new cation resin for U1 Econ, #11 & #12 polisher

new cation resin for LPI column in old lab

11-28-01 replaced reagents on U1 Boiler silica analyzer

calibrated and etched electrode on Demin Nat analyzer  
slope  $\rightarrow$  56.2  $E_0 \rightarrow$  -33.2

12-6-01 new resin for LPI cation column @ LPI

12-11-01 new reagent valves, tubing and lamp (total tubing replaced)  
on LPI SiO<sub>2</sub> analyzer @ LPI

new cation resin for U3 CPD & Econ columns

12-12-01 Calibrated U3 Nat Analyzers

Boiler  $\rightarrow$  88%

CPD  $\rightarrow$  106%

new reagents for U3 CPD silica analyzer

new reagents for U2 CPD silica analyzer

40

12-12-01 calibrated U1 Nat Analyzers  
Boiler slope  $\rightarrow$  83%  
CPD slope  $\rightarrow$  90%

calibrated U2 Nat Analyzers  
Boiler slope  $\rightarrow$  90%  
CPD slope  $\rightarrow$  82%

replaced cation resin on 2 1/2 & 7<sup>th</sup> floor "OT" panels

12-13-01 replaced cation resin on U1 Boiler & CPD  
replaced cation resin on U2 Econ, CPD & #21 polisher  
replaced cation resin on U3 #3, #32, #33 polishers

12-17-01 new standard LPI SiO<sub>2</sub> analyzer in lab  
new reagents Demin SiO<sub>2</sub> analyzer  
new tubing, o-rings, solution, reference solution, etched electrode and calibrated Demin Nat analyzer  
slope  $\rightarrow$  55.3      E<sub>0</sub>  $\rightarrow$  -35.7  
buffered U1 and U2 pH electrodes on boiler & economizer

12-18-01 successful calibration of DO sensors for the "OT" system (both 2 1/2 & 7) \*RLM/JPW\*  
new cation resin @ LPI  
replaced broken cap on Demin SiO<sub>2</sub> analyzer molybdate reagent bottle

Wold 000194

(xvva)

41

1-4-02 New reagents - LPI Series 5000 (@ LPI)

New cation resin - 22 Polisher C.C.

1-9-02 New cation resin - @ LPI WQP

" " " - U-3 survey cation cond.

1-11-02 New Cation resin - LPI WQP (backroom)

" - U-1 Econ Inlet

" - 11 Polisher

" - 12 Polisher

New Silica Reagents: U-3 Boiler  $\text{SiO}_2$  analyzer

1-14-02 DEMIN Na Analyzer :- Fresh reagent and tubing, orings

- etched measuring electrode

- calibration slope  $\rightarrow 57.0$

$E_0 \rightarrow -30.4$

1-18-02 New cation resin - U-2 Boiler

- U-2 Econ Inlet

New Silica reagents - U-2 Boiler  $\text{SiO}_2$

- U-2 CPD  $\text{SiO}_2$

1-21-02 Replaced Cal Std - DEMIN  $\text{SiO}_2$  analyzer.

Submitted MWR for cal problem on 22  $\text{SiO}_2$  analyzer.

1-25-02 - New Cal Standard at LPI analyzer ( $\text{SiO}_2$ )

- Installed Fresh  $\text{O}_2$  Sensor on U-3. 31 WQP.

S/N 37962 (From Orbisphere Service Program)

(Performed Air Cal)

- Fresh cation resin - 22 polisher C.C.

- New reagents - LPI  $\text{SiO}_2$  (backroom U1+2 lab)

42

1-28-02 Fresh cation resin - 7th floor, U-3 WQP

1-29-02 New Cal Std. - U-2 Boiler Silica analyzer

1-31-02 U-2 Sodium Analyzer calibrations.  
 CPD : Slope 82 %  
 Boiler : Slope 90 %

2-1-02 Fresh Reagents on U-1 CPD Silica analyzer.

2-6-02 Re-built O<sub>2</sub> sensor for portable analyzer.

2-7-02 Fresh cation resin - U-2 CPD cation cond.  
 Calibrated U-1 sodium analyzers:  
 Boiler, Slope - 83 %  
 CPD, Slope - 90 %

2-8-02 - Fresh cation resin - 7th floor (U-3)  
 Both boiler cation cond. columns.  
 - calibrated O<sub>2</sub> sensors: 7th floor + 2 1/2 floor.  
 (U-3 WQP's)

2-8-02 New SiO<sub>2</sub> Reagents: - U-3 CPD analyzer  
 - Demin analyzer (U1+2 Lab)

2-14-02 Replaced cation resin on all columns - U1 WQP

2-15-02 New SiO<sub>2</sub> reagents - U-1 Boiler analyzer.

2-18-02 New Cal Std on U-1 CPD SiO<sub>2</sub> analyzer.

2-19-02 New cation resin - 22 Polisher C.C.

2-20-02	- New resin at LPI WQP cation conductivity monitor.
2-21-02	- Etched measuring electrode (DEMIN Na Analyzer) Cal - slope $\rightarrow$ 58.5 $e_0$ $\rightarrow$ -29.5
2-22-02	Calibrated U-3 Na Analyzers CPD : Slope 106 % Boiler : Slope 88 %
2-26-02	Replaced Lamp Assembly - LPI SiO <sub>2</sub> Analyzer (Back room of Old Chem Lab)
2-28-02	Fresh Cation Resin - 21 Polisher C.C. U-2 Econ Inlet C.C.
3-1-02	New SiO <sub>2</sub> reagents - LPI WQP (offsite location)
3-7-02	New SiO <sub>2</sub> Std. - LPI WQP (Old Chem Lab)
3-8-02	Removed, dis-assembled, and cleaned Flow regulator + filter for U-2 Boiler SiO <sub>2</sub> analyzer.
3-11-02	New reagents in U-2 Boiler SiO <sub>2</sub> analyzer.  Primed both U-3 SiO <sub>2</sub> analyzers with D.I. water and turned / powered off for 5 week outage. Transferred reagents from U-3 analyzers to U-2 CPD SiO <sub>2</sub> analyzer.
3-14-02	Fresh cation resin - LPI-WQP (offsite)
3-20-02	Fresh cation resin - LPI-WQP (U1+2 chem lab)
3-21-02	Fresh cation resin - U-2 Boiler cation cond.
3-26-02	Replaced tubing + reagent, etched measuring electrode Cal - slope 58.0 (DEMIN Na analyzer) - $e_0$ -31.9



44

3-26-02	Fresh cation resin - 22 polisher C.C. U-2 CPD C.C.
3-28-02	Fresh cation resin - 11 + 12 Polishers C.C. U-1 Econ Inlet C.C.
4-1-02	new reagents for LPI silica analyzer in old lab new reagents for Demin silica analyzer new standard for U1 Boiler silica analyzer
4-3-02	new reagents & standard for U3 CPD silica analyzer new cation resin for U3 CPD column replaced resin in cation column @ LPI
4-4-02	new cation resin for U2 Economizer
4-11-02	Calibrated Na analyzers. Unit-3 Put new reagents into Boiler SiO <sub>2</sub> analyzer & calibrated it. Patched into MTC.
4-12-02	Replaced resin in cation col's. for Unit 3 Boiler, Econ In, & Steam. Recalibrated Na analyzers on Unit 3. CPD slope = 96%      Blr Slope = 90%
4-12-02	Replaced resin in Cation Col for: Unit 1 - CPD Unit 2 - Pol. 21
4-12-02	Replaced SiO <sub>2</sub> std in LPI (in-house) analyzer

Wold 000198

4-18-02	Replaced in-line filters on both <sup>unit 3</sup> BIR & <sup>unit 3</sup> CPD Na lines. 1000 Cleaned in line filters & pressure regulators on Unit 3 BIR & CPD SiO <sub>2</sub> analyzers.
	Cleaned in-line filter on Unit 3 Diss O <sub>2</sub> line
4-19-02	calibrated Na analyzers: Unit 1 - Boiler CPD Unit 2 - Boiler CPD
4-23-02	switched to North Bank for U3 oxygen feed (DSW) changed resin on 7 <sup>th</sup> floor Econ sample panel changed resin on 2 1/2 floor both downcomer samples
4-16-02	Replaced U1 CPD SiO <sub>2</sub> Reagents (JCK)
4-24-02	WQP on LPI & Sherco sites were overwhelmed by excess pressure & temp. Silica analyzers sample hoses were broken & instrument totally steamed up. Repaired hoses, cleaned cell, re-calibrated, & reset systems.
4-25-02	Duane found insufficient cooling water to sample chiller on LPI WQP. New cooling system has been designed/installed on the LPI site. Replaced cation resin for LPI site WQP.
4-25-02	Replaced cation resin on Unit 3 WQP
5-2-02	Replaced cation resin on Unit 2 Boiler cat. cond. " " " " " 1 Pol 11 & 12 " " " " " " " 3 Pol 33

46

5-2-02	Installed two filter combos on Econ In U-3 treatment boards. Mon-Tues; Wed-Thurs.
5-2-02	Refilled ref filling sol'n on Demin Na analyzer & calibrated. Slope=61 $E_0=$
5-3-02 JCK	- Replaced Reagents U2 BCR $SiO_2$ analyzer - Replaced Reagents U2 CPD $SiO_2$ analyzer - Replaced Cal Std U1 CPD $SiO_2$ analyzer
5-6-02	Replaced cation resin in: Unit 1-Econ In. cation cols. Unit 2-CPD Pol 22
5-8-02	Unit 2 CPD $SiO_2$ is 'unable to calibrate'. Took apart & cleaned cell. Found stir bar barely moving. MWR to Kevin.  LPI - WQP surveillance - everything looks good. Found new cooling water piping.
5-7-02	- Replaced BARNSTEAD filters in U1 + 2 LAB - REPAIRED Flow cell on U1 Diss $O_2$ analyzer
5-9-02	Replaced resin in Unit <sup>2</sup> Econ In Cat. Col. Replaced $SiO_2$ analyzer $SiO_2$ reagents Unit 1 CPD  LPI surveillance - all looks good at LPI Cooling water temp $\sim 60^\circ$ 4 in-house also g
5-15-02	LPI surveillance
5-16-02	Replaced resin in LPI Cat. Col. Found leak in $SiO_2$ analyzer sample hose @ LP. Removed hose & replaced w/ new, longer hose in case of need for future repair.

Wold 000200

5-17-02 Replaced Cation resin on Unit 3 Pol 31 & 32 cat. col.

5-21-02 LPI Surveillance - all looked good  
O<sub>2</sub> filter unit installed

5-22-02 Removed filter assembly O<sub>2</sub> W&P- 7<sup>th</sup> flr  
Retubed top of Demin SiO<sub>2</sub> analyzer.

5-24-02 Replaced Reagents & Std LPI in House SiO<sub>2</sub> analyzer  
JLK Replaced Resin U1 CPD Cat Column  
Replaced Resin 2d polishr Cat. Cond. Analyzer

5-29-02 Calibrated Unit 3 Boiler & CPD Na<sup>+</sup> analyzers.  
Boiler 90% slope  
CPD 96%

5-30-02 Calibrated Unit 1 Boiler Na<sup>+</sup> & CPD Na<sup>+</sup> analyzers → 6-3-02  
" Unit 2 CPD Na<sup>+</sup> & ~~ORR~~ Na<sup>+</sup> " → 6-3-02

Replaced Unit 3 CPD SiO<sub>2</sub> reagents, poured left overs into Boiler U-3 SiO<sub>2</sub>, because were running short.

LPI surveillance - looks good, C. Cond a little high 0.2745  
There was some steam flow problem. Graph went from mid-line to bottom. Alerted Gary Schmidt upon return.

Calibrated Demin Na analyzer - new tubing, o-rings, reagent - etched ref.

5-31-02 replaced in-line filter on U2 Boiler Na<sup>+</sup> analyzer (no flow)

6-3-02 Recalibrated Demin Analyzer - SLOPE = 61% E<sub>0</sub> = 30

6-6-02 O<sub>2</sub> treatment surveillance - all looks good, bank pressure = 1200

48

6-6-02 LPI Surveillance - Cond, flows, temps, pH look good. The bottom of the SiO<sub>2</sub> analyzer (reagent cabinet door) was open, so no R. pressure. Reestablished flow.

LPI was out of service Mon-Tues. Wed I had class, today it's back on line. Mark W. will change temp leads today or tomorrow.

6-6-02 Replaced standard in Unit 2 CPD SiO<sub>2</sub> analyzer

6-6-02 New resin in Cat. Col. Unit 1 Pol. 11 & 12

6-6-02 LPI Surveillance - all looks good  
O<sub>2</sub> U-3 " - all looks good System Press = 1200

6-10-02 O<sub>2</sub> Surveillance - all looks good System pressure = 1150

Replaced resin in LPI in-house Cat Col.

6-12-02 O<sub>2</sub> Surveillance - all good

LPI - at LPI: changed SiO<sub>2</sub> reagents & standard  
Replaced cation col. resin

Replaced resin in Cation col:  
Unit 1 - Boiler & Econ In  
Unit 2 - Pol. 22

6-13-02 Unit 1 Boiler SiO<sub>2</sub> analyzer: 'unable to calibrate'  
Found it very very dirty & crusty so I took it all apart. cleaned the cell. Replaced the stir bar & recalibrated to 518 ppb.

Replaced resin Unit 2 Econ In & CPD Cation Col.

Wold 000202

6-17-02	Replaced reagents in Unit 3 Boiler SiO <sub>2</sub> analyzer  O <sub>2</sub> treatment surveillance Bank pressure = 900# Conductivity on Econ too high ???
6-18-02	LPI - out of service
6-19-02	Unit 3 Boiler Silica Analyzer Took apart & cleaned cell & all surrounding area. Replaced lamp - Recaled - 502 ppb
6-20-02	Recalibrated Unit 2 CPD SiO <sub>2</sub> analyzer after checking on sample cell, etc.
6-21-02	LPI back in-service, Mark W. will do surveillance. Looked good on all O <sub>2</sub> Treatment on Unit 3.
6-25-02	Calibrated Unit 3 Boiler & CPD Na <sup>+</sup> analyzers.
6-27-02	Replaced resin Pol 21 Cation Col.
6-28-02	LPI Surveillance Changed resin in cation col.  Replaced SiO <sub>2</sub> reagents on Unit 2 Boiler & CPD SiO <sub>2</sub> anal.
7-1-02	- Replaced Resin U3 Survey CAT cond monitor JLK - Replaced Selenium UI BLR SiO <sub>2</sub> analyzer. Unable to calibrate, Low flow from STD. - Replaced STD UI BLR SiO <sub>2</sub> analyzer.
7-2-02	Replaced SiO <sub>2</sub> STD U3 CPD
7-3-02	LPI - Resin 80%, Reagent 66%, STD 70% - Sample Press ≈ 2.1 - Looks OK

50

7-3-02 JLK	- Replaced Resin U3 BLR Downcomer 2 1/2 floor
7-10-02	- Removed O <sub>2</sub> sensors 43524 + 45136 from service on 2 1/2 and 7th floor U3 O <sub>2</sub> Feed, will put new sensors in service when system is up and running.
7-11-02	- Replaced chart U3 NO analyzer - LPI - Resin 60%, Reagent 52, STD 60% - Changed Reagents + STD Demin SiO <sub>2</sub> analyzer
7-12-02	- Replaced Reagents + STD U1 CPD SiO <sub>2</sub> analyzer - Replaced std U2 BLR SiO <sub>2</sub> analyzer
7-18-02	LPI - Resin 30%, Reagent 41%, STD 50%
7-19-02	- Replaced Reagents LPI (in house) SiO <sub>2</sub> analyzer - Replaced Resin U2 Economizer CAT cond Analyzer - Replaced Resin U1 CPD, Econ " " " - Replaced Resin 11 + 12 polisher CAT cond. analyzer - Replaced Reagents U3 CPD SiO <sub>2</sub> analyzer
7-23-02	<del>Replaced</del> Calibrated U1 Nat Analyzers CPD 93% BLR 107%
7-24-02	Replaced Resin @ LPI CAT COND Analyzer Resin 100%, Reagent 30%, STD 40%
7-25-02	Replaced Resin LPI in House CAT. COND. analyzer
7-24-02	Calibrated U2 Nat Analyzers CPD 96% BLR 103%
7-25-02	- Changed Resin U2 CPD, 22 polisher Cat. Cond. Analyzer - Replaced Reagents U1 CPD SiO <sub>2</sub> analyzer

Wold 000204

7-30-02 - Replaced  $\text{SiO}_2$  std LPI in-House Analyzer  
 - Calibrated U3 Nat Analyzer - CPD 111%  
 - BLR 97%

8-1-02 - Replaced  $\text{SiO}_2$  Reagents @ LPI  
 Reagent 100%  
 Resin 60%  
 STD 20%

8-6-02 Replaced  $\text{SiO}_2$  std U2 CPD Analyzer

8-8-02 - Replaced  $\text{SiO}_2$  std @ LPI Resin 30%, Reagent 88%  
 - Buffered pH analyzer (LPI) Buffered fine, but wouldn't read sample accurately. K. Backes will install new pre-amp. Adjusted analyzer to pH of 9.0. Lab reading 9.0  
 - Replaced Resin U3 SAT/MAIN steam Cat Cond Analyzer  
 - Replaced  $\text{SiO}_2$  reagents U3 CPD  $\text{SiO}_2$  analyzer  
 - Replaced Resin 21 pol CAT. COND Analyzer  
 - Replaced Resin U2 Boiler CAT. COND. Analyzer

8-13-02 - Changed Resin U3 CPD CAT cond Analyzer  
 - Changed Resin U1 BLR CAT cond Analyzer  
 - Replaced Lamp U2 CPD  $\text{SiO}_2$  Analyzer  
 - Replaced Resin @ LPI, STD, 100%, Reagent 80%  
 - Buffered pH analyzer (OK) Adjusted pH reading to match that of U3 Lab 9.0  
 - Checked pH analyzer for LPI in old chem lab (OK) 9.3

8-14-02 - Changed Reagents U2 BLR  $\text{SiO}_2$  Analyzer

8-22-02 LPI - Resin 75%, Reagent 67%, STD 90%

8-28-02 - Replaced Resin U3 Econ CAT COND Analyzer  
 - Replaced Resin U2 Econ CAT COND Analyzer  
 - Replaced Reagents U1 CPD  $\text{SiO}_2$  Analyzer  
 - LPI Resin 50%, Reagent 56%, STD 80%



52

8-28-02 JKK	Replaced Resin U1 ESW CAT. Conv Analyzer
9-3-02	- replaced reagents on Demin SiO <sub>2</sub> analyzer - new cal standard for U1 Boiler SiO <sub>2</sub> analyzer
9-5-02	new resin for W&P @ LPI (100%) SiO <sub>2</sub> reagents → 43% SiO <sub>2</sub> standard → 70%
9-6-02	new resin for U1 CPD, #11 polisher & #12 polisher new resin for #22 polisher  new reagents in U3 CPD SiO <sub>2</sub> analyzer
9-11-02	etched electrode and calibrated the Demin Nat analyzer Slope → 56.9 E <sub>0</sub> → -29.2  calibrated U1 Nat analyzers Boiler slope → 95% CPD slope → 107% calibrated U2 Nat analyzers Boiler slope → 91% CPD slope → 105%
9-12-02	LPI W&P weekly check (everything was good) SiO <sub>2</sub> reagents → 32% SiO <sub>2</sub> standard → 60%
9-13-02	Replaced cation resin in Unit 3 Polisher #33 col.
9-17-02	- new SiO <sub>2</sub> reagents for U1 Boiler & LPI analyzer in old lab - new cation resin for CPD Unit 2 & #21 polisher
9-18-02	calibrated U3 Nat analyzers Boiler slope → 94% CPD slope → 103%
9-19-02	LPI W&P weekly check (looked good) cation → ~60% SiO <sub>2</sub> reagents → 20% (reset to 30) SiO <sub>2</sub> standard → 50%

Wold 000206

9-24-02	replaced reagents in SiO <sub>2</sub> analyzer @ LPI Reagents → 100%    Standard → 40%    Cation Resin → 40%
9-25-02	- new resin for #31 & #32 polisher - new resin for LPI cation in old lab - new reagents for U2 CPD silica analyzer
9-26-02	- new reagents and cal standard for U3 Boiler SiO <sub>2</sub> analyzer - replaced cation resin @ LPI
9-30-02	- new cal standard for U2 Boiler SiO <sub>2</sub> analyzer - new cal standard for Demin SiO <sub>2</sub> analyzer
10-3-02	LPI silica reagents 85%; silica standard @ 30% cation resin @ ~75%
10-7-02	new cal standard in U1 CPD SiO <sub>2</sub> analyzer
10-8-02	new cal standard in U3 CPD SiO <sub>2</sub> analyzer
10-9-02	U2 Boiler Reagents for SiO <sub>2</sub> analyzer replaced New solution, tubing, etched electrode and calibrated Demin Nat analyzer. Slope → 52.5 E <sub>0</sub> → -37.5
10-10-02	LPI reagents @ 72%, standard @ 20% cation resin ~ 50%
	new cation resin for U2 Economizer
10-16-02	- Calibrated U1 Nat analyzers; Boiler slope → 98%, CPD slope → 100% - calibrated U2 Nat analyzers; Boiler slope → 91%, CPD slope → 105% - calibrated U3 Nat analyzers; Boiler slope → 96%, CPD slope → 105%
10-17-02	LPI reagents @ 62%, standard @ 10%, cation resin @ ~ 25%

b4

- 10-17-02 - new resin for U2 Boiler cation column  
- new reagents for U1 CPD SiO<sub>2</sub> analyzer
- 10-22-02 replaced resin in East & West Downcomer Sample columns for OT system on 2 1/2 floor.  
Also installed new DO probes on 2 1/2 (Serial # 36103)  
& 7 (Serial # 46308)
- 10-23-02 - replaced cation resin @ LPI  
new SiO<sub>2</sub> standard @ LPI  
Reagents → 52% standard → 100% resin → 100%
- replaced cation resin in U1 Boiler, Econ, #11 & #12 polisher columns  
- replaced cation resin in U2 #21 & #22 polisher columns  
- new reagents in Demin SiO<sub>2</sub> analyzer
- 10-30-02 - new reagents in U3 CPD SiO<sub>2</sub> analyzer  
- Weekly LPI check  
SiO<sub>2</sub> standard → 90%; SiO<sub>2</sub> reagents → 41%; cation → 75%
- 11-6-02 replaced standards on U2 CPD SiO<sub>2</sub> analyzer and the LPI SiO<sub>2</sub> analyzer in the old lab  
Calibrated Demin Nat analyzer (etched electrode)  
slope → 55.1 E<sub>0</sub> → -28.6
- 11-7-02 - Weekly LPI check  
SiO<sub>2</sub> std → 80%; SiO<sub>2</sub> reagents → 28%; cation → 40%
- 11-12-02 - Calibrated U1 & U2 Nat analyzers  
U1 Boiler slope → 93% U2 Boiler slope → 92%  
U1 CPD slope → 100% U2 CPD slope → 106%  
- new reagents & standard for U2 CPD SiO<sub>2</sub> analyzer

Wold 000208

11-12-02	new cation resin for U1 CPD column
11-13-02	Calibrated U3 nat analyzers Boiler slope $\rightarrow$ 94% CPD slope $\rightarrow$ 105%
	- new cation resin for U3 Boiler column - new cation resin for U2 Econ & CPD columns
11-14-02	- new resin for Econ Inlet oxygenated treatment sample on 7 <sup>th</sup> floor - new cation resin @ LPI SiO <sub>2</sub> reagents $\rightarrow$ 16% ; SiO <sub>2</sub> STD $\rightarrow$ 70% ; Cation Resin $\rightarrow$ 100%
11-18-02	- new SiO <sub>2</sub> reagents @ LPI - new SiO <sub>2</sub> reagents for LPI W&P panel in old lab - new SiO <sub>2</sub> reagents for U2 CPD analyzer
11-19-02	- new SiO <sub>2</sub> reagents for U3 Boiler analyzer - new cation resin for LPI panel in old lab - new cation resin for U3 Make-Up To Condensor column
11-26-02	*LPI check* SiO <sub>2</sub> reagents $\rightarrow$ 87% ; SiO <sub>2</sub> STD $\rightarrow$ 60% ; Cation Resin $\rightarrow$ 50%
12-2-02	switched to North Bank oxygen cylinders U3
12-4-02	- new resin for #11 & #12 polisher cation columns - new resin for Econ inlet cation column - new SiO <sub>2</sub> reagents in U1 CPD analyzer - new resin for #21 & #22 polisher cation columns
12-9-02	calibrated Demin nat analyzer (new tubing, solution & etched electrode) slope $\rightarrow$ 52.5 E <sub>o</sub> $\rightarrow$ -36.2

56

- 12-6-02 JCK replaced resin @ LPI
- 12-11-02 new cation resin for "OT" panels on 2 1/2 & 7<sup>th</sup> floor
- 12-12-02 new cation resin for U2 Boiler & Econ columns  
new cation resin @ LPI (100%)  
weekly LPI check: SiO<sub>2</sub> reagents → 65%; SiO<sub>2</sub> STD → 30%
- 12-16-02 LPI surveillance: SiO<sub>2</sub> reagents → 59%; SiO<sub>2</sub> STD → 30%
- 12-17-02 - calibrated U3 Nat analyzers  
Boiler slope → 87% CPD slope → 103%
- replaced standard and reagents on U3 CPD silica analyzer
- calibrated U1 Nat analyzers  
Boiler slope → 93% CPD slope → 100%
- calibrated U2 Nat analyzers  
Boiler slope → 90% CPD slope → 101%
- new reagents and standard for Demin SiO<sub>2</sub> analyzer
- new standard for U2 Boiler SiO<sub>2</sub> analyzer
- 12-18-02 new cation resin for U3 Main steam, Economizer Inlet & CPD columns

Wold 000210

\* \* \*  
\* 2003 \*

- 1-3-03 LPI W&P  
Post New Year's Day Outage  
Replaced cation resin in col.; est. flows - all  
~~looks~~ looks good.
- 1-8-03 BLM-replaced cation col. resin on Unit 1 Boiler Cation Col.
- 1-6-03 Replaced Unit 1 Boiler SiO<sub>2</sub> analyzer reagents
- 1-9-03 Replaced Unit 2 CPD SiO<sub>2</sub> Analyzer:  
Reagents  
Filters-in reagent bottles  
The analyzer is 'unable to calibrate', this is the first  
troubleshooting attempt. Air is being delivered to  
sample cell from somewhere.
- 1-10-03 LPI Surveillance for week-end.  
Replaced SiO<sub>2</sub> reagents & standard.
- 1-13-03 Replaced reagents in Unit 2 Boiler SiO<sub>2</sub> analyzer
- 1-14-03 Replaced reagents in LPI Sherco In-house SiO<sub>2</sub> analyzer.  
  
Have been working on Demin Sodium Analyzer  
Replaced: Na<sup>+</sup> electrode; Reference Electrode &  
fill. solution; reagent, tubing & O-rings.  
I reset the PMA board & have tried several  
calibrations, but the slope is always too high. Still trying!
- 1-15-03 Replaced resin in Unit 2 Pol 22 & Unit 1 Pol 12 Cat. Col.
- 1-16-03 Cleared & rebuilt O<sub>2</sub> probe for Portable Drbisphere.

58

1-17-03	LPI Surveillance: SiO <sub>2</sub> reagents - 89% Std - 90% Replaced resin in Cation Column.
	Unit 1 Replaced resin in Econ In & Pol 11 Cat. Col.
	Unit 2 Replaced resin in Econ In & Pol 21 Cat. Col.
	Replaced resin in Survey Cation Col. on Unit 1
	O <sub>2</sub> treatment check on 7 <sup>th</sup> /2 1/2 flrs - looks good.
	Tried Cal. on Demin Na again - didn't work!
1-21-03	Replaced resin on Econ. O <sub>2</sub> Treat. 7 <sup>th</sup> Floor Cat. Col.
	Started up O <sub>2</sub> treatment system to 20% on BFP side only.
1-23-03	Replaced resin on LPI - (old lab) Cat. Col.
	Tried to Cal the Demin Na again - ???
	Replaced reagents & SiO <sub>2</sub> std on Unit 1 CPD SiO <sub>2</sub> Analyzer
1-24-03	LPI Surveillance - looks good reagent - 77% Std - 80%
1-27-03	Replaced Unit 2 CPD SiO <sub>2</sub> std in Series 5000.
1-28-03	Replaced Unit 3 Boiler SiO <sub>2</sub> Reagent in SiO <sub>2</sub> analyzer
	Restarted O <sub>2</sub> treatment Econ - 30% CPD - 10%
1-29-03	Demin Na Analyzer calibrated slope = 61.7 E <sub>0</sub> = -7.3

Wold 000212

1-30-03	Replaced resin in 32 Polisher Cat. Col.
1-31-03	LPI Surveillance: Good flows SiO <sub>2</sub> reagents - 68% Std=70%
1300 hrs	LPI SiO <sub>2</sub> Check Analyzer 35ppb Grab Value 34ppb Ops lead was going to call ALLEE So he could alert LPI to their process problem.
2-4-03	Replaced Resin @ LPI
2-7-03	LPI Surveillance - Good flows - all good
2-7-03	Unit 3 CPD SiO <sub>2</sub> Analyzer - replaced reagents Replaced cation resin in cation columns on: Unit 2 Boiler " CPD Unit 1 CPD
	Calibrated Na <sup>+</sup> Analyzers Unit 3 Boiler <del>CPD</del> CPD Slope → 108% ↳ Slope → 95%
2-3-03	Calibrated Na <sup>+</sup> Analyzers Unit 1 Boiler Slope → 96% CPD Slope → 100%
2-3-03	Calibrated Na <sup>+</sup> Analyzers Unit 2 Boiler Slope → 93% CPD Slope → 105%
2-12-03	Replaced SiO <sub>2</sub> reagents in Demin SiO <sub>2</sub> analyzer
2-13-03	LPI Surveillance - Plant is out of service - took a look at panel SiO <sub>2</sub> analyzer Reagents = 44% Std = 50% Cat Resin 1/2 used.



60

2-17-03	LPI Surveillance after an extended outage. Checked $\text{SiO}_2$ analyzer - theirs read 22ppb lab reading was 23ppb. The analyzer continually flashes an alarm of ↔ B reagent pressure - will have I & C look at it. Possibly replaced <del>gauge</del> <sup>sensor??</sup>
2-19-03	LPI Surveillance - $\text{SiO}_2$ check - see log book Unit 1/2  Replaced resin in cation column
2-21-03	LPI Surveillance $\text{SiO}_2$ analyzer still has pressure alarm Reading 43ppb today Reagent = 30% std = 31%  Replaced resin on Unit 3 $\text{O}_2$ treat Econ Panel
2-21-03	LPI - $\text{SiO}_2$ analyzer Duane - replaced all reagents and 1 of the reagent caps because it had fallen apart
2-24-03	Replaced U-3 Boiler $\text{SiO}_2$ analyzer → $\text{SiO}_2$ std.
2-24-03	Replaced resin in Cation Col: Unit 2 Pol 22 Unit 1 Pol 11 & 12 Replaced Whitey valve on Pol 11 Cat. Col.
2-25-03	Replaced cation resin on Polisher 22  cleaned flow cells on: CPD & Econ Unit 1 CPD Unit 2

Wold 000214

2-26-03 Replaced Econ In. Unit 2 Cation Resin.

2-28-03 LPI Surveillance

SiO<sub>2</sub> Analyzer - SiO<sub>2</sub> reagents → 87% Std → 25%

↳ still is in continual alarm of < 8psi reagent pressure

Portable Diss O<sub>2</sub> probe rebuilt & back in-service

All turbine oils & EHC's sampled & sent.

Corrosion samples gathered from O<sub>2</sub> treatment center.

O<sub>2</sub> pressure currently at 1000 psi → treatment both @ 10%.

3-3-03 LPI Surveillance

The plant was doing a boil-out on the paper roller.

The Cat. Cond. was 0.56

pH 9.6

SiO<sub>2</sub> 35ppb grabbed a sample

Lab → 14ppb

Analyzer Cal was 479ppb - some work may be required out there.

Patched out all analyzers for Unit 2 outage.

Put DI water in reagent bottles for SiO<sub>2</sub> analyzers on Unit 2 Boiler & SPD's

3-5-03 Replaced resin in Unit 1 Boiler & Econ In. cation col.

Replaced blue pen on Yokagawa ORP recorder Unit 3.

LPI

Replaced resin in cation col on their WAP

SiO<sub>2</sub> analyzer still flashing > 8psi reagent pressure

Cal value = 501ppb SiO<sub>2</sub> = 17ppb Grab = 12ppb

62

3-7-03	<p>Changed O<sub>2</sub> bank</p> <p>LPI Surveillance Looks good SiO<sub>2</sub> reagent pressure - still continuous alarm ↳ 72%      Sample press = 5 psi CC - 0.22 M5      pH 9.6</p> <p>SiO<sub>2</sub>      LPI WQP      14ppb      Grab = 8ppb Sherco WQP      25ppb      Grab = 6ppb(???)</p> <p>Called SS (Nordang) told him things look OK for WK-Ed.</p>
3-10-03	<p>LPI Surveillance all working well. SiO<sub>2</sub> → 10ppb Reagent → 67% <del>ppb</del>      Std → 30% C.C. 0.15 M5      pH 9.5</p>
3-11-03	<p>Replaced sample solenoid in Unit 3 Boiler SiO<sub>2</sub> 5000. It was 'unable to calibrate', sample was constantly dripping into sample cell - diluting sample.</p>
3-12-03	<p>LPI Surveillance SiO<sub>2</sub> - Site = 9ppb      Lab = 4ppb</p> <p>Sherco WQP SiO<sub>2</sub> analyzer has something wrong. I retubed <del>the</del> the upper half. It calibrates OK It read 20ppb - grab sample read 15ppb. Next sample, it read 5ppb, grab = 21ppb. ????</p>
3-14-03	<p>LPI Surveillance Looks good SiO<sub>2</sub> still same alarm. ↳ 8ppb</p>

Wold 000216

3-17-03 LPI Site

Replaced  $\text{SiO}_2$  std.

↳ the pressure sensor didn't register that the analyzer lost pressure. It should have put the system into alarm & it would have needed a reset - after the bottle was removed, etc, but none of that happened. It just continued reading the usual '>8 pressure' alarm.

A WO has been generated & parts have been ordered for the instrument to have an overhaul after Unit 2 outage is over.

3-19-03 Sherco LPI WAP  $\text{SiO}_2$  analyzer

Replaced reagents & moved sample tube in solenoid slightly.

Replaced resin in Cation Col.

Unit 2 CPD  $\text{SiO}_2$  analyzer Overhaul

Retubed all of the reagent delivery system, top & bottom

Replaced lamp

Replaced reagents

Recalibrated

Since this analyzer was intermittently unable to calibrate I found the sample cell filled with air bubbles when the reagents were low - during cal. cycle, but with full reagent bottles the calibration would be OK. After the retube I placed low level reagent bottles from another analyzer in there purposely & tried several calibrations & it worked. Hopefully this fixed the problem.

3-19-03 ~~Replaced  $\text{SiO}_2$  reagents on SHERCO LPI WAP  $\text{SiO}_2$  Analyzer~~

Replaced  $\text{SiO}_2$  reagents on Unit 1 Boiler  $\text{SiO}_2$  Anal.

" " " " " " CPD  $\text{SiO}_2$  Anal.

64

3-19-02

~~1. Resin in Cation Col. for Silica~~ ~~WAP~~'S  
 CALIBRATION UNIT 3 Sodium's  
 Boiler Sodium Analyzer  
 Slope → 90%

CPD Sodium Analyzer  
 Slope → 104%

3-20-03

CALIBRATION SODIUM ANALYZERS

UNIT 1

Boiler → Slope = 100%

CPD → " = 94%

UNIT 2

Boiler → Slope = 109%

CPD → " = 88%

3-21-03

Replaced reagents in Unit 3 Boiler Silica Analyzer

O<sub>2</sub> Bank pressure = 1700 psi

calibrated Demin Nat analyzer repeatedly all week  
 Left it with out-of-limit slope of 62.5 E<sub>0</sub> = -13.4

LPI-

Replaced cation resin at their WAP

Checked out SiO<sub>2</sub> analyzer - looks good. Still has  
 exact alarm situation. Readout = 45ppb

They are bringing several things back on-line today.  
 There was navy blue spill over everywhere over  
 there, it looked VERY strange.

pH was reading high → 9.8 c.c. 0.5B B-4 change-out

3-24-03

Corrosion Sampler in-service again. Samples gathered  
 Mon-Fri.

Wold 000218

~~3-23-03~~ Replaced resin in Cation Col. on Unit 2 Pol. 21 & 22

3-24-03 Unit 2 Boiler Silica Analyzer

Upper half retubed

Replaced lamp

Cleaned sample cell

Cleaned everything in upper half

Cleaned sample trough & replaced sample tubing on Unit 2.

LPI Surveillance - looks good throughout  $\text{SiO}_2$  Mon = 8ppb

3-25-03 Replaced resin in Unit 3 Polisher 31 & 33 Cation Col.

Replaced resin in both  $\text{O}_2$  treatment WQP treatment panels.

4-1-03 - Replaced CAL STD + Reagent U3 CPD  $\text{SiO}_2$  analyzer  
- LPI

- Reagent 31 90

- STD 80 90

- Resin 40 90

- Adjusted pH analyzer with sample cal. Was in alarm and reading 9.7. Adjusted to 9.3 lab reading.

4-1-03 Replaced Cation resin on Unit 2 in: Boiler; Econ; CPD Columns

4-2-03 Replaced Ref Solution, tubing, o-rings, etched electrode  
calibrated Demin Nat Analyzer Slope 59.2

4-4-03 - Changed  $\text{O}_2$  Banks U3

- Changed resin column U1 CPD

- changed reagents on Demin  $\text{SiO}_2$  analyzer

- Changed resin @ LPI C.C. analyzer

66

- 4-8-03 ~~scr~~ - Replaced  $\text{SiO}_2$  std U1 Boiler Analyzer
- 4-10-03 - Replaced Resin U3 Boiler, Econ, CPD, main steam Cation Conductivity Analyzer
- Replaced Reagents @ LPI  $\text{SiO}_2$  analyzer
- 4-16-03 Changed  $\text{SiO}_2$  std on LPI in-house  $\text{SiO}_2$  analyzer
- 4-17-03 - Changed Resin U3 Economizer Downcomer 7th Floor
- Changed Resin @ LPI C.C. Analyzer
- Changed Resin U1 Econ C.C. Analyzer
- 4-18-03 New Stir Motor U2 Boiler  $\text{SiO}_2$  Analyzer
- 4-22-03 New  $\text{O}_2$  Banks U3  $\text{O}_2$  Feed System
- 4-29-03 - New std U1 CPD  $\text{SiO}_2$  analyzer
- Installed + calibrated new Diss  $\text{O}_2$  probe U1 WQP.
- Installed + Calibrated new Diss.  $\text{O}_2$  probe U3 WQP.
- Installed + calibrated U3 7th Fl DO probe
- Installed + Calibrated U3 2 1/2 Fl D.O. probe
- Replaced resin U3 2 1/2 Floor C.C. analyzer
- 5-1-03 Replaced Resin in U2 CPD, Econ, 21 pol, 22 pol
- 5-6-03 Calibrated U3  $\text{Na}^+$  Analyzers BLR = 88% slope  
CPD = 111% slope
- 5-6-03 CHANGED Resin Column @ LPI

Wold 000220

5-7-03	Calibrated - U1 BLR Nat Analyzer - slope 93%
	- U1 CPD 94%
	- U2 BLR 97%
	- U2 CPD 115%
	- Demin Na Analyzer - slope - 59.2
5-8-03	Changed SiO <sub>2</sub> Reagents U3 BLR
5-16-03	- CHANGED Resin U2 CPD, 21 pol, 22 pol
	- New Reagent U3 Boiler SiO <sub>2</sub> analyzer
	- New Reagent U1 Boiler SiO <sub>2</sub> analyzer
	- New Reagent U2 Boiler SiO <sub>2</sub> analyzer
	- New Reagent LPI in House analyzer
5-20-03	New Resin U1 CPD, 11 pol, 12 pol
5-22-03	- Replaced SiO <sub>2</sub> std. at LPI
	- Replaced Resin @ LPI
	- Reagents @ 34% @ LPI SiO <sub>2</sub> analyzer
	- Replaced Resin U2 BLR CAT. cond. monitor
5-27-03	Replaced SiO <sub>2</sub> Reagents + STD Demin analyzer
	Replaced SiO <sub>2</sub> STD U3 CPD
5-30-03	- Replaced Resin U1 ECON CAT COND ANALYZER
	- Replaced Reagents U2 Boiler SiO <sub>2</sub> analyzer
	- Replaced Reagents LPI SiO <sub>2</sub> analyzer
	- Replaced Resin U3 32 pol CAT. COND. ANALYZER
6-5-03	- Replaced Resin 21 + 22 pol CAT COND ANALYZER
	- Changed O <sub>2</sub> Banks U3 O <sub>2</sub> Feed System
6-11-03	Calibrated U3 Nat Analyzers CPD Slope 108%
	BLR Slope 91%



68

6-12-03 Calibrated U1 CPD Na<sup>+</sup> analyzer  
 U1 BLR Na<sup>+</sup> analyzer 85.90  
 U2 BLR Na<sup>+</sup> analyzer 83.90  
 U2 CPD Na<sup>+</sup> analyzer 89.90  
 DEMIN Na<sup>+</sup> analyzer -59.2 slope

6-26-03 - CHANGED Resin 11 polisher Cat. cond. analyzer  
 - CHANGED Resin 12 polisher Cat. cond. Analyzer  
 - CHANGED Reagents U2 CPD SiO<sub>2</sub> analyzer  
 - CHANGED Reagents U1 Boiler SiO<sub>2</sub> analyzer  
 - CHANGED electrodes U1 CPD Na<sup>+</sup> analyzer  
 - CHANGED Reagents U3 Boiler SiO<sub>2</sub> analyzer

6-27-03 CHANGED Resin U3 O<sub>2</sub> feed 74 & 2 1/2 Floor  
 LPI 60.70 Resin  
 60.70 STD  
 60.70 Reagent  
 - Flows established after outage, filter plugged

7-3-03 new cation resin U2 economizer

7-7-03 new reagents U1 CPD SiO<sub>2</sub> analyzer

7-8-03 new reagents for U3 CPD SiO<sub>2</sub> analyzer

7-9-03 new cation resin @ LPI  
 SiO<sub>2</sub> reagents → 46% SiO<sub>2</sub> STD → 50%

7-10-03 new cation resin for U1 Econ & CPD

new cation resin for U2 Boiler, #21 & #22 polishers

7-16-03 Maintenance + calibration of DEMIN Na<sup>+</sup> analyzer.

RLM

Slope 59.0

- 7-17-03 Visit to LPI - cation column  $\frac{1}{2}$  depleted  
- reagents 32% std. 40%
- 7-21-03 Visit to LPI - reset reagents to 30%  
- cation is  $\frac{2}{3}$  depleted
- New reagents - Demin  $\text{SiO}_2$  analyzer  
New chart paper - 11WQP-01
- 7-23-03 New reagents - U-2 Boiler  $\text{SiO}_2$  analyzer
- 7-25-03 - LPI status - No sample flows due to steam +  
drain line maintenance activities.  
- New resin on 31 polisher cation column.
- 7-31-03 - New resin at LPI plant WQP.
- 8-1-03 - New resin - U-3 7th floor WQP
- 8-4-03 - New reagents at LPI  $\text{SiO}_2$  analyzer.  
- New reagents LPI WQP in U1+2 chem Lab  
-  $\text{SiO}_2$  Std. U1 - CPD  $\text{SiO}_2$  analyzer.  
- New Resin - U-2 Econ (cc. cond)  
U-2 CPD
- 8-5-03 New Resin - U3 Econ Inlet, 33 Polisher, Steam Sample,  
Sample Survey.
- 8-8-03 - New Resin - 11 + 12 Polisher cation cond.  
- Made a visit to LPI plant.
- 8-12-03 Air cleaned chiller units on 2.5 fl. + 7th floor  
(Unit 3 - Ox Feed WQP's)

70

8-14-03 Demin Na Analyzer - etched measuring elec.  
 - New filling solution bottle for Ref. elec.  
 Calibration - 59.5 slope

8-15-03 - New resin at LPI WQP  
 - New Cal Std at LPI  
 - New resin U1 Boiler + Econ } C.C.  
 U2 Polishets

8-18-03 New SiO<sub>2</sub> reagents :- U2 CPD  
 - U1 Boiler  
 New Cal Std : Demin SiO<sub>2</sub>

8-19-03 New reagents : U3 Boiler SiO<sub>2</sub>

8-21-03 New resin : U3 CPD Cation Cond.

8-28-03 New Resin : U1 CPD , U2 Boiler , Sherco LPI WQP

9-2-03 New Resin : LPI WQP

9-5-03 New Resin : U2 Econ Inlet

Na Calibrations U2 Boiler 84 %  
 CPD 89 %

9-8-03 Na Calibrations U1 Boiler 85 %  
 CPD 100 %

New Cal Stds : U1 Boiler SiO<sub>2</sub> , Sherco LPI WQP

9-9-03 New Resin : 11 + 12 Polishet C. Cond.

9-11-03 New Resin : U2 CPD column

9-12-03	New Resin : U1 Econ Inlet
	New Reagents : DEMIN SiO <sub>2</sub> analyzer
9-18-03	New Resin : U3 Boiler Cat., U3 32 Polisher cat.
	Na Calibrations U3 - Boiler Slope 91% CPD Slope 108%
	Na Calibration Demin Analyzer (60.8 slope)
9-19-03	New Resin at LPI WQP C.C.
9-19-03	New Resin : U2 Polishers - 21 + 22 Cat. Cond.
	New Reagents : U2 Boiler SiO <sub>2</sub> analyzer
9-22-03	New Reagents at LPI WQP SiO <sub>2</sub> analyzer.
9-30-03	new Reagents in LPI SiO <sub>2</sub> analyzer in old chem lab
10-1-03	new resin for U1 Boiler cation column
10-7-03	new cation resin @ LPI SiO <sub>2</sub> Reagents → 76% SiO <sub>2</sub> STD → 30%
	new cation resin for LPI panel in old lab
	new cation resin for U2 Econ
	new cation resin for U1 CPD
10-9-03	new reagents in U3 Boiler SiO <sub>2</sub> analyzer new reagents in U2 CPD SiO <sub>2</sub> analyzer new reagents in U1 Boiler SiO <sub>2</sub> analyzer
	new cation resin for OT panel West Downcomer sample on 2/2

72

10-14-03 Calibrated Unit 1 Nat Analyzers  
Boiler Slope  $\rightarrow$  85%  
CPD Slope  $\rightarrow$  112%

Calibrated Unit 2 Nat Analyzers  
Boiler Slope  $\rightarrow$  89%  
CPD Slope  $\rightarrow$  89%

manual check of  $\text{SiO}_2$  @ LPI return panel in old lab  
lab  $\rightarrow$  37 ppb monitor  $\rightarrow$  51 ppb

10-15-03 New resin for U1 Econ, #11 & #12 polishers  
New resin for U2 Boiler, CPD, #21 & #22 polishers

Calibrated Unit 3 Nat Analyzers  
Boiler Slope  $\rightarrow$  91%  
CPD Slope  $\rightarrow$  107%

10-16-03 etched electrode & calibrated Demin Nat analyzer  
Slope  $\rightarrow$  56.7  $E_0 \rightarrow$  -14.8

checked LPI  $\text{SiO}_2$  Reagents  $\rightarrow$  61%  $\text{SiO}_2$  STD  $\rightarrow$  10%  
Cation Resin  $\rightarrow$  ~60% left

10-23-03 checked LPI WSP:  $\text{SiO}_2$  Reagents  $\rightarrow$  50%  
 $\text{SiO}_2$  STD  $\rightarrow$  100% (replaced)  
Cation Resin  $\rightarrow$  100% (replaced)

10-29-03 new reagents & cal standard in the Demin  $\text{SiO}_2$  analyzer

10-30-03 replaced cation resin on U3 OT panel for economizer (7<sup>th</sup> floo)

check LPI WSP:  $\text{SiO}_2$  Reagents  $\rightarrow$  38%  
 $\text{SiO}_2$  STD  $\rightarrow$  90%  
Cation Resin  $\rightarrow$  60% left

11-4-03	cleaned nupro filter on DO sample line
	replaced reagent valve for citric acid on U3 CPD SiO <sub>2</sub> analyzer
11-6-03	new reagents U2 Boiler SiO <sub>2</sub> analyzer new resin for U2 Econ cation column
	LPI cation resin changed @ LPI cation resin → 100% SiO <sub>2</sub> Reagents → 27% SiO <sub>2</sub> STD → 80%
	new reagents for U3 CPD SiO <sub>2</sub> analyzer
11-10-03	new cal standard for U1 CPD SiO <sub>2</sub> analyzer
11-12-03	new resin for U3 Main steam cation column " " " U3 Economizer " " " " " #31 polisher " " " " " #33 polisher " "
	Calibrated U1 Nat Analyzers: Boiler slope → 85% CPD slope → 112%
	Calibrated U2 Nat Analyzers: Boiler slope → 89% CPD slope → 89%
11-13-03	new cation resin for LPI panel in old lab
	New solution, tubing, etched electrode & calibration of Demin Nat analyzer Slope → 51.5 E <sub>0</sub> → -22.8
	replaced SiO <sub>2</sub> Reagents in analyzer @ LPI: Reagents → 100% STD → 90% Cation Resin → 60%
11-18-03	new cation resin for U1 Boiler, Econ, CPD, #11 & #12 polisher new cation resin for U2 CPD, #21 & #22 polisher

74

11-19-03 - new reagents & STD for LPI silica analyzer in old lab  
 - new reagents for U1 CPD SiO<sub>2</sub> analyzer

11-20-03 LPI W&P check: changed cation resin @ LPI → 100%  
 Silica Reagents → 82%  
 Silica STD → 60%

calibrated U3 Nat Analyzers:  
 Boiler Slope → 83%  
 CPD Slope → 93%

11-24-03 new resin for U3 CPD cation column

11-25-03 - new cation resin for U2 Boiler cation column  
 - new reagents for U2 CPD SiO<sub>2</sub> analyzer  
 - replaced bulb in LPI SiO<sub>2</sub> analyzer in old lab

- LPI weekly check: SiO<sub>2</sub> Reagents: 74%  
 SiO<sub>2</sub> STD: 60%  
 Cation Resin: 75%

also replaced lamp in SiO<sub>2</sub> analyzer @ LPI

- new reagents for U3 Boiler SiO<sub>2</sub> analyzer  
 - new cation resin for Econ Inlet sample on "OT" system (7<sup>th</sup> floor)  
 - switched to North Bank for oxygen feed

12-1-03 - Replaced both "Boiler" and "CPD" sodium analyzer  
 DSW pre-filters (shot); Unit 3  
 - Restarted U-3 boiler sample, after packing  
 on valve SSG-TV-3105 was adjusted. Have full flow and valve continues to hold. W.O. was re-routed to "Outage" to replace packing

- 12-3-03 - new  $\text{SiO}_2$  STD for U1 Boiler  $\text{SiO}_2$  analyzer  
 - new cation resin for U2 Econ column  
 - new in-line filters for U1 Boiler & CPD Nat analyzers  
 - new in-line filters for U2 Boiler & CPD Nat analyzers
- 12-4-03 - LPI Weekly Check:  $\text{SiO}_2$  Reagents  $\rightarrow$  59%  
 $\text{SiO}_2$  STD  $\rightarrow$  40%  
 changed cation resin  $\rightarrow$  100%
- replaced reagent cap on U1 Boiler  $\text{SiO}_2$  analyzer STD Bottle  
 (it was cracked)
- 12-9-03 calibrated U3 Nat Analyzers: Boiler slope  $\rightarrow$  83%  
 CPD slope  $\rightarrow$  93%
- calibrated U1 & U2 Nat Analyzers:  
 U1 Boiler slope  $\rightarrow$  85%      U2 Boiler slope  $\rightarrow$  95%  
 U1 CPD slope  $\rightarrow$  112%      U2 CPD slope  $\rightarrow$  89%
- 12-10-03 calibrated Demin Nat Analyzer & etched electrode  
 Slope  $\rightarrow$  53.2       $E_0 \rightarrow$  -20.2
- 12-11-03 Weekly LPI check:  $\text{SiO}_2$  Reagents  $\rightarrow$  48%  
 $\text{SiO}_2$  STD  $\rightarrow$  30%  
~~changed~~ cation resin  $\rightarrow$  75%
- 12-15-03 new standard for U3 Boiler  $\text{SiO}_2$  analyzer
- 12-16-03 - new reagents for Demin  $\text{SiO}_2$  analyzer  
 - new reagents for U1 Boiler  $\text{SiO}_2$  analyzer  
 - new cation resin for U1 Boiler, Econ, CPD, #11 & #12 polisher  
 - new cation resin for U2 CPD, #21 & #22 polisher  
 - new cation resin for LPI panel in old lab
- Weekly LPI check:  $\text{SiO}_2$  Reagents  $\rightarrow$  60% (topped off)  
 $\text{SiO}_2$  STD  $\rightarrow$  30%      Cation Resin  $\rightarrow$  100%



76

12-31-03 LPI WQP Check: SiO<sub>2</sub> Reagents Level 36%  
 SiO<sub>2</sub> → 8 ppb  
 C.C. → 0.1845 col. Y2 full  
 pH → 9.4  
 They were up & down all day yesterday (???)

1-02-04 LPI Check- Looks good. Reagents Level=33%  
 In house SiO<sub>2</sub> still a bit high. 28ppb  
 Column over there still Y3 full.

O<sub>2</sub> treatment:  
 7th floor - col. slightly low - will last till Monday  
 2.5 floor - only right side has flow - don't know  
 if this is normal.  
 Ops put system IN @ 10%.

1-4-04 LPI check:  
 RLM \* replaced cation resin \*  
 \* replaced SiO<sub>2</sub> std. Reagent levels = 31%

1-5-04 O<sub>2</sub> Feed WQP 7th Floor  
 \* changed cation cond. resin  
 \* replaced Econ Inlet cond. resin (U-2)

1-9-04 Replaced 32 pol. cation cond. resin.

1-12-04 New SiO<sub>2</sub> reagents on U-3 CPD  
 New SiO<sub>2</sub> reagents on U-1 CPD (None left except citric)

Wold 000230

1-14-04 Replaced Diss. O<sub>2</sub> sensor on U1 WQP  
New S/N 51344 (replaced S/N 50632)

Maintenance + calibration of Demin Na analyzer:

- new tubing + reagent, etched measuring electrode
- slope: 61.0

1-19-04 LPI visit: Added reagent to each bottle to bring level to ~ 33%.

1-20-04 \* No SiO<sub>2</sub> reagent in stock \*  
Transferring from analyzer to analyzer in order to maintain levels around 30-35%.

1-21-04 Replaced Diss. O<sub>2</sub> sensors on U3 Oxygen Panels  
2.5 floor New S/N 33198 (replaced 34719)  
RLM 7th floor New S/N 35468 (replaced 45760)

1-26-04 Demin SiO<sub>2</sub> analyzer: Repaired/replaced leaking cap on Amino acid reagent.  
- New cal standard installed.

- New reagents at LPI WQP SiO<sub>2</sub> analyzer.
- Fresh cation resin at LPI WQP.

1-27-04 Swapped DO<sub>2</sub> sensors between U1 WQP + U3 2nd fl.  
U1 is now S/N 33198  
U3 2.5 floor is now 51344

1-28-04 Changed cation resin columns on U1 WQP.

1-29-04 - New reagents in U2 CPD SiO<sub>2</sub> analyzer.

- Switched from North bank to South bank of oxygen cylinders for O<sub>2</sub> feed, unit 3.

78

- 1-30-04 New reagents in LPI WQP  $\text{SiO}_2$  analyzer (Old Chem Lab)
- 2-6-04 Changed cation column resin (U3 - 7th Fl.)
- \* Refrigeration system pump leak repaired by Lloyd on 2-5-04.
- 2-9-04 - New cation cond. resin at LPI WQP panels  
- New reagents in U1 Boiler  $\text{SiO}_2$   
- New reagents in Demin  $\text{SiO}_2$  analyzer  
- New Std. in LPI WQP  $\text{SiO}_2$  analyzer (old chem lab)
- 2-13-04 - Fresh cation resin - U1 + U3 Boiler Cat. Cond.  
- Etched Na measuring electrode on Demin. Na analyzer.  
- Also replaced Reference Electrode solution.
- 2-16-04 - Demin Na analyzer Cal. Slope  $\rightarrow$  59.7  
- Replaced Cal stds. U1 Boiler + CPD analyzers.
- 2-19-04 New reagent + standard in U-3 CPD  $\text{SiO}_2$  analyzer.
- 2-23-04 New cation resin - U3 32 + 33 Polisher cation cond.
- 2-24-04 New cation resin - U2 CPD + both polisher cation cond.
- 2-25-04 U-3 Sodium Analyzer calibrations:  
CPD slope - 93 %  
Boiler slope - 83 %
- 3-3-04 Fresh cation resin in 31 Pol. cation cond.
- 3-3-04 Unit 3 WQP Oxygen Sensor replacement:  
New serial # (52516)

- b) 3-4-04 Calibration of Unit 2 Sodium Analyzers.  
CPD slope  $\rightarrow$  89 %  
Boiler slope  $\rightarrow$  95 %
- 3-5-04 Fresh cation resin today for various cation conductivities:  
- U3 boiler C.C. (2.5 Fl. Oxygen WQP)  
- LPI WQP (backroom old chem lab)  
- U2 boiler C.C.  
- U2 econ inlet C.C.
- 3-8-04 - Fresh cation resin for U3 CPD, Econ Inlet, Steam C.C.'s.  
- Layed up U1 Boiler + CPD SiO<sub>2</sub> analyzers for major unit overhaul (3-4 weeks).
- 3-12-04 Fresh cation resin for U3 7th Floor WQP (Oxygen Feed)
- 3-15-04 Fresh cation resin for LPI WQP C.C. at LPI.
- 3-18-04 Demin Na analyzer  
- New reagent + tubing  
- etched measuring electrode  
- slope 60.1
- 3-19-04 - New reagents over at LPI WQP silica analyzer.  
- New reagents in U-2 CPD SiO<sub>2</sub> analyzer.
- 3-24-04 - New reagents in U-3 Boiler SiO<sub>2</sub> analyzer.  
- Calibrated U-1 Sodium analyzers  
Boiler - 85 % slope  
CPD - 112 % slope
- 3-26-04 New reagents in U-1 CPD SiO<sub>2</sub> analyzer (ready for startup)
- 3-29-04 Changed 4 cation resin columns on U2 WQP:  
(Econ Inlet, CPD, 21 + 22 polishers)

80

3-30-04 - Changed all 3 cation resin columns on Oxygen Feed WQPs  
(U-3, 7th + 2.5 Floors)

- New reagents in Demin  $\text{SiO}_2$  analyzer.

4-1-04 - New cation resin in CPD + Econ Inlet columns, U1 WQP

- New cation resin at LPI WQP.

- Fresh reagents in U1 Boiler  $\text{SiO}_2$  analyzer.

4-7-04 \* LPI Weekly check \*

$\text{SiO}_2$  Reagents  $\rightarrow$  74%  $\text{SiO}_2$  STD  $\rightarrow$  80% Resin  $\rightarrow$  ~66%

4-8-04 New Reagents for U3 CPD Silica analyzer

4-13-04 replaced lamp on U3 Boiler silica analyzer

new in-line filters on U3 Boiler & CPD Nat analyzers

4-14-04 New reagents for U2 Boiler silica analyzer  
New cation resin for LPI column in old lab

4-15-04 new cation resin for U3 Survey cation column  
new cation resin for #32 polisher cation column  
new cation resin @ LPI  
Reagents  $\rightarrow$  61% STD  $\rightarrow$  70%

4-19-04 etched electrode & calibrated Demin Nat analyzer  
Slope  $\rightarrow$  61.7  $E_0 \rightarrow$  -14.2  
LPI check  $\rightarrow$  Reagents  $\rightarrow$  54% STD  $\rightarrow$  60%  
Cation @ ~80%

4-20-04 Calibrated ~~U3~~ U3 Nat Analyzers  
Boiler Slope  $\rightarrow$  83% CPD Slope  $\rightarrow$  93%

Calibrated U1 Nat Analyzers: Boiler Slope  $\rightarrow$  83% CPD Slope  $\rightarrow$  87%  
Calibrated U2 Nat Analyzers: Boiler Slope  $\rightarrow$  96% CPD Slope  $\rightarrow$  88%

- QPS 4-22-04 new cation resin for U2 Boiler column
- \* LPI<sup>bi-</sup> Weekly Check \*
- Reagents  $\rightarrow$  49% STD  $\rightarrow$  60% Cation  $\rightarrow$  66%
- 4-29-04 new cation resin U1 CPD column  
new cation resin U2 Econ column
- LPI looks good: Reagents  $\rightarrow$  38% STD  $\rightarrow$  50% Cation  $\rightarrow$  33%
- 5-3-04 - new STD for Demin SiO<sub>2</sub> analyzer  
- new STD for LPI SiO<sub>2</sub> analyzer in old lab  
- new electrodes for U2 Boiler & Economizer pH  
- new cation resin for U2 CPD, #21 & #22 polisher  
- new cation resin @ LPI  
- new pH electrodes @ LPI
- 5-5-04 - new SiO<sub>2</sub> reagents @ LPI  
- replaced reagent valve for molybdate reagent on SiO<sub>2</sub> analyzer @ LPI  
- new SiO<sub>2</sub> reagents for U2 CPD analyzer
- 5-6-04 - new cation resin for U1 Boiler, Econ, #11 & #12 polisher  
- Bi-weekly LPI check: SiO<sub>2</sub> Reagents  $\rightarrow$  98% SiO<sub>2</sub> STD  $\rightarrow$  40%  
Cation Resin  $\rightarrow$  ~85%
- 5-13-04 - new reagents for LPI SiO<sub>2</sub> analyzer in old lab  
- new reagents for U1 Boiler & U1 CPD SiO<sub>2</sub> analyzer  
- new reagents for Demin SiO<sub>2</sub> analyzer & new tubing from reagent valves & sample valve to sample cell  
- new reagents for U3 Boiler SiO<sub>2</sub> analyzer  
- weekly LPI check  
Reagents  $\rightarrow$  87% STD  $\rightarrow$  30% Cation Resin  $\rightarrow$  66%
- 5-17-04 New solution, tubing, o-rings & etched electrode on Demin Na<sup>+</sup> analyzer. Calibrated with a slope of  $\rightarrow$  53.1  
E<sub>o</sub> of  $\rightarrow$  -27.3

82

- 5-19-04
- new resin for east boiler downcomer on 2 1/2 floor "OT" panel
  - new resin for econ inlet on 7th floor "OT" panel
  - calibrated U3 Nat analyzers
    - Boiler Slope  $\rightarrow$  83%
    - CPD Slope  $\rightarrow$  93%
  - new resin in LPI cation column in old lab
- 5-20-04
- Calibrated U1 Nat analyzers: Boiler slope  $\rightarrow$  81%
  - CPD slope  $\rightarrow$  84%
  - Calibrated U2 Nat analyzers: Boiler slope  $\rightarrow$  90%
  - CPD slope  $\rightarrow$  88%
  - replaced in-line filters on both Nat analyzers on U1 & U2
  - Bi-weekly LPI Panel check
    - Reagents  $\rightarrow$  75%
    - STD  $\rightarrow$  20%
    - Cation  $\rightarrow$  ~45%
- 5-24-04
- replaced D.O. probe on 2 1/2 floor Boiler Downcomer sample line serial # 31591
  - replaced D.O. probe on 7th floor econ inlet sample line serial # 48906
  - new cation @ LPI
  - new SiO<sub>2</sub> STD @ LPI
  - new SiO<sub>2</sub> STD for U1 Boiler analyzer
- 5-25-04
- replaced pH electrodes on U3 Boiler & Economizer buffered with 7 & 10
- 5-27-04
- new reagents & STD for U3 CPD SiO<sub>2</sub> analyzer
- 6-1-04
- new reagents for U2 Boiler SiO<sub>2</sub> analyzer
  - new resin for U2 Boiler & Economizer columns

- 6-3-04 cleaned coils on "OT" cooling system on 2 1/2 & 7<sup>th</sup> floors U3  
 check of LPI  
 Reagents → 52% STD → 90% Cation → 60%
- 6-8-04 Air cleaned refrig. system grill on 7th Floor WQP. (U-3)
- 6-9-04 checked on LPI panel  
 Reagents → 42% STD → 80% Cation → 40%
- 6-10-04 - new STD for U1 CPD SiO<sub>2</sub> analyzer  
 - new cation resin for U1 Econ column  
 - new cation resin for U2 CPD, #21 & #22 columns
- 6-14-04 - new cation resin for U3 Main steam, Economizer, CPD, #31 polisher and #33 polisher columns  
 - new cation resin @ LPI
- 6-15-04 - etched electrode and calibrated Demin Nat analyzer  
 slope → 59.3 E<sub>0</sub> → -15.1
- 6-16-04 calibrated U1 & U2 Nat analyzers  
 U1 Boiler slope → 81% U2 Boiler slope → 82%  
 CPD slope → 82% CPD slope → 82%
- 6-21-04 - new resin for U1 Boiler, CPD, #11 & #12 polishers  
 - new cation resin for LPI column in the old lab  
 - new SiO<sub>2</sub> reagents for U2 CPD analyzer  
 - new SiO<sub>2</sub> reagents for LPI SiO<sub>2</sub> analyzer @ LPI  
 Reagents → 100% STD → 60% Cation → 75%
- 6-22-04 - new resin for Econ Inlet "OT" system 7<sup>th</sup> Floor U3  
 - calibrated U3 Nat analyzers  
 Boiler slope → 83% CPD slope → 93%



84

- 6-28-04 - LPI WQP Check  
Reagents → 88% STD → 50% Cation → 50%  
- new STD for U3 Boiler SiO<sub>2</sub> analyzer
- 6-29-04 new cation resin for U2 economizer column
- 6-30-04 new reagents for U1 Boiler & CPD SiO<sub>2</sub> analyzers
- 7-1-04 new cation resin @ LPI  
Reagents → 83% STD → 50% Cation → 100%
- 7-8-04 LPI WQP CHECK  
Reagents → 72% STD → 40 CATION → 80%
- 7-8-04 Replaced U3 Boiler Silica Analyzer Reagents.
- 7-13-04 LPI WQP CHECK  
- Fluctuating Flow → Fixed by MPW I+C
- 7-14-04 - New CATION Resin U1 Survey analyzers  
- Calibrated 1811 EL  
Slope → 59.2 E<sub>0</sub> → 7.8  
Etched electrode, new o-rings, solution, tubing
- 7-15-04 - New Resin U3 Boiler column  
- New Reagents U3 CPD SiO<sub>2</sub> analyzer  
- U3 O<sub>2</sub> feed check  
- Replaced Resin 2 1/2 Floor EAST  
Adjusted Flow to 1000 mls
- Replaced Resin U2 CPD, 21 pol, 22 pol  
-  
- LPI WQP Check  
Resin → 50% STD → 30% Reagent → 60%

Wold 000238

7-20-04 \* LPI WQP CHECK\*  
 Resin 40% Reagents 52% STD 20%

- New Resin U1 Econ CAT COND Analyzer

- New STD Demin SiO<sub>2</sub> Analyzer

- Calibrated U1 + U2 Nat Analyzers

U1 CPD Slope → 82%

U1 BLR Slope → 81%

U2 CPD Slope → 82%

U2 BLR Slope → 82%

7-22-04 Calibrated U3 Nat Analyzers  
 CPD Slope → 83%  
 Boiler Slope → 89%

- New Reagents U2 Boiler SiO<sub>2</sub> analyzer

\* LPI CHECK\* - everything OK

7-23-04 Replaced Resin U2 BLR Cat. Cond. Analyzer

\* U3 O<sub>2</sub> feed check\* - Adjusted Flows

Resin 2<sup>1</sup>/<sub>2</sub> = 80% Resin 7<sup>1</sup>/<sub>2</sub> = 30%

7-27-04 \* LPI Check\*

Resin 10% Reagent 41% STD 10%

- Replaced Silica STANDARD

- Replaced Reagents Demin Silica analyzer

7-29-04 \* LPI Check\*

Replaced Resin Reagent 37% STD 100%

- Replaced Resin 32 pol CAT cond Analyzer

86

- 7-30-04 \*LPI CHECK\*
- Cleaned sample cell
  - cleaned Flow Sight Glass + sample table
  - Looks Good
- Replaced Resin 7<sup>th</sup> Floor O<sub>2</sub> feed
- ordered new O<sub>2</sub> sensor, 7<sup>th</sup> Floor O<sub>2</sub> sensor not working
- New Resin U2 Econ CAT COND Analyzer
- 8-5-04 \*LPI WQP CHECK\*
- Replaced SiO<sub>2</sub> Reagents, adjusted flows after outage  
Resin 80% STD 90%
- 8-6-04 Replaced resin 11 + 12 pol CAT COND Analyzer  
Replaced SiO<sub>2</sub> STANDARD U2 CPD SiO<sub>2</sub> analyzer  
Replaced SiO<sub>2</sub> STD U1 BLR Analyzer
- 8-10-04 \*LPI WQP CHECK\*
- Replaced sample cell after the 'clean sample cell' error code would not clear
  - Resin 60%, Reagent 92% STD 90%
- 8-12-04 New Electrodes Unit one Na<sup>+</sup> Analyzers  
U1 CPD Slope → 85%  
U1 BLR Slope → 80%
- 8-13-04 \*LPI WQP CHECK\*
- Resin 50% Reagent 87% STD 80%
  - Replaced Resin at the SHERCO LPI CAT COND Analyzer
  - Kevin Backes Working on Sample Pressure fluctuation in the SHERCO WQP
- 8-17-04 Calibrated 1811 EL Demin Na<sup>+</sup> Analyzer  
- Slope → 59.2 E<sub>0</sub> -9.8  
- Etched electrode

8-17-04 \*LPI WQP Check\*

Resin 40% Reagent 80 STD 70%

8-18-04 ~~Resin~~ NEW Electrodes Unit Two Nat Analyzers

U2 CPD Slope → 85%

U2 BLR Slope → 80%

8-19-04

- Replaced Reagents U1 BLR + CPD  $\text{SO}_2$  analyzers
- Replaced Electrodes U3 Nat Analyzers NEW
- Calibrated U3 Nat Analyzers
  - CPD - 86% Slope
  - BLR - 92% Slope
- Replaced D.O. probes on 7<sup>th</sup> Floor econ inlet sample Line
  - Serial # 42858
  - Model # 3110
  - Membrane S2

8-24-04 Replaced Cal STD U3 CPD  $\text{SO}_2$  analyzer

8-24-04 Replaced Resin @ LPI Cat. Cond. Analyzer

STD 60% Reagent 69%

8-26-04 \*LPI WQP Check\*

- Replaced Lamp in the  $\text{SO}_2$  analyzer. This cured the 'clean sample cell' alarm.
- Resin, STD, Reagents OK

- Replaced Resin in U1 Econ Inlet CAT. COND. Analyzer

8-27-04 - Replaced Reagents U3 Biler  $\text{SO}_2$  Analyzer

- Replaced Resin U2 Econ, CPD, 21 pol, 22 pol

88

8-31-04 Replaced Cal STD U1 CPD SiO<sub>2</sub> analyzer

9-2-04 - New Resin 2 1/2 Floor U3 O<sub>2</sub> PANEL  
 - New Resin 7th Floor U3 O<sub>2</sub> PANEL  
 - HAD K. Backes Blowdown 2 1/2 floor O<sub>2</sub> panel  
 - Installed New O<sub>2</sub> Sensor 2 1/2 floor  
 S/N 48427  
 Membrane 52  
 MODEL 3110

\*LPI WQP CHECK

- Resin 80% STD 40% Reagent 49

9-3-04 - New Reagents U3 CPD SiO<sub>2</sub> analyzer  
 - New Resin U1 CPD CAT COND analyzer  
 - Switched O<sub>2</sub> Binks U3 O<sub>2</sub> Feed System

9-8-04 Replaced Reagents U2 BCR SiO<sub>2</sub> analyzer

"LPI WQP CHECK"

- Replaced SiO<sub>2</sub> STD Sample Valve  
 - Replaced SiO<sub>2</sub> STD  
 - Replaced Sample Cell cover plate  
 - molybdate plugged  
 - cured LOW CALIBRATION values  
 - Resin 50% STD 100% Reagent 44%

9-14-04 - Replaced SiO<sub>2</sub> STD U3 BCR Silica Analyzer

- Calibrated RHEIL Demin Na<sup>+</sup> Analyzer  
 Slope → 59.2 E<sub>0</sub> → -11.1  
 New Solution, Tubing, O-rings, etched electrode.

- 9-15-04 - Calibrated U1 Na<sup>+</sup> Analyzers  
 CPD Slope 86 %  
 BLR Slope 80 %
- Calibrated U2 Na<sup>+</sup> Analyzers  
 CPD Slope 86 %  
 BLR Slope 80 %
- 9-16-04 - Replaced Reagents Demin SiO<sub>2</sub> Analyzer  
 - Calibrated U3 Na<sup>+</sup> Analyzers  
 CPD Slope → 96 %  
 Boiler Slope → 86 %
- \* Replaced Resin @ LPI CAT. COND. Analyzer  
 - Resin 100 % Reagent 31 % STD 80 %
- 9-17-04 - New Resin 11 polisher CAT. COND. Analyzer  
 - New Resin 12 polisher CAT. COND. Analyzer  
 - New Resin U2 Boiler CAT. COND. analyzer
- 9-22-04 \* Replaced SiO<sub>2</sub> Reagents @ LPI  
 - Resin 90 % Reagent 100 % STD 70 %
- Replaced Lamp U2 Boiler SiO<sub>2</sub> Analyzer
- 9-24-04 - Replaced Reagents U2 CPD SiO<sub>2</sub> analyzer  
 - Cleaned Coils U3 - 2 1/2 #7 Floor O<sub>2</sub> feed System
- 9-28-04 Replaced Resin U3 CPD CAT COND. Analyzer  
 " " 31 polisher " " "  
 " " 33 polisher " " "  
 " " U3 MAIN STEAM " "  
 " " U3 ECONOMIZER " " "

90

9-28-04 \*LPI WQP CHECK\*

- STD 100% Reagent 90% Resin 75%
- Cleaned Sample cell
- Software Restart Alarm - System Reset

9-29-04 - Replaced Cal STD U3 CPD SiO<sub>2</sub> analyzer

9-30-04 - Replaced Resin U1 Econ CAT COND Analyzer  
 " " U2 " " " "  
 " " 21 pol " " "  
 " " 22 " " " "

10-1-04 \*LPI CHECK\*

- Resin 60% STD 40% Reagent 86%
- Cleaned Filter, Blew Down Lines

10-5-04 LPI  
 Reagents 78% STD 30% Resin 50%  
 "Clean sample cell" alarm - I cleaned it & v'ed it again later & same thing happened. There is condensation on the outside of the cell, due to the excess heat created by the lamp housing.  
 I installed a hose clamp on the sample cell outlet hose. I tried to identify liquid anywhere & that was suspect.  
 Now the cell housing cover doesn't tightly fit like it did, but maybe that will help w/ the alarm. It looks to me like the condensation may be a problem.

10-6-04 LPI is clear

10-7-04 Replaced cation resin in Unit 2 CPD column.  
 LPI is good.

10-11-04 Replaced reagents on Unit 1 CPD  $\text{SiO}_2$  analyzer.

10-11-04 LPI: Replaced cation resin  
 $\text{SiO}_2$  analyzer looks good:  
 Reagents = 68% Std = 40%  
 Slight condensation on upper part of sample cell,  
 but no 'clean sample cell' alarm.

10-20-04 "LPI WQP ✓"  
 Resin @ 60% new  
 $\text{SiO}_2$  analyzer → 13 ppb  
 Reagents = 54% Std = 30%

10-20-04 Cleaned sample cell and area on Boiler  $\text{SiO}_2$  Unit 1

10-22-04 Demin  $\text{Na}^+$  Analyzer  
 Replaced reagent, tubing, O-rings  
 Etched electrode  
 Calibrated slope → 59.2  $E_0$  → -9.7

10-23-04 Replaced cation resin on Unit 1:  
 CPD; Polisher 11 & 12

10-22-04 LPI WQP ✓  
 Reagent → 50% Std → 30% C.C. Resin → 60%

10-25-04 Unit 1 Boiler  $\text{SiO}_2$  Analyzer had a problem  
 reading - 0 ppb.  
 Cleaned cell, checked all tubing  
 Found O-ring in housing, crimped.

10-26-04 Replaced  $\text{SiO}_2$  reagents on Unit 3 Boiler and  
 CPD Series 5000 analyzers.

10-26-04 Replaced  $\text{SiO}_2$  std in Unit 1 Boiler 5000 Series.



92

10-26-04	Replaced cation resin for Boiler Unit 1.
"	LPI Check - Reagent % → 42      Resin % → 40
10-26-04	Unit 1 Boiler Na <sup>+</sup> Analyzer Calibration Slope → 91%
10-27-04	Unit 2 Na <sup>+</sup> Analyzers Calibration Boiler      Slope → 94% CPD      Slope → 106%
10-28-04	Unit 3 Na Analyzer Calibrations Boiler      Slope → 91% CPD      Slope → 101%
10-29-04	LPI Reagents 37%      Resin 100% Replaced cat. resin - to assure weekend flows Replaced SiO <sub>2</sub> std in SiO <sub>2</sub> analyzer
11-1-04	LPI ✓ Reagents → 41%      STD → 90%      Resin → 90% came in on Sat. (10-30-04) found loss of reagent pressure. No SiO <sub>2</sub> readings for 5 hrs.
11-2-04	Replaced O <sub>2</sub> probes on: Unit 3 WQP      Unit 3 7 <sup>th</sup> floor Model # 31110      31110 Membrane 52      52 Serial # 48929      53322  Unit # 1 WQP Model # 31110A Membrane 52 Serial # 44936

11-3-04 Replaced cation resin in Unit 2:

Econ. Inlet

Pol 11

Pol 12

Cleaned flowmeters on Unit 2 Econ. In; pH and Cat. Cond.  
↳ CPD: Cat. Cond.

Calibrated all new DO probes

Replaced electrodes on Unit 1 CPD Na analyzer.

11-4-04 Recalibrated Unit 3 O<sub>2</sub> sensor on 7<sup>th</sup> floor.

Cleaned portable DO sensor

Replaced Cat. resin in Unit 3 DO<sub>2</sub> WQP 2.5 fl.

11-5-04 Calibrated Portable DO analyzer

Replaced Unit 2 Boiler SiO<sub>2</sub> reagents

New SiO<sub>2</sub> std in Demin SiO<sub>2</sub> analyzer

Cleaned flowmeter on Unit 1 Econ. In. Cond.'s

Called Hach with question on reagent pressure alarms on the Series 5000 analyzers

There is one regulator therefore one alarm source, either high, low or no reagent psi.

The alarm only appears if there is abnormal pressure at the END of a cycle.

If the instrument (bottom) happens to be opened and closed during the cycle span, no alarm will appear. If it's open (with no pressure) at the end of a cycle, the alarm will appear & need resetting.

94

11-5-04	Replaced in-line filter on Unit 1 Boiler Sodium analyz
11-8-04	LPI WQP ✓ Reagents-29% Std-80% Resin-70%
	Replaced SiO <sub>2</sub> reagents in Demin analyzer
11-9-04	Recalibrated Unit 1 & Portable O <sub>2</sub> analyzers
11-10-04	cleaned flowmeters on Unit 3 CPD SiO <sub>2</sub> & Cond's.
	Replaced resin in Cation col. of: Unit 1- Econ. In. Unit 2- Boiler and CPD
	LPI WQP "✓" Reagent-25% Std-80% Resin-60%
11-12-04	Replaced SiO <sub>2</sub> reagents over at LPI WQP Rgt → 100% Std → 80% Resin → 55%
11-15-04	Replaced SiO <sub>2</sub> reagents on Sherco's LPI WQP (in lab)
11-17-04	Replaced resin on O <sub>2</sub> WQP 7 <sup>th</sup> fl. Unit 3. Replaced resin on Unit 2 Survey Cat. Cond. Col.
	Replaced Unit 2 CPD SiO <sub>2</sub> reagents.
<sup>lost flow</sup> 11-18-04	New in-line filters for Unit 3 Na analyzer
11-19-04	LPI → Reagents 88% Std 80% Resin 40%
	Cleaned in line filters on SiO <sub>2</sub> analyzers: Unit 1 Boiler Unit 2 Boiler Unit 3 Boiler CPD CPD CPD

11-19-04	Replaced resin in Unit 2 Cation Col. <sup>s</sup> : Polisher 21 & 22										
	cleaned in-line filters on:										
	<table border="0"> <tr> <td>Unit 1</td> <td>Unit 2</td> <td>Unit 3</td> <td rowspan="3">} SiO<sub>2</sub>'s</td> </tr> <tr> <td>Blr</td> <td>Blr</td> <td>Blr</td> </tr> <tr> <td>CPD</td> <td>CPD</td> <td>CPD</td> </tr> </table>	Unit 1	Unit 2	Unit 3	} SiO <sub>2</sub> 's	Blr	Blr	Blr	CPD	CPD	CPD
Unit 1	Unit 2	Unit 3	} SiO <sub>2</sub> 's								
Blr	Blr	Blr									
CPD	CPD	CPD									
11-20-04	Buffered pH elec. on Unit 2 Boiler & Econ. Tr.										
	cleaned sample cells & stir bars on Unit 2 Blr & CPD SiO <sub>2</sub> 's										
11-22-04	Unit 1 & Unit 2 Na Analyzer calibrated (Slopes):										
	<table border="0"> <tr> <td>1 Blr →</td> <td>2 Blr →</td> </tr> <tr> <td>1 CPD →</td> <td>2 CPD →</td> </tr> </table>	1 Blr →	2 Blr →	1 CPD →	2 CPD →						
1 Blr →	2 Blr →										
1 CPD →	2 CPD →										
11-23-04	Unit 3 Na analyzers calibrated (Slopes):										
	<table border="0"> <tr> <td>Blr → 107%</td> <td>CPD → 91%</td> </tr> </table>	Blr → 107%	CPD → 91%								
Blr → 107%	CPD → 91%										
	Replaced in-line filters on Unit 2 Na <sup>+</sup> analyzers										
	Cleaned Unit 2 Boiler: SiO <sub>2</sub> sample cell, in-line filter stir bar changed cat. col. resin after										
	Drag valve was replaced. Root valve was removed for replacement (no parts available). It was cleaned & reinstalled.										
	LPI ✓ - Looks good SiO <sub>2</sub> reag → 81% Std → 60%										
	Replaced cat. col. resin										
	Rinsed resin works great. Back to pre-change value within 5 minutes of replacement.										
11-24-04	Replaced cation resin for Polisher 32.										
11-30-04	Replaced cation resin on In house LPI W&P.										

96

11-30-04 LPI WQP "✓"  
 Reagent = 70%    Std = 50%    Resin = 60%

12-1-04 Demin Na analyzer:  
 New: reagent, tubing, O-rings, ref. fill solution  
 Replaced air pump  
 Etched measuring electrode  
 Calibrated. slope = 59.2     $E_0 = -9.4$

12-2-04 Demin SiO<sub>2</sub> analyzer:  
 cleaned cell, re-tubed top, tried recal- didn't  
 work - shut it off!

12-3-04 Replaced SiO<sub>2</sub> reagents in Unit 1 CPD.  
 Replaced cation resin in: Unit 1 Polisher 11  
 Unit 2 CPD

12-7-04 Replaced cation resin in:  
 Unit 1 Polisher 12  
 Unit 2 Econ. In.

LPI WQP "✓"  
 Resin 40%    SiO<sub>2</sub> reagent 59%    std 40%

12-9-04 New O<sub>2</sub> sensor 2.5 floor Unit 3  
 SN → 48890  
 Model → 31110  
 Membrane # type 2952A

12-9-04 Demin SiO<sub>2</sub> analyzer is "unable to calibrate"  
 I checked everything. Suspected leak through  
 on std solenoid, but a new one installed  
 didn't remedy the problem. The 500ppb std  
 reads over 100ppb.

Wold 000250

~~12-9-04~~ Replaced unit 1 CPD SiO<sub>2</sub> std  
↳ Blr SiO<sub>2</sub> reagents

12-10-04 New O<sub>2</sub> sensor unit 3 WQP  
SN → 46862  
Model → 31110  
Membrane 52

LPI WQP ✓  
Replaced cation resin  
SiO<sub>2</sub> reagents 51% std 50%

12-17-04 LPI WQP ✓  
Resin → 60% SiO<sub>2</sub> reagent → 41% std → 50%  
LPI was out for maintenance on the 15<sup>th</sup>. Back  
on-line. SiO<sub>2</sub> analyzer had a 'clean sample cell'  
alarm. Took care of that - now reads 17ppb

Replaced reagents in Unit 3 SiO<sub>2</sub> for Boiler & CPD

SERIES 5000 Overhauled Demin SiO<sub>2</sub> analyzer completely  
this week. It was 'unable to calibrate'.

New cation resin for: Unit 1 Econ In  
Unit 2 Polishers 21 & 22

cleaned sample cell on unit 1 Blr SiO<sub>2</sub>

12-21-04 Sodium Analyzer Calibrations

SLOPES =	unit 1	unit 2	unit 3
Blr →	83%	111%	97%
CPD →	—	111%	95%

Replaced resin in Unit 1 CPD Cat. Col.

LPI WQP '✓' - Resin → 50% std → 40% Reagent → 35%

98

12-27-04 LPI WQP "✓"  
Replaced resin in Cation Col  
Reag. 30% std. 30% Resin-100%

New reagents in Unit 2 Boiler  $\text{SiO}_2$

12-28-04 LPI WQP "✓"  
Reag. 26% std 30% Resin 100%

Had an upset yesterday, today  $\text{SiO}_2$  is back to 14ppm

12-30-04 LPI WQP  
Replaced  $\text{SiO}_2$  reagents Cat Col ~90%

Replaced resin in Unit 1 Boiler Cation

1-4-05 Fresh cation resin - Unit 3 (2.5 fl) WQP ( $\text{O}_2$  Feed)

1-6-05 Fresh cation resin - Old Chem Lab (LPI WQP)

1-6-05 Fresh cation resin - U3 Econ Inlet C.C.

1-6-05 New silica std. (at LPI WQP)

1-10-05 - Fresh cation resin - Unit 2 Boiler + Econ C.C.  
- New Reagents and std. LPI WQP (Old chem lab)

1-11-05 Fresh cation resin on WQP at LPI plant.

1-12-05 - Calibration of Demin Na analyzer  
(Slope 61.8)

- New  $\text{SiO}_2$  Reagents - Unit 2 CPD analyzer

1-14-05 Fresh cation resin - Unit 1 Polishers C.C.  
- Unit 2 CPD C.C.

1-19-05 Fresh cation resin - Unit 2 Polishers C.C.

1-21-05 Fresh cation resin in nearly all the U-3 WQP columns.

1-24-05 New  $\text{SiO}_2$  Std - Unit 1 Boiler  $\text{SiO}_2$  analyzer

1-25-05 New  $\text{SiO}_2$  reagents - Unit 1 CPD  $\text{SiO}_2$  analyzer

1-25-05 LPI cation resin changed by JPW.

1-27-05 Fresh cation resin - Unit 1 Econ Inlet C.C.

1-31-05 - New DO probe, U-3 WQP (S/N 52771)  
- New standard, Demin  $\text{SiO}_2$  analyzer  
- Fresh reagents, Unit 1 Boiler  $\text{SiO}_2$  analyzer.

\*(Work done by Jim W. the week of Feb 7-11)

- 7th Fl. cation
- $\text{O}_2$  Feed to 350
- U-3 CPD  $\text{SiO}_2$
- U-2 Boiler  $\text{SiO}_2$
- Cation Resin LPI in lab
- LPI cation resin
- LPI  $\text{SiO}_2$  reagents

2-15-05 Demin Na analyzer rebuild + calibration:  
(Slope 59.3)

2-18-05 Fresh cation resin in the following:  
- U-2 Polisher + CPD columns.  
- U-1 Polisher, CPD, Boiler columns



100

2-25-05 Fresh cation resin - U-1 Polisher C.C.  
U-2 Boiler C.C.

3-2-05 Fresh cation resin at LPI plant.  
(LPI having a 1 day outage)

3-4-05 Fresh cation resin - U2 Econ Inlet  
- U1 Econ Inlet

New Reagents - U2 CPD  $\text{SiO}_2$  analyzer

3-7-05 New  $\text{SiO}_2$  Stds - U1 CPD analyzer  
U3 CPD analyzer  
at LPI WQP

3-9-05 U-3 Sodium analyzer calibrations:  
Slope of CPD 95%  
Boiler 97%

3-10-05 U-2 Sodium analyzer calibrations:  
Slope of CPD 111%  
Boiler 111%

3-11-05 U-1 Sodium analyzer calibrations:  
Slope of CPD 104%  
Boiler 83%

3-17-05 DEMIN Na analyzer calibration  
Slope 58.2

3-18-05 Fresh resin, LPI WQP in old chem lab.

Fresh  $\text{SiO}_2$  reagents, U-1 CPD analyzer.

Wold 000254

- 3-21-05 Fresh cation resin - 11 Polisher C.C.
- 3-22-05 Replaced U-3 7th fl Oxygen sensor with sensor from U-3 Lab WQP. The sensor from the lab appears to work. It is "s/n 52771".  
The sensor originally in place is completely exhausted. "s/n 48890"  
2.5 fl sensor seems to be marginal. It is "s/n 46862"  
Unit 1 sensor is "s/n 44936".
- \* We'll begin the process of ordering replacement sensors.
- 3-22-05 Fresh cation resin in U-2 CPD, 21 Pol + 22 Pol. C. Columns.
- 3-23-05 Fresh cation resin at LPI plant - WQP
- 3-24-05 New Reagents - U1 Boiler SiO<sub>2</sub> analyzer  
Demin SiO<sub>2</sub> analyzer
- 3-28-05 Fresh cation resin on U-3 7th fl. WQP (oxygen feed)  
Fresh cation resin on U-3 2.5 fl. WQP (oxygen feed)  
New SiO<sub>2</sub> Std in LPI WQP, (backroom old chem lab)
- 3-29-05 Replaced 2 oxygen sensors today:  
- Unit 3 WQP (Lab) now has s/n 29502  
- Unit 3 2.5 fl. WQP now has s/n 36825
- [s/n's sent back: 46862 + 48890]
- \* Replaced S.O.S. in line filter for Dissolved Oxygen analysis on U-3 Lab WQP.
- 3-30-05 Fresh cation resin on U-3 WQP, 32 polisher c.c.
- 3-31-05 New Reagents - U2 Boiler SiO<sub>2</sub> analyzer  
U3 CPD SiO<sub>2</sub> analyzer  
Fresh cation resin on U2 WQP, Econ Inlet C.C.

102

4-4-05 new  $\text{SiO}_2$  Reagents @ LPI  
 Reagents  $\rightarrow$  100%  
 SPD  $\rightarrow$  60%  
 Cation  $\rightarrow$  ~50%

4-6-05 - new cation resin for U1 Boiler, Econ, CPD and #12 polisher  
 - new cation resin for U2 Boiler

4-8-05 new cation resin @ LPI (JCK)

4-11-05 new STD'S for U1 Boiler  $\text{SiO}_2$  analyzer and Demin  $\text{SiO}_2$  analyzer

4-12-05 Calibrated U1 & U2 Nat analyzers  
 U1 Boiler slope  $\rightarrow$  87% U2 Boiler slope  $\rightarrow$  109%  
 CPD slope  $\rightarrow$  106% CPD slope  $\rightarrow$  111%

Calibrated U3 Nat analyzers  
 Boiler slope  $\rightarrow$  97% CPD slope  $\rightarrow$  105%

4-13-05 new solution, tubing & orings on Demin Nat analyzer  
 also etched electrode & calibrated  
 slope  $\rightarrow$  58.2  $E_0$   $\rightarrow$  -14.8

4-18-05 recalibrated Demin Nat analyzer  
 slope  $\rightarrow$  55.6  $E_0$   $\rightarrow$  -14.9

4-20-05 - new cation resin for #11 polisher  
 - new cation resin for U2 Econ, CPD, #21 & #22 polisher  
 - new cation resin for LPI column in old lab.  
 - new  $\text{SiO}_2$  Reagents for U2 CPD analyzer

4-21-05 LPI check:  $\text{SiO}_2$  Reagents  $\rightarrow$  72%  $\text{SiO}_2$  STD  $\rightarrow$  40%  
 Cation Resin  $\rightarrow$  ~50%

4-27-05 new  $\text{SiO}_2$  Reagents for U1 CPD, Demin & LPI Analyzer in old lab

- 4-27-05 new cation resin @ LPI  
Reagents → 64% STD → 30%
- 5-5-05 new reagents for U1 Boiler SiO<sub>2</sub> analyzer  
LPI Weekly check: Reagents 49% STD 20% Cation 66%
- 5-10-05 - Replaced in-line filters on U1 & U2 Nat analyzers  
Also calibrated: U1 Boiler → 92% U2 Boiler → 93%  
U1 CPD → 113% U2 CPD → 111%
- new cation resin for U1 Economizer
- replaced in-line filters on U3 Nat analyzers
- 5-11-05 LPI Weekly check: Reagents → 39% STD → 100% Cation → 45%  
Calibrated U3 Nat Analyzers: Boiler → 90%  
CPD → 105%
- 5-16-05 Replaced resin @ LPI
- 5-18-05 - new cation resin for #12 polisher  
- new cation resin for U2 Boiler & Economizer  
- new reagents for U2 Boiler SiO<sub>2</sub> analyzer  
- calibrated Demin Nat analyzer & etched electrode  
slope → 53.1 E<sub>0</sub> → -19.3
- 5-19-05 - New SiO<sub>2</sub> Reagents @ LPI  
Reagents → 100% STD → 90% Cation → 90%  
- New SiO<sub>2</sub> Reagents for U3 Boiler SiO<sub>2</sub> analyzer  
- New cation resin for LPI in old lab
- 5-24-05 - new cation resin for U2 CPD, #21 & #22 polishers

104

- 5-24-05 new cation resin for U3 Main Steam
- 5-26-05 new cation resin for U1 Boiler, CPD & #11 polisher
- \* LPI Weekly Check \*
- SiO<sub>2</sub> Reagents → 88% SiO<sub>2</sub> STD → 80% Cation → ~60%
- 6-2-05 new cation @ LPI
- SiO<sub>2</sub> Reagents → 77% SiO<sub>2</sub> STD → 70% Cation → 100%
- 6-6-05 - new standard for LPI SiO<sub>2</sub> analyzer in old lab  
- new standard for U1 CPD SiO<sub>2</sub> analyzer  
- new Reagents for U2 CPD SiO<sub>2</sub> analyzer
- 6-8-05 new reagents & STD for U3 CPD SiO<sub>2</sub> analyzer
- 6-13-05 replaced reagents in Demin SiO<sub>2</sub> analyzer
- 6-14-05 Calibrated U1 & U2 Nat Analyzers
- |                 |                 |
|-----------------|-----------------|
| U1 Boiler → 93% | U2 Boiler → 93% |
| CPD → 113%      | CPD → 114%      |
- 6-15-05 - new cation resin for U1 Economizer, U2 Economizer and LPI in old lab
- new SiO<sub>2</sub> reagents in U1 Boiler & CPD analyzers  
- new SiO<sub>2</sub> reagents for LPI analyzer in old lab
- Replaced tubing, solution & reference electrode filling solution on Demin Nat analyzer  
Also etched electrode & calibrated: slope → 57.2  
E<sub>0</sub> → -14.4
- rebuilt & calibrated DO probe for the portable
- 6-16-05 Calibrated U3 Nat analyzers: Boiler slope → 85%  
CPD slope → 103%

6-16-05	LPI WQP check: Reagents → 55% STD → 50% Cation → 50%
6-20-05	- new SiO <sub>2</sub> STD for U3 Boiler analyzer - new cation resin for #32 polisher column - new STD for Demin SiO <sub>2</sub> analyzer
6-21-05	new cation resin @ LPI new in-line filter @ LPI
6-22-05	LPI WQP check: Reagents → 45% STD → 40% Cation → 95%
6-29-05	- new pH electrodes for U2 Economizer - new SiO <sub>2</sub> reagents for U2 Boiler - new cation resin for U2 Boiler, CPD and #21 polisher - new cation resin for #11 and #12 polisher
	New Reagents for LPI silica analyzer @ LPI Reagents → 100% STD → 30% Cation → 66%
7-5-05	Replaced Lamp @ LPI SiO <sub>2</sub> analyzer
7-6-05	Replaced SiO <sub>2</sub> STD U1 Boiler SiO <sub>2</sub> analyzer
7-8-05	Erratic Reading @ LPI SiO <sub>2</sub> analyzer - replaced Reagents - replaced Lamp - cleaned Sample cell + Assembly - Calibrated 509 ppb
7-12-05	Installed new O <sub>2</sub> probe on portable Analyzer - calibrated the instrument
7-13-05	Calibrated U1 Na <sup>+</sup> Analyzers CPD Slope → 109 BLR Slope → 93 Calibrated U2 Na <sup>+</sup> Analyzers CPD Slope → 111 BLR Slope → 88

106

7-14-05 - Replaced reagents U3 BLR  $S_iO_2$  analyzer  
 - Replaced Resin U2 Econ Cat. Cond. ANALYZER

\*LPI WQP Check:\*

Reagent 90%  
 STD 100%  
 Resin 75%

- Calibrated 1811 EL Demin  $Na^+$  Analyzer  
 Slope  $\rightarrow$  59.7  $E_0 \rightarrow$  -5.9

7-19-05 Calibrated U3  $Na^+$  Analyzers  
 Boiler Slope  $\rightarrow$  85% CPD Slope  $\rightarrow$  103%

7-20-05 Replaced Resin LPI Cat Cond Analyzer @ SHERCO

7-21-05 Replaced Resin U1 BLR, Econ, CPD Cat Cond Analyzers

7-22-05 \*LPI WQP Check\*  
 Resin 100% Reagent 77% STD 90%  
 - Replaced Resin @ LPI

7-26-05 \*LPI WQP Check\*  
 Resin 80% Reagent 70% STD 80%

7-27-05 - Replaced <sup>Reagent</sup> Resin U2 CPD  $S_iO_2$  analyzer  
 - Replaced Reagent U3 CPD  $S_iO_2$  analyzer

7-28-05 Replaced Resin 22 pt Cat COND.  
 \*LPI WQP CHECK  
 Resin 75% Reagent 63% STD 80%

7-29-05 New Reagents U1 BLR, CPD  $S_iO_2$  analyzer  
 New Reagents Demin  $S_iO_2$  analyzer

8-4-05	* LPI WQP CHECK *
	- changed RESIN - 100% Reagent 47% Std 70%
8-5-05	New Reagents LPI $\text{SiO}_2$ analyzer @ SHERCO New Resin 21 polisher, U2 CPD
8-9-05	New Resin 11, 12 polisher CAT cond Analyzer New Resin U2 Boiler CAT COND analyzer New Resin 31, 33, polisher U3 CPD U3 ECON CAT COND ANAL. New Resin U3 Boiler CAT COND Analyzer
8-10-05	* LPI WQP CHECK *
	Resin $\rightarrow$ 75% Reagent $\rightarrow$ 43% STD $\rightarrow$ 60%
8-16-05	- Replaced Resin U2 ECON CAT COND Analyzer - Calibrated Demin Nat Analyzer Slope $\rightarrow$ 59.2 $E_0 \rightarrow$ -5.6
	* LPI WQP Check *
	Reagent $\rightarrow$ 35% STD $\rightarrow$ 50% Resin 35%
8-17-05	Calibrated U1 Nat Analyzers Boiler Slope 87 CPD Slope 106
	Calibrated U2 Nat Analyzers Boiler Slope 90 CPD Slope 108
	Calibrated U3 Nat Analyzers Boiler Slope 91 CPD Slope 98
8-18-05	* LPI WQP Check *
	Resin 100% Reagent 33% STD 50%
	- Replaced Reagent U2 Boiler $\text{SiO}_2$ analyzer



108

8-25-05 New STD U3 CPD  $\text{SiO}_2$  analyzer  
 New Reagent @ LPI WQP  $\text{SiO}_2$  analyzer  
 \* LPI WQP CHECK \*  
 Reagent  $\rightarrow$  100      STD  $\rightarrow$  40      Resin  $\rightarrow$  50

8-30-05 New Cal STD U1 CPD  $\text{SiO}_2$  analyzer  
 New Cal STD Demin  $\text{SiO}_2$  analyzer  
 New Resin U1 Econ Inlet Cat Cond Analyzer

8-31-05 Replaced Resin 22 pol CAT. COND. Analyzer

9-1-05 \* LPI WQP CHECK \*  
 Reagent  $\rightarrow$  89      STD  $\rightarrow$  30      Resin  $\rightarrow$  100  
 - replaced Resin @ LPI CAT COND Analyzer

Replaced Reagents U3 Baker  $\text{SiO}_2$  analyzer  
 Replaced STD U3 Baker  $\text{SiO}_2$  analyzer

9-9-05 Replaced Resin U2 CPD, 21 pol CAT COND Analyzers

\* LPI WQP CHECK \*  
 Reagent  $\rightarrow$  76%      STD  $\rightarrow$  20%      Resin  $\rightarrow$  75%

9-15-05 Replaced Reagents U3 CPD  $\text{SiO}_2$  analyzer

\* LPI WQP CHECK \*  
 Reagent  $\rightarrow$  66%      STD  $\rightarrow$  10%      Resin 40%

9-15-05 - Replaced pH electrodes U2 Econ Sample Analyzer  
 - Replaced Reagents and STD's U1  $\text{SiO}_2$  analyzers  
 Replaced Reagents U2 CPD  $\text{SiO}_2$  analyzer

9-21-05 Replaced Resin @ LPI WQP  
 Resin - 100%      STD - 100%      Reagents 54%

109

9-21-05	- New Resin U2 Econ Inlet CAT COND Analyzer - New Reagent Demin SiO <sub>2</sub> analyzer
9-22-05	Calibrated U1 Nat Analyzers Boiler Slope → 91 CPD Slope → 99
	Calibrated U2 Nat Analyzers Boiler Slope → 97 CPD Slope → 111
	Calibrated U3 Nat Analyzers Boiler Slope → 93 CPD Slope → 99
	Calibrated 1811EL Demin Na Analyzer Slope → 59.2 E <sub>0</sub> → -8.5
9-27-05	Replaced Resin U3 SAT Steam CAT COND Analyzer  * LPI WQP CHECK * Resin 7570 STD 9090 Reagents 4670
9-28-05	Replaced Reagents LPI SiO <sub>2</sub> analyzer @ SHERLO Replaced Resin LPI CAT COND analyzer @ SHERLO Replaced Resin U2 BLR CAT COND analyzer Replaced Resin U1 BLR CAT COND Analyzer Replaced Resin U1 Econ Inlet CAT COND analyzer Replaced Resin 11 polisher CAT COND Analyzer
10-3-05	Replaced Unit 1 Boiler sample solenoid on SiO <sub>2</sub> analyzer.  Replaced tubing & O-rings & reagents on 1811EL Demin Sodium Analyzer.  DO probe on Unit 1 replaced: old S/N: 44936 New S/N: 44465

Wold 000263

110

10-4-05	LPI ✓ Reagents 34% Resin 30%
10-7-05	LPI ✓ Reagents 30% Resin 100% Replaced cation Resin @ 1515 hrs.
10-10-05	LPI ✓ Replaced SiO <sub>2</sub> reagents SiO <sub>2</sub> Reag-100% Std=84% Resin-80%  Valued out all of Unit 3 WQP Replaced SiO <sub>2</sub> reagents w/ DI H <sub>2</sub> O. Left std in service. Removed DO probe - will install new one just prior to U-3 start-up.
10-11-05	New cation resin for Unit 2 - 22 polisher col. Stored Na electrodes on analyzers on Unit 3.
10-12-05	LPI ✓ Reagent = 97% Std = 80% Resin 70%  Replaced SiO <sub>2</sub> reagents on Unit 2 Boiler SiO <sub>2</sub> analyzer
10-17-05	LPI ✓ Reagent = 88% Std = 60% Resin = 45%
10-19-05	LPI ✓ OK
10-21-05	LPI WQP ✓ Resin replaced in cation col. - 100% Reagents = 82% Std = 60%

10-21-05	Replaced resin in col. of: Unit 2 - Econ. In. CPD Pol 21																
10-24-05	LPI WQP ✓ Resin=80% Reag=77% Std=48%																
10-27-05	Replaced resin in: Unit 1 Pol 12 LPI (in house) WQP																
	Etched electrode & calibrated 1811E Demin Sodium																
10-31-05	Calibrated Sodium Analyzers																
	<table border="0"> <thead> <tr> <th colspan="2"><u>Unit 1</u></th> <th colspan="2"><u>Unit 2</u></th> </tr> <tr> <th></th> <th>slope</th> <th></th> <th>slope</th> </tr> </thead> <tbody> <tr> <td>Boiler</td> <td>91%</td> <td>Boiler</td> <td>94%</td> </tr> <tr> <td>CPD</td> <td>100%</td> <td>CPD</td> <td>108%</td> </tr> </tbody> </table>	<u>Unit 1</u>		<u>Unit 2</u>			slope		slope	Boiler	91%	Boiler	94%	CPD	100%	CPD	108%
<u>Unit 1</u>		<u>Unit 2</u>															
	slope		slope														
Boiler	91%	Boiler	94%														
CPD	100%	CPD	108%														
	LPI WQP ✓ Resin 40% Std. 40% Reagent 65%																
	Series 5000																
11-1-05	Rebuild of <u>Unit 3</u> Boiler Silica Analyzer Retubed upper manifold (reagent) delivery to cell. Cleaned lamp/photocell housing (VERY DIRTY) Replaced lamp & interference filter																
11-2-05	Rebuild of Unit 3 CPD Silica Analyzer. Exactly the same as above (boiler)																
11-3-05	LPI WQP ✓ - Post outage (11-2-05) Replaced cation resin SiO <sub>2</sub> reagent = 60% Std = 48% (adjusted to 50%)																

112

11-3-05	Replaced Unit 1 Econ In Cation resin
11-7-05	<sup>(NEW HOUSE)</sup> LPI SiO <sub>2</sub> Analyzer Rebuild
SERIES 5000	Retubed upper & lower parts Replaced: lamp, interference filter, capillary module, sample cell, stir bar, bottle caps, bottle filters.
	Replaced SiO <sub>2</sub> reagents in: Unit 1 Boiler & CPD Unit 2 Boiler
11-9-05	New resin in Cat. Col. for Unit 1: CPD & Po11
11-10-05	LPI WQP ✓ - Resin 60% Reag & Stds - OK
	Cleaned sample cell & filter (sample) on Unit 2 Boiler Silica. Found liquid in the reagent air press. reg. Will order new one. to replace.
	Replaced reagents in Demin SiO <sub>2</sub> & std. Cap was broke on Amino Cap reagent bottle. Replaced cap & filter ↗
10-14-05	LPI ✓ Resin 35% SiO <sub>2</sub> - OK
10-17-05	Unit 3 CPD SiO <sub>2</sub> Installed reagents & calibrated
11-18-05	Unit 3 Sodium - CPD Installed elec. & calibrated Slope = 101%
	LPI WQP ✓ Replaced cation resin. SiO <sub>2</sub> reag. → 40% Std → 40%

11-18-05 Replaced cation resin in Unit 2: Boiler  
Econ In  
Pol. 22

11-21-05 LPI WQP ✓  
SiO<sub>2</sub> reag → 30% Std → 35% Resin → 85%

Replaced cation resin on LPI WQP (Sherco site)

Replaced std in Unit 1 CPD SiO<sub>2</sub>

11-23-05 LPI ✓ Resin - 70% SiO<sub>2</sub> reag <sup>Replaced</sup> 100% Std ~~100%~~

11-28-05 Replaced resin cat. col. Unit 2 → CPD; ½ Pol 21

11-29-05 LPI WQP ✓  
Resin 50% SiO<sub>2</sub> reag. 90% std 80%

Calibrated Sodium Analyzers

Unit 1		Unit 2	
	SLOPE		SLOPE
Boiler	98%	Boiler	94%
CPD	103%	CPD	113%

Demin Nat analyzer

Changed: Ref. elec. fill. sol'n

Reagent: tubing, O-rings

Etched Na elec.

Calibrated

SLOPE 61

E<sub>0</sub> - 8.9

12-2-05 Replaced resin @ LPI WQP  
SiO<sub>2</sub> reag. 85% Std 90%

Put Unit 3 Boiler SiO<sub>2</sub> in-service

Fresh reagents & stds.

Calibrated

Replaced all tubing, fittings, & bottle cap on std.  
(too short)

114

12-2-05	Placed Unit 3 <del>Boiler</del> Boiler Sodium Analyzer in-service. Calibration slope $\rightarrow$ 93%	11
	Replaced cation resin in Unit 3; CPD's 31, 32, 33 Polishers	1
12-5-05	New reagents in Unit 2 Boiler SiO <sub>2</sub> analyzer.	
	Replaced cation resin in Unit <del>1</del> Pol. 12 col.	
12-9-05	LPI WQP $\checkmark$ SiO <sub>2</sub> Analyzer Reag $\rightarrow$ 74% Std $\rightarrow$ 80% Resin $\rightarrow$ 60% Cat. Cond. is on the high side $\rightarrow$ 0.487 $\mu$ S	1
12-12-05	Cleaned filter & sample cell on Unit 3 Boiler SiO <sub>2</sub> Post start-up	
	Replaced resin in Unit 1 Econ. In. Cation Col. Cleaned flow cells for Econ. In. Cond's & ppt.	
12-10-05	DD probe placed in-service in Unit 3 WQP	
12-15-05	LPI WQP $\checkmark$ Reag $\rightarrow$ 63% Std $\rightarrow$ 70% Replaced cation resin @ LPI.	
12-16-05	unit 1 CPD SiO <sub>2</sub> - replaced reagents only	
12-19-05	Removed & cleaned in-line filter & sample cell on Unit 2 Boiler SiO <sub>2</sub> . Post start-up.	
12-21-05	Replaced reagents & std in Sherco side LPI SiO <sub>2</sub> analyzer. Replaced sample tubing.	
12-22-05	Cleaned sample cell on Unit 3 CPD silica.	1
	Replaced Pol. 11 cation resin.	

Wold 000268

	12-23-05	LPI WQP ✓ SiO <sub>2</sub> slightly high Reagent → 50% Std → 60% Resin → 50%
rets	12-27-05	Replaced LPI (Sherco WQP) cation resin. Replaced cation resin Unit 2: Econ In. Pol. 22
%		LPI WQP ✓ Reagent 35% Std 50% Resin 40%
	12-29-05	Replaced reagents Unit 1 Boiler SiO <sub>2</sub> .
	12-30-05	Replaced reagent Unit 2 CPD SiO <sub>2</sub>
		LPI WQP ✓ Replaced resin
		* <span style="border: 1px solid black; padding: 5px;">2006</span> *
	1-3-06	Unit 3 Boiler Silica Analyzer "Unable to calibrate" Cleared sample cell & stir bar Sample solenoid - leaking - REPLACED
		New reagents in Demin SiO <sub>2</sub> analyzer.
		Replaced cation resin in Unit 1: CPD Unit 2: CPD & Pol. 21
	1-4-06	Etched Demin Na <sup>+</sup> - tried to cal - NOT!
	1-6-06	calibrated Demin Na <sup>+</sup> - slope → 61 E <sub>0</sub> → -9



116

1-06-06 LPI WQP ✓  
Resin-60% std-40% R-40%

1-09-06 Replaced reagents Unit 3 CPD Silica.

1-12-06 Calibrated Unit 1 & 2 Sodium Analyzers

Unit 1	SLOPE	Unit 2	SLOPE
Boiler	94%	Boiler	82%
CPD	101%	CPD	107%

1-13-06 LPI WQP ✓  
Resin-40% std-40% Reag-35%

Replaced cation resin Unit 2 Boiler

1-16-06 Replace Unit 3 Boiler Sodium monitor inlet filters

1-17-06 LPI WQP  
- replaced RESIN

- Replaced CAL STD Perm. SiO<sub>2</sub> analyzer

1-18-06 Replaced Econ. Inlet Cation Column 7<sup>th</sup> Floor

1-20-06 Replaced Reagents @ LPI WQP  
Reagents - 100  
STD - 10  
RESIN - 90

- Replaced U3 Boiler SiO<sub>2</sub> Reagents & STDs

- Replaced STD @ LPI WQP

- Replaced RESIN U1 BLR, Econ, 12 polisher CAT  
CONDUCTIVITY analyzers

Wold 000270

1-23-06	Replaced SiO <sub>2</sub> std U1 CPD
1-24-06	* LPI WQP CHECK * - Replaced Sample cover - moly plugged - unable to Calibrate, multiple CALS - Replaced Resin - Reagent 93% STD 70% Resin 100%
1-25-06	Replaced SiO <sub>2</sub> Reagents U2 Boiler
1-26-06	* LPI WQP CHECK * Reagent - 90 STD 70 Resin 95
1-27-06	Replaced Resin LPI CAT COND Analyzer @ SHERCO Reagents on SiO <sub>2</sub> analyzer were at 43%, changed to 26%.
2-3-06	* LPI WQP CHECK * Reagent 77% STD 60% Resin 50% Replaced Resin 11 polisher CAT COND Analyzer Replaced Resin U2 ECON CAT. COND. Analyzer Replaced Reagents U1 CPD SiO <sub>2</sub> analyzer Replaced Reagents LPI SiO <sub>2</sub> analyzer @ SHERCO
2-8-06	* LPI WQP CHECK * - LPI down for OUTAGE - Replaced Resin in CAT. COND. analyzer Reagent - 68% STD - 60% Resin - 100%
2-10-06	* LPI WQP CHECK * Reagent - 65 STD - 50 Resin 95%

118

2-10-06 Replaced Cation Resin 22 pol cond analyzer

2-12-06 Calibrated Na<sup>+</sup> Analyzers

	BLR	← slope →	CPD
U1	99		108
U2	100		108
U3	94		95

- Calibrated Demin Na<sup>+</sup> Analyzer

slope 59.2  
E<sub>0</sub> 2.1

- New O-rings, solution, tubing and etched electrode - Demin Na<sup>+</sup> Analyzer

2-13-06 Replaced CAL STD U3 CPD SiO<sub>2</sub> analyzer

2-16-06 Replaced Resin U2 CPD Cat cond. Analyzer  
Replaced Resin 21 pol CAT cond analyzer

Replaced Bulb LPI SiO<sub>2</sub> analyzer @ SHERCO  
- this was to try and cure a software reset alarm

2-17-06 \*LPI W&P CHECK\*

Reagent 54% Resin 60% STD 40%

New reagent U2 CPD SiO<sub>2</sub> analyzer.

2-20-06 New SiO<sub>2</sub> reagent<sup>std</sup> in Sherco LPI analyzer.

2-21-06 Replaced SiO<sub>2</sub> reagents in U1 Boiler

2-20-06 New cation resin in U-3 ~~Pol~~ 33 col.

2-27-06	Replaced Demin $\text{SiO}_2$ reagents
2-28-06	LPI WQP $\checkmark$ $\text{SiO}_2 \rightarrow R = 35\%$ Std-40 Resin- <sup>new</sup> 100%
3-2-06	Replaced resin Unit 3 Cat. Col: Econ & M. steam
3-3-06	New silica reagents in U-3 CPB & LPI. LPI WQP $\checkmark$ New reagents $\rightarrow 100\%$ Std $\rightarrow 100\%$ Resin $\rightarrow 90\%$
3-6-06	Replaced resin on Unit 1 Econ. In. & Pol. 12 cat. col. & LPI Here
3-8-06	LPI WQP $\checkmark$ Reag. -100% Std-90% Resin-60%
3-9-06	Replaced resin on Cation col's: Unit 1 $\rightarrow$ CPD Unit 2 $\rightarrow$ Boiler & Econ. In. also cleaned all flow meter glass.
3-10-06	Cleaned U-3 Boiler silica in-line filter
3-10-06	Calibrated Unit 3 Sodium Analyzers Boiler slope 89% CPD " 99%
	Calibrated Unit 1 & 2 Sodium Analyzers Boiler U1 slope $\rightarrow$ 95% Boiler U2 " 90%
	CPD U-1 slope $\rightarrow$ 98% CPD U-2 " 102%
3-13-06	Calibrated Demin Na EL1811 Etched Na elec. slope $\rightarrow$ 59.2 E=0.1

120

3-14-06

Overhaul of the LPI Silica analyzer:

Series 5000

All chemical and sample delivery tubing

Lamp

Interference filter

Stir motor

Sample cell

Reagent solenoids

NOTE: The #2 solenoid wiring has been modified. The ground wire is relocated to a functioning site.

Calibrated and functioning 3-14-2006

3-15-06

Replaced resin Unit 1 Boiler cation col.

3-17-06

Unit 3: New resin in → CPD

Pol 31

New reagents for Boiler SiO<sub>2</sub>.Replaced SiO<sub>2</sub> reagents in Unit 2 Boiler analyzer

3-24-06

- New Reagents U2 CPD SiO<sub>2</sub> analyzer- New Reagents LPI (@ SHERCO) SiO<sub>2</sub> analyzer

- New Resin @ 21, 22 pol cat. cond. analyzers

3-23-06

LPI WQP CHECK - OK

3-27-06

Replaced SiO<sub>2</sub> STD Demin Analyzers

121

3-28-06 \*LPI WQP CHECK\*  
 STD- 40% Resin 50% Reagent 68%

3-29-06 Unit 2 Boiler Silica  
 Reading negative #'s.  
 Sample solenoid leaking slowly. REPLACED  
 checked reagent flow rates. GOOD  
 Replaced interference filter. Found no O-ring over filter.  
 Replaced lamp. Replaced sample straw assembly.  
 Calibrated  
 "Unable to calibrate" at first. Did a grab sample of  
 500ppb std - value = 514ppb. Installed std was  
 reading 738ppb. Replaced std and it read 514ppb.  
 Called it good.

3-31-06 cleaned sample cells on Unit 1 Boiler & CPD silica's.

LPI WQP ✓  
 Resin 50% Reag 62% Std 40%

4-3-06 New STD. U1 CPD S<sub>2</sub>O<sub>2</sub> analyzer.

4-5-06 New STD. U3 Boiler S<sub>2</sub>O<sub>2</sub> analyzer.

4-5-06 \*LPI WQP CHECK\*  
 - changed Resin  
 Resin - 100% Reagent - 55% STD - 30%

4-6-06 New Resin 32 pol. CAT. COND. analyzer.  
 New Resin U2 CPD CAT. COND. analyzer  
 New Resin U3 7<sup>th</sup> FI. O<sub>2</sub> System (CAT. COND.)

4-7-06 \*LPI WQP CHECK\*  
 Resin 90% Reagent - 51% STD - 30%

Wold 000275