

Table of Contents

I. Introduction	1
II. Overall Response to Witness Richard Polich	3
III. Xcel Energy's Water and Steam Chemistry Practices at Unit 3	9
IV. Conclusion	28

Schedules

DOC Response to Xcel Energy Information Request No. 3	Schedule 1
Rebuttal to Expert Opinion of William Allmon Regarding the Effects of Chemistry Control on the Failure of the LP Turbine of Sherco Unit 3	Schedule 2
Excerpt from GE Litigation Trial Transcript, Testimony of William Allmon	Schedule 3
Excerpt of GE Litigation Duane Wold Deposition Transcript	Schedule 4
Enlarged Copy of Figure 1b	Schedule 5
Sherburne County Generating Plant Calibration Logs	Schedule 6
Rebuttal to Expert Opinion of James D. Schultz	Schedule 7

**PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED**

I. INTRODUCTION

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26

Q. PLEASE STATE YOUR NAME AND EMPLOYER.

A. My name is David G. Daniels. I am a Senior Principal Scientist with Acuren Inspection, Inc.

Q. HAVE YOU PREVIOUSLY PROVIDED TESTIMONY IN THIS PROCEEDING?

A. Yes. On June 16, 2023, I filed my Direct Testimony on behalf of Northern States Power Company (Xcel Energy or the Company) regarding Xcel Energy's water and steam chemistry practices at Unit 3 of its Sherburne County (Sherco) Generating Plant (Plant).

Q. ON WHAT EXPERIENCE IS YOUR TESTIMONY IN THIS PROCEEDING BASED?

A. I have over 40 years of experience with steam and water chemistry, including directly working as a plant chemist at a coal-fired power plant very similar to the Sherco station. As a consultant, I have performed independent evaluations of the boiler and steam cycle chemistry at nearly 100 different power plants. I have published over two dozen articles as a contributing editor on water and steam chemistry topics for Power magazine. I have authored and edited technical documents for the Electric Power Research Institute (EPRI) on water treatment equipment, steam cycle inspection, treating boiler chemical cleaning wastes, steam cycle lay-up and start up, and anime use and degradation in the steam cycle. In addition, I have served on relevant professional committees, including serving as chairman of the American Society of Mechanical Engineers (ASME) Research and Technology Committee on Water and Steam in Thermal Power Systems.

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 Q. CAN YOU PROVIDE A BRIEF SUMMARY OF YOUR TESTIMONY IN THIS
2 PROCEEDING?

3 A. I researched the plant chemistry practices, analyzed the data, and interviewed
4 plant personnel to develop a thorough understanding of the Company's
5 chemistry practices specific to Sherco's Unit 3. Based on this research and
6 analysis, I concluded that the Company's practices at Sherco complied with, and
7 in some cases even exceeded, industry practices at similar large, coal-fired units.
8 The Company's water and steam chemistry practices reflect that, as an operator,
9 the Company proactively worked to ensure the proper monitoring of steam
10 chemistry and responded quickly and thoroughly whenever there were signs of
11 contamination of the condensate, feedwater or steam. In short, the Sherco
12 Operations and Laboratory were acting as prudent operators of their
13 equipment. In addition, after thorough review of the materials provided to me
14 between 2000 and the steam turbine failure on November 19, 2011 (Event), I
15 found that the Company prudently monitored the water and steam chemistry at
16 Unit 3, and its practices from 2000 to 2011 were sufficient to identify any
17 significant acute or chronic contamination events that would have warranted
18 removal of the blades and the related inspection discussed by other Company
19 witnesses. No such events were identified.

20

21 Q. WHAT IS THE PURPOSE OF YOUR REBUTTAL TESTIMONY?

22 A. My Rebuttal Testimony replies to testimony filed by Mr. Richard Polich of GDS
23 Associates, Inc. on behalf of the Minnesota Department of Commerce
24 (Department), specifically as it relates to the water and steam chemistry
25 practices and procedures at Sherco 3 and any alleged impact on the Event.

**PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED**

II. OVERALL RESPONSE TO WITNESS RICHARD POLICH

1
2
3 Q. WHAT OVERARCHING OBSERVATIONS DO YOU HAVE REGARDING MR. POLICH'S
4 TESTIMONY?

5 A. There are three overarching observations I have that are important context for
6 Mr. Polich's testimony. *First*, Mr. Polich does not appear to have done any
7 independent review or analysis of the chemistry data related to Unit 3. Instead,
8 his testimony relies on a selective review of the record in a separate proceeding,
9 brought in state court by several insurers against General Electric (GE), the
10 turbine manufacturer (GE Litigation). For example, the perfunctory portion of
11 his testimony that discusses water and steam chemistry appears to rely not on
12 the actual steam chemistry data, but rather solely on reports written by witnesses
13 for GE in the GE Litigation. In particular, in his testimony related to water and
14 steam chemistry, Mr. Polich relies on the ChemStaff Report written by Mr.
15 William Allmon, and in a subsequent Information Request, Mr. Polich points
16 to a report by James D. Schultz. It is my understanding that neither of these GE
17 Litigation witnesses are providing testimony in this regulatory case.

18
19 *Second*, Mr. Polich has no experience or training in water and steam chemistry
20 of a fossil-fired power plant. Mr. Polich "does not have any degrees or specific
21 course work in the area of water chemistry," only "understands the
22 fundamentals of proper water chemistry," "does not have any memberships in
23 water chemistry," and is unable to provide any other reports, testimony, or
24 conclusions reached as an expert in water chemistry. (*See* the Department's
25 response to Xcel Energy's Information Request No. 3, included as
26 Exhibit___(DGD-2), Schedule 1.) At most, Mr. Polich has experience
27 reviewing historical water chemistry data, and even then, Mr. Polich was only

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 able to identify with any specificity his involvement in failure analyses at two
2 coal-fired power plants and one combined cycle plant.¹ The majority of his
3 experience appears to have been at nuclear power plants and combined cycle
4 power plants and unrelated to water chemistry. Both nuclear and combined
5 cycle power plants have steam generator steam cycles that are significantly
6 different than those at a conventional coal-fired plant. As a result, Mr. Polich's
7 experience does not translate to the Sherco 3 system, and as I detail below, that
8 lack of experience is apparent from his testimony here.

9
10 *Third*, Mr. Polich mischaracterizes the findings of Thielsch Engineering's root
11 cause analysis report (Thielsch Report)² in his testimony on p. 19, line 6. I
12 address the specific mischaracterizations of the Report by Mr. Polich as it relates
13 to water and steam chemistry below. However, my overarching observation is
14 that I have not seen anything to indicate that Mr. Polich himself conducted a
15 root cause analysis, let alone reviewed the relevant steam chemistry data, and
16 therefore he has no basis that I have seen from which to draw any conclusions
17 about the root cause of the Event or, more particularly, about the part the steam
18 chemistry played in the corrosion mechanism.

19
20 In short, Mr. Polich's methodology and experience – reflected in his Direct
21 Testimony – do not provide him with a basis to reliably, independently opine
22 on the condition or prudence of the water and steam chemistry program at
23 Sherco 3.

¹ This experience also appears to be irrelevant here, where Mr. Polich did *not* review the historical water chemistry data.

² The Thielsch Report is included in Company witness Anthony A. Tipton's Direct Testimony as Exhibit____(AAT-1), Schedules 2 and 3.

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 Q. CAN YOU GIVE SOME EXAMPLES THAT DEMONSTRATE MR. POLICH’S LACK OF
2 UNDERSTANDING OF UNIT 3’S STEAM CYCLE?

3 A. There are several, but I will highlight a few significant examples of the
4 fundamental misunderstandings underlying Mr. Polich’s testimony.

5

6 *First*, contrary to his representations, Mr. Polich does not appear to understand
7 fundamental concepts of steam chemistry. For example, he states that “cation
8 conductivity . . . is a measure used to determine chloride concentrations in
9 steam.”³ In reality, cation conductivity is a property of the water that reflects
10 not only the chloride concentration, but also sulfate and other anions such as
11 bicarbonate (HCO₃) and organic acids, some of which are not harmful to the
12 steam turbine. In another place in his testimony he simply refers to this
13 measurement as “cation limits.”⁴ There are cation resins, cation vessels, but
14 there is no such thing as a “cation limit.” Further emphasizing the lack of
15 understanding of cation conductivity, Mr. Polich later equates the measurement
16 of cation conductivity with sodium.⁵ Sodium and cation conductivity are two
17 completely different measurements, and equating one with the other is wrong.
18 These fundamental errors underscore the unreliability of Mr. Polich’s testimony
19 regarding steam chemistry.

20

21 *Second*, Mr. Polich does not seem to possess a correct understanding of the
22 steam path through the Sherco Unit 3 turbine, which is no different from the
23 steam path at most similar power fossil-fired plants in the world. He states:

³ Polich Direct, p. 44 lines 17-18.


⁴ Polich Direct, p. 51 line 11.

⁵ Polich Direct, p. 50 line 15-16 (“cation conductivity (i.e., sodium concentration)”).

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 “The Sherco 3 steam path flows from the *IP turbine through the reheat section* of the
2 boiler to raise the steam temperature *prior to entering the LP turbine.*”⁶ (emphasis
3 added). This is wrong. As seen in Figure 1a below (which is Figure 1 from my
4 Direct Testimony with the relevant section identified in yellow), the steam exits
5 the HP turbine and then passes through the reheater before going to the *IP*
6 *turbine*. There is no reheating of steam after the IP turbine. Mr. Polich makes
7 this basic and fundamental error despite Figure 1 below and Figure 2 in his own
8 testimony which show the correct location of the reheater. This, when
9 combined with his lack of experience and independent analysis, underscores the
10 unreliability of his testimony.

Figure 1a
Diagram of Unit 3’s Steam Cycle: HP Turbine to IP Turbine



⁶ Polich Direct, p. 45.

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 *Third*, Mr. Polich does not appear to fully grasp the chemistry of contaminants
2 in steam. For example, Mr. Polich’s testimony on drum boilers (the only
3 relevant boiler to Sherco 3) has a significant gap: it does not consider long-
4 established research from the 1990s showing that the potential for chemical
5 impurities (such as sodium hydroxide) to enter the steam is very low when the
6 operating pressure of the boiler is less than 2500 psig. Mr. Polich appears to be
7 completely unaware of this research, as his explanation of the differences
8 between steam purity in once-through boilers and drum boilers does not
9 recognize that different chemical compounds have different volatility in steam,
10 and that chemical volatility (potential for leaving the boiler water and becoming
11 part of the steam) is impacted by a number of variables, including operating
12 pressure. For example, while my direct testimony discussed this, Mr. Polich’s
13 testimony does not address that the Sherco 3 boiler often operated at pressures
14 below 2500 psig, thus limiting the periods when sodium hydroxide (caustic)
15 could even possibly enter the steam, further rendering Mr. Polich’s over-
16 simplified understanding of steam chemistry in a boiler and related testimony
17 unreliable.

18
19 *Finally*, Mr. Polich confuses the steam chemistry data sources available to
20 Sherco operators. He states: “Sherco 3 was unable to accurately monitor sodium
21 levels of 6 ppb as recommended by GE nor EPRI recommendations of 3-6
22 ppb.”⁷ This again is simply wrong. Sherco monitored sodium continuously with
23 on-line analyzers with a detection limit of 0.1 ppb Na at three separate points
24 in the cycle: the demineralizer effluent, the condensate pump discharge, and in
25 the boiler.

⁷ Polich Direct, p. 52 lines 7-8.

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 These examples demonstrate the fundamental lack of experience and
2 understanding that undermine Mr. Polich's testimony.

3
4 Q. DO YOU AGREE WITH MR. POLICH'S USE AND DEFINITION OF THE TERM "GOOD
5 UTILITY PRACTICE"?

6 A. I agree with Mr. Polich that any analysis of utility practices should consider
7 "reasonable judgment in light of the facts known at the time [a] decision was
8 made,"⁸ but I otherwise strongly disagree with Mr. Polich's suggestion that
9 "good" utility practices require compliance with every guideline in any EPRI or
10 GE document without considering its date, particular application to a specific
11 unit's equipment, or a utility's specific experience.⁹ As Mr. Polich acknowledges,
12 he did not derive his definition from any primary source, (*See* the Department's
13 response to Xcel Energy's Information Request No. 25, included in Company
14 witness Herbert J. Sirois' Rebuttal Testimony as Exhibit___(HJS-2), Schedule
15 1), and I do not think Mr. Polich is qualified to define "good" utility practice as
16 it relates to water and steam chemistry because he has no experience in this area.
17 He claims no experience in visiting a coal-fired power plants to evaluate their
18 steam chemistry practices and compare them to other similar units.

19
20 Q. IS IT YOUR TESTIMONY THAT THE COMPANY'S WATER AND STEAM CHEMISTRY
21 PRACTICES WERE PRUDENT?

22 A. Yes. Unlike Mr. Polich, I have worked with nearly 100 fossil-fired plants
23 specifically on water and steam chemistry issues over the course of my over 40-
24 year career, including 7 years working directly in the laboratory of coal-fired

⁸ Polich Direct, p. 7.

⁹ *See* Polich Direct, pp. 47-48 (listing "documentation available . . . that described good utility practice for water chemistry requirements").

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 power plants, involved every day with water and steam chemistry. I reviewed
2 Xcel Energy’s practices, procedures, and data leading up to the Event, and my
3 conclusion is that, overall, the Company’s water and steam chemistry program
4 aligned with, and in some cases exceeded, the standards for programs at similar
5 large coal-fired units. Based on the information available to the Company at the
6 time, the Company’s water and steam chemistry practices for Sherco 3 fell well
7 within the range of reasonable utility actions.

8
9 Q. WHAT DO YOU CONCLUDE FROM REVIEWING MR. POLICH’S TESTIMONY?

10 A. Mr. Polich’s testimony amounts to an inaccurate and incomplete summary of
11 information that he did not personally review, and therefore runs far afield from
12 the expectations associated with expert testimony. Due to his lack of experience
13 with water and steam chemistry issues at a coal-fired plant, combined with his
14 selective review of only a small portion of the available reports and data, Mr.
15 Polich is not qualified to provide testimony on the prudence of the Company’s
16 operation of Sherco 3 before the Event. He does not understand how the
17 Sherco 3 system works, including the key steam cycle and chemistry concepts.
18 Without this knowledge and experience, or even an independent review of the
19 relevant data, Mr. Polich cannot know whether the Company was acting as a
20 prudent operator of Sherco 3 with respect to steam chemistry.

21
22 **III. XCEL ENERGY’S WATER AND STEAM CHEMISTRY**
23 **PRACTICES AT UNIT 3**

24 Q. DOES MR. POLICH UNDERTAKE A REVIEW OF THE STEAM CHEMISTRY DATA
25 FROM SHERCO 3 TO SUPPORT HIS CLAIMS THAT WATER CHEMISTRY WAS A
26 “LIKELY CONTRIBUTOR” TO THE EVENT AT UNIT 3?

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 A. No, there is no indication that Mr. Polich independently reviewed the data on
2 which the ChemStaff Report, provided in the GE Litigation, relied.¹⁰

3

4 Instead, Mr. Polich relies almost entirely on the ChemStaff Report to support
5 his claims that water and steam chemistry at Sherco 3 was a “likely contributor”
6 to the Event.¹¹ There is no indication that Mr. Polich independently assessed
7 the validity of the claims made in the ChemStaff Report (whose author Mr.
8 William Allmon is not a witness in the current regulatory case) or that he has
9 the competency to do so.

10

11 Specific issues with the ChemStaff Report are detailed in my extensive rebuttal
12 in the GE Litigation, refuting many of the claims in that Report. My rebuttal
13 report is attached as Exhibit____(DGD-2), Schedule 2.¹² Mr. Polich does not
14 address any of the problems with the ChemStaff Report.

15

16 Q. MR. POLICH CLAIMS THAT THE COMPANY FAILED TO “FOLLOW GOOD UTILITY
17 PRACTICE WITH RESPECT TO MONITORING STEAM CHEMISTRY AT SHERCO 3.”
18 HOW DO YOU RESPOND?

19 A. As I stated above, Mr. Polich lacks the experience and knowledge to define or
20 assess “good” utility practices, as he has defined the term, with respect to water
21 and steam chemistry. In addition, Mr. Polich did not review the Sherco 3 steam
22 chemistry data and has no experience with the day-to-day water and steam
23 chemistry of coal-fired plants. Therefore, any conclusion he reaches with

¹⁰ Polich Direct, pp. 44-45. The ChemStaff Report is attached as Schedule 22 (RAP-D-22) to Polich Direct.

¹¹ Polich Direct, p. 44-45.

¹² The Company provided this report to the Department in response to Department Information Request No. 2.

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 respect to “good” utility practice—or prudence—of the Company’s steam
2 chemistry monitoring at Sherco is baseless.¹³

3
4 The procedures, on-line analyzers, grab sampling locations, and chemistry limits
5 that the Company used at Sherco during this period were prudent. This
6 conclusion is based on my own review of the procedures and data from Sherco
7 3, as well as my experience working with close to 100 fossil-fired power plants
8 during my over 40 years in this industry.

9
10 Mr. Polich’s emphasis on the fact that Sherco did not have a separate sample
11 point for the hot reheat steam¹⁴ is irrelevant because the Company already had
12 sufficient monitoring to determine if there was contamination entering the unit
13 without this specific sample point. There was no industry-wide “requirement”
14 for a reheat sample in the steam cycle. Pointing to a single page from a nearly
15 300-page EPRI 2002 Guidelines, Mr. Polich concludes that failure to monitor
16 this sample point meant that the Company failed to follow “good utility
17 practices.” But the Guidelines on which Mr. Polich relies are just that—
18 guidelines, not requirements, and even those guidelines acknowledge that
19 “specific unit characteristics and/or experience” could result in modifications
20 of the(se) Guidelines for a specific unit.¹⁵

¹³ Polich Direct, p. 45.

¹⁴ Polich Direct, p. 45.

¹⁵ Polich Direct, Schedule 29 (RAP-D-29) at 127 (“Copies of Figures 4-1 to 4-3, ***modified if necessary to reflect specific unit characteristics and/or experience, could be*** included in the plant operating procedures and prominently displayed in the control room, water and steam sample room, and chemistry laboratory.” (emphasis added)).

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 Specific to the reheat sample, the EPRI 2002 Guidelines on which Mr. Polich
2 relies acknowledge that a reheat steam sample may not be available at every
3 plant. Because the reheat sample is the combination of Main Steam plus
4 attemperation spray water added in the reheater, the EPRI 2002 Guidelines
5 stated: “Should this sample point not be available, the steam chemistry may be
6 calculated from the chemistries of the saturated steam and feedwater...”¹⁶ The
7 Company relied on this alternative monitoring method at Sherco 3 in alignment
8 with the EPRI 2022 Guidelines. Indeed, because the boiler design of Sherco 3
9 required very little reheat attemperation, the Main Steam sample that the
10 Company already monitored was sufficient to meet the Guidelines, and would
11 have been chemically indistinguishable from a reheat sample.¹⁷ As a result, and
12 as Sherco plant chemist Mr. Duane Wold testified, the Company prudently
13 weighed the cost and benefits of adding additional monitoring to existing
14 monitoring and determined that, the sampling points and analyzers they already
15 had were sufficient to determine if there was contamination in the unit; that
16 capability would not be enhanced by the addition of a separate reheat sample.¹⁸
17 That was a reasonable decision on their part and complied with the EPRI 2002
18 Guidelines which specifically allowed for such plant-specific adaptations.

19
20 Mr. Polich’s conclusion further ignores, as I stated in my direct testimony, that
21 this is a *cycle* and that the Company undertook substantial monitoring of the

¹⁶ Polich Direct, Schedule 29 (RAP-D-29) at 95.

¹⁷ This was confirmed by Mr. Allmon, the author of the ChemStaff Report, in the GE Litigation. He testified at trial that he calculated reheat steam sodium by adding attemperator sodium to main steam sodium and concluded that there was not “much of a difference” between the reheat steam sodium and the main steam sodium. An excerpt from Mr. Allmon’s trial testimony is included as Exhibit___(DGD-2), Schedule 3.

¹⁸ An excerpt of Mr. Wold’s trial deposition transcript is included as Exhibit___(DGD-2), Schedule 4.

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 entire steam cycle at Sherco 3. The Company had been monitoring the Main
2 Steam sample for cation conductivity since the unit was commissioned, and
3 began monitoring sodium at this sample point in 2008. The Company had also
4 been continuously monitoring sodium at the demineralizer effluent, at the
5 condensate pump discharge, and at the boiler since 1987.¹⁹ Therefore, the
6 Company had the two potential sources of sodium hydroxide contamination at
7 Sherco 3 covered—the demineralizer and a condenser tube leak. It also
8 monitored sodium in the boiler, which concentrates any contamination about a
9 hundred-fold. Thus, even trace amounts of contamination coming in with the
10 feedwater would be obvious in the chemistry of the boiler sample. Shown in
11 Figure 1b below (which is Figure 1 from my Direct Testimony, modified to
12 show all of the continuous monitoring and grab at each sample point on Unit
13 3) are the grab and continuous monitoring sample location across the steam
14 chemistry cycle at Unit 3.²⁰

¹⁹ Polich Direct, Schedule 29 (RAP-D-29) at 95 (providing alternative to reheat sample).

²⁰ An enlarged copy of Figure 1b is also included as Exhibit___(DGD-2), Schedule 5.

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

Figure 1b
Diagram of Unit 3's Steam Cycle:
Identifying Chemical Monitoring Locations




Table 1 below further shows chemical parameters analyzed at each sample location.

Table 1
Unit 3's Steam Cycle Chemical Monitoring at Each Sample Location

Location	Main Steam	Boiler	Economizer Inlet
Grab Sample Testing	1. Sodium (Na) 2. Cation Conductivity 3. Ammonia 4. pH 5. Silica 6. Specific Conductivity	1. Sodium (Na) 2. Specific Conductivity 3. Cation Conductivity 4. Silica 5. pH	1. Specific Conductivity 2. Cation Conductivity 3. pH 4. Dissolved Oxygen 5. Sodium 6. Ammonia 7. Silica 8. Iron
Continuous Monitoring	1. Sodium (Na) (after 2008) 2. Cation Conductivity	1. Sodium (Na) 2. Specific Conductivity 3. Cation Conductivity 4. Silica 5. pH	1. Specific Conductivity 2. Cation Conductivity 3. pH

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

Table 1 (continued)
Unit 3's Steam Cycle Chemical Monitoring at Each Sample Location

Location	Deaerator Outlet	Polisher Effluent	Condensate Pump Discharge	Demineralizer Effluent
Grab Sample Testing	1. Dissolved Oxygen	2. Cation Conductivity 3. Dissolved Oxygen 4. pH 5. Silica 6. Sodium	1. Sodium (Na) 2. Specific Conductivity 3. Cation Conductivity 4. pH 5. Dissolved Oxygen 6. Ammonia 7. Iron 8. Silica	No routine grab sample testing at this location
Continuous Monitoring	No continuous monitoring at this location	1. Cation Conductivity	1. Sodium (Na) 2. Specific Conductivity 3. Cation Conductivity 4. Silica	1. Sodium (Na) 2. Specific Conductivity 3. Silica

As seen from Figure 1b and Table 1, the Company has monitored key chemical parameters across the water and steam cycle at Sherco 3 to control steam purity. Because these sampling points and analyzers would have alerted Sherco 3 operators to significant contamination, I view these practices at Sherco as reasonable and prudent and sufficient to identify any steam contamination at Sherco 3 that would have required removal of the blades.

Q. DOES EPRI SET REQUIREMENTS FOR FOSSIL-FIRED PLANTS?

A. No, it sets guidelines. It is important to remember that EPRI is an advisory (not regulatory) organization (I have been a contributing author and editor to the organization for decades.). EPRI's chemistry guidelines recommend the *best practices* intended to encompass the entire range of the types of boilers and turbines used by their membership. Their recommended practices are aspirational—intended to improve industry practices among its members and

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 not to reflect the entire range of *reasonable practices* that can be employed by
2 prudent plant operators.

3
4 This is shown through EPRI's documentation. For example, in EPRI's 1986
5 Cycle Chemistry Guidelines, it expressly states: "These guidelines . . . are not
6 intended to be used as a code or standard. The guidelines . . . can be adapted
7 and customized to a utility's individual situation."²¹ It goes on to acknowledge
8 that "[a]ll utilities will not be able to monitor all the parameters at all the sample
9 points nor maintain all the target values and action levels. In each case,
10 monitoring of cycle chemistry should be consistent with the existing sample
11 system, instrumentation, and manpower."²² EPRI further recommended
12 modification of the guidelines based on "plant-specific" design and "local
13 operating experience."²³ Another EPRI Guideline points to the same cost-
14 benefit analysis that Mr. Wold testified to: "[S]ome units may be currently
15 operating with sufficient availability and efficiency, and without any problems,
16 that additional expenditures or changes in the current treatment cannot be
17 justified."²⁴ The other EPRI guidelines on which Mr. Polich relies similarly set
18 forth recommendations or suggestions and support plant-specific and
19 experience-based modifications.²⁵

²¹ Polich Direct, Schedule 26 (RAP-D-26) at 2.

²² *Id.* at 3.

²³ *Id.* at 6 ("Modification of portions of the Guidelines to reflect actual, plant-specific design characteristics and local operating experience is recommended when appropriately justified.").

²⁴ Polich Direct, Schedule 28 (RAD-D-28) at 11.

²⁵ For example, Polich Direct, Schedule 27 (RAP-D-27) at 4 ("Sampling and control range limitations are suggested on Figure 4-1."); RAP-D-27 at 10 ("If the addition of a downcomer sample is a burden to the utility, the utility may consider using the downcomer sample . . . as a matter of convenience."); Polich Direct, Schedule 28 (RAP-D-28) at 2 ("Sample points, monitoring parameters, target values, and action levels . . . may be modified as appropriate."); RAP-D-28 at 7 "Modification of portions of the Guidelines to reflect actual, plant specific design characteristics and local operating experience is necessary by all

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 The GE documents that Mr. Polich points to similarly state repeatedly that they
2 are “recommendations,” not requirements.²⁶ They also state up front that they
3 do “not purport to cover all details or variations in equipment nor to provide
4 for every possible contingency to be met in connection with installation,
5 operation or maintenance.”²⁷

6
7 Q. DOES MR. POLICH CLAIM THERE ARE “OTHER EXAMPLES” OF THE COMPANY’S
8 FAILURE TO ADEQUATELY MONITOR STEAM CHEMISTRY AT SHERCO 3?

9 A. Yes, but again he relies entirely on the ChemStaff Report for this claim rather
10 than on any independent review of underlying data or documents.²⁸

11
12 Q. HOW DO YOU RESPOND TO THESE “OTHER EXAMPLES”?

13 A. The list of Mr. Polich’s “other examples of Xcel’s failure to adequately monitor
14 steam chemistry at Sherco 3”²⁹ is simply a list of things he states that the
15 Company did not do, with no context or justification and no consideration of
16 what the Company *did* do. As such, he provides no basis to support a claim that
17 Xcel Energy had an unreasonable chemistry program at Sherco 3.³⁰ As I stated
18 above, EPRI’s industry guidelines are general guidelines on the whole water and
19 steam chemistry system of an idealized unit which must be adapted to individual
20 plant equipment and operating conditions. Based on my extensive experience

utility users.”); RAP-D-28 at 10 (“The purposes of these Guidelines are . . . to provide a document that can be used by utility personnel as a guide in setting up their own AVT operating guidelines for their own unique combination of units and current chemistry control.”); RAD-D-28 at 11 (“It is strongly recommended that these Guidelines be customized and modified to reflect local operation experience and conditions.”).

²⁶ Polich Direct, Schedules 25 and 30.

²⁷ Polich Direct, Schedule 25 at p.1; Polich Direct, Schedule 30 at p. 1.

²⁸ See Polich Direct, p. 46 line 6.

²⁹ Polich Direct, pp. 46-47.

³⁰ As I have stated, he also has no experience from which to judge the Company’s chemistry program.

**PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED**

1 and independent review, the Company’s water and steam chemistry program
2 for Sherco 3 fell well within the range of reasonable utility actions.

3 The list of Mr. Polich’s “other examples of Xcel’s failure to adequately monitor
4 steam chemistry at Sherco 3” is also riddled with unfounded claims and outright
5 falsehoods, which I address below.

6
7 **[PROTECTED DATA BEGINS**

8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25 **PROTECTED DATA ENDS]**

**PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED**

1 **[PROTECTED DATA BEGINS**

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

PROTECTED DATA ENDS]

**PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED**

1 **[PROTECTED DATA BEGINS**

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

PROTECTED DATA ENDS]

**PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED**

1 **[PROTECTED DATA BEGINS**

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

PROTECTED DATA ENDS]

**PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED**

1 **[PROTECTED DATA BEGINS**

2

3

4

5

6

7

8

9

PROTECTED DATA ENDS].

10

11 Q. HOW DO YOU RESPOND TO MR. POLICH’S CLAIM THAT “XCEL’S INTERNAL
12 REQUIREMENTS FOR WATER CHEMISTRY WERE NOT FOLLOWED AT SHERCO 3.”³¹

13 A. Here again, Mr. Polich points to a document and section titled
14 “recommendations” and takes the position that they are “requirements.” As Mr.
15 Wold acknowledged, the Company considered the need for a reheat sample and
16 determined that its existing program – specific to the unit and chemical
17 monitoring Sherco 3 already had in place – was sufficient to meet the goals of
18 the water and steam chemistry program.³² Based on my own extensive review
19 of the Company’s steam chemistry program and my knowledge of industry
20 guidelines, this was well within the range of reasonable utility actions.

21

22 Q. AT PAGES 50 AND 51, MR. POLICH AGAIN PROVIDES HIS INTERPRETATION OF
23 WHAT HE CALLS “CHEMSTAFF’S FINDINGS IN REGARD TO SHERCO 3’S WATER
24 CHEMISTRY PRACTICES.” HOW DO YOU RESPOND?

³¹ Polich Direct, p. 48.

³² Exhibit___(DGD-2), Schedule 4.

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 A. Again, Mr. Polich does not draw any conclusions from his own independent
2 review of available information, but instead summarizes the ChemStaff Report,
3 a Report he did not write or contribute to. Mr. Polich cites the GE Litigation
4 testimony of the Report’s author, Mr. Allmon, that “reviewing the available
5 Serco (sic) 3 data collected on sodium, Sherco 3 would have exceeded GE
6 guidelines for sodium 5% of the time and EPRI guidelines 6% of the time.”³³
7 The referenced statement refers to Mr. Allmon’s analysis of the main steam
8 sodium analyzer data to which he added a sodium contribution from the reheat
9 attemperation sprays to produce a “calculated” reheat steam result. He then
10 used this data to calculate the number of data points above the EPRI and GE
11 limits of sodium in the reheat steam. In his analysis, Mr. Allmon did not fully
12 account for elevated results due to sampling issues that occur during startup or
13 any instrument maintenance or calibration periods. Considering the number of
14 unit starts and the frequency of periodic maintenance and calibration required
15 on these instruments, if the data collected during these periods were to be
16 omitted, the resulting percentages above the normal limits are not what I would
17 consider unreasonable for an operating power plant. They certainly do not point
18 to a significant contamination event during this period or imprudent operation
19 on the part of Sherco.

20
21 Mr. Polich tries to quote the ChemStaff Report regarding the findings on cation
22 conductivity limits on the main steam sample.³⁴ A complete discussion of the
23 improper assumptions on which the ChemStaff Report relied in order to arrive
24 at these conclusions are detailed in my rebuttal expert report,³⁵ and in particular

³³ Polich Direct, p.50, lines 13-15.

³⁴ Polich Direct, Schedule 22 at p. 29.

³⁵ Exhibit___(DGD-2), Schedule 2 (to this Rebuttal Testimony).

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 its decision to include chemistry readings taken during unit starts and equipment
2 maintenance in his results, which Mr. Polich again does not even attempt to
3 address. In any event, the cation conductivity of the condensate, feedwater,
4 boiler water or steam are irrelevant to the Event. Chloride and sulfate
5 concentrations, which are approximated by cation conductivity, do not produce
6 caustic-induced stress corrosion cracking. Only the level of caustic in the steam,
7 which is approximated by the sodium concentration, is relevant here. And
8 despite what Mr. Polich claims, cation conductivity is not equal to the sodium
9 concentration in any sample.

10
11 Q. MR. POLICH DISMISSES THE THIELSCH REPORT DISCUSSION AND CONCLUSIONS
12 REGARDING THE COMPANY’S WATER AND STEAM CHEMISTRY PRACTICES AS
13 “NOT VALID” AND “WITHOUT MERIT.” DO YOU AGREE?

14 A. Absolutely not. Again, Mr. Polich did not himself actually review the Company’s
15 water and steam chemistry practices or data, and has no relevant experience
16 from which to form an opinion. In contrast, I have significant relevant
17 experience, I have reviewed all of the relevant data and documents, and I
18 conducted the chemistry analysis underlying, and agree with conclusions, of the
19 Thielsch Report. Mr. Polich gives no basis for his dismissal of the Thielsch
20 Report or his statement that the Thielsch Report “assumed the monitoring of
21 water chemistry at Sherco 3 was being performed properly, the water chemistry
22 monitoring and testing equipment was properly calibrated, and data was
23 obtained at the correct points in the feedwater and steam cycle.”³⁶

³⁶ Polich Direct, pp. 51-52.

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 The Thielsch Report did not make these assumptions. Rather, the Report relied
2 on my independent review and analysis of the water chemistry practices at
3 Sherco 3, my assessment of the equipment calibration, and my assessment of
4 the sufficiency of the steam cycle monitoring done by the Company.

5
6 Mr. Polich also asserts that the Thielsch Report could not be valid because
7 “Sherco 3 was unable to accurately monitor sodium levels of 6 ppb as
8 recommended by GE nor EPRI recommendations of 3-6 ppb.”³⁷ As I stated
9 above, this is simply wrong. The Company monitored sodium continuously at
10 Sherco 3 with on-line analyzers with a detection limit of 0.1 ppb Na at three
11 separate points in the cycle: the demineralizer effluent, the condensate pump
12 discharge, and in the boiler.

13
14 Next, Mr. Polich states that “Thielsch never verified the water chemistry
15 monitoring practices or equipment calibration practices of Sherco 3.” The
16 online chemistry analyzers were indeed routinely maintained and calibrated.
17 Evidence of this can be found in the calibration logbooks maintained by the
18 plant.³⁸ The reason for performing the grab samples was as a second check on
19 the on-line instruments.

20
21 The laboratory also calibrated the laboratory instruments they used including
22 the instrument (Flame AAS) used for measuring sodium in grab samples. In this
23 case, the instrument was calibrated every time before it was used. Here again,
24 Mr. Polich’s statement is completely at odds with the facts.

³⁷ Polich Direct, p.52 lines 7-8.

³⁸ The calibration logs are included as Exhibit____(DGD-2), Schedule 6.

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 Finally, the Thielsch Report ultimately concluded that the design by GE of the
2 turbines led to high stress during normal operation that led to the Event: “The
3 primary causal factor responsible for the stress corrosion cracking of the low-
4 pressure turbine L-1 disks was the high static stresses generated during normal
5 operation [which] are solely a function of the original design and operation at
6 design conditions. The water chemistry of Unit 3 conformed to EPRI guidelines
7 and was not a significant factor contributory to the stress corrosion cracking
8” Nevertheless, Mr. Polich misstates the conclusion of the Thielsch Report,
9 claiming that the Thielsch Report found that the cause of the Event was “pre-
10 existing SCC . . . likely caused by sodium hydroxide.”³⁹ There is no basis for
11 this mischaracterization of the Thielsch Report. Indeed, I understand that in
12 this case, Mr. Tipton’s testimony makes clear that that the Event would have
13 occurred even with *pure* steam.

14
15 Q. WHAT DOES MR. POLICH STATE IS HIS “CONCLUSION REGARDING THE IMPACT
16 OF SHERCO 3’S WATER CHEMISTRY PROGRAM ON THE SCC FAILURE” OF UNIT
17 3?

18 A. Mr. Polich purports to “conclude”:

19 Sherco 3 failed to monitor and control water chemistry within GE
20 and EPRI guidelines in accordance with good utility practice. This
21 resulted in chemical higher concentrations of caustic chemicals in the
22 steam flowing through the LP turbine and increased accumulation of
23 SCC inducing chemicals on the L-2 – L-0 stages of the LP turbine.
24 Xcel also failed to perform recommended inspections of the LP
25 turbine rotor disks in accordance with industry standards based upon
26 the level of chemicals in Sherco 3’s steam. Xcel should have
27 performed the LP rotor inspection and inspected the LP turbine rotor

³⁹ Polich Direct, p. 19, lines 8-10.

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 L-1 disk finger dovetails using MPI in 2011, which would have
2 discovered the high level of SCC and avoided the accident.⁴⁰
3

4 In his summary, Mr. Polich similarly claims:

- 5 1. Xcel was well aware of the importance of water chemistry and the
6 potential for poor water chemistry to cause stress corrosion cracking in
7 portions of the LP turbine.
- 8 2. Xcel did not maintain water chemistry in accordance with industry
9 recommended practices that resulted in sodium induced SCC in the LP
10 turbine rotor L1 disk.

11
12 Q. HOW DO YOU RESPOND?

13 A. I strongly disagree with Mr. Polich’s conclusions. *First*, it is important to note
14 again that Mr. Polich does not have the training, experience, or knowledge of
15 the relevant information in this case to draw *any* conclusion with regard to the
16 reasonableness of the water and steam chemistry program at Sherco 3. And Mr.
17 Polich does not actually present his own conclusions here, relying instead on a
18 report from a different expert, written and used in a different case in a different
19 jurisdiction. It is unclear why the Department chose not to present testimony
20 from ChemStaff, or any other chemistry expert. Mr. Polich’s attempt to render
21 testimony not based on his own review and analysis of the underlying facts runs
22 afoul of the standards for expert testimony.

23
24 *Second*, Mr. Polich is simply wrong with his main allegation that the Company
25 “failed to monitor and control water chemistry within GE and EPRI guidelines

⁴⁰ Polich Direct, p. 53

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 in accordance with good utility practice” or “did not maintain water chemistry
2 in accordance with industry recommended practices.” I have been in this
3 industry for over 40 years, I reviewed the Company’s steam chemistry program
4 for Sherco 3, and contrary to Mr. Polich’s conclusion, I can confidently state
5 that the Company complied with, and at times exceeded, water and steam
6 chemistry practices at similar large coal-fired units. Moreover, in my review of
7 the chemistry data, the Company maintained water chemistry for Sherco 3
8 within reasonable limits and were prudent operators. More important than the
9 number of on-line monitors and their locations was the overall importance the
10 plant gave to water and steam chemistry issues. The laboratory was present
11 during every startup of the unit following an outage (regardless of the time of
12 day or night it occurred). Operators were aware of and responded to water and
13 steam chemistry analyzer and equipment alarms. The laboratory always had
14 someone on call to answer questions or come out to the plant, and look at the
15 issue, firsthand as required. And, finally, a complete review of the water and
16 steam chemistry data showed that, during the period in question, Sherco 3 was
17 operated in such a way as to produce good steam purity.

IV. CONCLUSION

18
19
20
21 Q. PLEASE SUMMARIZE YOUR TESTIMONY.

22 A. My testimony focuses on the Company’s water and steam chemistry program
23 at Sherco 3 from 2000 through November 2011. I personally researched the
24 plant chemistry practices, analyzed the data, and interviewed plant personnel to
25 develop a thorough understanding of the Company’s chemistry practices
26 specific to Sherco’s Unit 3. Based on this research and analysis, I first explain
27 (1) that the Company’s practices at Unit 3 generally complied with, and in some

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

1 cases exceeded, industry practices at similar large, coal-fired units; (2) the
2 Company prudently operated and monitored the water and steam chemistry of
3 Unit 3; and (3) from 2000-2011 there were no significant acute or chronic
4 contamination events which would have sent contaminated steam to the turbine
5 sufficient to have prompted the Company to remove the L-1 blades to inspect
6 the finger dovetail attachments for cracks.

7
8 Next, Mr. Polich has none of the day-to-day experience or industry knowledge
9 that would qualify him to provide either a definition of “good industry
10 practices” for water and steam chemistry from 2000 to 2011 or provide qualified
11 testimony regarding whether the Company’s water and steam chemistry
12 practices met that definition. In particular, it does not appear that Mr. Polich
13 personally reviewed the available water or steam chemistry data for Sherco 3
14 before providing his testimony.

15
16 Finally, he has misinterpreted or misunderstood the information he has
17 reviewed, in particular the Thielsch Report, in order to reach what appear to
18 have been his foregone conclusions. In so doing, he has repeatedly manifested
19 his lack of understanding of basic water and steam chemistry concepts that
20 anyone should understand to qualify to testify in this area.

21
22 Q. DOES THIS CONCLUDE YOUR REBUTTAL TESTIMONY?

23 A. Yes, it does.

**Northern States Power Company, doing business as Xcel Energy
Information Request**

Docket No.: E002/GR-12-961, E002/GR-13-868; E999/AA-13-599;
E999/AA-14-579; E999/AA-16-523; E999/AA-17-492;
E999/AA-18-373; OAH 65-2500-38476
Sherco 3

Requestor: Xcel Energy - Tara R. Duginske, Assistant General Counsel, Xcel Energy
Requestor email: Tara.R.Duginske@xcelenergy.com
Requested from: Minnesota Department of Commerce – Richard A. Polich
Date of Request: August 9, 2023 Information Request No. 3
Response Due: August 21, 2023

Reference: Direct Testimony of Mr. Richard Polich

Question:

- a) State all education, degrees, coursework, memberships, etc. Mr. Polich has in the area of water chemistry.
- b) State all experience Mr. Polich has in operating, monitoring, evaluating, or analyzing water chemistry.
- c) State all experience Mr. Polich has in analyzing historical water chemistry data.
- d) Provide a list of all matters or cases in which Mr. Polich been offered as an expert in water chemistry.
 - i. Indicate if any of these matters or cases in which Mr. Polich has been offered as an expert in water chemistry involved the steam path in a fossil unit.
- e) Produce all reports, testimony, opinions and conclusions reached for each matter or case in which Mr. Polich has been offered as an expert in water chemistry.

Response:

- a) Mr. Polich does not have any degrees or specific course work in the area of water chemistry. Mr. Polich has taken college courses in chemistry, understands

- the fundamentals of proper water chemistry, and how it affects materials in the steam turbine. Mr. Polich does not have any memberships in water chemistry.
- b) Mr. Polich's experience with steam turbines are discussed in response to Xcel's Information Request No. 2. Some of that experience includes review of water chemistry impacts on plant operations and damage to plant equipment.
 - c) During the startup of Consumers Energy Campbell 3 power plant, Mr. Polich was part of the team assigned to determine the root cause of the super heater failure. Mr. Polich reviewed the water chemistry data as well as the boiler operational data. The final cause of the super heater failure, which had only been subject to steam conditions for three months, was boiler drum carryover during a power increase and subsequent plant shutdown shortly afterwards. Sodium in the boiler drum was carried over into the super heater and left deposits on the tubes. During the subsequent cooldown and the plant being idle for three days after the carryover, the boiler tubes experienced stress corrosion cracking in the weld areas. Upon startup, the welds failed resulting in the replacement of the superheater. Mr. Polich also analyzed water chemistry data for Plum Point power station as part of assessment of weld failure in the boiler economizer. In assessing the low pressure steam turbine last stage blade failure of Duke Energy Florida's Bartow combined cycle plant, Mr. Polich reviewed historical plant water chemistry data. Mr. Polich has also had discussions with plant personnel at a variety of power plants on water chemistry as it relates to various plant problems.
 - d) Mr. Polich has not provided direct testimony on water chemistry in regulatory proceedings because the equipment failure presented in his testimony was not related directly to water chemistry. As part of his investigation into equipment failures, Mr. Polich has reviewed water chemistry because of its potential to impact material failure.
 - e) Not applicable.

Preparer: Richard A. Polich
Title: Managing Director
Department: Power Supply
Telephone: 501-316-9805
Date: August 21, 2023

PUBLIC DOCUMENT
NOT-PUBLIC DATA HAS BEEN EXCISED

Northern States Power Company

MPUC Docket No. E999/AA-18-373, et al.
OAH Docket No. 65-2500-38476
Exhibit____(DGD-2), Schedule 2

Schedule 2

Exhibit____(DGD-2), Schedule 2 has been marked Not-Public in its entirety. This Schedule was provided by M&M Engineering Associates, Inc. and responds to a report by William Allmon (Allmon Report), on behalf of General Electric (GE) and subject to a confidentiality agreement. GE considers the Allmon Report to constitute confidential and proprietary information to GE. Therefore, the Company considers this Schedule to be trade secret data as defined by Minn. Stat. § 13.37(1)(b) and Xcel Energy maintains this information as a trade secret pursuant to Minn. Rule 7829.0500, subp 3.

Pursuant to Minn. R. 7829.0500, subp. 3, the Company provides the following description of the excised material:

1. **Nature of the Material:** Rebuttal to Expert Opinion of William Allmon Regarding the Effects of Chemistry Control on the Failure of the LP Turbine of Sherco Unit 3
2. **Authors:** David G. Daniels, M&M Engineering Associates, Inc.
3. **Importance:** Responds to confidential and proprietary information of GE and that is subject to a confidentiality agreement between the Company and GE.
4. **Date the Information was Prepared:** March 25, 2016

1 STATE OF MINNESOTA DISTRICT COURT
2 COUNTY OF SHERBURNE TENTH JUDICIAL DISTRICT
Case Type: Property Damage
3

4 AEGIS INSURANCE SERVICES, LTD., AND OTHER INTERESTED INSURERS AS SUBROGEEES OF NORTHERN STATES POWER CO. AND SOUTHERN MINNESOTA MUNICIPAL POWER AGENCY,
5
6
7
8 Plaintiffs,
9 vs. VOLUME IX
10 GENERAL ELECTRIC COMPANY; GENERAL ELECTRIC INTERNATIONAL, INC.; GE ENERGY SERVICES, INC.,
11
12 Defendants.
13

14
15 The above-entitled matter came duly on for
16 trial before the Honorable Sheridan Hawley, one of the
17 judges of the above-named court, on October 26, 2018, at the
18 Sherburne County Courthouse, Elk River, Minnesota.
19
20
21
22
23
24
25

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25

TABLE OF CONTENTS

PAGE

WILLIAM ALLMON

Continued Direct Examination By Mr. Schupp	1558
Cross-Examination By Mr. Berglund	1622
Redirect Examination By Mr. Schupp	1698
Recross-Examination By Mr. Berglund	1702

EXHIBITS

<u>Exhibit</u>		<u>Marked</u>	<u>Offered</u>	<u>Received</u>
1168		1561	1561
1169		12	1565
1171		1567	1567
1172		1577	1577
1173A		1580	1580
1173E		1587	1587
1174A-D		1590	1590
1174B		1620	1620
1174E-F		1595	1595
1175		1607	1608
1176A		1611	1611

William Allmon Continued Direct Examination by Mr. Schupp

1 truncated data, Action Level 3, the plant would have,
2 according to the EPRI guidelines, been shut down
3 within four hours. In the Action Level 2, the plant
4 should have been shut down within 24 hours, and in
5 Action Level 1 here, the plant should have been
6 shutdown within a week. So we have lots of periods
7 here where the plant should have been shut down based
8 on main steam sodium and it was not.

9 Q. And then 1174F?

10 A. So I calculated --

11 Q. Go ahead. Tell us what this chart shows. It says,
12 calculated reheat steam sodium?

13 A. Yes. This is calculated reheat steam sodium.
14 Essentially, it adds the attemperator sodium in for
15 the reheat steam that is not accounted for in main
16 steam.

17 Q. Is there much of a difference?

18 A. No.

19 Q. All right. So did you do an action level analysis on
20 what sodium measurements did exist?

21 A. Yes, I did.

22 Q. And can you refer to your -- refer to your report and
23 tell us what your analysis showed?

24 A. Yes, so the -- in that 12-and-a-half year period they
25 exceeded the GE limits for 774 hours, which is about

CONFIDENTIAL - SUBJECT TO PROTECTIVE ORDER

1

1 STATE OF MINNESOTA DISTRICT COURT

2 COUNTY OF SHERBURNE TENTH JUDICIAL DISTRICT

3 Case Type : Property Damage

4 - - - - -

5 NORTHERN STATES POWER COMPANY;
6 SOUTHERN MINNESOTA MUNICIPAL
7 POWER AGENCY; AEGIS INSURANCE
8 SERVICES, LTD. and other Interested
9 Insurers as subrogees of Northern
10 States Power Company,

Plaintiffs,

vs. Case No. 71-CV-13-1472

11 GENERAL ELECTRIC COMPANY;
12 GENERAL ELECTRIC INTERNATIONAL,
13 INC.; GE ENERGY SERVICES, INC.; and
14 GE ENERGY CONTROL SOLUTIONS, INC.,

Defendants.

15 - - - - -

16 DEPOSITION OF DUANE S. WOLD
17 VOLUME I, Pages 1 - 260
18 DECEMBER 16, 2015

19 (The following is the deposition of DUANE
20 S. WOLD, taken pursuant to Notice of Taking
21 Deposition, via videotape, at the offices of Gaskins
22 Bennett Birrell Schupp, LLP, 333 South Seventh
23 Street, Suite 3000, in the City of Minneapolis, State
24 of Minnesota, commencing at approximately 8:57
25 o'clock a.m., December 16, 2015.)

CONFIDENTIAL - SUBJECT TO PROTECTIVE ORDER

140

13:22:14 1 with would be NQ 810131.

13:22:23 2 Q. Okay. And what's the title of that?

13:22:25 3 A. And the title is "Piping and Instrument

13:22:30 4 Diagram, Reheat Steam."

13:22:32 5 Q. Okay. Thank you.

13:22:33 6 (Witness handing documents to counsel.)

13:22:42 7 Q. But in any event, after receiving the e-mail

13:22:46 8 on EPR 5.736G, you didn't start monitoring the reheat

13:22:52 9 steam differently than -- Strike that. You hadn't --

13:22:56 10 You didn't start monitoring the reheat steam

13:22:58 11 after receiving that; right?

13:22:59 12 A. No.

13:23:01 13 Q. You continued to monitor the main steam, and

13:23:07 14 what you did is you added a continuous sodium monitor

13:23:11 15 after this; right?

13:23:15 16 A. Yeah. On main steam.

13:23:17 17 Q. Right.

13:23:17 18 And is the reason you added that, is that

13:23:20 19 because of receiving EPR 5.736G?

13:23:29 20 A. No. I think we had -- I actually a year or

13:23:34 21 two earlier put in for it, capital money for a sodium

13:23:39 22 analyzer, but didn't get it. And so we put it in

13:23:43 23 again and then got it in 2008.

13:23:47 24 Q. So you were looking at adding a main steam

13:23:49 25 sodium analyzer earlier, and it just was coincident

CONFIDENTIAL - SUBJECT TO PROTECTIVE ORDER

141

13:23:54 1 that you received this in 2008 and added the sodium --

13:23:54 2 A. Yeah.

13:23:57 3 Q. -- analyzer in 2008?

13:23:59 4 A. Yeah.

13:24:00 5 Q. Okay.

13:24:00 6 A. And the...

13:24:07 7 Again, you know, it -- I want to emphasize

13:24:10 8 that in my tenure there I do not believe that we

13:24:16 9 exceeded the sodium levels in the steam drum --

13:24:20 10 Q. You're talking about the boiler --

13:24:20 11 A. Yep.

13:24:22 12 Q. -- when you talk about the drum; right?

13:24:24 13 A. Yep.

13:24:25 14 And the amount of attemperator steam or

13:24:29 15 water that you use is a very small percentage which

13:24:33 16 would not considerably add to sodium levels that would

13:24:37 17 carry over into the turbine. So my -- the whole

13:24:44 18 premise of -- of recommendations is to try to be as

13:24:49 19 prudent as you can but be as -- as -- from a economic

13:24:55 20 standpoint, and at the same time try to weigh the

13:24:59 21 fruits of benefit to the operation of the plant.

13:25:04 22 And so if they're recommendations, like

13:25:08 23 these are, you have to put those into the budgetary.

13:25:12 24 If they're imminent crisis things that, you know, a

13:25:16 25 memo is coming up with a red flag and it's blinking at

CONFIDENTIAL - SUBJECT TO PROTECTIVE ORDER

142

13:25:21 1 me you're going to have imminent failure if you don't
13:25:23 2 do this and follow it to the letter, I wouldn't do it.

13:25:29 3 Q. Well according to your thinking then the
13:25:31 4 only places we -- you'd need to monitor would be the
13:25:34 5 boiler and the condensate pump discharge?

13:25:38 6 A. I think you could meet the 2 ppb sodium
13:25:43 7 level at the steam if you monitored the -- the
13:25:46 8 condensate pump discharge coming out of the condenser
13:25:50 9 and you monitored the boiler water and you followed
13:25:53 10 the -- the EPRI guideline limits. They're all based
13:25:57 11 on -- on good technical science.

13:26:00 12 Q. Umm-hmm. Okay.

13:26:08 13 MR. SCHUPP: Would you mark this as the
13:26:09 14 next one.

13:26:21 15 (Exhibit 347 marked for identification.)

13:26:21 16 BY MR. SCHUPP:

13:26:24 17 Q. You seen this document before, Mr. Wold?


13:26:34 18 A. (Witness reviewing exhibit.) I can't tell
13:27:30 19 you if I've seen it before or not.


13:27:31 20 Q. Okay. Let's just go through the information
13:27:34 21 and see if it's accurate. The first line says, Na,
13:27:38 22 sodium online analyzer (initially 2) located on
13:27:41 23 condensate pump discharge and boiler, main steam added
13:27:44 24 2008.

13:27:45 25 That's an accurate statement; isn't it?

Figure 1b

Diagram of Unit 3's Steam Cycle Identifying Chemical Monitoring Locations





Wold 000001

3

9-2-87 CKF,CMK	Both unit One and Two SPD Silica Analyzers were took apart the Delay blocks were Soaked, and new tubing was put in service, and Instruments were calibrated.
9-3-87 CKF,CMK	Hydrazine Analyzer probe on unit #1 was replaced and regelled. Unit #2 probe was regelled.
9-2-87 CKF,CMK	Sodium Sleds were calibrated and new filters and Reagent were put in CPS Analyzers on Both Units.
9-4-87 CKF,CMK	Sodium Sleds were calibrated and new Filters and Reagents were put in Boiler Analyzers on Both Units.
9-14-87 CKF,CMK	Sp. Cond. Cell for unit one Economizer was cleaned.
9-18-87 CKF,CMK	Cleaned delay blocks of #31 & #32 Silica analyzers with 115 NH ₄ OH. Also replaced tubing for reagents and sample port.
9-21-87 CKF,CMK	Calibrated #31 & #32 Sodium analyzers. Replaced diffusion tubing and monoethylamine solution prior to calibration.
9-17-87 CKF,CMK	Etched #31 & #32 Sodium analyzer probes. Refilled reference electrode solutions.

Wold 000003

10/2/87 CKF, CMK	Calibrated #32 Sodium Analyzer.
10/2/87 CKF, CMK	Placed new ^{robo} probe in Hydrazine analyzer #31. Calibrated Analyzers.
10/3/87 CKF, CMK	Calibrated #11, #21 Sodium Analyzers. Replaced tygon tubing and soaked delay blocks in the KOH solution for #11, #21 Silica Analyzers.
10/5/87 CKF, CMK	Calibrated #11, #21 Sodium Analyzers.
10/9/87 CMK	Replaced Light Bulb in #31 CPD Silica Analyzer.
10/11/87 CMK	Realigned Lamp in #31 CPD Silica Analyzer and Calibrated.
10/11/87 CMK	Calibrated #32 Sodium Analyzer.
10-28-87 CMK	Cleaned anodes and cathode on unit's one and two and the potable Dissolved Oxygen analyzer probes.
11/3/87	New electrode on the Amperometric chloride titrator
11-9-87	Found lamp in 11 Silica Analyzer burnt out. Replaced lamp & calibrated it 1300 hrs. Checked flows, etc prior to calibration.

Wold 000004

11-10-87 #12; #21; & #22 Sodium Analyzers were taken out of service for the following:
 etched the Na⁺ electrode
 rinsed & cleaned the reference electrode
 replaced diffusion tubing
 replaced monoethylamine jar

11-12-87 Calibrated #12 & #22 Sodium Analyzers

11-13-87 Calibrated #21 Sodium Analyzer
 Calibrated #21 Silica Analyzer

11-18-87 #11; #31 Sodium Analyzers were taken out of service for the following:
 etched Na⁺ electrode
 rinsed & cleaned the reference electrode
 replaced diffusion tubing
 replaced monoethylamine jar

11-19-87 Calibrated #11 & #31 Sodium Analyzers

11-18-87 Soaked & cleaned mixing blocks on 32 Silica analyzer. Checked flows & adjusted sample flow thru mixing block to 5ml/min. Calibrated & put back into service.

11-19-87 Soaked & cleaned mixing blocks on 31 Silica analyzer.
 Calibrated & put back into service.

Wold 000005

6

11-21-87 RAC	Replaced diffusion tubing and Seelde solution in Hydrazine analyzer # (Unit #3). Found old solution out and diffusion tubing in backwards.
11-30-87	Regelled cell & calibrated Hydrazine analyzer Unit 1
11-30-87	Regelled cell, replaced pleated capsule filter & calibrated Hydrazine analyzer Unit 2
11-24-87	Replaced diffusion tubing, iodine solution, and etched electrode, then calibrated Unit 3 Hydrazine analyzer.
12-3-87	Calibrated CPD 1 & CPD 2 Silica analyzers
12-4-87	Soaked mixing blocks, cleaned capillaries & calibrated 31 Silica analyzer.
12-7-87	Found the mixing (2 nd one) block had a leak near the plug site on 31 SiO ₂ analyzer. It was repaired with epoxy, cleaned, calibrated & put back in service.
12-8-87	Soaked mixing blocks, cleaned capillaries & calibrated 11 & 21 Silica analyzers
1-11-88 CKF	Replaced O-rings, diffusion tubing and solution, and in-line filters for #31 and #32 Sodium Analyzers. * these two monitors still need to have the Na ⁺ electrodes and etched & then required calibration.

Wold 000006

1/15/88 RLM	Unit 1+2 CPD Na Sleds calibrated New electrodes on Unit 2 only. Replaced reagent, tubing, filter, ref. solution
1/19/88 RLM	Unit 1+2 Boiler Na Sleds calibrated Replaced electrodes, reagent, tubing, filter, ref. solution
1/20/88 RLM	Unit 3 Sodium Sleds (CPD + Boiler) Electrode maintenance and calibration
2/24/88 RLM	Changed membrane and electrolyte, polished cathode, cleaned anode. Unit 1+2 orbisphere O ₂ cells.
3-28-88	Did an auto calibration on Unit 1 O ₂ electrode
6-1-88 CKF	Replaced diffusion tubing & iodine solution, reference electrode, and inlet filter for 31 NaH ₄ analyzer. Calibrated instrument. Also replaced o-rings.
6-1-88 RAC	Unit #2 Sodium Analyzer - CPD & Boiler rebuilt. Diffusion tubing replaced, solution replaced, filter replaced, column replaced.
6-2-88 RAC	Calibrated CPD & Boiler Sodium Analyzers Unit #2 Rebuilt Unit #2 Hydrazine probe. Replaced tubing, cleaned blocks and cleaned analyzers for Boiler and CPD Unit #2 Silica

Wold 000007

8

6-6-88 Calibrated Unit #2 Boiler and CPD
 RAC Silica Analyzers. Note flow going through them
 and all reagent tanks cleaned and filled with
 new chemicals. R.A.C.

6-29-88 Replaced Resin Column (and) Diffusion tubing & Soln,
 RAC on Unit #1 Boiler & CPD Sodium Analyzers.
 Replaced CPD reference and Na probe.
 ? Ask Roger

6-30-88 Calibrated Unit #1 Sodium analyzers.
 RAC They seemed to have come in at
 appropriate values, system seems OK

7/7/88 Replaced diffusion tubing and iodine solution;
 CKF polished iodide probe; calibrated
 #31 Hydrazine Analyzer.

7/7/88 Performed the following maintenance on #31
 and #32 Sled Sodium Analyzers:
 - replaced or rings and fuse
 - replaced diffusion tubing and solution
 - replaced in-line filters
 - installed new sodium and reference electrodes

7/8/88 Calibrated #31, #32 Sled Sodium Analyzers.
 CKF

7/11/88 Calibrated and checked reagent levels
 CKF of #21, #22 Sled Sodium Analyzers.

Wold 000008

7/11/88 CKF	Rebuilt Unit #1 Hydrazine cells.
7/11/88 CKF	Cleaned and calibrated 31, 32 Silica analyzers. 31 Silica analyzer not calibrating Full range → will investigate further.
7/12/88 CKF	Cleaned delay blocks and calibrated 21, 22 Silica analyzers.
7/13/88 CKF	Cleaned delay blocks and calibrated 11, 12 Silica analyzers.
7/14/88 CKF	Buffered Unit #1 pH probes for boiler and economizer Continuous probe pH meter. Replaced reference and measuring electrodes for Unit #2 boiler and economizer Continuous probe pH meter.
7/27/88 CKF	Calibrated #11, #12 Sted Sodium Analyzers.
8/3/88 CKF	Cleaned and calibrated 31, 32 Silica analyzers.
8/3/88 CKF	Replaced o-rings, diffusing tubing, iodide sol'n, and polished iodide probe on #31 Hydrazine analyzer.

Wold 000009

10

8/4/88 CKF	Filled reagents and calibrated # 31, # 32 Sodium Analyzers.
	Calibrated # 31 Hydrazine Analyzer.
8/10/88 CKF	Replaced in-line filter, o-rings, fuse, diffusion tubing and solution; and etched sodium electrodes for # 21, # 22 Sodium Analyzers.
	Replaced burnt out light bulbs for # 21 Silica analyzer.
8/11/88 CKF	Calibrated # 21, # 22, # 12 Sodium Analyzers.
8/22/88 CKF	Rebuilt and cleaned Unit 1 & 2 Dissolved Oxygen probes. New membranes installed also.
8/24/88 CKF	Replaced in-line filter, o-rings, fuse, diffusion tubing and solution; and etched sodium electrode for # 11, # 12 Sodium Analyzers.
8/24/88 CKF	Working with I & C to straighten out calibration problems with # 31, # 32 Silica analyzers.
8/25/88 CKF	Worked on

Wold 000010

8/25/88 CKF	Calibrated #11, #12 Sodium analyzers.
8/25/88 CKF	Calibrated Units 1 & 2 Dissolved Oxygen monitors.
8/29/88 CKF	Replaced in-line filter, o-rings, diffusion tubing and solution for # 31 Hydrazine analyzer. Polished Iodide electrode.
8/29/88 CKF	Replaced o-rings, diffusion tubing and solution for # 31, #32 Sodium analyzers.
8/29/88 CKF	Cleaned rebuilt, and calibrated Unit #3 D.O. probe and portable D.O. probe.
8/30/88 CKF	Calibrated # 31 Hydrazine Analyzer. Calibrated # 31, #32 Sodium Analyzers.
9-8-88 MTB	Calibrated # 31 SiO ₂ Analyzer
9-20-88	Standardized 11, 12 21, 22 31, 32 SiO ₂ Analyzers
10-6-88	Cleaned delay blocks and cal'd 162 SiO ₂ analyzers

Wold 000011

12

10-18-88	Cleaned delay blocks and calibrated U3 CPD SiO_2 analyzer
10-20-88	cleaned delay blocks and calibrated U3 Brier SiO_2 analyzer
10-23-88	New diffusion tubing - o-rings and solution calibrated #12 NH_4^+ Analyzer CPD
10-25-88	Replaced μA and reference electrodes on Econ Inlet
10-26-88	Replaced o-rings, diffusion tubing and solution for 31 & 32 Selenium analyzers
10-26-88	Standardized 31 & 32 SiO_2 Analyzers
11/15/88	STANDARDIZATION COMPLETED ON: UNIT 3 31, 32 SILICA ANALYZERS UNIT 2 21, 22 SILICA ANALYZERS UNIT 1 11, 12 SILICA ANALYZERS NOTE: BULB BURNED OUT ON 22
11/21/88	REPLACED BULB & DESICCANT ON 22 SiO_2 ANALYZER (CPD)

Wold 000012

13

11/22/88 REBUILT NO. 31 HYDRAZINE ANALYZER
USED 4-DECADE PROCEDURE (SLED)
REPLACED: IODIDE ELECTRODE
FILTER ASSEMBLY
REAGENT DIFFUSION BOTTLE
AND TUBING
DEIONIZATION CARTRIDGE

12/12/88 #21 SiO₂ ANALYZER CLEANED
& STANDARDIZED

12/13/88 CLEANING & STANDARDIZATION COMPLETED
ON #31, #32 SILICA ANALYZERS

12/22/88 OVERHAULED & CALIBRATED SODIUM
(SLED) ANALYZERS ON UNIT 2 (BOILER + CPD)
CHANGED OUT: MONOETHYLAMINE BOTTLE + TUBING
FILTER
PH + REF. PROBES

12/22/88 CALIBRATED UNIT 1 SODIUM SLED
ANALYZERS (BOILER + CPD)

12/28/88 STANDARDIZED #31, #32 SILICA ANALYZERS

Wold 000013

14

1/6/89 CKF	Replaced lamp on #11 Silica Analyzer.
1/9/89 CKF	Rebuilt hydrazine cell on Unit 2 hydrazine analyzer.
1/11/89 CKF	Filled diffusion solution and checked reference electrode solution, then calibrated 31, 32 Sodium Analyzers.
1/17/89 CKF	Filled diffusion solution and changed tubing on 31 Hydrazine analyzer.
1/13/89 CKF	Cleaned delay blocks for #31, #32 Silica analyzers.
1/24/89 CKF	Filled reagent levels for #21, #22 Sodium analyzers. Replaced o-rings, diffusion tubing, and reagents for #11, #12 Sodium analyzers.
1/30/89 CKF	Calibrated #11, #12, #21, and #22 Sled Sodium analyzers.
3/13/89 CKF	Rebuilt, retubed, and cleaned #31, #32 Silica analyzers.

Wold 000014

3/15/89 CKF	Replaced o-rings, diffusion tubing, diffusion solution, and in-line filters for # 31, # 32 Sodium Analyzers and # 31 Hydrazine analyzer. Etched # 31, # 32 Sodium measuring electrodes. Replaced # 31 Hydrazine Iodide and reference electrodes.
3-16-89 RLM	Calibrated # 31, # 32 Na Steds. and # 31 N_2H_4 Sted
3-20-89 CKF	Replaced o-rings, diffusion tubing, diffusion solution, and in-line filters for # 11, 12, 21, 22 Sodium Analyzers. Etched # 11, 12, 21, 22 sodium electrodes.
3-21-89 CKF	Calibrated # 11, 12, 21, 22 Sodium Steds.
4-10-89 SSB	Cleaned; filled reservoirs, checked flows; & calibrated SiO_2 analyzers: 21; 22; 11; & 12.
4-11-89 SSB	cleaned & regelled Unit 2 N_2H_4 analyzer cell. Replaced pleated capsule filter & tubing.
4-27-89 DSW	31 & 32 SiO_2 analyzers; cleaned & calibrated.

Wold 000015

5-1-89	Replaced Unit 1 N_2H_4 analyzer pleated capsule filter. I was going to regel the cell, but there was no powder available.
5-2-89	Filled reagents bottles & calibrated Na^+ SLEDS: 11; 12; 21; 22; (31; 32) 5-4-89
5-3-89	Regelled cell on 11 N_2H_4 analyzer. Calibrated 5-4-89
5-10-89 CKF	Cleaned & calibrated # 31, 32 Silica analyzers.
5-11-89 RLM	Dissolved Oxygen Monitors Unit 1, 2, + 3 electrodes rebuilt and calibrated. Portable Monitor done in April
5-15-89	Cleaned & calibrated Silica analyzers: 11; 12; 21 & 22.
5-19-89	Cleaned & Calibrated Silica analyzers; 31 & 32
5-31-89	Calibrated 31 SiO_2 analyzer
6-2-89	Cleaned & Calibrated SiO_2 analyzers; 11-12-21-22.
5-31-89	Cleaned mixing block; capillaries; cell on 32 SiO_2 analyzer. Added a splashguard behind the mixing blocks & calibrated it.

Wold 000016

4-89

6-5-89 Etched Hydrazine Electrode; Cleaned N_2H_4 ref. elec.; retubed & replaced Iodine bottle and calibrated Unit 3 Hydrazine analyzer.

6-13-89 Etched Na electrode; replaced ref. elec. sol.; replaced diffusion tubing; replaced O-rings. Calibrated 32 Na analyzer (Boiler).

6-15-89 Etched Na electrode; replaced diffusion tubing & O-rings. Calibrated 31 Na analyzer (CPD).

6-14-89 Cleaned mixing blocks & cell on 31 SiO_2 analyzer. Changed Molyb. capillary. Added a splashguard behind the mixing blocks. Calibrated (long form).

6-20-89 Recalibrated Boiler Sodium SLED Unit 3.

6-21-89 #12 Silica Analyzer:
Soaked mixing blocks & sample cell
Replaced ALL tygon tubing
New capillary tubes for reagents.
Fresh reagents in reservoirs
Replaced colorimeter lamp
Calibrated - also new reagent^{tank} filters.

6-22-89 #21 Silica Analyzer
Same as #12 SiO_2 analyzer on 6-21-89 except I didn't change the capillaries, only cleaned them. Calibrated.

Wold 000017

6-22-89	SiO ₂ analyzer 31 & 32: Soaked & cleaned mixing blocks & sample cell & capillaries. Calibrated both Had I & C check the colorimeter on Blr.
6-23-89	Regelled the cell in Unit 1 Hydrazine Analyzer. It needs a new pleated capsule filter.
6-27-89	Regelled the cell in Unit 2 Hydrazine Analyzer.
6-28-89	Etched Na ⁺ electrode; replaced diffusion tubing, O-rings, replaced in-line filter & deionizing cartridge on 21 Boiler Na SLED.
7-3-89 CKF	Replaced electrodes (Iodide & Reference), replaced diffusion tubing, solution, and O-rings on 31 Hydrazine analyzer. Calibrated instrument.
7-5-89	Recalibrated (31) Hydrazine analyzer.
7-6-89	Replaced Deionization Cartridge on 31 Hydrazine analyzer and recalibrated instrument.
7-11-89	Etched Na ⁺ electrode; replaced diffusion tubing, monoethylamine solution, orings, and in-line filter for 12 & 22 Sodium Sled Analyzers.

Wold 000018

7-13-89	Calibrated # 12, # 22 Sodium Analyzers
7-19-89	Replaced deionization cartridge, diffusion tubing and solution, in-line filter, Na ⁺ electrode, and reference electrode for # 11 Na sled Analyzer. Etched new Na ⁺ electrode.
7-20-89	Calibrated # 11 Na Sled Analyzer Replaced in-line filters on # 31, # 32 Na ⁺ sleds. Cal Filled monoethylamine jars for # 31, # 32 Na ⁺ sleds. Calibrated # 31, # 32 Na ⁺ sleds.
7-25-89	Cleaned & calibrated # 31, # 32 silica analyzers
7-27-89	Filled monoethylamine solution # 21 Sled Sodium analyzer and calibrated instrument. Calibrated # 11, # 21 Boiler Silica Analyzers.
8-2-89	Replaced diffusion tubing, solution, & o-rings, and calibrated 31 N ₂ H ₄ analyzer.
8-2-89 CK	Calibrated # 21 Sodium analyzer following a unit outage.
8-9-89	Silica Analyzers → cleaned & calibrated # 11 & # 21 # 31 & # 32

Wold 000019

20

8-16-89	#31 Hydrazine Analyzer - Had I&C check out electronics on block thermistor and monitor module. Found corrosion of some degree on most connections. They cleaned it & I calibrated it.
8-16-89	cleaned & calibrated #11 & #21 Boiler Silica analyzers.
8-17-89	#31 & #32 Silica Analyzers The precipitate on the mixing blocks is rapid & very annoying. I called HACH-tech services & they don't know why it's happening. Cleaned & calibrated both of them. I turned the vent fan around on the Boiler Silica analyzer. I suspect the fumes from the Iodine reagent on the N ₂ H ₄ SLED may be contributing to the precipitate problem.
8-22-89	Serviced the Unit 2 Orbisphere probe & calibrated it.
8-23-89	Unit 1 Hydrazine Analyzer Replaced pleated capsule filter; regelled cell. Calibrated 8-24-89
8-24-89	Serviced the Unit 3 Orbisphere probe. Instrument was reading negative numbers. Servicing <u>didn't</u> help. MWR to I&C for electronics check. 8-29-89

Wold 000020

8-29-89	Cleaned & calibrated #31 Silica Analyzer
8-30-89	Cleaned & calibrated #32 Silica Analyzer
9-5-89	#31 & #32 Sodium SLED's; Changed Deionization Cartridge Installed new Na ⁺ electrode & reference electrode Replaced diffusion tubing Topped off the reagent bottle - No stock available Replaced O-rings
9-6-89	Calibrated #31 & #32 Na ⁺ SLED's
9-6-89	#22 Sodium SLED (CPD) Replaced O-rings; replaced diffusion ^{tubing} ; Etched Na ⁺ electrode; replaced reference elec. solution; topped off reagent bottle.
9-7-89	Calibrated #22 Sodium SLED (CPD) Recalibrated #31 Sodium SLED - reading negative.
9-7-89	#31 Hydrazine SLED Etched Iodine electrode Replaced: ref. electrode filling solution diffusion tubing iodine reagent bottle reagent bottle; cap; o-rings; lg. o-ring O-ring on electrode holder Calibrated it.

Wold 000021

22

9-8-89	Recalibrated #31 Hydrazine Analyzer
9-8-89	Cleaned and calibrated #31 & #32 Silica. Turned vent fan on Boiler back to original design.
9-12-89	Replaced cell in Unit 2 Hydrazine Analyzer.
9-12-89	Cleaned sample cell on silica Analyzers: 11; 12; 21; & 22 and calibrated them.
9-13-89	#12 Sodium SLED: (CPD) Calibrated 9-14-89 Replaced Na^+ electrode (etched) - twice Replaced reference electrode Topped off reagent bottle Changed O-rings on electrodes only
9-13-89	#11 Sodium SLED (Boiler) Calibrated * Replaced diffusion tubing Cleaned ref. ref. elec. & replaced filling solution Etched Na^+ electrode Topped off reagent bottle
9-13-89	#21 Sodium SLED (Boiler) Etched Na^+ electrode Cleaned ref. elec. & replaced filling solution Replaced diffusion tubing Topped off reagent bottle Calibrated.
	Monoethylamine reagent was short for this month. Not enough for 6 analyzers.

Wold 000022

23

9-15-89	#21 Sodium Analyzer (Boiler)
RLM	Put in a new measuring electrode
9-19-89	Installed new reference electrode in #21 SLED
9-20-89	Calibrated #21 Sodium SLED (Boiler).
9-20-89	Installed new pH & reference electrodes on Unit 2 Economizer Inlet.
9-26-89	Cleaned & calibrated #31 & 32 Silica Analyzer
9-26-89	#12 Silica Analyzer Had lost flow at some time. I cleaned the mixing cell & recalibrated it. Put in an MWR for I&C to change the needle valve on the solenoid.
9-27-89	Found the solenoid on the #11 Polisher to #12 Silica is leaking by & causing part of the problem in the flow for #12 SiO ₂ . I&C will repair - next week. #12 cleaned & calibrated again.
9-27-89	The backpressure & shut-off valves for the Unit 1 Dissolved Oxygen monitor need repair or replacement. MWR written.
9-27-89	Replaced the pH measuring & reference electrodes for Unit 1 Economizer Inlet.

Wold 000023

10-3-89	Rebuilt the Orbisphere probes on Unit 3 and for the portable.
10-4-89	Found, after extensive testing, that the O ₂ sensing probe for the Unit 3 Orbisphere, is not working. There was moisture <u>inside</u> the housing. Kevin Lalloi is working on it.
10-4-89	
10-4-89	Cleaned and calibrated #31 & 32 Silica analyzers. USE ROOM TEMP DI H ₂ O!
10-19-89 OKF	Cleaned # 31 & # 32 Silica analyzers. Soaked blocks in 20% Ammonium Hydroxide Solution.
10-24-89	Replaced diffusion tubing, o-rings, and diffusion solution on # 31 Hydrazine analyzer. Polished iodide electrode. Calibrated instrument. Replaced in-line filter.
10-25-89	Replaced in-line filters on 11, 12, 21, 22, 31, 32 Sodium Analyzers. Replaced gray cap, o-rings, and diffusion tubing on # 32 Sodium analyzers. Filled monoethyleneamine containers on 11, 12, 21, 22, 31, 32 Sodium analyzers. Calibrated 11, 12, 22, 31, 21, 32 Sodium Analyzers.

Wold 000024

25

10-27-89	Cleaned and rebuilt Units 1, 2, 3 Dissolved oxygen probes. Calibrated D.O. analyzers on units 1, 2, 3.
11/3/89	Replaced tubing and capillaries for # 31, # 32 Silica analyzers. Soaked and cleaned blocks in NHyot solution. Calibrated instruments
11/9/89	Retubed 11, 12, 21, 22 Silica analyzers. Wiped down instruments, rinsed blocks and calibrated 11, 12, 21, 22 Silica analyzers.
11/20/89	Replaced o-rings, diffusion tubing, and solution for # 31 Hydrazine analyzer. Re Polished the Iodide electrode and refilled reference electrode.
11/28/89	Replaced o-rings, diffusion tubing, and solution for 11, 12, 21, 22 Sodium analyzers. Replaced reference and measuring electrodes and gray cap for # 2 CPD sodium analyzer. Replaced ion exchange cartridge for # 1 CPD sodium analyzer. Etched sodium electrodes for 11, 12, 21, 22 analyzers.

Wold 000025

26

11/29/89	Calibrated 11, 12, 21, 22 Sodium analyzers. Replaced O-rings, diffusion tubing and solution for # 31 sodium analyzer. Etched sodium electrodes for # 31, 32 Sodium analyzers.
11/30/89	Calibrated # 31, 32 sodium analyzers
12/6/89	Cleaned delay blocks and soaked them in ammonium hydroxide solution for # 31, # 32 Silica analyzers. Calibrated # 31, # 32 Silica analyzers.
12-14-89	Cleaned the mixing cells & calibrated Silica Analyzers: # 12, 11, 21, 22. MWR sent for colorimeter on Unit 2 CPD.
12-18-89	cleaned and soaked delay blocks on #31, #32 silica analyzers also calibrated #31 & #32 silica analyzers
12-18-89	replaced membrane and calibrated unit 2 dissolved oxygen monitor
12-20-89 CKP	Replaced measuring and reference electrodes for the economizer pH monitor on Unit 3.

Wold 000026

12-20-89	removed sample cells from #31 & #32 silica analyzers and soaked them in 20% ammonium hydroxide solution. Also recalibrated both #31 & #32.
12-29-89 CKF	Polished electrode on #31 Hydrazine Analyzer. Replaced diffusion tubing, O-rings, and solution.
1-2-90	calibrated #11, #12, #21, & #22 silica analyzers
1-8-90	replaced membrane and calibrated Unit 3 dissolved oxygen monitor
1-8-90	- replaced diffusion tubing and O-rings on #32 sodium sled - also topped off monoethylamine on #11, #12, #21, #22 and #31. #32 monoethylamine was changed - put new reference electrode filling solution on all sodium sleds (#11, #12, #21, #22, #31, #32) - calibrated #11, #12, #21, #22, #31 & #32 sodium analyzers
1-10-90	calibrated #11, #12, #21, #22, #31, #32 silica analyzers
1-10-90	replaced cell on unit 1 hydrazine analyzer (CKF)
1-15-90	replaced diffusion tubing & O-rings on #31 sodium sled along with monoethylamine bottle

Wold 000027

28

1-22-90	calibrated #11, #12, #21, & #22 silica analyzers also soaked #31 & #32 silica blocks in 20% ammonium hydroxide solution calibrating them both upon completion of cleaning!
1-23-90	replaced monoethylamine, diffusion tubing and O-rings on #11 & #12 sodium sleds also calibrated both of them (#11, #12)
1-29-90	replaced monoethylamine, diffusion tubing and O-rings on #21 & #22 sodium sleds also calibrated #21 & #22 sodium sleds
1-29-90	replaced membrane and calibrated Unit 3 dissolved oxygen monitor
2-7-90	Unit 3 HYDRAZINE MONITOR CALIBRATED, REPLACE IODIDE SOLUTION AND DIFFUSION TUBING.
2-20-90	Replaced ^{Hydrazine} tubing, solution, calibrated monitor and replaced reference electrode solution.
3-9-90	Filled monoethylamine sol. calibrated #32 sodium sled. Rinsed and cleaned reference electrode.
3-14-90	CALIBRATED ^{#21 & #22} SODIUM SLED (COMPLETE OVERALL)
3-15-90	OVERALLED SILICA ANALYZER UNIT 2 BOILER & CPD.
3-16-90	REBUILT ^{UNIT 2} OXYGEN ELECTRODE/CALIBRATED.
3-16-90	REBUILT CALIBRATED #31, 32, 21, 22 ^{SILICA} ANALYZERS.
3-16-90	REBUILT UNIT 3 OXYGEN ELECTRODE/CALIBRATED.

Wold 000028

29

3-16-90 CALIBRATED SILICA ANALYZERS (11, 12, 31, 32)

3-20-90 Replaced monoethylamine, diffusion tubing, O-rings, in-line filter and calibrated 31, 11, AND 12 sodium analyzers.

3-21-90 REBUILT OXYGEN ANALYZER (UNIT 2 & 3)

CLEANED CATHODE & ANODE REPLACED MEMBRANE & CALIBRATED.

3-29-90 RECALIBRATED BOILER ^{UNIT 3} SODIUM ANALYZER. Replaced Cation Column and in-line filter.

3-30-90 Calibrated # 11, # 12, # 21, # 22, # 31, # 32 SILICA Analyzers. Cleaned blocks.

April 5 1990

#31 N₂H₄ Analyzer

Replaced reagent bottle and, diffusion tubing, and O-rings.

Replaced measuring and reference electrodes.

Checked all flows & I&C checked thermistor, etc.

Calibrated.

April 6 #31, 32, 11, 21 Silica Analyzers

Cleaned delay blocks & mixing cells & calibrated.

4-19-90 #31, 32 SiO₂ analyzers - also # 11, 12, 21, 22 were done! Cleaned delay blocks, mixing cells, & calibrated.

#

4-24-90 #32 Sodium SLED

Topped off reagent; etched Na elec; filled ref. elec. Calibrated

Wold 000029

30

4-24-90	#31 Sodium SLED Replaced reagent bottle diffusion tubing, O-rings, ref. fill. solution, etched Na elec. Calibrated
4-24-90	#11 & #12 Sodium SLED Topped off reagent bottle; etched Na elec. Calibrated
4-27-90	#32 Sodium SLED NEW: Na measuring elec; ref. elec; tubing; O-rings; electrode holder; Demin cartridges; I & C checked electronics & thermistor. Calibrated Cleaned flow regulator 5-3-90
5-2-90 ^{MTB}	Rebuilt O ₂ -Orbisphere probe Unit 3
5-3-90	Unit 1 Hydrazine Analyzer Replaced pleated capsule filter; regelled the cell - Calibrated 5-4-90
5-3-90	Unit 2 Hydrazine Analyzer Regelled & cleaned the cell Calibrated - 5-4-90
5-4-90	Unit 3 Hydrazine Analyzer Etched Iodine Electrode; replaced ref. elec. filling solution. Replaced reagent bottle; diffusion tubing; all O-rings Calibrated.

Wold 000030

31

5-4-90	21 Silica Analyzer Cleaned mixing cell & calibrated
5-2-90	31 & 32 Silica Analyzer Duane cleaned both of them. Replaced the Molybdate reagent (the filter, tubing, & capillary). Cleaned mixing blocks & cells & then calibrated them.
5-1-90	31 Hydrazine Analyzer Etched I ⁻ electrode; cleaned & refilled ref. electrode & calibrated it, again!
5-11-90	#21; 22; 31; 32 Silica Analyzers Cleaned mixing blocks & mixing cells & Calibrated them.
5-15-90	Rebuilt the O ₂ sensor in Unit 3 orbisphere Calibrated. I had I & C repipe the drain line, to go directly to the floor drain, instead of up to the header, (reduce syphon action).
5-16-90	#11, 12, 22 Silica Analyzers Cleaned mixing cells & calibrated.
5-17-90	Unit 3 Orbisphere - changed probes (port. meter probe now installed) & calibrated. Seems to work better. Suspect bad probe! Unit 2 Orbisphere - sensor cleaned. Calibrated Probe sent back to Orbisphere.

Wold 000031

32

5-23-90	Unit 1 Boiler pH Changed measuring & reference electrodes.
5-25-90	Unit 2 Hydrazine Analyzer Crashed at 3:00 PM. Regelled cell & replaced pleated capsule filter.
5-28-90	Unit 2 Hydrazine Analyzer Replaced cell with a brand new one
5-29-90	#31, #32 Silica Analyzers Cleaned mixing blocks & cells. Calibrated.
5-30-90	#11, 12, 21, 22 Silica Analyzers Cleaned mixing blocks & cells. Calibrated.
6-5-90	#31 & #32 sodium sleds were both calibrated, new in-line filters installed and monoethylamine bottles were topped off.
6-6-90	#11 & #12 sodium sleds were both calibrated, new in-line filters, new diffusion tubing, o-rings and monoethylamine
	#21 & #22 sodium sleds were both calibrated, new deionization cartridges were installed on both along with in line filters, diffusion tubing, o-rings and the monoethylamine bottle

Wold 000032

6-8-90	Calibrated #11, #12, #21 & #22 silica analyzers also calibrated #31 & #32 silica analyzers
6-15-90	- cleaned #31 & #32 silica analyzer delay blocks by soaking in ammonium hydroxide solution. calibrated both #31 & #32 (F) wiped them down
	- cleaned, rebuilt and calibrated Unit 3 dissolved oxygen probe
6-18-90	Unit 3 Orbisphere - same as above
6-19-90	calibrated #11, #12, #21 & #22 silica analyzers
6-19-90	calibrated #31 & #32 silica analyzers
6-19-90	replaced deionization cartridge along with reagent bottle, diffusion tubing and O-rings on Unit 3 hydrazine analyzer. Also calibrated U3 hydrazine analyzer
6-21-90	- calibrated Unit 3 hydrazine analyzer again
	- calibrated Unit 3 sodium Boiler sled
6-26-90	calibrated #11, #12, #21 & #22 silica analyzers
6-28-90	Unit 3 Boiler Water Sodium A/sled Disassembled & cleaned the flowmeter valve assembly.

Wold 000033

34

- 7-2-90 - calibrated #11, #12 & #21 sodium sleds
also topped off monoethylamine bottles on those sleds ⊕ #22 (which is out of service ∴ not calibrated)
- calibrated #11, #12, #21, & #22 silica analyzers
- 7-5-90 Orbisphere - O₂ sensor Unit 3
Chemical cleaning, rebuilt, calibrated.
It was very dirty! Reading erratically!
- 7-6-90 Calibrated Unit 3 Boiler A/SLED Sodium
- 7-9-90 Cleaned & calibrated CPD Silica Unit 3.
- 7-5-90 calibrated Unit 3 hydrazine (LLS)
- 7-10-90 - calibrated #11, #12, #21 & #22 silica analyzers
- calibrated Unit 3 Boiler silica analyzer
- calibrated Unit 3 CPD sodium sled, topped off monoethylamine
- 7-16-90 Unit 3 Orbisphere - O₂ Probe
chemical cleaning & calibrated
- 7-17-90 Unit 3 Econ pH } new measuring & reference electrodes
Unit 3 Boiler pH }
- 7-18-90 rebuilt and calibrated Unit 1 DO probe (chemical cleaned)
- calibrated #11, #12, #21 & #22 silica analyzers

Wold 000034

35

7-24-90	cleaned & rebuilt Unit 2 DO probe	
7-25-90	- calibrated unit 3 hydrazine analyzer (LLS)	
	- calibrated #31 & #32 silica analyzers (JPN)	
	* - changed tubing and reagent bottle and o-rings on unit 3 hydrazine analyzer *	
7-31-90	Unit 2 Boiler Sodium	
	Changed reagent bottle, diffusion tubing bottle cap, O-rings, Na ⁺ Elec and ref electrode & calibrated it.	
	Unit 3	
	Orbisphere	
	Installed the O ₂ sensor we just received from the company. Calibrated. Sent the one that was on it back to Orbisphere.	
	N ₂ H ₄ Analyzer	
	Regelled the cell. Couldn't get it to span correctly.	
8-1-90	Recalibrated #2 Boiler Na ⁺ Analyzer	
8-2-90	N ₂ H ₄ Check Unit 3	
	8-1-90	MONITOR 25
	8-2-90 ⁰⁷³⁰	22
	1230	24
	8-3-90 ⁰⁷³⁰	29
		LAB 21
		29 ← adjusted
		19
		29

Wold 000035

36

8-3-90 Cleaned & Calibrated all the Silica analyzers.

8-7-90 Unit 1 Hydrazine Analyzer - regelled; calibrated.

*** FYI ***

Orbisphere O₂ sensor Serial Numbers

No. 1	4751	(sent out July '90)
2	3225	(in-service Unit 3)
3	5921	(portable)
4	5787	(installed Unit 1)

8-8-90 Unit 2 Hydrazine Analyzer - regelled; calibrated.

Unit 3 Boiler A/SLED - installed new flowmeter.

8-13-90 Unit 3 Boiler A/SLED

Replaced reagent bottle & diffusion tubing; ref. elec. fill. solution; O-rings; etched Na⁺ electrode. Calibrated.

Unit 3 CPD A/SLED

Replaced reagent bottle; diffusion tubing; ref. elec. fill. sol.; O-rings; etched Na⁺ elec.

7-14-90 Calibrated

7-14-90 Sodium SLED^s #12 & #22

Etched Na⁺ Electrodes

Replaced: Reagent bottle; diffusion tubing; ref. elec. fill. sol.; O-rings

Wold 000036

7-14-90	Unit 3 CPD Na ⁺ ASLED Installed new Na ⁺ electrode & ref. electrode, due to inability to calibrate analyzer.
7-15-90	Calibrated all 3 CPD Sodium Analyzers.
8-20-90 ckf	Cleaned & calibrated CPD (3) Silica Analyzer.
8-21-90	Calibrated CPD (3) SiO ₂ analyzer
8-22-90	Regelled the cell for Unit 3 Hydrazine Analyzer.
8-24-90	Cleaned mixing blocks & cell on Unit 3 Silica analyzers. Calibrated both.
8-28-90	Boiler Sodium Unit 1 Installed new Na ⁺ electrode; ref. electrode. Replaced reagent bottle; diffusion tubing; O-rings; Calibrated
8-29-90	#11; 12; 21; 22 Silica Analyzers Cleaned mixing cell & calibrated
9-11-90	#31 & #32 Silica Analyzers Soaked & cleaned mixing blocks & mixing cells. Calibrated Checked & cleaned capillaries

Wold 000037

38

9-18-90	Unit 1 Boiler Sodium Topped off reagent & etched Na elec. Refilled ref. elec. & calibrated
9-19-90	CPD Sodium SLED Unit 1 & 2 Topped off reagent; etched Na elec; refilled ref. elec. & calibrated
	CPD Silica Unit 2 Cleaned & calibrated.
9-21-90	CPD Silica Unit 2 cleaned & calibrated again, found to have low sample flow.
9-24-90	CPD Silica Unit 2 Replaced colorimeter (took old one to I&C for repair - wouldn't calibrate.) Cleaned capillaries, & mixing cell. Replaced dessi- cant cartridge. Calibrated
9-24-90	CPD Silica Unit 1 Replaced lamp; dessicant cartridge; cleaned capillaries; mixing cell. Calibrated.
9-25-90	#31 & #32 Sodium p/SLED's Topped off reagent; etched Na elec; refilled ref elec. & calibrated.

Wold 000038

39

9-25-90	#31 & #32 Silica Analyzers Cleaned mixing blocks & mixing cells; replaced floats. Calibrated. Replaced dessicant.
9-26-90	#21 Silica Analyzer Replaced colorimeter (I & C worked on this one: replaced lamp; range switch) & dessicant cartridge. Calibrated.
	#11 Silica Analyzer Cleaned mixing cell; capillaries; replaced dessicant cartridge. Calibrated.
11-13-90	Unit 2 N ₂ H ₄ analyzer Replaced in-line filter; regelled cell; calibrated
11-16-90	Unit 3 N ₂ H ₄ analyzer Replaced in-line filter; regelled cell; calibrated
1-2-91	Changed monoethylamine bottles, diffusion tubing, o-rings, etched electrodes and calibrated #31 & #32 sodium sleds
1-3-91	changed monoethylamine bottles, diffusion tubing, o-rings, etched electrodes and calibrated #11, #12, #21 & #22 sodium sleds
1-7-91	calibrated #11, #12, #21, #22, #31 & #32 silica analyzers
1-9-91	Rebuilt Unit 3 hydrazine cell (regelled)

Wold 000039

40

1-14-91	calibrated #11, #12, #21, #22, #31 & #32 silica analyzers
1-15-91	soaked and regelled a new cell for Unit 3 hydrazine analyzer
1-22-91	calibrated #11, #12, #21 & #22 silica analyzers cleaned all delay blocks and calibrated Unit 3 boiler silica analyzers
1-28-91	rebuilt Units 1 & 2 DO probes and calibrated calibrated #11, #12, #21 & #22 silica analyzers
1-30-91	calibrated #31 & #32 silica analyzers
2-21-91	Calibrated 31 & 32 Silica analyzer Rebuilt and calibrated 31 & 32 Na Slects Diffusion tubing, o-rings
2/22/91	Rebuilt and calibrated 11, 12, 21, 22 Na Slects Diffusion tubing ^{oring} calibrated 11, 12, 21, 22 SiO ₂ analyzers
2/23/91	Re-calibrated 12, 22 SiO ₂ analyzers
3/8/91	Calibrated 11, 12, 21, 22, 31, 32 SiO ₂ analyzers
3/15/91	Calibrated 11, 12, 21, 22 SiO ₂ analyzers rebuilt unit 2 boiler drug valve on WOP

Wold 000040

41

3/27/91	Calibrated 11, 12, 21, 22 Na sleds and SiO ₂ sleds
4/5/91	Calibrated 11, 12, 21, 22 SiO ₂ analyzers
4/7/91	Re-built and calibrated 31, 32 Na ⁺ sleds cleaned and rebuilt 31, 31 SiO ₂ analyzer Jim put D.O. probe in service and rebuilt the old one U3
4/12/91	Calibrated 11, 12, 21, 22 SiO ₂ analyzers
4/17/91	Calibrated 11, 12 SiO ₂ analyzers - cleaned out capillary tubes
4/18/91	Re-gelled unit 1 and 2 N ₂ H ₄ probes
4/23/91	re-gelled and calibrated U1 N ₂ H ₄ probe/analyzer
4/26/91	Calibrated 11, 12, 21, 22, 31, 32 SiO ₂ analyzers
5/6/91	Cleaned and calibrated 31, 32 SiO ₂ analyzers.
CRF	Replaced o-rings, diffusion tubing and solution, in-line filter and etched Na ⁺ electrodes for Unit 1 & 2 CPD Sodium sleds. (#12, #22)
5/7/91	Calibrated #12, #22 Na sleds. (Unit #1, 2 CPD).
CRF	Replaced o-rings, diffusion tubing and solution, in-line filter and etched Na ⁺ electrodes for #11, #21 Sodium sleds. (Unit 1 & 2 Boiler).

Wold 000041

162

5/8/91 CKF	Calibrated 21, 11 Sodium Steds. (Unit 1 & 2 Boiler)
5/14/91 CKF	Calibrated Calibrated # 11, 12, 21, 22 Silica analyzers. Retubed # 31, 32 silica analyzers and inspected all capillary tubes.
5/16/91 CKF	Calibrated # 31, 32 Silica analyzers.
5/20/91 CKF	Topped off monoethylene amine containers and calibrated # 31, # 32 Sodium Steds. (Unit # 3 Boiler & CPD).
	Adjusted cation conductivity meters to actual values for Unit # 3.
	Removed cell from # 31 Hydrazine Analyzer for periodic maintenance. Soaking cell in 20% NaOH solution over-night.
5/21/91 CKF	Regelled Unit # 3 Hydrazine Analyzer measuring cell. Cleaned, rebuilt and calibrated Unit # 3 D.O. Analyzer.

Wold 000042

43

5/21/91 CK 1815	N ₂ H ₄ monitor check Unit #3 mon. 21 ppb results. 27 ppb
5/22/91 CK	Calibrated # 11, 12 Silica Analyzers. Ran wire through capillary tubes.
5/22/91 CK	N ₂ H ₄ monitor check Unit #3 mon. 21 ppb results 25 ppb
6/3/91 CK	Calibrated # 31, #32 Silica analyzers.
6/11/91 CK	Calibrated # 31, 11, 12 Silica analyzers.
6/18/91 CK	Topped off the mono ethylene amine solution containers for 11, 12, 21, 22 Sodium analyzers. Calibrated 11, 12, 21, 22 Sodium analyzers.
	Replaced o-rings, in-line filter, mixed bed cartridges, diffusion tubing and solution, and etched sodium electrodes for # 31, 32 Sodium analyzers.
	Replaced # 32 Na electrode and reference electrode.
	Calibrated # 31, 32 Sodium analyzers.

Wold 000043

44

6-20-91 ckf	Soaked new hydrazine cells in 2% NaOH solution overnight for 11, 21 N ₂ H ₄ analyzers.
6-21-91 ckf	Gelled 11, 21 N ₂ H ₄ and cells and returned analyzers to service. Replaced filters on N ₂ H ₄ analyzers # 11, 21.
	Cleaned Unit # 2 D.O. probe. (the cathode, anode, & guard.) Polished D.O. probe and put unit back on line.
	Calibrated # 31, 32 Silica analyzers. Calibrated # 11, #12 Silica analyzers.
6-21-91 ckf	This concludes my two month rotation.
7-2-91 AM	AND ELECTROLYTE REPLACE MEMBRANE ON UNIT 3 D.O. ANALYZER. NOISY SIGNAL. MAY NEED ADDITIONAL WORK.
7-3-91 AM	#31 & #32 SiO ₂ ANALYZERS CLEANED SiO ₂ BLOCKS, REPLACED CAPILLARY TUBES; AND CALIBRATED. ALSO FILLED WITH REAGENTS.
7-3-91 AM	UNIT 3 N ₂ H ₄ CHECK: MONITOR 24 ppb RESULT 24 ppb

Wold 000044

45

7-5-91 CALIBRATED 21 & 22 SiO_2 ANALYZERS.
FILLED WITH REAGENTS.

7-15-91 rebuilt U3 DO probe
JPW

7-25-91 FILLED MONOETHYLAMINE SOLUTION BOTTLES.
RAM CALIBRATED BOILER AND CPO SODIUM ANALYZERS.
UNITS 1, 2, 3.

7-25-91 FILLED SILICA REAGENTS ON 31 & 32 SiO_2
RAM ANALYZERS.

7-25-91 FILLED MONOETHYLAMINE BOTTLES ON BOILER/CPO ^(ON ORDER) ~~SHORT 2 MONOETHYLAMINE~~ BOTTLES.
RAM UNIT 2 AND REPLACED UNIT 1 SOLUTIONS.
CALIBRATED BOTH UNIT 1 AND UNIT 2 & 3
SODIUM ANALYZERS. ALSO REPLACED TUBING
AND IN-LINE FILTERS.

7-26-91 CALIBRATED SiO_2 ANALYZERS,
RAM ON ~~UNIT~~ UNITS 1, 2, 3. (BOILER/EPD)

8-2-91 CALIBRATED SiO_2 ANALYZER - UNITS ~~1, 2, 3~~ 1, 3.

8-9-91 CALIBRATED SiO_2 ANALYZERS - UNITS 1 & 3.

8-12-91 REPLACED O.O. MEMBRANE ON UNIT 3.

Wold 000045

46

8-16-91 RAM	FILLED REAGENTS AND CALIBRATE #1,2,31,32 SiO_2 ANALYZERS.
8-19-91 RAM	REPLACED MEMBRANE AND ELECTROLYTE ON UNIT 2 D.O. PROBE
8-20-91 RAM	INSTALLED NEW PROBE ON <u>UNIT 2</u> N_2H_4
8-22-91 RAM	CALIBRATED AND ADDED CHEMICALS TO #31,32 SiO_2 ANALYZERS.
8-26-91 RAM	REBUILT UNIT #1 N_2H_4 PROBE.
8-26-91 RAM	REPLACED MEMBRANE AND ELECTROLYTE ON UNIT 1 D.O. PROBE
8-26-91 RAM	REBUILT UNIT 3 N_2H_4 PROBE.
8-29-91 RAM	REPLACED MONOETHYLAMINE REPLACED IN-LINE FILTER CALIBRATE 31,32,11,12,21,22 Na ANALYZERS.
8-29-91 RAM	CALIBRATED SiO_2 ANALYZERS - UNITS 1 & 3.

Wold 000046

47

9-3-91 mtb	refilled replaced reagent for series 500 Silica analyzer for Unit 2
9-3-91 mtb	replaced both sets of reference and pH probes on Unit 3 circ H ₂ O
9-9-91 mtb	calibrated 11, 12 SiO ₂ analyzers
9-11-91 mtb	Rebuilt U2 D.O. Probe
9-18-91 mtb	Removed delay blocks, cleaned and calibrated 31, 32 SiO ₂ Analyzers
9-18-91 mtb	Replaced pH and reference electrodes in north pot on Unit 3 circulating water
9-18-91 mtb	Rebuilt Unit 3 D.O. probe
9-19-91 mtb	Calibrated 11, 12 SiO ₂ analyzers
9-27-91 mtb	Cal 11, 12, 31, 32 SiO ₂ Analyzers
10-1-91 mtb	Cal 31 SiO ₂ Analyzer
10-2-91 mtb	Replaced diffusion tubing, O-rings, and monoethylamine and calibrated 31, 32 Na Sled
10-2-91	Re-gelled Unit 3 N ₂ H ₄ probe

Wold 000047

48

10-2-91 mTB	Replaced diffusion tubing, rings, monoethylamine and calibrated 11, 12, 22 Na sled
10-4-91 mTB	Calibrated 21 Na sled - replaced tubing and rings
10-4-91	11, 12 SiO ₂ analyzer calibrated
10-7-91 mTB	put new measuring and ref electrodes in 31 Na sled and calibrated it
10-7-91 mTB	calibrated 31, 32 SiO ₂ analyzers
10-17-91 mTB	Calibrated 11, 12, 31, 32 SiO ₂ analyzers
11-6-91	Removed delay blocks and soaked in NH ₄ OH solution cleaned capillary tubes refilled reagent tanks calibrated #31 & #32 silica analyzers
11-7-91	calibrated U1 Silica analyzers cleaned capillary tubes refilled reagent tanks replaced bulb in Boiler silica analyzer replaced CPD silica analyzer (U1) with one of the old ones from Unit 2. → working fine so far
11-11-91	calibrated #11 & #12 SiO ₂ analyzers

Wold 000048

49

11-12-91 rebuilt and calibrated U1 DO probe

11-13-91 calibrated #31 & #32 silica analyzers
topped off reagent tanks

11-14-91 calibrated boiler silica analyzer for Unit 3
again

11-18-91 changed O-rings and diffusion tubing ^{monoethylamine too} on
#11, #12, #21 and #22 Na⁺ sleds

calibrated #11, #12, #21 and #22 Na⁺ sleds
installed new in line filters on #11, #12 and #22
Na⁺ sleds

11-19-91 changed O-rings, diffusion tubing, monoethylamine
and in line filters on #31 and #32 Na⁺ sleds
calibrated #31 and #32 Na⁺ sleds

installed new electrodes on #11, #12, #21 and #22
Na⁺ sleds. Recalibrated those same sleds!

rebuilt Unit 3 DO probe

11-20-91 calibrated #31 and #32 Silica analyzers
cleaned precipitate off of #31 and #32 Silica
analyzers.

Replaced burnt out bulbs on WGP alarm board
MWR in for CPD cation conductivity nuisance alarm

Wold 000049

50

11-21-91	calibrated #11 and #12 silica analyzers
11-27-91	calibrated #31 and #32 silica analyzers
12-3-91	calibrated #11 and #12 silica analyzers
12-4-91	regelled units / #2 hydrazine cells
12-5-91	cleaned delay blocks on #31 and #32 silica analyzers in ammonium hydroxide solution calibrated #31 and #32 silica analyzers
12-11-91	rebuilt U3 DO probe
12-12-91	calibrated U1 silica analyzers
12-17-91	put new reagent and standard into U2 Series 5000 silica analyzer
	changed deionization cartridges on #21 and #22 Na ⁺ sleds
	new reference electrode solution on U1 Boiler Na ⁺ and U2 Boiler Na ⁺ sleds
	calibrated #11, #12, #21 and #22 Na ⁺ sleds
	calibrated #31 and #32 Na ⁺ sleds changed reference electrode solution on CPD Na ⁺ sled
12-18-91	calibrated #31 and #32 silica analyzers

Wold 000050

51

12-27-91	calibrated U1 silica analyzers
12-30-91.	rebuilt U1 DO probe rebuilt U3 DO probe
1-3-92 CK	Calibrated #31 and #32 Silica Analyzers.
1-6-92 JPW	calibrated #31 and #32 silica analyzers
1-7-92 RLM	Cleaned + Calibrated #31 + #32 silica analyzers. Having some problems with span adjustment on #31.
1-8-92 RLM	1811LL Sodium Analyzer - installed new electrodes, sensing + reference - new tubing + reagent - calibration Slope \rightarrow 59.6 * This analyzer now uses a pink or orange colored cesium chloride filling solution for the ref electrode.
1-9-92	New Unit 3 pH electrodes for Economizer pH installed.
1-10-92 RLM	New measuring + reference electrodes for Boiler + Economizer pH installed on Unit 1.
1-13-92	New measuring + reference electrodes for Boiler pH on Unit 3.

Wold 000051

52

1-15-92 RUM	Cleaned + calibrated 31 + 32 silica analyzers.
1-21-92	Changed 31 Pol. cation column resin. Changed 12 Pol, #1 Econ, #2 CPD cation resin columns.
1-23-92	Calibrated 11, 12, 21, 22 Na analyzers. * New reagent + tubing * New sample inlet filters. * Etched measuring electrodes * New Demin cartridges on 11 + 12 analyzers
1-24-92	Calibrated 31 + 32 Na analyzers * New reagent + tubing * Etched measuring electrodes
	Cleaned + calibrated 31 + 32 silica analyzers.
	Changed 3 cation columns on Unit 2 WQP.
	Cleaned + Calibrated 11 + 12 silica analyzers
^{27x} 1-28-92	Complete annual maintenance of TRACE Pump Silica analyzer.
2-3-92	Changed Reagent + tubing on 1811LL sodium analyzer. Etched measuring electrode.

Wold 000052

2-4-92 Performed calibration on 1811LL analyzer.
Slope = 60.3

2-4-92 Cleaned + calibrated 11 + 12 silica analyzers.

2-6-92 * Cleaned + calibrated 31 + 32 silica analyzers.

* Rebuilt unit 3 dissolved Oxygen probe.

* New reagents put in series 5000 silica analyzer, unit 2.

* Changed 2 cation resin columns.

* Econ Inlet pH monitor needs work (Unit 1) - MWR -

2-17-92 rebuilt and calibrated UI DO probe

2-25-92 New reagents in Trace Pump Silica analyzer.
* out of standard, DI water in its place.

2-21-92 Calibrated 31 + 32 silica analyzers.
CKF

2-27-92 Calibrated 31 + 32 silica analyzers
* Silica reagents
Changed several cation columns on all 3 units today.

3-2-92 Replaced in-line filter on Unit 3 N_2/H_4 analyzer.

3-5-92 Changed reagent/tubing/O-rings; etched Na electrode
Calibrated. 1811LL Na analyzer.

3-10-92 cleaned & calibrated 31 & 32 SiO_2 analyzers.
Soaked all blocks; replaced Molyb cap on 31.
cleaned all

Wold 000053

54

3-12-92	Cleaned all flow cells in Unit 1/2 Lab.
3-12-92	Had Kevin L. check out the 31 SiO ₂ colorimeter. He tuned it. We reinstalled it and calibrated.
3-12-92	A/SLED Na analyzers 12 & 22. Replaced tubing & reagent; new ref. sol'n; Etched Na elec;
3-13-92	Calibrated 12 & 22 A/SLEDs.
3-16-92	31 & 32 Na SLED's: Etched Na elec. Replaced reagent; tubing; O-rings; ref. fill. sol'n. Removed/cleaned elec. block on B1r SLED Calibrated both.
3-16-92	11 & 12 SiO ₂ analyzers: Cleaned mixing cell; capillary tubes Calibrated both
3-17-92	Unit 1 Boiler Na SLED Etched Na elec. Replaced; reagent; tubing; O-rings; ref. fill. sol'n. Removed/cleaned elec block Replaced holding screw and fitted cap on reagent bottle. Calibrated. Replaced entry port and recalibrated.

Wold 000054

3-18-92	Unit 1 N ₂ H ₄ analyzer Regelled cell & replaced in-line filter.
3-19-92	Calibrated 11 & 12 SiO ₂ analyzers
3-23-92	Cleaned 31 & 32 SiO ₂ analyzers Replaced Amino Acid; tubing; capillary 31 SiO ₂ There are calibration problems on both of these.
3-22-92	Kevin Lavoie checked & cleaned all of the electronics on 11; 12; 31; 32 A/SLEDs. Recalibrated.
3-26-92 RLM	Rebuilt dissolved oxygen probe for Unit 1 WQP. "Chemical Cleaning"
3-27-92	Still lots of problems with Unit 3 SiO ₂ analyzers. Regelled N ₂ H ₄ cell on Unit 3.
3-26-92	Monthly Maint. of TRACE. / Shut down 5000 SiO ₂ ^{81r} 2
3-30-92	Cleaned/Calibrated #11; 12; 31 SiO ₂ analyzer
4-6-92	Unit 1 Boiler Silica Replaced colorimeter lamp & calibrated
	Unit 3 Boiler Silica Replaced H ₂ O capillary & screw. Cleaned the blocks & calibrated it.
	Unit 3 CPD - cleaned mix. cell / calibrated it!

Wold 000055

4-3-92	1811 LL Na Analyzer Etched electrode; replaced bottle & tubing for reagent; replaced ref. sol'n, O-rings Calibrated. SLOPE = 60.5
3-26-92 thru 4-11-92	Unit 2 Outage Work 5000 Silica Analyzer - Emptied/Out for extended shutdown. Replaced: reagent filters & caps; tubing from manifold to cell cover; reagent valve fittings on Amino F & sample; colorimeter lamp; reagents;
3-26	
4-8	std; Tried a calibration \bar{c} a 50ppb std: it wouldn't do it (unable to cal) Found out from HACH, the lowest std used should be a 100ppb.
4-10	Calibrated on 500ppb std = 501ppb
3-31-92	N ₂ H ₄ Analyzer - Out of Service Replaced in-line filter. Cleaned cell holder; cell; flow meter. Soaked cell overnight in 2% NaOH. Regelled cell 4-6-92. In service \bar{c}
4-6	Make-up H ₂ O.
3-31-92	Dissolved Oxygen - Orbisphere Out of service Electronically cleaned probe/chemical soak
4-1	Rebuilt probe - stored in Na ₂ SO ₃
4-9	In-service and calibrated
	Removed cat. cond. resin col. & B.J. placed new unit in back panel.

Wold 000056

57

4-1-92	A/SLED Na Analyzers Boiler & CPD
4-2-92	Etched Na electrodes / soaked. Cleaned out ref. electrodes / replaced fill. sol'n. Replaced reagent bottle & tubing & all O-rings Removed & cleaned electrode block & flow cells. Replaced in-line filters.
4-9	Blr - Replaced cal. entry port & fitted bottle cap CPD - Replaced fitted cap and holding screw.
4-9	Calibrated both - placed in service.
4-10-92	Unit 3 Boiler Installed new 5000 Series Silica Analyzer
4-11-92	Calibrated! std = 508ppb Put in service.
4-13-92	Zeroed/calibrated Trace Silica - Molybdate delivery hose was out of sol'n / triggered alarms.
4-14-92	31 & 32 Na ⁺ A/SLEDs Topped off reagents and calibrated.
4-14-92	Installed new control box on 5000 SiO ₂ Unit 3 Blr. Calibrated \bar{c} 500ppb std = 511ppb
4-21-92	Installed/calibrated 5000 Series SiO ₂ analyzer Boiler - Unit 1 - 500ppb std = 491.8ppb
	Old 1234B/D from Unit 1 Blr - torn apart, Cleaned, new: tubing, capillaries, filters (reagent) & o-rings.

Wold 000057

58

4-22-92	Unit 3 CPD Silica Analyzer Rebuilt. Replaced: blocks, tubing, reagents, reagent-filters & o-rings. Calibrated.
4-23-92	#12 CPD Na ⁺ A/SLED Topped off reagent & calibrated
4-27-92	#11 Boiler Na ⁺ A/SLED Topped off reagent. Replaced ref. electrode due to unsuccessful calibration. Kevin cleaned all the contacts & ISA. Old dynamic calibrator is broken, sent in for repair.
5-1-92	Calibrated Unit 1 CPD & Unit 3 CPD SiO ₂ analyzers.
5-6-92	Etched electrode and calibrated 1811 LL Na ⁺ analyzer. Slope → 58.9 E _c → -71.8
	calibrated U1 silica analyzer and topped off reagent tanks
5-8-92	changed reagent and standard on U2 Series 5000 silica analyzer. Set to autocal and returned to service
	calibrated U3 CPD silica analyzer and topped off reagent tanks

Wold 000058

59

5-12-92	replaced standard on U3 series 5000 silica analyzer. Also ran auto cal → calibration value at 0000 hrs 5-11 was 392, new cal value is 490 ppb!
5-15-92	calibrated U1 and U3 silica (CPD) analyzers topped off reagent tanks on U3
5-19-92	transferred Betz chemical at 1 & 2 lab new nitrogen bottle for N_2H_4 transfer to measuring tank
5-20-92	topped off U2 Nat sleds monoethylamine bottles. Still waiting on dynamic calibrator to come back from servicing
	cleaned and calibrated U1 CPD silica analyzer also topped off reagent tanks
	changed in-line filters and deionization cartridges on #31 and #32 sodium sleds
5-27-92	changed reagents and standard on trace pump silica analyzer
5-31-92 CK	Calibrated and rinsed 32 Silica analyzer.
5-29-92	replaced reagents on U3 silica analyzer (Series 5000)

Wold 000059

6-2-92 topped off monoethylamine bottles on U3
Nat sleds (Dynamic calibrator still not back)

6-3-92 replaced monoethylamine on U1 Boiler and
CPD Nat sleds. Also replaced diffusion tubing,
O-rings and in line filters on both sleds.
calibrated both sleds also.

6-3-92 replaced monoethylamine, diffusion tubing, O-
rings and calibrated U2 Boiler and CPD
Nat sleds

6-3-92 calibrated U1 CPD silica analyzer and topped
off reagent tanks

6-4-92 replaced monoethylamine, O-rings and diffusion
tubing on 1811LL Nat analyzer.
Also etched electrode and calibrated
Slope \rightarrow 60.6
 $E_0 \rightarrow$ -76.1

6-4-92 replaced monoethylamine, O-rings and diffusion
tubing on U3 Nat analyzers.
Also etched electrodes and calibrated

6-4-92 rebuilt Unit 1 DO probe

sent U3 dynamic calibrator to Orion for repairs (#GP22D)

sent spare DO probe to orbisphere for check and
modifications (Model 2110, #5921)

Serial Number



Wold 000060

6-5-92	replaced in-line filter on Unit 3 hydrazine analyzer sample line
	rebuilt and cleaned U3 DO probe
6-9-92	replaced reagents and standard on U2 Series 5000 Boiler Silica Analyzer. Also switched to the long cycle program instead of the short cycle
6-10-92	regelled U3 hydrazine cell
	replaced reagents and standard on U1 Series 5000 Boiler Silica analyzer
6-18-92	replaced burnt out bulb on U1 CPD silica analyzer, calibrated and topped off reagent tanks
6-24-92	replaced reagent on trace pump silica analyzer
	calibrated U1 CPD silica analyzer and topped off reagent tanks
6-26-92	transferred Betz chemical at 1 & 2 lab
7-2-92	etched electrode and calibrated 181122 Nat analyzer Slope \rightarrow 61.6 $E_o \rightarrow -76.8$

Wold 000061

62

7-6-92	new standard in U3 Series 5000 silica analyzer
7-7-92	topped off reagent pans on U1 CPD and U3 CPD silica analyzers
7-8-92	rebuilt U2 DO probe
7-13-92	* New pH + ref. electrodes installed on Unit 3 Econ. RLM * Replaced reagents in Unit 2 series 5000 silica analyzer.
7-16-92	* Changed cation columns, unit 2 boiler + polishets RLM * Filled reagent tanks, old silica analyzers.
7-20-92	* New reagents in Unit 3 series 5000 silica analyzer. RLM
7-21-92	All 4 sodium Sleds in Unit 1 + 2 lab. RLM * new reagent and tubing * etched Na sodium electrodes * calibrated with 1 ppm std.
7-22-92	Unit 3 Na analyzers: RLM * new reagent and tubing * etched Na electrodes * calibrated
7-23-92	* New reagents in Trace Pump Silica analyzer. RLM * New reagent + tubing in 1811LL Na analyzer. Etched ^{Na} electrode. Calibrated: slope $\rightarrow +59.3$ $E_0 \rightarrow -74.0$

Wold 000062

63

7-23-92	* Filled reagent tanks on 12 and 32 silica analyzers. RLM Calibrated.
	* Changed unit 1 boiler cation cond. column.
7-29-92	* New Reagents - Unit 1 Boiler Silica analyzer RLM * Changed 2 cation resin columns - Unit 3 WQP
7-30-92	* Changed 3 cation resin columns - Unit 1 WQP RLM * Changed 2 resin columns - Unit 2 WQP
	* added reagents to # 32 + # 12 silica analyzers.
8-11-92	* New silica std. in Unit 2 series 5000.
8-18-92	* Replaced reagents on Trace Pump Silica Analyzer RLM Installed new tubing in pinch valve area. Replaced 2 pieces of tubing from the mixing block that were coated with the moly blue color.
	* New silica std. in Unit 1 series 5000.
8-25-92	Maintenance performed on Trace Pump Silica Analyzer due RLM to calibration problems: * removed sample piston and cleaned sample cell * soaked mixing block in NH ₄ OH * replaced a leaky fitting on the piston, new teflon tape
8-27-92	Calibrated 1811LL Sodium Analyzer RLM Slope → 60.6

Wold 000063

8-28-92 RLM	* Changed a couple cation resin columns
	* Topped off silica reagent tanks
	* Took Trace Pump Silica analyzer out of service. seems to be a problem in the mechanical pinch system. Suction to reagent pistons will not come open very much, if at all.
9-2-92 DAM	* (CHANGED) ADDED REAGENTS ON UNIT 2 BOILER SiO ₂ ANALYZER. * ADDED MONOETHYLAMINE TO UNITS 1,2,3 Na ⁺ ANALYZERS.
9-4-92 DAM	REPLACED AMINO ACID REAGENT ON UNIT 3 BOILER SiO ₂ ANALYZER. ADDED REAGENT TO CPO SiO ₂ ANALYZER ON UNIT 3.
	REPIPED CPO THROUGH CPO AFTER CHEMICAL FEED SPEC. COND. PROBLEM ON UNIT 3. WILL DISASSEMBLE FOR OVER LABOR DAY WEEKEND AND REASSEMBLE ON TUESDAY OF NEXT WEEK.
9-3-92 RLM	I+C repaired the mechanical problem with the TRACE Pump Silica analyzer. Placed back in service. ON 9-8-92, it appears that "standard" and "zero" calibrations were performed successfully all weekend. Operation looks good.
9-8-92 DAM	CLEANE, CALIBRATED AND FILLED REAGENTS ON UNIT 3 CPO SiO ₂ ANALYZER.
9-8-92 DAM	LAST FRIDAY, 9-4-92 I CHANGED THE CPO AFTER CHEMICAL FEED SAMPLE TO THE CPO SAMPLE.

Wold 000064

9-8-92 THE SET POINTS WERE ALSO LOWERED TO 5.5.
HOPEFULLY THE NH₃ FEED WILL BE CONTROLLED

~~THE~~ MORE PRECISELY UNTIL MADE OBSERVATIONS

TODAY: INCREASED TO .05 ON 9-14-92
9-9-92 UNIT 1 START-UP

9-10-92 CHANGED RESIN ON UNIT 2 (AMMONIUM) (UNIT 2)

9-12-92 CHECK REPLACE UNIT 1 BOILER PH PROBE.

9-14-92 ADJUSTED SPECIFIC CONDUCTIVITY TRANSDUCER

CONDUCTIVITY MONITORS ON UNIT 3 TO
AN AVERAGE OF TWO MONITORS.

REBUILT D.O. PROBE ON UNIT 3.

9-15-92 REPLACED PH AND REFERENCE ELECTRODES ON:

UNIT 1 ECONOMIZER

UNIT 2 BOILER

UNIT 2 ECONOMIZER

UNIT 3 ECONOMIZER BOILER

9-16-92 CALIBRATED AND FILLED REAGENTS ON
UNIT 2 SiO₂ ANALYZER.

CALIBRATED PH PROBES ON UNITS 1 & 2.

9-18-92 UNIT 1 SHUT-DOWN BEGAN AT 0700.

TOOK ALL ANALYZERS OUT OF SERVICE.

PLACED ALL PROBES IN PROPER STORAGE SOLUTIONS.

FILLED NH₃ SOLUTION TANKS ON UNITS 1, 2, 3.

9-21-92 REBUILT Na ANALYZERS ON UNIT 3.

REPLACED PROBES, FILTERS, MONOETHYLAMINE SOLUTION, PUMP &

CALIBRATED.

Wold 000065

66

- 9-22-92 CLEANED, CALIBRATED, AND ADDED REAGENTS TO UNIT 3 CPO ANALYZER.
CHANGED CATION RESIN COLUMN ON UNIT 2.
TRANSFERRED BETZ CHEMICAL.
- 9-23-92 CHANGED RESIN ON 31, 32, & 33 CATION COND. MONITORS.
- 9-25-92 REPLACED REAGENTS ON TRACE PUMP SiO_2 ANALYZER
- 9-25-92 REBUILT UNIT 3 N_2H_4 PROBE.
- 9-25-92 REPLACED MONOETHYLAMINE SOLUTION & CALIBRATED THE
BOILER AND CPO Na^+ ANALYZER ON UNIT 2.
- 9-29-92 CALIBRATED AND FILLED REAGENTS ON UNIT 3 SiO_2
ANALYZER. ALSO CLEANED CAPILLARIES.
- 10-5-92 REBUILT UNIT 1 BOILER & CPO Na^+ ANALYZERS.
REPLACE REFERENCE & MEASURING ELECTRODE ON CPO Na^+ ANALYZER.
- 10-6-92 REBUILT O_2 PROBE - REPLACED ELECTROLYTE & MEMBRANE.
- 10-19-92 REPLACED BULB IN BOILER ^{UNIT CPO} SiO_2 ANALYZER.
- 10-20-92 CALIBRATED Na^+ ANALYZER ON THE DEMINERALIZER.
- 10-21-92 REPLACED REAGENTS & CALIBRATED DEMINERALIZER
 SiO_2 ANALYZER. ALSO ETCHED ELECTRODE.
- 10-21-92 ADDED MONOETHYLAMINE SOLUTION TO UNIT 1 & 2
SODIUM ANALYZERS. ALL WERE ALSO CALIBRATED.
- 10-23-92 ADDED MONOETHYLAMINE SOLUTION TO UNIT #3.
SODIUM ANALYZERS. ALSO CALIBRATED.
- 10-23-92 CLEANED, ADDED REAGENTS AND CALIBRATED UNIT 3 CPO
 SiO_2 ANALYZER.

Wold 000066

67


10-26-92	CHANGED REAGENTS AND CALIBRATED UNIT 3 BOILER SiO_2 ANALYZER.			
10-26-92	ADDED REAGENTS AND CALIBRATED UNIT 1 CPD SiO_2 ANALYZER - INITIAL START-UP COMPLETED.			
10-29-92	REBUILT UNIT 2 N_2H_4 PROBE.			
11-9-92	Replaced in-line filters on Unit 3 Blr Na and N_2H_4 analyzers.			
11-9-92	Rebuilt DO Probe for Unit 2			
11-10-92	Calibrated Unit 2 Orbisphere.			
	Silica 5000 SERIES Std Conc. Check			
11-10-92	auto-cal 500ppb	100ppb	50ppb	10ppb
U-3 Boiler	497.7	105.4	54.4	13.3
U-2 Boiler	500.4	107.7	57.7	17.1
U-1 Boiler	497.8	106.7	56.3	14.1
U-1 CPD	497.7	103.6	53.8	9.4
11-13-92	I've been working on the Trace Pump SiO_2 analyzer all week. The system loses sample flow then flow, once established, is so low it won't successfully calibrate.			

Wold 000067

68

11-16-91	Series 5000 Silica Analyzer for Unit 3 CPD is in service & calibrated 497.7 ppb = 500 ppb
11-17-92	TPA is still malfunctioning. Cleaned mixing block & replaced tubing/fit.
11-19-92	Monthly maint. on 1811L Na analyzer. Etched elec. Replaced: tubing, O-rings, fill sol., reagent Calibrated / 58.8 SLOPE
11-19-92	TPA cannot successfully calibrate.
11-23-92	Purged lines in TPA and increased sample flow to 100mls/min. Now IT WORKS!?
11-24-92	Unit 3 CPD SiO ₂ 5000 is in-service and calibrated - 501.2 ppb on 500ppb std.
11-30-92	TPA has lost all flow. Disconnected at inlet - NO FLOW.
12-2-92	Unit 3 A/SLED ^s Blr & CPD: Etched Na elec; refilled ref. electrodes; replaced monoethylamine reagent; diffusion tubing; all O-rings. Soaked Elec. holder in HCl for Boiler to clean off rust. Calibrated both.

Wold 000068

12-3-92	Replaced reagents in TPA. Overhauled sample piston. ⊗
12-7-92	Unit 1 Boiler Na analyzer. Replaced: ref. electrode, ref. elec. fill. solution reagent & diffusion tubing etched electrode
12-14-92	Unit 1/Unit CPD Na analyzer u-1 changed Na elec & ref elec. Replaced: reagent & diff. tubing u-2 Etched Na elec; filled ref. elec. Replaced in-line filter Calibrated.
12-15-92	Unit 2 Boiler Na Replaced: Reagent, tubing, O-rings, in-line filter, ref. elec. fill. sol'n. Calibrated.
12-17-92	Unit 1 Blr SiO ₂ -changed reagents
12-23-92 ^{JPW}	monthly maint. on 1811L Na analyzer Calibrated - 58.7 slope
12-31-92	Unit 1 CPD SiO ₂ -changed reagents
 <p>★ Δ ★ HAPPY NEW YEAR! ★ ★</p>	

Wold 000069

70

1993

1/6/93 ckf	- New reagent for Series 5000 #32 CPD; - New reagent for Trace Pump Analyzer. - Changed #11, #12 Polisher Resin for Cation conductivity
1/18/93 ckf	New reagent for Series 5000 #11 Blr; New reagent for Series 5000 #22 CPD. Calibrated both monitors after changing reagents.
1/19/93 ckf	Re-gelled unit 1 and 2 hydrazine analyzers.
1/20/93 ckf	Re-gelled Unit 3 hydrazine analyzer.
1/26/93 ckf	Re-tubing Trace pump analyzer. System alarm → std pump failure. & Piston failure.
2/3/93 ckf	Replaced tubing, orings, monoethylamine solution, and etched sodium electrodes for 11, 12, 21, 22, 31 and 32 sodium sleds. Replaced mixed resin beds for 12, 21, and 22 Sodium sled analyzers. Topped off reference electrode solutions as needed.
2/2/93 ckf	Replaced reagent for 21 Silica monitor. (Series 5000)
2/8/93 ckf	Replaced reagent for 12 Silica Series 5000 Analyzer.
2/5/93 ckf	Re-tubed #12 sled Sodium Analyzer, the portion running from the block to the mixed resin bed column. Also replaced in-line filter for #12 sled Sodium analyzer.
2/9/93 ckf	Replaced reagent for 31 Silica Series 5000 Analyzer.

Wold 000070

71

2/10/93 ckf	Polished, electronically cleaned, replaced solution and membrane for Unit One and Unit 2 D. O. Analyzers.
	Calibrated # 11, 12, 21, and 22 Sodium Analyzers.
2/12/93 ckf	Calibrated # 31, and # 32 Sodium Analyzers.
2/16/93 ckf	Replaced monoethylamine, diffusion tubing on the 1811 Na ⁺ Analyzer. Attempted to calibrate but was unsuccessful. May be due to the fact that I etched the Na ⁺ electrode this morning. Will try calibration again.
2/17/93 ckf & RUM	Found, air pump assembly failed. New part on order. The air pump assembly is needed for proper mixing during calibration. This is the reason for calibration failure.
2/26/93 ckf	Calibrated Unit 1 and 2 D.O. Analyzers. Replaced reagent for # 11 Silica analyzer and calibrated instrument.
3/2/93 ckf	Replaced air pump assembly on Na ⁺ Analyzer for Demin. Calibrated. Slope = ERROR Mw.

Wold 000071

3/4/93 AM	CALIBRATED BOILER AND ECONOMIZER PH PROBES ON UNIT 1.
3/8/93 AM	CALIBRATE 1811 Na ⁺ ANALYZER FOR DEMINERALIZER. SUCCESSFUL CALIBRATION.
3/9/93 AM	RUN NEW D.O. MEASURING SYSTEM ON UNIT 2 D.O. D.O. PROBE CAN BE PATCHED-IN TO PATCH BOARD AND MEASURED DIRECTLY OFF HERE WITH FLOW METER, VALVE, AND D.O. ASSEMBLY CONNECTED TO THE ASSEMBLY.
3/19/93 AM	CHANGED REAGENTS ON BOILER $\frac{1}{2}$ CPO SiO ₂ ANALYZERS ON UNITS 1 & 2.
4/16/93	CALIBRATED, CHANGED MONOETHYLAMINE; DIFFUSION TUBING IN ALL Na ⁺ ANALYZERS EXCEPT UNIT 3 BOILER Na ⁺ ANALYZER.
4/21/93	REPLACED MONOETHYLAMINE SOLUTION AND DIFFUSION TUBING ON UNIT 3 BOILER Na ⁺ ANALYZER AND CALIBRATED.
4/21/93	CHANGED REAGENTS IN SiO ₂ ANALYZERS ON UNITS 1 AND 2.
5-4-93	Cleaned Nupro in-line filter on U3 DO sample line it was plugged up and restricting the flow replaced SiO ₂ standard on U1 Series 5000 Boiler silica analyzer. It was unable to calibrate, successful calibration with new standard

Wold 000072



5-4-93	submitted an mwr for pressure relief valve replacement on U2 Boiler silica analyzer
	replaced and calibrated a DO probe on U1 (previously rebuilt) cleaned and rebuilt the spare probe that I removed from U1.
5-7-93	Replaced reagents on U1 and U2 CPD silica analyzers
	Replaced filling solution on U1 Boiler Nat sled
5-11-93	soaked and regelled U3 hydrazine cell
5-14-93 SSB	Replaced unit 3 N_2H_4 cell. Soaked overnight in 2% NaOH, regelled, installed, stabilized, & calibrated Fri. PM.
5-18-93	replaced monoethylamine, diffusion tubing, o-rings, in-line filters, deionization cartridges and etched electrodes on #31 and #32 Nat sleds calibrated both #31 and #32 Nat sleds
	installed new in-line filters on U1 & U2 N_2H_4 analyzers
	replaced reagents and standard on Trace Pump Silica analyzer
	etched electrodes also
5-19-93	changed diffusion tubing, monoethylamine, o-rings & in-line filters on all U1 & U2 Nat sleds. Calibrated U1 & U2 Nat sleds

Wold 000073

14

5-19-93	changed reagents on U3 CPD Series 5000 silica analyzer
5-20-93	replaced standard on U3 CPD Series 5000
5-26-93	1811LL Nat Analyzer Maintenance - changed tubing, o-rings & monoethylamine - etched electrode - new reference solution - calibrated (slope \rightarrow 58.6, $E_0 \rightarrow$ -74.7)
6-1-93	installed and calibrated a DO probe on U3
6-2-93	replaced standard on U1 & U2 Boiler silica analyzers replaced reagents and standard on U3 Boiler silica analyzer transferred Betz chemical at U1 & U2 lab
6-3-93	installed new pH measuring and reference electrodes on U1 Boiler pH
6-4-93	Kevin LaVoi rebuilt U2 economizer drag valve
6-9-93	rebuilt and cleaned the new DO probe and calibrated it for U3. The new one seems to work better for U3. cleaned and rebuilt the spare DO probe so it is ready

Wold 000074

75

6-11-93	replaced reagents on U1 and U2 Series 5000 Boiler silica analyzers
6-15-93	replaced reagents and standard on the Trace Pump Silica Analyzer
6-17-93	installed and calibrated a DO probe for Unit 2. (was rebuilt on 6-9-93)
6-22-93	topped off monoethylamine and calibrated all U1 and U2 Nat sleds
	topped off monoethylamine and calibrated U3 Boiler and CPD Nat sleds
6-23-93	1811LL Nat Analyzer calibrated - etched electrode - calibrated (Slope \rightarrow 60.5, $E_0 \rightarrow$ -75.1)
6-24-93	changed reagents on U3 CPD Series 5000 silica analyzer
6-29-93	replaced bulb on Trace Pump Silica Analyzer
	replaced standard on U1 Boiler Series 5000 Silica Monitor
	replaced reagents and standard on U1 and U2 CPD Series 5000 Silica Analyzers

Wold 000075

76

7/22/93 msb	Rebuilt and Calibrated 1811LL Na Analyzer (Slope = 61.3 / E ₀ - 75.5)
7/21/93 msb	put new membrane on and calibrated O ₂ monitor on U2
8/3/93 msb	Rebuilt and calibrated all Na ⁺ sleds for units 1 & 2
8/16/93 msb	Rebuilt and cal'ed 31 & 32 Na sleds
8/25/93 msb	Rebuilt U3 Netty probe
8/26/93 msb	Calibrated 1811LL Na analyzer / slope 61.3 = E ₀ - 78.4
* 9/8/93 CKF	Replaced reagents for # 31 SiO ₂ analyzer. Replaced SiO ₂ standard for # 12, 22 analyzers.
9/13/93 LLS	Reset Trace Pump Silica Analyzer for 21 days before required maintenance - system alarm cleared.
9/29/93 EUD CKF	New Na, Ref electrodes, diffusion tubing, o-rings, MEA solution, and inline filters for # 31, # 32 Sodium Sleds
9/30/93 CKF	New Na electrode # 12, 21, 22 sleds, New ref electrode # 21, 22 sleds. New MEA & diffusion tubing & air line filter. # 12, 21, 22

Wold 000076

77

9/30/93 CKF	Calibrated # 11, # 21 Sleds. Replaced Replaced Na ⁺ & Ref electrode for Demin. New diffusion tubing & MCA.
9/30/93 LLS	Calibrated # 31, 32 Sodium Analyzer.
10/1/93 CKF	Calibrated # 12, 22 Sleds.
10/4/93 CKF	Replaced SiO ₂ standard on # 32 ^{SiO₂} monitor. Replaced reagents on Trace Pump Silica analyzer and reset system for 28 days.
10/5/93 CKF	Re Re-gelled Unit 2 Hydrazine cell.
10-12-93	Checked out Unit 2 CPD A/SLD. Thought the ref. elec. was bad. NOT. The flow was still in calibration mode. Changed it, recalibrated, works fine. changed cation columns: Unit 2, CPD, 22 Pol. 181114 Demin Na ⁺ may have an electrical problem. I reset the electronics & it seems to do what it's supposed to, but it won't calibrated correctly. Will try again.

Wold 000077

78

10-13-93	Found a broken cable on Na electrode on 1811 LL. BJ fixed it. Etched Na elec. Calibrated 10-14-93 slope = 60.4 $E_0 = 55$
10-14-93	Boiler U-1 SiO_2 analyzer "Unable to Calibrate" - cleaned cell, reaq. feed tubes. Checked flows for all. Good! Std reading too low. On advice from HACH - found stir motor unable to rotate stir star. BJ removed motor, found magnet moved down shaft (too far apart to move star), raised magnet, reinstalled.
10-15-93	Tried calibration - didn't work. Too hi 630
10-15-93	U-3 N_2H_4 - 3 different cells have been installed. Not functional yet. Pump in manual @ 15% for week-end.
10-18-93	N_2H_4 may have a pump problem. #32 MWR was complete, but after being placed in-service, tripped after 10 min. MWR reissued.
10-18-93	Tried another auto-cal on U-1 Boiler got 480 ppb
10-19-93	U-3 Blr SiO_2 - replaced SiO_2 std.
10-19-93	U-1 Blr SiO_2 - auto cal - 505 ppb ★ Cleaned sample cell - wet outside. Drain tube hose clamp loose - leaked

Wold 000078

79

10-19-93	Changed cat. col. resin on Pol 21. Cleared the flow cells on Unit 1,2,3.
10-20-93	U-1 CPD SiO ₂ - reagent replacement.
10-22-93	U-2 CPD SiO ₂ - reagent replacement
10-25-93 CKF	Cleaned Unit 3 O ₂ probe, replaced membrane, and calibrated.
10-29-93 CKF	Replaced reagents on 31 SiO ₂ analyzer
11-1-93 CKF	Replaced reagents on Trace Pump analyzer for D ₂ m. Replaced Moly III tubing and primed line. Rest for 28 days.
11-4-93 BAM	REBUILT O.O. PROBE ON UNIT 1.
11-9-93 BAM	ADJUSTED FLOWS ON UNIT 1 BOILER - A HIGHER WAP BOILER FLOW WITH THE SAME BACK PRESSURE RESULTED IN A LOWER O.O. VALUE -> (5ppb) THE INITIAL O.O. VALUE WAS 8.0ppb. SUSPECT A PROBLEM WITH THE BACK PRESSURE OR MAIN FLOW VALVE.
11-12-93 BAM	ADDED MONOBETHYLAMINE TO UNIT 3 Na ANALYZERS
11-16-93 BAM	REPLACED SiO ₂ REAGENTS - BOILER SiO ₂ ANALYZER UNIT 1

Wold 000079

50

11-16-93 LLS	Unit 1 boiler SiO ₂ -5000 series Replaced lamp; sample cell; sample cell cover assembly & calibrated 464 ppb
11-16-93 DAM	REPLACED REAGENT UNIT 1 BOILER SiO ₂ ANALYZER.
11-17-93 DAM	REPLACED REAGENTS AND STANDARD - UNIT 2 BOILER SiO ₂ ANALYZER. REPLACED STANDARD - UNIT 2 CPD SiO ₂ ANALYZER. ADDED MONOETHYLAMINE TO UNIT 1 AND 2 SODIUM ANALYZERS. REPLACED ELECTRODE FILLING SOLUTION ON #21 SODIUM ANALYZER.
11-18-93 DAM	REPLACED SiO ₂ STANDARD ON UNIT 2 BOILER SiO ₂ ANALYZER. REPLACE IN-LINE FILTER ON UNIT 3 BOILER Na ⁺ ANALYZER.
11/24/93 CKF	Replaced MEA, tubing, o-rings, and C ₂ Cl ₂ on Amin Na ⁺ analyzer. Etched Sodium electrode. Calibrated; slope = 58.6 E ₀ = -60
11/24/93 CKF & Bryan	Johnson Trace pump silica analyzer lost prime again for the Moly III reagent. Took moly III section apart and cleaned holder, replaced o-ring to try to reestablish flow. Also replaced connections and piston. Primed Moly III and calibrated.
11/30/93 DAM	CHANGED RESINS ON ECON, CPD, ZI POLISHED CAT. COND. ANALYZERS.

Wold 000080