

**STATE OF MINNESOTA
BEFORE THE OFFICE OF ADMINISTRATIVE HEARINGS
FOR THE MINNESOTA PUBLIC UTILITIES COMMISSION**

In the Matter of the Review of the July 2018-
December 2019 Annual Automatic
Adjustment Reports

MPUC Docket No. E-999/AA-20-171

OAH Docket No. 82-2500-37082

MINNESOTA POWER'S INITIAL BRIEF

June 28, 2021

MINNESOTA POWER

David R. Moeller
Senior Attorney and Director
of Regulatory Compliance
30 West Superior Street
Duluth, MN 55802
Telephone: (218) 723-3963

**TAFT STETTINIUS &
HOLLISTER LLP**

Kodi J. Verhalen
Matthew R. Brodin
Elizabeth M. Brama
2200 IDS Center
80 South Eighth Street
Minneapolis, MN 55402
Telephone: (612) 977-8400

Attorneys on behalf of
Minnesota Power

TABLE OF CONTENTS

	Page
I. INTRODUCTION	3
II. ISSUES AND LEGAL STANDARD.....	10
III. MINNESOTA POWER’S MAINTENANCE PROGRAMS AND ASSOCIATED EXPENSES WERE CONSISTENT WITH GOOD UTILITY PRACTICE.....	12
A. The Parties Agree on the Definition of Good Utility Practice.....	12
B. Variations Between Actual and Test Year Generation Maintenance Expenses Are Not Evidence of Failure to Comply with Good Utility Practice.....	13
1. The Department Originally Argued that Correlation Equates to Causation.....	14
2. Differences Between Test Year and Actual Generation Maintenance Expenses Were Unrelated to the Outages	15
3. Minnesota Power Did Not Reduce Maintenance or Inspection Levels Related to the Boswell Systems at Issue.....	18
4. Peer Comparisons and Broader Historical Data Provide More Insight into the Reasonableness of Minnesota Power’s Maintenance Spending than Test Year Comparisons.....	18
5. The Department Abandoned its Test Year Comparison Justification	20
C. Minnesota Power’s Maintenance and Inspection Programs Were Consistent with Good Utility Practice	20
1. Minnesota Power’s Maintenance and Inspection Programs were Developed Consistent with Good Utility Practice	21
2. Long-Term Outage Plans at Boswell are Consistent with Good Utility Practice.....	22
3. Minnesota Power Implemented its Generation Maintenance and Engineering Programs Consistent with Good Utility Practice	25
4. Employee Training and Certification are Consistent with Good Utility Practice.....	27
5. The Occurrence of Unplanned Outages Does not Necessarily Indicate a Deviation from Good Utility Practice.....	28
6. Minnesota Power’s Maintenance and Inspection Programs are Highly Effective	29
7. The Record Does Not Support the Department’s Conclusions that Good Utility Practices Were not Implemented.....	32
D. The Undisputed Outage Costs Were Reasonably and Prudently Incurred	34
E. Hydrogen Gas Leak Maintenance, Identification, and Repair Were Consistent with Good Utility Practice	37

1.	Minnesota Power’s Hydrogen-Filled Generator Inspection Protocol Was Consistent with Good Utility Practice	37
2.	Minnesota Power’s Handling of the Hydrogen Gas Leak Outages Was Consistent with Good Utility Practice	38
3.	The Department’s Criticisms Are Unsupported by Evidence.....	44
F.	Phase Bushing Maintenance, Identification, and Repair Were Consistent with Good Utility Practice	46
1.	Minnesota Power’s Phase Bushing Inspection and Maintenance Protocol Was Consistent with Good Utility Practice	46
2.	Minnesota Power’s Handling of the Phase Bushing Outage Was Consistent with Good Utility Practice	47
3.	General Electric Could Not Identify the Proximate Cause of the Bushing Failure	50
4.	The Department’s Conclusions Are Unsupported by Evidence	52
G.	Hot Reheat Maintenance, Identification, and Repair Were Consistent with Good Utility Practice	55
1.	Minnesota Power’s HRH Line Inspection and Maintenance Program Was Consistent with Good Utility Practice	55
2.	Minnesota Power’s Handling of the HRH Steam Line Outage Was Consistent with Good Utility Practice	58
3.	Minnesota Power’s Learning Team Provided Recommendations to Improve the HEP Maintenance and Inspection Program	60
4.	The Department’s Position Is Unsupported By Evidence	61
IV.	REPLACEMENT POWER COSTS WERE REASONABLE AND PRUDENT	76
V.	MINNESOTA POWER’S PROPOSED REFUND METHODOLOGY SHOULD BE USED IF A REFUND IS ORDERED	78
VI.	CONCLUSION.....	80

I. INTRODUCTION

Minnesota Power (the “Company”) respectfully submits this initial post-hearing brief (“Initial Brief”) to the Administrative Law Judge (“ALJ”) in support of the Company’s March 2, 2020 Annual Automatic Adjustment (“AAA”) Report (“2020 AAA Report”). Specifically, Minnesota Power requests that the ALJ find that the Company’s actions prior to and during all unplanned outages from July 1, 2018 and December 31, 2019, were consistent with good utility practice and all replacement power costs were reasonably and prudently incurred.

Public electric utilities like Minnesota Power are required to submit detailed information in their AAA reports supporting the automatic adjustment of energy related costs over a certain period that were included in rates through the automatic adjustment of tariffs authorized by the Minnesota Public Utilities Commission (“Commission”).¹ Minnesota Power’s tariff contains a fuel adjustment clause (“FAC”) that automatically adjusts rates to include certain energy-related costs outside of a general rate case. These automatic adjustments are later subject to Commission review and approval, which the Commission is conducting in the instant docket for the period of July 1, 2018 to December 31, 2019.

The Department reviewed Minnesota Power’s AAA report and submitted its comments, summarizing its review and suggestions.² The Department determined that the Company had substantially complied with the AAA reporting requirements, but concluded that certain replacement power costs incurred by Minnesota Power because of unplanned outages were not reasonable and prudent.³ More specifically, the Department incorrectly assumed a causational link between (1) Minnesota Power’s lower generation maintenance expenses in 2018 and 2019

¹ See Minn. Stat. § 216B.16, subd. 7 (2020); Minn. R. 7825.2390-.2920 (2019).

² REVIEW OF THE JULY 2018-DECEMBER 2019 ANNUAL AUTOMATIC ADJUSTMENT REPORTS, Apr. 15, 2020 (eDocket No. 20204-162132-02).

³ Ex. 9, Schedule 1 at 10 (Rostollan Direct).

compared to the 2017 test year from the Company's last rate case, and (2) the unplanned forced outages experienced by Minnesota Power over the 18 month AAA evaluation period.⁴ The Department took particular issue with three high-impact outages that occurred in 2019: (1) the hydrogen gas leak outage at Boswell Energy Center ("Boswell") Unit 3 ("BEC3"); (2) the phase bushing failure outage at BEC3; and (3) the hot reheat ("HRH") pipe failure outage at Boswell Unit 4 ("BEC4").⁵ The Department suggested that the Commission should order Minnesota Power to reimburse customers for half of the forced outage replacement power costs, which equaled \$3.864 million.⁶ The Company opposed this recommendation, explaining both why the generation maintenance expenses were lower than the test year and why correlation does not equate to causation.⁷ Despite these explanations, the Department stood by its reimbursement suggestion.⁸

The Commission issued an Order Accepting 2018-2019 Electric AAA Reports; Notice of and Order for Hearing ("Order for Hearing") on September 16, 2020 after finding an issue of material fact as to whether Minnesota Power, applying good utility practice, reasonably and prudently incurred forced outage costs during the AAA evaluation period, and referred the issue to the Office of Administrative Hearings ("OAH") for a contested case proceeding.⁹ The parties agree that "good utility practice" in the context of this proceeding includes practices, methods, and acts engaged in or approved by a significant portion of the electric industry, or in the exercise of reasonable judgment given the known facts, could have been expected to accomplish the desired result at a reasonable cost consistent with good business practices, reliability, safety,

⁴ *Id.*

⁵ Ex. 5, Schedule 4 at 7-9 (Simmons Direct).

⁶ Ex. 9, Schedule 1 at 10 (Rostollan Direct).

⁷ Ex. 5, Schedules 3 and 5 (Simmons Direct).

⁸ *Id.*, Schedule 4 at 7-9.

⁹ ORDER FOR HEARING at 8.

and expedition. The parties further agreed that “good utility practice” is not limited to the optimum practice to the exclusion of all others, but rather includes all regionally acceptable practices.¹⁰

Through this contested case proceeding, Minnesota Power presented direct testimony and evidence describing how it developed its maintenance and inspection programs consistent with good utility practices. Specifically, the Boswell programs incorporate information from a number of different internal and external sources, and the Company balances that information to determine what programs and protocols should be incorporated into Boswell’s maintenance program. These programs have been audited by multiple third-party consultants as well as Minnesota Power’s insurance provider.¹¹ Minnesota Power also communicates with peer utilities to discuss standards and any new issues that arise each year.¹² Additionally, the Company confirmed that its programs are performing above industry averages by comparing reliability and outage statistics with other similar units.¹³ By taking into account all of these sources, Minnesota Power ensures that its programs are consistent with good utility practice.

Minnesota Power’s direct testimony and evidence demonstrated two more essential things. First, the correlation between reduced generation maintenance spending compared to 2017 test year levels that the Department relied upon is entirely unrelated to causation of the increased levels of unplanned outages during the AAA evaluation period. Second, Minnesota Power’s maintenance programs and activities and its responses to the unplanned outages were consistent with good utility practice.

¹⁰ See Section III.A below.

¹¹ Ex. 6 at 7 (Poulter Direct).

¹² *Id.* at 6 at 7.

¹³ Ex. 9 at 12-14 (Rostollan Direct).

In general, short-term differences in actual generation maintenance spending from test year levels cannot reliably be used to show any correlation with outage activity.¹⁴ Minnesota Power's direct testimony and associated schedules demonstrated that generation maintenance expenses are cyclical, significantly depend on where in the ten-year major outage cycle the Company is in any given year, and planned maintenance expenses may end up as capital.¹⁵ As a result, it is entirely normal for actual generation maintenance expenses to be higher or lower than the test year levels, depending on the types of maintenance and inspections that occur in a particular year.

Minnesota Power further provided evidence establishing that the differences between the 2017 test year generation maintenance budget and the actual expenses for 2018 and 2019 are almost entirely explained due to the following: inclusion of a three week boiler outage at BEC4 in the test year without a corresponding significant planned outage in 2018 and 2019, which were scheduled to occur in later years; retirement of several generation facilities in 2018 and 2019; changes in the maintenance spending at facilities that did not experience outages in the AAA evaluation period (and thus unrelated to this proceeding); and higher than average project capitalization (lowering maintenance expenses with an increase in capital expenses).¹⁶ Notably, Minnesota Power also clarified that it had not reduced spending or protocols in any of the maintenance or inspection programs related to the systems that experienced unplanned outages during the AAA evaluation period.¹⁷ This demonstrated that the test year versus actuals

¹⁴ *In re the Complaint of Myer Shark et al. Regarding Xcel Energy's Income Taxes*, Docket No. E, G-002/C-03-1871, ORDER AMENDING DOCKET TITLE AND DISMISSING COMPLAINT at 4 (Oct. 1, 2004); Exs. 12 and 13 at 24 (Campbell Direct) (Public and Nonpublic).

¹⁵ Ex. 9 at 4-7 (Rostollan Direct).

¹⁶ *Id.* at 17, 20-23.

¹⁷ Ex. 6 at 6-17 (Poulter Direct); Ex. 5 at 15-20 (Simmons Direct); Exs. 14 and 15 at 17 (Undeland Rebuttal) (Public and Nonpublic).

differences that the Department relied upon to justify its initial refund recommendation were caused by operational differences that had no impact on the level of unplanned outages.

In its direct testimony in this contested case, the Department abandoned its argument that lower generation maintenance spending in 2018 and 2019 compared to the test year caused or contributed to the level of unplanned outages.¹⁸ Instead, for the first time, the Department argued, through its expert witness Mr. Richard Polich, that specific maintenance protocols and actions taken by Company employees were not consistent with good utility practice.¹⁹

With regard to the BEC3 hydrogen leak outage, Mr. Polich does not assert that Minnesota Power could have done anything to prevent the leak. Instead, he argues that Minnesota Power should have immediately identified the float valve as a potential cause of the leak and removed it to test for leakage.²⁰ In response, Minnesota Power reiterated that neither the original equipment manufacturer (“OEM”), General Electric, nor other hydrogen system consulting experts identified the float valve as a potential source until all other sources had been eliminated.²¹ This was because, in their extensive history working with the particular hydrogen system at issue, they could identify only a single other customer that experienced an outage that was resolved by replacing the float valve.²² The OEM and the consultants also indicated that they knew of no testing techniques that would have identified the float valve as defective other than replacing it with a new one, which would have taken 15 weeks to procure.²³ Ultimately, Minnesota Power was able to identify the cause of an extremely rare hydrogen leak and engineer a solution that reduced the necessary outage time by approximately 14 weeks compared to if it had simply

¹⁸ Exs. 12 and 13 at 21-24 (Campbell Direct) (Public and Nonpublic).

¹⁹ Exs. 10 and 11 (Polich Direct) (Public and Nonpublic).

²⁰ *Id.* at 44 (Polich Direct).

²¹ Exs. 14 and 15 at 10 (Undeland Rebuttal) (Public and Nonpublic).

²² Ex. 7 at 28-29, Schedule 4 at 9 (Undeland Direct).

²³ *Id.* at 29, Schedule 4 at 9.

procured a replacement valve from the OEM.²⁴ Thus, Mr. Polich's arguments are entirely without merit. In any event, the Department concedes that any failure by the Company to follow good utility practices did not materially extend the hydrogen leak outage, and, thus, that Minnesota Power's associated replacement power costs were reasonable and prudent.²⁵

With respect to the BEC3 phase A phase bushing failure, Mr. Polich avers that the associated outage was due to Minnesota Power maintenance personnel actions that were not consistent with good utility practice. Specifically, Mr. Polich claims that, during Minnesota Power's efforts to fix the hydrogen leak, it allowed seal oil to spill into the phase bushings, which then caused one of them to overheat and fail.²⁶ As a primary matter, the OEM, General Electric, could not determine whether the phase bushing failure was due to the presence of oil or one of many other possible reasons, so Mr. Polich's causation conclusion is merely speculation.²⁷ Additionally, Minnesota Power was initially unaware that seal oil had spilled because of a faulty alarm setup and the fact that there was no standard industry practice for the use of oil in the novel hydrogen leak testing conducted by Minnesota Power that allowed it to identify and fix the leak.²⁸ Once Minnesota Power became aware of the presence of oil, it drained the oil from the system using the liquid detector drain valve and performed a visual inspection to determine if there was oil remaining in the system.²⁹ Boswell personnel observed the leadbox area near the bushings to be dry and clean, and, thus, did not believe that oil had migrated further into the system, let alone into the phase bushings.³⁰ While Mr. Polich criticizes

²⁴ Exs. 14 and 15 at 10 (Undeland Rebuttal) (Public and Nonpublic).

²⁵ Exs. 12 and 13 at 17 (Campbell Direct) (Public and Nonpublic).

²⁶ Exs. 10 and 11 at 48 (Polich Direct) (Public and Nonpublic).

²⁷ See generally *Id.*, RAP-16.

²⁸ *Id.*, RAP-15 at 6-7.

²⁹ *Id.*, RAP-15 at 4-5.

³⁰ *Id.*, RAP-15 at 4.

the actions of Company employees with the benefit of perfect hindsight, their actions were entirely reasonable given the information they had at the time.

With respect to the HRH steam line seam-weld failure at BEC4, Mr. Polich claims that Minnesota Power's failure to follow the Electric Power Research Institute's ("EPRI") suggested guidelines for the inspection of seam-welded high-energy-piping ("HEP") led to the HRH pipe failure at BEC4.³¹ Specifically, Mr. Polich claims that to be consistent with good utility practice, a utility must perform phased array ultrasonic testing of 100 percent of seam-welded HEP at least every five years.³² He bases these conclusions on his review of EPRI literature and his experience reviewing the HEP inspection programs for three facilities.³³

EPRI, however, is not a standard-setting organization, but rather is a member utility organization that provides suggested practices and procedures to its members for a fee.³⁴ Additionally, the EPRI materials relied upon by Mr. Polich specifically concede that, at one point, only 50 percent of survey respondents *thought* that they were following EPRI's guidelines for seam-welded HEP inspections, but that only 2 percent were *actually* complying with all recommendations.³⁵ EPRI also acknowledged that utilities found its five-year inspection frequency recommendation to be economically untenable, which is why Minnesota Power never seriously considered inspecting on that frequency.³⁶ As a result, Mr. Polich has failed to demonstrate that the EPRI guidelines define the minimum threshold for good utility practice or that Minnesota Power's ten-year inspection protocol, which prioritized high-stress areas for

³¹ *Id.* at 39-40.

³² Exs. 10 and 11 at 39-40 (Polich Direct) (Public and Nonpublic).

³³ Exs. 14 and 15 at 4, Rebuttal Schedule 1 at 2, response to MP IR 04(c) (Undeland Rebuttal) (Public and Nonpublic).

³⁴ Ev. Hrg. Tr. at 75 (Polich).

³⁵ Exs. 14 and 15, Rebuttal Schedule 1 at 33 (Undeland Rebuttal) (Public and Nonpublic).

³⁶ *Id.* at 25, Rebuttal Schedule 1 at 427.

multiple inspections during each period, was inconsistent with any other significant portions of the industry.

Additionally, the three facilities of which Mr. Polich has personal knowledge does not even come close to constituting a “significant portion” of the industry, which consists of hundreds of coal-fired generation facilities. To the contrary, Minnesota Power’s HEP consulting expert, Thielsch Engineering, Inc., informed the Company that its ten-year risk-based HEP inspection program was consistent with Thielsch’s other nationwide clients, and that none of its approximately 50 utility customers performed phased array ultrasonic testing of 100 percent of their HEP on a five year frequency.³⁷ As a result, Mr. Polich has failed to demonstrate that the minimum five-year inspection frequency falls within the range of good utility practice, much less that they define the minimum threshold of good utility practice, as he asserts.

In sum, the record demonstrates that Minnesota Power’s maintenance and inspection programs, protocols, and acts were consistent with good utility practice. Further, the Company reasonably and prudently incurred the replacement power costs during the unplanned outages over the AAA evaluation period. As a result, the Company should not be ordered to refund to customers replacement power costs for unplanned outages that occurred from July 1, 2018 through December 31, 2019.

II. ISSUES AND LEGAL STANDARD

In its Order for Hearing, the Commission determined that the Company has the “burden to establish that any or all of the July 1, 2018 through December 31, 2019, replacement power costs were reasonably and prudently incurred, applying good utility practices.”³⁸

³⁷ Ex. 7 at 18 (Undeland Direct).

³⁸ ORDER FOR HEARING at 8.

A public utility like Minnesota Power has the burden of proving by a fair preponderance of the evidence that any proposed change in rates is just and reasonable.³⁹ A public utility meets its burden of proof by producing affirmative evidence that its costs were prudent and reasonable and that the utility acted reasonably in incurring the costs.⁴⁰

In determining whether to include a claimed cost in rates, the Commission exercises both quasi-judicial and quasi-legislative authority.⁴¹ On the one hand, the Commission acts in a judicial capacity in its fact-finding function to determine the validity of presented facts, and on the other hand, the Commission acts in a legislative function when it balances both cost and non-cost factors in order to arrive at a conclusion among various alternatives.⁴² That is, a public utility must demonstrate both the accuracy of costs incurred in serving its customers and that it would be just and reasonable for it to recover these costs from its customers in rates rather than from its shareholders. Once a public utility has presented substantial evidence, establishing by a fair preponderance of the evidence that its proposed rate change is just and reasonable, then it has met its burdens of production and proof. As demonstrated by the record, Minnesota Power has provided affirmative evidence, not only that replacement power costs were prudently incurred during the unplanned outages experienced from July 1, 2018 through December 31, 2019, but that the Company's generation maintenance programs are consistent with good utility practice.

³⁹ Minn. Stat. § 216B.16, subd. 4 (2020); *In re N. States Power Co.*, 416 N.W.2d 719, 722-23 (Minn. 1987).

⁴⁰ See *In re N. States Power Co.*, 416 N.W.2d at 723.

⁴¹ *Id.* at 722-23.

⁴² See *City of Moorehead v. Minn. Pub. Utils. Comm'n*, 343 N.W.2d 843, 846 (Minn. 1984); see also *St. Paul Area Chamber of Commerce v. Minn. Pub. Utils. Comm'n*, 251 N.W.2d 350, 358 (Minn. 1977).

III. MINNESOTA POWER'S MAINTENANCE PROGRAMS AND ASSOCIATED EXPENSES WERE CONSISTENT WITH GOOD UTILITY PRACTICE

The actions taken by Minnesota Power in the years leading up to the unplanned outages were consistent with good utility practice.

A. The Parties Agree on the Definition of Good Utility Practice

Department witness Richard Polich defined “good utility practice” as follows:⁴³

[A]ny of the practices, methods, and acts engaged in or approved by a significant portion of the electric utility industry during the relevant time period, or any of the practices, methods, and acts which, in the exercise of reasonable judgment in light of the facts known at the time the decision was made, could have been expected to accomplish the desired result at a reasonable cost consistent with good business practices, reliability, safety, and expedition....

“Good Utility Practice” is not intended to be limited to the optimum practice, method, or act, to the exclusion of all others, but rather to refer to acceptable practices, methods, or acts generally accepted in the region in which the Project is located. “Good Utility Practice” includes, but is not limited to, North American [Energy] Reliability Corporation (NERC) criteria, rules, guidelines, and standards, Federal Energy Regulatory Commission (FERC) criteria, rules, guidelines, and standards, and Minnesota Public Utilities Commission criteria, rules, guidelines, and standards, where applicable, and as they may be amended from time to time, including the rules, guidelines, and criteria of any predecessor or successor organization to the foregoing entities.

Minnesota Power generally agrees with this definition, but would add that “good utility practice” in the context of power producing facilities such as Boswell is the product of many different sources of information, including OEM recommended practice and procedures, accepted standards, hands-on experience with the equipment, continuing education and external training of personnel, information shared through interaction with operators of similar equipment, and relevant information from news outlets and trade articles. Additionally,

⁴³ Exs. 10 and 11 at 6-7 (Polich Direct) (Public and Nonpublic).

independent consultants and contractors, especially those who have an expansive client base within the electric utility industry, are a very good source of information regarding the maintenance and inspection programs and practices in place at similar operating units in the region and throughout the country.⁴⁴

B. Variations Between Actual and Test Year Generation Maintenance Expenses Are Not Evidence of Failure to Comply with Good Utility Practice

The Department initially recommended in the AAA proceeding that the Commission require a refund of a portion of Minnesota Power's forced outage expenses because the Department erroneously drew a causation connection between generation maintenance expense lower than the last-approved test year amounts and the unplanned outages that occurred from July 1, 2018 through December 31, 2019 at Boswell. The Department reached this conclusion without engineering analysis of Minnesota Power's generation maintenance programs. The parties' disagreement regarding this issue led the Commission to order additional fact finding through this contested case proceeding. As discussed below, however, correlation does not equate to causation, and there are valid reasons that Minnesota Power's generation maintenance spend was lower than the test year.

Notably, in its direct testimony, the Department essentially abandoned its initial argument that the generation maintenance cost levels are evidence that Minnesota Power's maintenance and inspection programs were not consistent with good utility practice. Despite the Department's apparent reversal of opinion on the probative value of test year comparisons, as the party with the burden of proof, Minnesota Power provides a full explanation below why the Department's initial argument lacks merit.

⁴⁴ Exs. 14 and 15 at 9 (Undeland Rebuttal) (Public and Nonpublic).

1. The Department Originally Argued that Correlation Equates to Causation

In Response Comments filed on May 29, 2020, in the AAA docket, the Department recommended that the Commission disallow approximately half of the Company's forced outage replacement power costs from the eighteen-month period, which equaled \$3.864 million.⁴⁵ The Department concluded that these costs should be disallowed solely for the following reasons:

Given the high level of forced outage costs, [Minnesota Power]'s low level of maintenance of generation plants, especially compared to the amounts charge (*sic*) to ratepayers, and the fact that the Commission previously indicated the significance of maintaining generation facilities to keep outage costs reasonable, the Department concludes that [Minnesota Power] has not demonstrated that it is reasonable for [Minnesota Power] and its shareholders to keep the \$12.4 million in underspent generation and maintenance expense (which is a base rate expense) at the same time that ratepayers have had to pay \$7.727 million in forced outage costs via the fuel clause.⁴⁶

In other words, the Department felt that an increased level of outages occurred as a result of “underspent generation and maintenance expense.”

Minnesota Power filed additional comments explaining how the three outages with which the Department took issue were not the result of maintenance underspend, and that there were valid reasons why the generation maintenance and inspection expense costs were lower than the generation maintenance test year, particularly given the cyclical nature of long-term maintenance schedules.⁴⁷ The Department was unmoved, and maintained its recommendation.⁴⁸ Because the Commission determined it did not have sufficient information and the Department lacked staff engineering expertise, on September 16, 2020, the Commission ordered this contested case

⁴⁵ Ex. 9, Schedule 1 at 10 (Rostollan Direct).

⁴⁶ *Id.*

⁴⁷ Ex. 5, Schedules 3, 5 (Simmons Direct).

⁴⁸ *Id.*, Schedule 4 at 8-9.

proceeding to develop a full record addressing whether Minnesota Power's forced outage costs for the period were reasonably and prudently incurred, applying good utility practices.

2. Differences Between Test Year and Actual Generation Maintenance Expenses Were Unrelated to the Outages

The Department's original justification for recommending a refund assumed that a correlation equated to causation between Minnesota Power's lower-than-test-year generation maintenance expenses in 2018 and 2019 and the number and cost of unplanned outages at Boswell over that period. In doing so, the Department failed to consider the critical factual context or acknowledge that differences between test year and actual maintenance spending are completely normal and expected or, as in this case, can be explained by other factors.

Rate cases use the concept of a test year for purposes of establishing just and reasonable base rates for customers. Generally speaking, a test year allows a comparison of a utility's base costs over a defined period (i.e., the test year), including operating expenses, with its total revenues from electricity sales. A future test year uses forecasts of expenses and sales that are intended to be reasonably representative of both actual costs and revenues of a utility but are not intended to match exactly actual costs and revenues.⁴⁹ The Commission has previously described the "test year" method as follows:

Rates that ratepayers pay are based on representative levels of revenue, costs, and investments in a "test year" determined at the time of the most recent rate case. Once rates are set, they are considered to be reasonable until they are changed in the next rate case, or pursuant to any pass-through mechanisms that have been approved by the Commission. Although individual cost components that were used to develop the rates may vary (increase or decrease) after the rates are set, no adjustment (with the

⁴⁹ Ex. 9 at 6-7 (Rostollan Direct).

exception of the pass-throughs) is made outside of a rate case for increases or decreases in the individual components of rates.⁵⁰

Thus the Commission does not expect that utilities will spend, or will seek to spend, the exact amounts included in the test year, but rather understands that actual spend will vary from year to year for a multitude of reasons. In direct testimony, the Department largely concurred that “expenses approved in the test year are not intended to exactly reflect actual spending levels . . . and “the Commission does not approve generation maintenance expense on a plant-by-plant basis.”⁵¹

Rather than using the test year as a basis for budgeting purposes, the Company establishes its maintenance expense budget using a “zero-based” process.⁵² This requires building the budget from a baseline, while taking into account historical amounts and activities as well as operational changes.⁵³ In doing so, the Company evaluates its operating and maintenance needs for that year based on multiple inputs including labor, equipment, tools, and supplies.⁵⁴ The amount budgeted in a given year for generation maintenance fluctuates, in part, based on the length and scope of planned outages each year at the Company’s generation units according to the long-term outage plan.⁵⁵ Consistent with the outage plan, the length and scope of the outages vary each year, which, in turn, causes fluctuations in the generation maintenance expense from year to year.⁵⁶ In addition, organizational and operational changes, as well as the evolution of operating and maintenance practices, can impact the amount of a specific expense

⁵⁰ *In re the Complaint of Myer Shark et al. Regarding Xcel Energy’s Income Taxes*, Docket No. E, G-002/C-03-1871, ORDER AMENDING DOCKET TITLE AND DISMISSING COMPLAINT at 4 (Oct. 1, 2004).

⁵¹ Exs. 12 and 13 at 24 (Campbell Direct) (Public and Nonpublic).

⁵² Ex. 9 at 4-6 (Rostollan Direct).

⁵³ *Id.*

⁵⁴ *Id.*

⁵⁵ *Id.*

⁵⁶ *Id.*

incurred compared to a given test year. Ultimately, the Company invests in maintenance expenses across the Company where it is needed to best serve customers in any given year, which may or may not match the Company's representative test year budget for a specific maintenance category.

In the present proceeding, the differences between the 2017 test year maintenance budget and the actual maintenance expenses for 2018 and 2019 can largely be explained due to the retirement of certain generation facilities in 2018 and 2019, changes to the maintenance expenses of facilities that did not contribute to increased unplanned outages, and higher than projected capitalization of maintenance projects that unexpectedly grew in scope.⁵⁷ Taking these explainable differences between the 2017 test year and 2018 to 2019 actual spend into account, the Company's actual maintenance spend for Boswell in 2018 and 2019 was only about \$1.9 million, or 5.4 percent (as an average over that period), lower than the test year.⁵⁸ That difference, however, is almost entirely due to the fact that the 2017 test year amount included a three-week boiler outage at BEC4, which, consistent with its long-term outage plan, had much shorter planned outages in 2018 and 2019, but would occur again in future years. This difference in length and scope of planned outages, associated with plant systems not the subject of the primary outages the Department raised issues with, contributed to lower generation maintenance expense of approximately \$1.5 million in 2018 and \$2.2 million in 2019 as compared to the 2017 test year.⁵⁹ Thus, the lower amount of maintenance spending in 2018 and 2019 compared to the 2017 test year, which the Department relied upon to justify its initial refund recommendation,

⁵⁷ *Id.* at 17, 22-23.

⁵⁸ *Id.* at 20.

⁵⁹ *Id.* at 22-23.

was caused by operational differences that are entirely unrelated to the outages at issue in this proceeding.

3. Minnesota Power Did Not Reduce Maintenance or Inspection Levels Related to the Boswell Systems at Issue

The heart of the Department's original rationale for recommending a reimbursement of unplanned outage costs was its conclusion that Minnesota Power reduced maintenance levels to an extent that caused an increase in unplanned outages. But the evidence and testimony demonstrates that Minnesota Power has made no reductions in the maintenance and inspection protocols related to the systems affected by unplanned outages during the applicable period.⁶⁰ The Department neither produced nor pointed to any evidence of maintenance or inspection program reductions. Rather, as discussed in more detail below, the Department now argues that Minnesota Power should have been doing more than was called for under the programs in place during the last rate case. In fact, as discussed in detail below, the programs and practices that the Department advocates should have been in place, if adopted as good utility practice, would cost the Company (and its customers) more than the amounts incurred in replacement power costs as a result of the unplanned outages.

4. Peer Comparisons and Broader Historical Data Provide More Insight into the Reasonableness of Minnesota Power's Maintenance Spending than Test Year Comparisons

When comparing Boswell's maintenance expenses to those of other similarly sized coal-fired units across the country, BEC3 and BEC4's maintenance expense per megawatt ("MW") of installed capacity from 2015 to 2019 is slightly higher than the average of the other comparable facilities.⁶¹ More specifically, Boswell's 2019 maintenance expense per MW of installed

⁶⁰ Ex. 6 at 11 (Poulter Direct); Ex. 5 at 15-20 (Simmons Direct); Exs. 14 and 15 at 17 (Undeland Rebuttal) (Public and Nonpublic).

⁶¹ Ex. 9 at 12 (Rostollan Direct).

capacity was approximately eight percent higher than the average of the other comparable facilities.⁶² This demonstrates that the amount of maintenance expenses incurred for BEC3 and BEC4 is consistent with other comparable facilities, which is contrary to the Department's theory that the Company reduced its maintenance spending below industry norms or good utility practice.

Several other metrics further demonstrate that Minnesota Power is maintaining its generating facilities consistent with good utility practice. For example, the Department's own analysis of outage costs as a percentage of energy costs for each Minnesota investor-owned utility shows that over the last ten AAA periods (2010 to 2019), Minnesota Power's outage costs as a percentage of energy costs are on par with Xcel Energy's averages.⁶³ For the 2019 AAA period specifically, outage costs as a percentage of energy costs for Minnesota Power were 2.92 percent.⁶⁴ This is nearly 30 percent lower than the Company's 10-year average and is the third lowest percentage in that 10-year period.⁶⁵ The 2.92 percent during the 2019 AAA period for the Company is also approximately 10 percent lower than Xcel Energy's 3.25 percent for the same period.⁶⁶ This analysis indicates that Minnesota Power's outage costs as a percentage of energy costs for the 2019 AAA period were reasonable compared to the Company's historical average as well as Xcel Energy's 2019 AAA period and historical average.

The fuel and purchased power costs per megawatt-hour ("MWh") for Minnesota Power customers during the 18-month period were also about six percent lower than the customers of

⁶² *Id.* at 13.

⁶³ *Id.*

⁶⁴ *Id.* at 13-14.

⁶⁵ *Id.*

⁶⁶ Ex. 9 at 14 (Rostollan Direct).

other Minnesota investor-owned utilities.⁶⁷ This shows that Minnesota Power's rates for fuel and purchased power are not only reasonable, they are actually lower than the average rates of the other Minnesota utilities.

5. The Department Abandoned its Test Year Comparison Justification

In response to Minnesota Power's testimony demonstrating the Department's erroneous assumptions related to, and use of, its comparison between the 2017 test year and 2018 to 2019 actual maintenance costs, the Department abandoned that argument through its direct testimony.⁶⁸ Rather, the Department asserted that the original reason it objected to the Company's replacement power costs is now irrelevant, and that the focus should be solely on whether Minnesota Power acted in accordance with good utility practice with regard to the contested forced outages.⁶⁹ In other words, the Department is no longer arguing that test year comparisons provide evidence of whether Minnesota Power's maintenance practices are consistent with good utility practice. Instead, the Department asserted, for the first time in this proceeding through its expert's direct testimony, that specific elements of Minnesota Power's maintenance programs and actions (or inactions) taken by the Company were inconsistent with good utility practice and resulted in the contested outages.⁷⁰

C. Minnesota Power's Maintenance and Inspection Programs Were Consistent with Good Utility Practice

The Department largely does not take issue with Minnesota Power's overall maintenance and inspection programs, but rather it takes issue with specific elements of the maintenance and

⁶⁷ *Id.*

⁶⁸ Exs. 12 and 13 at 21-24 (Campbell Direct) (Public and Nonpublic).

⁶⁹ *Id.* (adjustments to the test year to reflect known operational differences unrelated to the outages "are ultimately irrelevant to the Commission's directive; namely, to consider whether Minnesota Power's actual maintenance activities and forced outage events reflect good utility practice.").

⁷⁰ LPI also moved to intervene in this proceeding and was granted party status, but offered no pre-filed testimony or witnesses for cross-examination.

inspection practices for the equipment that caused the disputed outages. But all of Minnesota Power's maintenance and inspection programs and protocols were created using a common overall methodology, which, as discussed below, is consistent with good utility practice.

1. Minnesota Power's Maintenance and Inspection Programs were Developed Consistent with Good Utility Practice

To ensure that its maintenance and inspection programs are consistent with good utility practice, Minnesota Power utilizes many different sources of information and expertise to develop and analyze its programs. Specifically, Minnesota Power's maintenance programs incorporate applicable OEM recommended practice and procedures, industry-accepted and applicable standards, Minnesota Power's decades of hands-on experience with the equipment, continuing education and external training of maintenance personnel, information shared through trade groups and interaction with operators of similar equipment, recommendations from independent engineering vendors and outside consultants, its own internal learning teams, and relevant information from news outlets and trade articles.⁷¹ The various maintenance programs at Boswell continuously evolve as new procedures and technologies are introduced across the industry and become more economical and practical to use. Minnesota Power also seeks input from independent consultants, contractors, independent consultants, and the Company's insurers to inform Boswell about the programs utilized at other operating units and help evaluate whether those programs (or portions thereof) should be incorporated into Boswell's maintenance program.⁷²

The Company had its preventative maintenance process audited by third-party consultants Idcon, Reliability Solutions, Genesis Solutions, and RMG approximately a decade

⁷¹ Exs. 14 and 15 at 9 (Undeland Rebuttal) (Public and Nonpublic).

⁷² Ex. 6 at 7 (Poulter Direct).

ago.⁷³ The audit concentrated on the Boswell facility but also provided opinions on the other generating facilities including hydro and the renewable energy stations.⁷⁴ The audit resulted in additional training in the form of Reliability University, which over 60 engineers, superintendents, and maintenance leads attended and led to modifications of the overall maintenance work process.⁷⁵ Minnesota Power’s insurance carrier, FM Global, also reviewed the Company’s maintenance plans and records and provided recommendations and guidelines to minimize risks.⁷⁶

2. Long-Term Outage Plans at Boswell are Consistent with Good Utility Practice

To plan maintenance and inspection activities at Boswell, the Company utilizes a 10-year rolling schedule that corresponds with the OEM and insurer recommended inspection interval for the turbines in each facility.⁷⁷ Table 1 provides a generalized turbine and boiler major outage schedule for these units.

Table 1. Generalized Turbine and Boiler Major Outage Schedule⁷⁸

Year 0	Year 1	Year 2	Year 3	Year 4	Year 5	Year 6	Year 7	Year 8	Year 9	Year 10
Major Outage			Boiler Outage		Half-Major Outage			Boiler Outage		Major Outage
6-8 weeks			3 weeks		6-8 weeks			3 weeks		6-8 weeks

Boiler and turbine outages are planned in tandem to minimize facility downtime due to planned outages. In year zero, the Company conducts a six to eight week “Major Outage,” which consists of a five-year turbine outage as well as a ten-year major boiler outage. A

⁷³ *Id.* at 14.

⁷⁴ *Id.*

⁷⁵ *Id.*

⁷⁶ Ex. 7 at 25 and 34, Schedule 3 at 7 and 11 (Undeland Direct).

⁷⁷ An example long-term outage schedule is included in Ex. 5, Schedule 6 (Simmons Direct).

⁷⁸ *Id.* at 7.

standard boiler outage, which typically takes approximately three weeks, is scheduled for 30 months after the initial major outage. In year five, the Company conducts a “Half-Major” outage, which consists of a five-year turbine outage along with a standard boiler outage. Another three-week standard boiler outage is scheduled for 30 weeks after the Half-Major outage. Finally, in year 10 the outage schedule starts over again with another six to eight week “Major Outage.”⁷⁹

Four to five day maintenance outages are also scheduled for every spring and fall when there is less demand on the system and replacement power costs are lower. The Company uses these short outages to clean and inspect the boiler and perform balance of plant work that is needed to keep the units operating safely and reliably until the next scheduled boiler or turbine outage.⁸⁰ When issues arise between scheduled outages that were not accounted for in existing outage planning, they are added to a “hot list” of items that will be completed at the next practicable scheduled or unscheduled outage.⁸¹

The long-term outage schedule is reviewed and updated at least once a year and outage dates are scheduled with Midcontinent Independent System Operator (“MISO”) two years in advance. Capital projects are aligned with the outage schedule years in advance. As soon as a scheduled outage is complete, the Company begins detailed preparation for the next planned outage.⁸² The outage plan preparation process is detailed in the Direct Testimony of Mr. Simmons.⁸³

⁷⁹ *Id.* at 8.

⁸⁰ *Id.*.

⁸¹ *Id.* at 8-9.

⁸² *Id.* at 9.

⁸³ Ex. 5 at 10-11, Schedule 7 (Simmons Direct).

Minnesota Power collaborates with third-party consultants to aid in developing outage schedules, inspections, and repair plans when industry expertise in a particular area is necessary or would be beneficial to the planning and implementation of the outages.⁸⁴ Minnesota Power does not, however, hire specialty consultants to perform overall outage scheduling and planning for the Company, but rather selectively incorporates the recommendations of contractors into the Company's broader outage planning and scheduling.⁸⁵ Minnesota Power's Boswell outage planning team works with consultants and OEMs to efficiently coordinate scheduling and the scope and timing of outage work.⁸⁶ The development of the work scope and schedule is the responsibility of the Company's Boswell outage planning team.⁸⁷

One of the most significant benefits of collaborating with consultants who work at other facilities around the United States is that their industry-wide experience becomes available to Minnesota Power. OEMs and independent consulting engineers can provide Minnesota Power with valuable information about industry practices and issues that have arisen at other facilities.⁸⁸

Minnesota Power also uses information from similar plants around the country when developing its outage plans. For example, the Company is a member of the Association of Edison Illuminating Companies ("AEIC"), which is a working group that serves as a network to compare best practices and lessons learned with other utilities.⁸⁹ The Company also currently holds annual benchmark meetings with the Xcel Energy Sherco Station to discuss maintenance, inspection, and operational issues that are being experienced.⁹⁰

⁸⁴ *Id.* at 11.

⁸⁵ *Id.*; Exs. 14 and 15 at 31 (Undeland Rebuttal) (Public and Nonpublic).

⁸⁶ Ex. 5 at 12 (Simmons Direct).

⁸⁷ *Id.*

⁸⁸ *Id.*; Ex. 6 at 14-16 (Poulter Direct).

⁸⁹ Ex. 5 at 13 (Simmons Direct).

⁹⁰ *Id.*

In sum, Minnesota Power, and specifically Boswell, utilize a variety of resources to ensure its outage plans are consistent with good utility practice. The Company follows OEM guidelines for maintaining inspections, repairs, and upgrades to equipment, and uses those guidelines to drive the maintenance planning schedule.⁹¹ Boswell follows all state guidelines and regulations for the inspections of its boiler piping, welding repairs inspections and HEP lines.⁹² Utilizing external and internal experts provides more industry-wide expertise that better informs the Company's maintenance and inspection program planning. And finally, the Company leverages the experience gained through decades of operation at the facility and the knowledge and confidence of the staff to implement improvements.⁹³

There is risk with any maintenance testing and inspection program. For example, while it may be technically possible to test every pipe in the plant every year using outages of sufficient length, such a program would not be fiscally responsible given the low probability of failure. It is the responsibility of the system engineer, in coordination with the external engineers and consultants, the other system engineers, and the plant manager, to establish the appropriate maintenance and inspection cycles.⁹⁴ These cycles are based on risk analysis of the HEP.⁹⁵

3. Minnesota Power Implemented its Generation Maintenance and Engineering Programs Consistent with Good Utility Practice

The goal of Boswell's maintenance programs is to have the units available for full, reliable production when needed to provide energy to customers. Ideally, this means that a unit is available for full production except for during planned outages.⁹⁶

⁹¹ *Id.* at 14.

⁹² *Id.*

⁹³ *Id.*

⁹⁴ Ex. 6 at 4 (Poulter Direct).

⁹⁵ Exs. 14 and 15 at 18 (Undeland Rebuttal) (Public and Nonpublic).

⁹⁶ Ex. 5 at 15 (Simmons Direct).

The maintenance programs for BEC3 and BEC4 generally fall within three categories: preventative maintenance (“PM”); predictive maintenance (“PdM”); and corrective maintenance. Minnesota Power leverages several different types of resources to carry out the maintenance programs, including people, tools, parts, Computer Maintenance Management Systems (“CMMS”), and metric collection and analysis.⁹⁷

Boswell uses the PM program to inspect and maintain the equipment on a time-based frequency to ensure system reliability and availability.⁹⁸ PM includes regular maintenance activities such as lubrications, minor adjustments, etc. that are scheduled based upon the calendar or runtime intervals recommended by the manufacturer or adjusted because of hands on experience with the equipment.⁹⁹

The PdM program, which operates in parallel to the PM program, utilizes the latest in technology such as vibration, thermography, motor testing, and other methods to monitor the equipment while it is operating in order to predict and identify when equipment will need maintenance, repair, or replacement.¹⁰⁰ Plant operators utilize the Company’s distributed control system (“DCS”) with integrated alarms and the Black & Veatch 24/7 Asset 360 Plant System Monitoring to proactively identify abnormalities in equipment operation.¹⁰¹ When abnormalities are detected, plant staff takes steps to further minimize the risk of unplanned outages with several maintenance programs and support technology.¹⁰² Not all failures are detectable by PdM, so the program works in concert with the PM and other programs to improve reliability.¹⁰³

⁹⁷ Ex. 6 at 6 (Poulter Direct).

⁹⁸ Ex. 5 at 15 (Simmons Direct).

⁹⁹ Ex. 6 at 6 (Poulter Direct).

¹⁰⁰ *Id.*; Ex. 5 at 15 (Simmons Direct); Ex. 7 at 3 (Undeland Direct).

¹⁰¹ Ex. 7 at 2-3 (Undeland Direct).

¹⁰² *Id.*

¹⁰³ Ex. 5 at 15 (Simmons Direct).

Finally, corrective maintenance includes day-to-day maintenance, repairs, and replacements that can occur during planned maintenance outages, unplanned outages, or while the unit is online and there is enough time to execute work prudently and safely.¹⁰⁴

4. Employee Training and Certification are Consistent with Good Utility Practice

As described in more detail by Company witness Mr. Poulter, Minnesota Power requires that Boswell engineers, technicians, and trade employees complete a variety of internal and external training and certifications as a condition of their employment and advancement.¹⁰⁵ The licenses and certifications held by Boswell employees also include various continuing education requirements.¹⁰⁶

Minnesota Power also employs a number of professional engineers (“PE”) licensed in the state of Minnesota.¹⁰⁷ A PE license requires a four-year engineering degree, completion of a requisite number of years of engineering experience in various areas, and passing technical competency examinations.¹⁰⁸ Maintaining a PE license requires completion and reporting of continuing education credits.¹⁰⁹ Licensed PEs participate in various aspects of the Boswell maintenance programs.¹¹⁰

Additionally, in 2011, Minnesota Power began participating in a training and education program called Reliability University as part of the Company’s continued improvements to its PdM, PM, and engineering programs.¹¹¹ Reliability University instructors, who are subject matter experts in specific areas, provided training regarding best practices surrounding

¹⁰⁴ Ex. 6 at 6 (Poulter Direct).

¹⁰⁵ *Id.* at 10-12.

¹⁰⁶ Ex. 5 at 22 (Simmons Direct).

¹⁰⁷ Ex. 6 at 11 (Poulter Direct).

¹⁰⁸ *Id.*

¹⁰⁹ *Id.*

¹¹⁰ *Id.*

¹¹¹ Ex. 5 at 22 (Simmons Direct).

equipment maintenance, predictive strategies, failure analysis, pumping systems, bearing design, installation, and testing of equipment, along with the use of proactive instead of reactive tools to ensure equipment reliability.¹¹²

As employees learn new information through training and continuing education that is relevant to Boswell's systems, Minnesota Power utilizes it to improve the facility's maintenance and inspection programs.¹¹³

5. The Occurrence of Unplanned Outages Does not Necessarily Indicate a Deviation from Good Utility Practice

Even if a power generation facility uses all available information and technology to create a maintenance and inspection program that applies good utility practice, unplanned outages will still occur.¹¹⁴ First, it is not possible to predict or avoid all types of defects through testing and monitoring.¹¹⁵ Second, while increased inspections and testing of almost all systems would likely reduce the overall amount of failures and unplanned outages, such testing may not be operationally or economically practical. For example, it is tremendously difficult to access, or would require a significant amount of labor hours to provide access to, certain system components.¹¹⁶ These types of labor- and time-intensive inspections can only be completed during longer outages, so they may only be scheduled at the same time as major outages or they would require longer planned outages on a more frequent basis.¹¹⁷ Other more frequent testing and inspection protocols would be extremely expensive when compared to the potential

¹¹² *Id.*

¹¹³ Ex. 6 at 11-12 (Poulter Direct).

¹¹⁴ Ex. 5 at 22 (Simmons Direct).

¹¹⁵ See Ex. 7 at 8 (Undeland Direct) ("It would be extremely difficult and very expensive to eliminate all unplanned outages."); see also Exs. 10 and 11 at 14 (Polich Direct) (Public and Nonpublic) ("Yes, some forced outages, such as boiler leaks, are unavoidable even with the best maintenance practices.").

¹¹⁶ Ex. 5 at 24 (Simmons Direct).

¹¹⁷ *Id.*

benefits.¹¹⁸ As a result, system engineers and plant managers must make judgments to weigh the costs of implementing more frequent or expensive inspection and monitoring with the potential costs associated with an outage that could have been avoided.

6. Minnesota Power's Maintenance and Inspection Programs are Highly Effective

Unplanned outages are an unavoidable reality. As a result, Minnesota Power, and the power generation industry in general, assume and plan for a number of unplanned outages at each facility. To track and plan for these unplanned outages, the Company utilizes the Equivalent Unplanned Outage Factor ("EUOF"), which is the fraction (or percentage) of a given period in which a generating unit is not available due to outages or de-ratings.¹¹⁹ The Company's 2015 Integrated Resource Plan ("IRP") utilized an EUOF of 7.4 percent for BEC3 and 7.2 percent for BEC4.¹²⁰ The EUOF calculation method follows the North American Electric Reliability Corporation ("NERC") Generation Availability Data System data reporting instructions.¹²¹ Due to the substantial impact a significant outage can have on an EUOF in a single year or over a short period, Minnesota Power looks at a ten year average for forecasting and budgeting purposes, and often excludes the most significant events from the calculations.¹²²

In order to analyze the efficacy Minnesota Power's maintenance and inspection programs, it is necessary to look at a longer period of time because significant outages occur sporadically and skew short term analyses. The fifteen-year history of the actual EUOFs for BEC3 and BEC4, which are depicted in the figures below, demonstrate that they are trending

¹¹⁸ Ex. 7 at 8 (Undeland Direct).

¹¹⁹ Ex. 5 at 31 (Simmons Direct).

¹²⁰ *Id.*

¹²¹ *Id.* at 32.

¹²² *Id.*

closely with budget and IRP EUOFs, with some years lower and some years higher than budget and IRP.¹²³

Figure 1. BEC3 EUOF (2005 through 2020)¹²⁴





Figure 2. BEC4 EUOF (2005 through 2020)¹²⁵



These historical trends show that, although BEC3 and BEC4's EUOFs are volatile from year to year, they have generally trended downward over time. Additionally, the EUOF levels

¹²³ *Id.* at 32-33.


¹²⁴ *Id.* at 32.

¹²⁵ Ex. 5 at 33 (Simmons Direct).

from 2018 and 2019 are less than some of the EUOFs from prior years, demonstrating that the outages at issue did not fall outside of each facility's historical range.


When compared to the industry, BEC3 and BEC4 have considerably outperformed their peers, even when including the outages at issue in this proceeding. Figure 3 and Figure 4, below, provide BEC3 and BEC4's EUOFs for 2014 to 2019 compared to similar size units.

Figure 3. Industry EUOF Comparison for BEC3 (2014-2020)¹²⁶



¹²⁶ *Id.* at 34.

Figure 4. Industry EUOF Comparison for BEC4 (2014-2020)¹²⁷



Over the six-year period, despite annualized variations, BEC3 operated 36 percent better than the NERC average and BEC4 operated 53 percent better than NERC average.¹²⁸

The EUOF history and comparison to industry peers speaks to the actual efficacy of Minnesota Power's maintenance and inspection programs at Boswell, as compared to limiting analysis to an 18-month snapshot in an attempt to define the effectiveness of those programs.

7. The Record Does Not Support the Department's Conclusions that Good Utility Practices Were not Implemented

Department expert Mr. Polich only took issue with two of Minnesota Power's general maintenance program practices. First, he criticized Minnesota Power's reliance upon outside consultants to develop its maintenance inspection plans and protocols. Second, he indicated that Minnesota Power must conduct a detailed cost-benefit analysis when evaluating every potential change in inspection frequency, method, technology, etc.

With respect to Minnesota Power's level of reliance on industry expert consultants, Mr. Polich misrepresents both the Company's level of reliance on such consultants and the

¹²⁷ *Id.*

¹²⁸ *Id.*

significance of the information and expertise they can provide to Company decision makers. As discussed in more detail in Section III.G.4.b below, Minnesota Power does not rely exclusively on Thielsch or any other third party consultant to develop maintenance and inspection programs. The development of maintenance schedules, inspection and outage procedures and plans, and repair plans requires a significant collaborative and detailed process. Minnesota Power maximizes the knowledge, capabilities, and experience of Boswell personnel and system engineers by obtaining and incorporating information from OEMs, third-party consultants and contractors, and other outside sources.¹²⁹ While the knowledge that outside consultant experts have gained through experience at coal-fired power plants around the country is invaluable, the Company weighs it against all other sources of internal and external information utilized in developing the Company's maintenance program.¹³⁰ This allows Minnesota Power to leverage information from industry experts while also ensuring the Company maintains knowledge and ultimate control over the maintenance program at Boswell.¹³¹

Obtaining information from industry experts is not contrary to good utility practice, as the Department seems to opine. Rather, utilizing industry experts, especially in highly specialized areas, is entirely consistent with good utility practice.

Department expert Mr. Polich also opines that “a cost benefit analysis on maintenance activities that incorporate[s] probabilistic risk analysis that compares the impact of additional maintenance costs versus cost of forced outage costs on customer rates” is necessary to evaluate risk against expenditure of maintenance costs.¹³² That level of analysis, however, is not

¹²⁹ Exs. 14 and 15 at 15 (Undeland Rebuttal) (Public and Nonpublic).

¹³⁰ *Id.* at 30-32.

¹³¹ *Id.* at 15.

¹³² *Id.*

necessary or even appropriate to justify undertaking or not undertaking every possible maintenance activity.¹³³

As a primary matter, the term “probabilistic risk analysis” is prevalent in nuclear facilities, but not in coal-fired facilities.¹³⁴ Additionally, it is not realistic to expect a facility to run a probabilistic risk analysis for every possible change in maintenance frequency or methods, because the possibilities are endless.

The Company completes all maintenance that is necessary to maintain generating units’ operations as identified through the collaborative, iterative, and coordinated process described above. While power production facilities must certainly consider different options, certain proposals are, on their face, not appropriate for further analysis. Other proposals require additional diligence before they are accepted or rejected for the specific system programs at Boswell.¹³⁵

Ultimately, the Company has provided more than sufficient evidence in the record to establish that its methods for developing its generation maintenance and inspection programs are consistent with good utility practice.

D. The Undisputed Outage Costs Were Reasonably and Prudently Incurred

From July 1, 2018 through December 31, 2019, Boswell experienced 26 unplanned outages.¹³⁶ Minnesota Power provided details and discussion regarding each of these outages in Company witness Mr. Undeland’s Direct Testimony.¹³⁷ No unplanned outages occurred at any

¹³³ *Id.* at 16.

¹³⁴ *Id.*

¹³⁵ Exs. 14 and 15 at 16 (Undeland Rebuttal) (Public and Nonpublic).

¹³⁶ Ex. 5 at 29 (Simmons Direct).

¹³⁷ Ex. 7, Schedule 2 (Undeland Direct).

other Minnesota Power facility during that period, so only Boswell's maintenance programs and unplanned outages are at issue in this contested case.¹³⁸

Of the 26 unplanned outages during the evaluation period, the Department took specific issue with three of the outages when the matter was initially before the Commission: the BEC4 HRH line steam leak, the BEC3 A phase bushing failure, and the BEC3 hydrogen leak. Although the Department did not take issue with the remaining 23 unplanned outages, Minnesota Power provides a brief discussion of how the unplanned outage costs were reasonably and prudently incurred, taking into account good utility practice.

Boswell experienced three types of outages over the eighteen-month evaluation period in 2018 and 2019: low impact, predicted, and high impact.¹³⁹ The 23 outages that the Department did not specifically address fall into the first two categories, while the three outages challenged by the Department were high impact outages.

The causes of outages with a low impact from an outage time and replacement energy cost perspective, such as boiler water wall tube leaks, are difficult to predict and locate.¹⁴⁰ Low impact outage maintenance and repair can typically be completed within 24 to 48 hours.¹⁴¹ Developing PM and PdM programs to attempt to eliminate low impact outages would require many additional weeks of planned outage time a year and a significant increase in the Company's annual generation maintenance expenses.¹⁴² It is neither operationally feasible nor fiscally reasonable to inspect 100 percent of Boswell's generating facilities on an annual basis.

¹³⁸ Ex. 5 at 34 (Simmons Direct).

¹³⁹ Ex. 7 at 8 (Undeland Direct).

¹⁴⁰ *Id.*

¹⁴¹ *Id.* at 9.

¹⁴² *Id.* at 8.

For example, the BEC4 boiler measures approximately 60 feet by 53 feet across and 200 feet in height, and the overall length of tubing within the boiler totals approximately 147.6 miles.¹⁴³ The boiler is not easily accessible and takes significant planning and coordination to access, clean, and inspect.¹⁴⁴ A full, 100 percent inspection of the 147.6 miles of tubing in the BEC4 boiler during every outage is neither feasible from a business standpoint nor a common utility practice.¹⁴⁵ Instead, the Company relies upon information from its decades of experience with the boilers as well as recommendations from OEMs and independent consulting engineers to identify and concentrate inspections on higher risk areas of the boiler between more thorough inspections during major planned outages.¹⁴⁶ Minnesota Power has not made any reductions in the frequency or methods in its well-established boiler inspection program.¹⁴⁷

Predicted outages are identified prior to the actual outage occurring, but, for a variety of reasons, the required maintenance could not be delayed to a planned outage.¹⁴⁸ Examples are the condenser leaks and boiler circulating pump outages that occurred during 2018 and 2019. In both cases, the Company diagnosed the problems using available technology and needed to take an outage to safely perform needed repairs.¹⁴⁹ While Minnesota Power tries to delay this type of maintenance activity to a planned outage, sometimes the Company must take an unplanned outage to address the emergent work.¹⁵⁰ In that case, the Company tries to delay the outage to a time where replacement power is at a more preferential price for customers, if possible.¹⁵¹

¹⁴³ Ex. 5 at 27 (Simmons Direct).

¹⁴⁴ *Id.*

¹⁴⁵ *Id.*

¹⁴⁶ *Id.*

¹⁴⁷ *Id.*

¹⁴⁸ Ex. 7 at 9 (Undeland Direct).

¹⁴⁹ *Id.*

¹⁵⁰ *Id.*

¹⁵¹ *Id.*

Notably, the Company has not elected to forgo or significantly delay required maintenance, inspections, or repairs on any of the systems identified as contributing to the 26 unplanned outages during the evaluation period.¹⁵² Low impact and predicted outages are an expected occurrence in coal-fired facilities of BEC3 and BEC4's vintage. The levels of low impact and predicted outages experienced by Minnesota Power during the evaluation period were not out of the ordinary, and the Company did everything reasonable to minimize the operational and financial effects of the outages. As a result, Minnesota Power's actions related to the 23 unplanned outages that the Department did not challenge were consistent with good utility practice, and the Company reasonably and prudently incurred the associated outage expenses.

E. Hydrogen Gas Leak Maintenance, Identification, and Repair Were Consistent with Good Utility Practice

During the winter and early spring of 2019, BEC3 experienced two unplanned outages to address a leak in the hydrogen gas system at the facility.¹⁵³

1. Minnesota Power's Hydrogen-Filled Generator Inspection Protocol Was Consistent with Good Utility Practice

The Company's PM and PdM programs and inspection and testing protocol for the hydrogen-filled generator system were developed in collaboration with General Electric, the OEM.¹⁵⁴ Specifically, General Electric recommends the inspection of areas where hydrogen leakage is possible during outages that include generator disassembly, which occur once every

¹⁵² *Id.* at 15.

¹⁵³ A diagram of the sealed hydrogen generator system is included in Ex. 7, Schedule 4 at 3 (Undeland Direct).

¹⁵⁴ *Id.* at 25.

five years for each unit at Boswell.¹⁵⁵ These inspections include close examination of shaft hydrogen seals, all joints with gaskets, and the float trap.¹⁵⁶

Minnesota Power completed its last inspection of the hydrogen-filled generator components at BEC3 in May of 2014.¹⁵⁷ At that time, none of the gaskets were leaking and an inspection of the original float valve for the system showed no signs of obvious wear, no binding, and no debris that might compromise its operation.¹⁵⁸

2. Minnesota Power's Handling of the Hydrogen Gas Leak Outages Was Consistent with Good Utility Practice

Over the winter of 2018 and 2019, BEC3's generator system engineer identified a high consumption of hydrogen gas in the system.¹⁵⁹ Plant personnel, using a combustible gas detector while BEC3 was operating, narrowed the leak location to somewhere in the leadbox/bushing area.¹⁶⁰ Due to the high voltage and magnetic fields in that area of the leadbox, plant personnel were unable to safely access the area in order to identify the precise location of the leak while the unit was running.¹⁶¹ During an unplanned outage from the evening of February 2, 2019 until the morning of February 4, 2019, Minnesota Power pressurized the BEC3 hydrogen unit with air and helium gases in an effort to locate the source of the leak.¹⁶² Minnesota Power identified and sealed a substantial leak on a gasket in the leadbox area in order to allow the unit to continue operating until the leak could be further diagnosed and repaired during the March 30, 2019

¹⁵⁵ *Id.*

¹⁵⁶ *Id.* at 25, Schedule 4.

¹⁵⁷ *Id.* at 26.

¹⁵⁸ *Id.*

¹⁵⁹ Ex. 7 at 23 (Undeland Direct).

¹⁶⁰ *Id.*

¹⁶¹ *Id.* at 23-24.

¹⁶² *Id.* at 23.

planned outage.¹⁶³ Prior to that scheduled outage, the system engineer worked with the OEM to develop a plan to complete both the root cause analysis and implement necessary repairs.¹⁶⁴

The BEC3 generator system engineer contacted General Electric's district service manager and generator specialist to discuss the leak and formulate a plan to determine the root cause and repair the leak.¹⁶⁵ Additionally, the Company asked General Electric, the OEM, for advice on how to proceed based upon its experiences with this type of hydrogen leak at other facilities.¹⁶⁶ General Electric recommended installing a dam system in the leadbox.¹⁶⁷ General Electric indicated that the cost of removing and replacing the bushings and gasket system would significantly exceed the cost of the dam system.¹⁶⁸ Minnesota Power contracted with General Electric to implement the repair plan during the planned spring outage.¹⁶⁹

Unfortunately, despite being successful at other General Electric units, the OEM's suggested repairs were unsuccessful during the spring 2019 planned outage and required that the planned outage be extended to finalize the repairs. By using the planned outage for a portion of the root cause analysis, however, the Company was able to reduce the total number of unplanned outage hours than if it had attempted to complete all work during the February 2019 unplanned outage.¹⁷⁰

During the inspections conducted throughout the spring 2019 planned outage, technicians determined that the valve was clean of any debris, moved freely, and showed no sign of wear on

¹⁶³ *Id.* at 23, Schedule 4 (The leadbox area is illustrated in Schedule 4).

¹⁶⁴ *Id.* at 23.

¹⁶⁵ Ex. 7 at 24 (Undeland Direct).

¹⁶⁶ *Id.*

¹⁶⁷ *Id.*

¹⁶⁸ *Id.*

¹⁶⁹ *Id.*

¹⁷⁰ *Id.* at 26.

the linkage.¹⁷¹ Additionally, neither the float valve nor “trap” showed any signs of wear, defects, or debris that would be causing a hydrogen leak like the one BEC3 had experienced in the winter of 2018 and 2019.¹⁷² Technicians visually inspected and measured the system components as recommended by the OEM.¹⁷³ The Company sent the existing hydrogen seals to a third-party vendor for refurbishment consistent with the OEM’s associated specification.¹⁷⁴ Additionally, the Company hired a fabricator to machine shaft surfaces to ensure there were no surface defects that would fail to provide a smooth, sealed surface.¹⁷⁵ General Electric also performed the previously mentioned “dam repair” in the bushing leadbox.¹⁷⁶ After Minnesota Power, General Electric, and third-party contractors completed the inspection and repair work, the Company reassembled the components to test whether the process that was successful for General Electric at other facilities worked at BEC3.¹⁷⁷

Although the testing and repair processes were time-intensive, the Company had the hydrogen-filled system ready for testing to bring the system online before the end of the original planned outage. When the generator was air-tested in preparation for returning BEC3 to operation, the Company identified a large leak in the generator.¹⁷⁸ Using specialized inspection equipment and visual inspections, technicians observed no deviations that would be causing the continued major leak, although they did identify and quickly repair a few minor leaks.¹⁷⁹ The next step in the OEM’s protocol included disassembly of the outer oil seals to ensure no leaking

¹⁷¹ Ex. 7 at 27, Schedule 4 at 4 (Undeland Direct) (Schedule 4 provides a detailed discussion of the inspection and testing process.).

¹⁷² *Id.* at 27.

¹⁷³ *Id.*

¹⁷⁴ *Id.*

¹⁷⁵ *Id.*

¹⁷⁶ Ex. 7 at 27, Schedule 4 at 4 (Undeland Direct).

¹⁷⁷ *Id.*

¹⁷⁸ *Id.*

¹⁷⁹ *Id.*

was present in the bearing cavity.¹⁸⁰ The Company was able to determine that the leaking was coming from the turbine end, and not the generator end, of the unit.¹⁸¹ Based on the location of the leaking, the OEM and site specialists identified two possible sources: The gasket on the hydrogen seal leaking or the hydrogen seal itself leaking.¹⁸² At this point, BEC3 was several days beyond its scheduled planned outage end date.¹⁸³

The Company continued further root cause analysis on the various hydrogen-filled system components, testing the system after each reassembly, but could not identify the source of the major leak.¹⁸⁴ Each round of testing and reassembly took approximately four hours to complete.¹⁸⁵

Minnesota Power brought in both General Electric and a contractor that specializes in hydrogen leaks to assist in the iterative root cause analysis to identify and repair the source of the hydrogen leak. Unfortunately, they were also unable to identify the cause of the leak at BEC3.¹⁸⁶ During this time, Minnesota Power began discussions about refurbishing the equipment.¹⁸⁷ The Company continued diagnostic testing by raising the level of oil in the float trap to observe how high the oil had to be to stop the hydrogen leak. Boswell personnel learned that the hydrogen leak stopped when the float trap was completely filled with oil to approximately eight to twelve inches above the valve.¹⁸⁸

¹⁸⁰ *Id.*

¹⁸¹ *Id.*

¹⁸² Ex. 7 at 27 (Undeland Direct).

¹⁸³ *Id.* at 28.

¹⁸⁴ *Id.*

¹⁸⁵ *Id.*

¹⁸⁶ *Id.*

¹⁸⁷ *Id.*

¹⁸⁸ Ex. 7, Schedule 4 at 9 (Undeland Direct).

After receiving the results of Minnesota Power's float trap testing, General Electric searched internally for any other possible causes of the hydrogen leak, and they were able to identify a single customer that had experienced a similar issue.¹⁸⁹ In that case, despite no visual defects in the float valve, the facility was able to resolve the leak issue by replacing the float valve. General Electric could not provide an explanation why the float valve replacement was necessary or why it eliminated the leak.¹⁹⁰ General Electric informed Minnesota Power that, because failure of float valves is exceedingly rare, it did not have any replacement float valves available, and it would take approximately 15 weeks from procurement to provide that part to the Company.¹⁹¹

When the Company and the OEM narrowed the root cause of the hydrogen leak to the float valve, BEC3 was about a week beyond the scheduled planned outage end date. Due to the hydrogen leak, however, the Company could not have safely brought the system online while waiting for General Electric to deliver the replacement float valve.¹⁹² At this point, Minnesota Power had two options: leave BEC3 offline until General Electric delivered the replacement float valve fifteen weeks later; or try to find an alternative solution that would allow the unit to safely return to operations.

Minnesota Power's engineers and technicians worked tirelessly and creatively to fabricate an onsite solution that would meet all safety requirements and provide a long term solution to the float valve leak at BEC3.¹⁹³ This required purchasing multiple float valves and float balls and testing them in different combinations to determine if an engineered solution

¹⁸⁹ *Id.* at 28-29, Schedule 4 at 9.

¹⁹⁰ *Id.*

¹⁹¹ *Id.* at 29, Schedule 4 at 9.

¹⁹² *Id.* at 29.

¹⁹³ *Id.*

would be possible.¹⁹⁴ The Company was able to find a valve that, when used in combination with a new float ball from McMaster-Carr Supply Company, would prevent hydrogen from leaking when the system oil was at operational levels.¹⁹⁵

The Company implemented its self-engineered solution and successfully performed the required air testing, hydrogen system purge, and leak verification. With the successful testing results, the hydrogen-filled system met the criteria for long-term operation, and Minnesota Power returned BEC3 to service on June 20, 2019.¹⁹⁶

The second unplanned outage started at the end of the spring 2019 planned outage after BEC3 failed the original air test on June 3, 2019. The problem was narrowed to the float valve on June 11, 2019. Minnesota Power's engineered solution was completed, and BEC3 was returned to operations, on June 20, 2019.¹⁹⁷ Had Minnesota Power decided to rely solely on General Electric rather than internally engineering a solution, the outage would have lasted fifteen weeks, plus time for installation, from June 11, 2019. Thus, Minnesota Power avoided approximately fourteen weeks of unplanned outage by implementing a self-engineered solution.

Since the outage, General Electric has not been able to replicate the float valve failure experienced by BEC3, and neither General Electric nor other hydrogen leak specialty contractors were able to definitively identify what caused the BEC3 float valve to leak hydrogen or how to prevent or identify such a leak in the future.¹⁹⁸ This underscores the novelty and complexity of the float valve defect, and speaks to Minnesota Power's ability to identify the problem and implement a self-engineered solution.

¹⁹⁴ *Id.*, Schedule 4 at 10.

¹⁹⁵ Ex. 7 at 29 (Undeland Direct).

¹⁹⁶ *Id.*

¹⁹⁷ *Id.* at 30.

¹⁹⁸ *Id.* at 31-32.

Minnesota Power's handling of the hydrogen leak was not only consistent with good utility practice: it exceeded that standard. Prior to and during the outage, Minnesota Power followed the proper maintenance practices suggested by General Electric (the OEM). Even since the outage, General Electric has not suggested any changes to the Company's PM or PdM programs for this system.¹⁹⁹ The Company completed all maintenance and inspections recommended by the OEM, and worked as quickly as possible to return the unit to long-term operation safely and efficiently for the benefit of customers.²⁰⁰ Given these circumstances, Minnesota Power did exceptionally well to return BEC3 to service months earlier than it would have had the Company relied exclusively on the solution offered by General Electric.

3. The Department's Criticisms Are Unsupported by Evidence

The Department's expert, Mr. Polich, suggests in his direct testimony that Minnesota Power did not apply good utility practices in how it investigated and repaired the hydrogen leak in the BEC3 generator. Specifically, Mr. Polich contends that Minnesota Power should have "removed and tested the float valve for leakage"²⁰¹ He further opines that the failure to immediately test the float valve led to other testing that resulted in the overfilling of hydrogen seal oil in the system.²⁰²

Mr. Polich's testimony does not cite to any information or evidence indicating that Minnesota Power should have known, without the benefit of hindsight, to start its investigation and testing with the float valve. Additionally, Mr. Polich does not explain how the float valve could have been tested for leakage to identify the defect, which is notable because neither General Electric nor other hydrogen system expert consultants have been able to devise a testing

¹⁹⁹ *Id.* at 31.

²⁰⁰ *Id.*

²⁰¹ Exs. 10 and 11 at 44 (Polich Direct) (Public and Nonpublic).

²⁰² *Id.*

methodology for the float valve.²⁰³ Also, the float valve operates in an open position and is never closed during operation, so testing for leakage, as Mr. Polich suggested, would not have provided any information regarding the functionality of the float valve.²⁰⁴

Mr. Polich also fails to acknowledge that, months prior to the outage, Minnesota Power worked with General Electric, the OEM, to formulate a plan to determine the root cause and repair the hydrogen leak.²⁰⁵ As the OEM, General Electric had the best information in the industry regarding both what could have caused the hydrogen leak as well as the processes and testing that Minnesota power could undertake to identify the root cause. Minnesota Power sought expertise and assistance from the industry experts and followed their recommendations in attempting to address the hydrogen leak, which is wholly consistent with good utility practice.²⁰⁶ Undetectable float valve defects are exceedingly rare, and the OEM and other hydrogen leak experts were unaware of any testing that would confirm the float valve as the root cause other than completely replacing it, which, given the availability of that part, would have taken fifteen weeks to procure. Thus, there is no basis for Mr. Polich's suggestion that Minnesota Power should have immediately determined that the float valve was a likely cause of the hydrogen leak.

Mr. Polich's standard is not consistent with good utility practice, and, in fact, exceeds even optimum utility practice because it would have required Minnesota Power to know more than the OEM and industry experts. Based on what the Company knew about the system, its operation, and likely failure conditions at the time of the leak, the methodical and iterative testing, repair, and engineering process was consistent with good utility practice.

²⁰³ *See id.* at 44-45.

²⁰⁴ Exs. 14 and 15 at 10 (Undeland Rebuttal) (Public and Nonpublic).

²⁰⁵ *Id.*

²⁰⁶ *Id.*

In any event, the Department concluded that any potential deviations from good utility practice by Minnesota Power did not cause or materially lengthen the outage.²⁰⁷ As a result, the Department does not recommend that the Commission order Minnesota Power to refund any replacement power costs related to this outage.²⁰⁸

F. Phase Bushing Maintenance, Identification, and Repair Were Consistent with Good Utility Practice

1. Minnesota Power's Phase Bushing Inspection and Maintenance Protocol Was Consistent with Good Utility Practice

Electricity is transmitted in three phases (A, B, C) and there are two bushings per phase (line and neutral), totaling six bushings in BEC3's system.²⁰⁹ Minnesota Power tests all unit phase bushings every five years pursuant to the recommendation of the OEM, General Electric.²¹⁰ The Company tests the bushings using a hi-pot, or overpotential, test, which is an electrical test that measures the amount of leakage current an insulated system has to ground when a high voltage is applied to the winding.²¹¹ The test procedure is consistent with Institute of Electrical and Electronics Engineers ("IEEE") standards, the OEM's suggested practices, and FM Global's insurance guidance, which are all consistent in their testing frequency and protocol recommendations.²¹² The Company has followed these recommendations since the unit was constructed in 1970.²¹³

²⁰⁷ Exs. 12 and 13 at 17 (Campbell Direct) (Public and Nonpublic).

²⁰⁸ *Id.*

²⁰⁹ Ex. 7 at 32 (Undeland Direct).

²¹⁰ *Id.* at 34.

²¹¹ *Id.*

²¹² *Id.*

²¹³ *Id.*

On April 18, 2019, the Company's contractor (General Electric) completed the five-year testing and inspections on BEC3's six bushings and three windings.²¹⁴ The General Electric generator specialist reported that all six phase bushings installed on BEC3 were operating within General Electric's acceptable limits. The direct-current ("DC") leakage test indicated that all bushings performed within acceptable criteria with no other indication to support further investigation.²¹⁵ The report noted, however, that the DC leakage test indicated a higher rate of leakage for the A phase bushing, even though its operation was within limits of testing.²¹⁶

2. Minnesota Power's Handling of the Phase Bushing Outage Was Consistent with Good Utility Practice

On July 8, 2019, a relay in BEC3 was tripped offline due to a ground fault alarm.²¹⁷ To investigate the cause of the relay's safety response, the Company conducted additional analysis of the electrical circuit consisting of the isophase bus, the step-up transformer, three generator windings, and six phase bushings.²¹⁸

Minnesota Power utilized employees who specialized in circuit system failures from the Boswell relay work area as well as the Company's transmission construction and maintenance work areas to assist in isolating the equipment that caused the ground fault alarm.²¹⁹ The Company disconnected the system components at the generator and then tested the isophase bus and step-up transformer in order to eliminate them as potential causes of the ground fault alarm.²²⁰ Boswell electricians then separated the three phase systems at the generator and, based upon further testing, they were able to determine that the ground fault occurred on the A phase of

²¹⁴ *Id.* at 32. The Company provides a detailed summary related to this outage in Ex. 7, Schedule 5 (Undeland Direct).

²¹⁵ Ex. 7 at 32 (Undeland Direct).

²¹⁶ Exs. 14 and 15 at 35 (Undeland Rebuttal) (Public and Nonpublic).

²¹⁷ Ex. 7 at 32 (Undeland Direct).

²¹⁸ *Id.*

²¹⁹ *Id.* at 33.

²²⁰ *Id.*

the system.²²¹ This discovery indicated that the root cause was likely a failure of an A phase bushing, the neutral side bushing, or the winding in the generator itself.²²² The Company determined that specialized personnel would be necessary to assist in the investigation effort and remove asbestos containing materials prior to further investigation. On July 10, 2019, the Company contacted General Electric to assist with diagnosing and repairing the A phase bushings.²²³

On July 12, 2019, General Electric began working in cooperation with Boswell personnel to identify the cause of the relay fault. On July 14, 2019, General Electric's engineer determined that the failure was on the A phase line side bushing, which would need to be replaced.²²⁴

Minnesota Power does not keep spare phase bushings in stock because they do not have a history of frequent failure.²²⁵ As a result, the Company contacted General Electric to procure three replacement bushings, which General Electric indicated could be delivered to BEC3 on July 16, 2019.²²⁶ While the bushings were en route to Boswell, the Company had General Electric remove the asbestos containing insulation in all six of the phase bushings at BEC3 to allow for the flex leads inspection that General Electric recommends when phase bushings are replaced.²²⁷ No defects were found in the leads.²²⁸

When the replacement bushings arrived on July 16, 2019, the shipment included six bushings instead of the three bushings that the Company had ordered.²²⁹ Minnesota Power

²²¹ *Id.*

²²² *Id.*

²²³ Ex. 7 at 33 (Undeland Direct).

²²⁴ *Id.*

²²⁵ *Id.*

²²⁶ *Id.*

²²⁷ *Id.*

²²⁸ *Id.*

²²⁹ Ex. 7 at 33 (Undeland Direct).

decided that it was most prudent to replace all six bushings given that General Electric did not know why the A phase line side bushing failed and because of the overall age of the bushings.²³⁰ Additionally, much of the preparation necessary to replace six bushings would be the same as that which would be required even if only three bushings were replaced. General Electric installed six new bushings on July 18 and 19, 2019.²³¹ Final inspections and testing were completed on July 21, 2019, and the unit was brought online on July 22, 2019.²³² The unit returned to service on July 26, 2019.²³³

Minnesota Power's phase bushing maintenance and inspection program, as well as its response to the BEC3 phase bushing outage in 2019, were consistent with good utility practice. The Company has utilized the same phase bushing inspection methods and testing schedule, which are consistent with OEM and industry recommendations, since the construction of the unit in 1970.²³⁴ The Company has made no reductions in its phase bushing maintenance expenses during the evaluation period.

The Company worked as quickly as possible, while maintaining safety and ensuring that the repair would be sufficient for continued operations, to return the unit to operation for the benefit of customers. The Company was not able to take any steps to try and delay the outage because when a ground fault occurs, the unit must be taken offline.²³⁵

The Company was following industry practice, OEM recommendations, and IEEE guidelines. Further, the Company consulted with the OEM after this outage and the OEM has not suggested any changes to its instructive maintenance and inspection guidelines. Instead, the

²³⁰ *Id.*

²³¹ *Id.*

²³² *Id.* at 33-34.

²³³ *Id.* at 37.

²³⁴ *Id.* at 35.

²³⁵ Ex. 7 at 37 (Undeland Direct).

Company is adding to its five-year inspection and testing procedure for the circuit system that the Company be provided with the raw test results while the Engineer, technicians, and test equipment are still on site. That allows sufficient time for any re-inspection or re-testing the Company may request.²³⁶

3. General Electric Could Not Identify the Proximate Cause of the Bushing Failure

Minnesota Power asked General Electric if it could determine the root cause of the phase bushing failure. While General Electric identified a couple of potential causes, it did not make an ultimate determination regarding the actual cause of the A phase bushing failure.²³⁷

One potential cause listed by General Electric in its Ground Fault Investigation report was the presence of oil in the phase bushings, which can block cooling passages and cause the bushings to overheat.²³⁸ When the phase bushings were opened up after the unit was shut down during the outage, the Company and General Electric found that oil had ingressed into the phase bushings after the testing and restart associated with the hydrogen gas leak outage.

Pursuant to the testing procedures suggested by General Electric for the spring 2019 hydrogen gas leak repair, Minnesota Power varied the oil levels in the hydrogen gas system in order to help diagnose the cause of the leak and identify potential solutions.²³⁹ Unfortunately, the alarm that would have notified BEC3 personnel regarding the overflow of oil was not properly configured at the time, so it did not alert plant personnel when oil overtopped the sight glass during hydrogen leak testing.²⁴⁰ When Minnesota Power discovered the overflow, it

²³⁶ *Id.* at 37-38.

²³⁷ *See generally* Exs. 10 and 11, RAP-16 (Polich Direct) (Public and Nonpublic).

²³⁸ *Id.*, RAP-16 at 3, 5.

²³⁹ *Id.*, RAP-15 at 4-6.

²⁴⁰ *Id.*, RAP-15 at 6-7.

removed oil from the system using the liquid detector drain valve.²⁴¹ Minnesota Power's visual inspection of the system did not indicate that the oil had entered the phase bushings, as the leadbox area was clean and dry.²⁴² General Electric did not recommend or suggest any additional inspections or verifications related to the hydrogen leak testing that would have included removing the insulation in order to visually inspect the phase bushings.²⁴³ As a result, Minnesota Power was not aware of the presence of oil in the phase bushings until after the outage.

Given the presence of oil in the phase bushings, Minnesota Power specifically asked General Electric whether the oil could have caused the A phase bushing failure. Although General Electric indicated that the presence of oil could lead to overheating, it could not determine whether the presence of oil in the BEC3 phase bushings contributed to the A phase failure, and was unable to identify any testing that would be determinative of the root cause of the bushing failure.²⁴⁴

General Electric's Ground Fault Investigation report also indicated that, although no definitive physical damage was apparent on the bushing, "there were tell-tale signs of a black tar-like substance seen on the porcelain at the flange just above the ferrule. This might be a sign that the bushing failure is under the mounting flange."²⁴⁵ If the unit experienced vibration, either short term or long term, the greatest point of distress would be the mounting flange.²⁴⁶ General

²⁴¹ *Id.*, RAP-15 at 5.

²⁴² *Id.*, RAP-15 at 4.

²⁴³ Exs. 10 and 11, RAP-15 at 4 (Polich Direct) (Public and Nonpublic).

²⁴⁴ *Id.*, RAP-15 at 7-8.

²⁴⁵ *Id.*, RAP-16 at 4.

²⁴⁶ Exs. 14 and 15 at 35-36 (Undeland Rebuttal) (Public and Nonpublic).

Electric issued technical bulletins in 2013 and 2017 in response to units experiencing bushing failures due to natural frequency (resonance) vibration.²⁴⁷

Ultimately, neither General Electric nor Minnesota Power were able to make a definitive determination of the root cause of the phase bushing failure. General Electric also indicated that it was unaware of any testing that would provide a definitive result.²⁴⁸

4. The Department's Conclusions Are Unsupported by Evidence

Mr. Polich contends that Minnesota Power failed to follow good utility practice by not investigating whether seal oil had leaked into the bushings when it was addressing the hydrogen gas leak earlier in 2019, and that the presence of seal oil caused the bushings to overheat and fail.²⁴⁹ His arguments fail on two fronts. First, there is insufficient evidence in the record to determine that the seal oil was the cause of the phase bushing failure. Second, Minnesota Power did not deviate from good utility practice.

Mr. Polich contends, without citing to any reports or evidence, that had Minnesota Power removed the seal oil from around the phase bushings immediately, it “would have avoided the bushing failure, having to purchase replacement bushings and the roughly two-week outage.”²⁵⁰ This conclusion, however, assumes that the oil present in the phase bushings definitely caused the failure. As discussed above, not even the OEM could determine whether oil was the proximate cause, or even a contributing cause, of the failure.

Mr. Polich also failed to acknowledge the numerous reasons a phase bushing could fail. Phase bushings may be damaged by sudden load changes, excessive vibration, overheating,

²⁴⁷ Ex. 7, Schedule 5 at 9 (Undeland Direct).

²⁴⁸ Exs. 14 and 15 at 36 (Undeland Rebuttal) (Public and Nonpublic).

²⁴⁹ Exs. 10 and 11 at 48 (Polich Direct) (Public and Nonpublic).

²⁵⁰ *Id.*

overheating of the leads, and normal vibration over long periods of time.²⁵¹ In this case, the A phase bushing could have been the original from 1970 or a replacement from 2001, so it could have been approximately 50 years old at the time it failed.²⁵² Additionally, the DC leakage test performed during the Spring 2019 outage indicated a higher rate of leakage for the A phase bushing, which suggests that there could have been some underlying issues that later caused the failure.²⁵³ As discussed above, General Electric's finding of a tar-like substance on the porcelain at the flange suggests that the failure might have occurred under the mounting flange as a result of either short or long term vibration.²⁵⁴

In sum, there are multiple possible causes of the phase bushing failure, but it is impossible to determine with any certainty what the actual cause was. As a result, Mr. Polich's contention that the phase bushing failure would not have occurred but for the presence of seal oil constitutes a guess regarding the root cause rather than a definitive, evidence-based conclusion.

Mr. Polich's conclusion that Minnesota Power failed to follow good utility practice by not immediately finding and removing the seal oil from the phase bushings after the hydrogen leak testing similarly lacks an evidentiary basis. As discussed above in more detail, Minnesota Power was unaware that seal oil had overtopped the sight glass on the hydrogen system due to an alarm failure.²⁵⁵ After it became aware of the spill, Minnesota Power drained the oil from the system and performed a visual inspection that provided no indications that oil had leaked into the phase bushings since the leadbox area was clean and dry.²⁵⁶ Because such an overflow of oil had never happened in the past, Minnesota Power did not know that oil would make its way into the

²⁵¹ Exs. 14 and 15 at 35 (Undeland Rebuttal) (Public and Nonpublic).

²⁵² *Id.*

²⁵³ *Id.*

²⁵⁴ *Id.* at 35-36.

²⁵⁵ Exs. 10 and 11, RAP-15 at 4-7 (Polich Direct) (Public and Nonpublic).

²⁵⁶ *Id.*

phase bushings.²⁵⁷ And absent removing the insulation from and observing the bushings, which is a time and labor intensive process involving asbestos, Minnesota Power would not have been able to discover the oil.²⁵⁸

It is also important to acknowledge that the testing Minnesota Power conducted to identify the hydrogen leak was far from a standard process. In fact, General Electric identified only one other facility that experienced the same float valve failure as BEC3.²⁵⁹ Given the novelty of the testing procedures, there really is no established good utility practice or even any suggested protocols from the OEM or industry experts.²⁶⁰ Instead, BEC3 personnel were required to move forward using their best judgment given the information available at the time.²⁶¹

Minnesota Power's innovative testing and repair of the hydrogen leak reduced that outage by approximately fourteen weeks compared to if Minnesota Power had just waited for a new float valve from General Electric.²⁶² That type of ingenuity should not be punished by denying Company recovery of replacement energy expenses from a much shorter outage that only may have been caused because employees did not design a perfect testing protocol on the fly, as Mr. Polich suggests should have happened. Ultimately, given the extremely novel circumstances and without the benefit of hindsight, Minnesota Power's efforts to identify and fix the hydrogen leak were consistent with good utility practice.

²⁵⁷ *Id.*

²⁵⁸ Ex. 7 at 33, 35-36, Schedule 4 at 9 (Undeland Direct).

²⁵⁹ *Id.* at 28-29, Schedule 4 at 9.

²⁶⁰ *Id.*

²⁶¹ *Id.*

²⁶² *Id.*

G. Hot Reheat Maintenance, Identification, and Repair Were Consistent with Good Utility Practice

1. Minnesota Power's HRH Line Inspection and Maintenance Program Was Consistent with Good Utility Practice

The HRH line is an insulated HEP system that is 640 feet in length and spans 20 floors with limited access within the unit.²⁶³ It is rare to perform a complete inspection of an entire HRH system during a single planned outage because it is cost-prohibitive and time-consuming.²⁶⁴ Minnesota Power plans inspections based on past results, known areas of risk, industry bulletins, insurance carrier guidance, and third-party HEP expert recommendations among the many other sources the Company uses in developing its maintenance and inspection programs, as discussed above.²⁶⁵ Minnesota Power utilizes all of the information available to it, including recommendations from the last inspection and the input of third-party HEP experts, to develop inspection plans prior to planned outages to determine where, what, how, and how much to inspect.²⁶⁶

Minnesota Power inspects high stress and high risk sections of each of Boswell's HEP systems every two to five years, with low stress level areas (such as the vertical section of HRH line where the seam weld failed) due for inspection every five to ten years based upon relative risk.²⁶⁷ Minnesota Power inspected sections of the BEC4 HRH line in 2017 prior to the 2019 failure, but not the particular section that failed. The HRH line was scheduled for inspection every ten years due to its relatively low stress and risk, and was last inspected in 2010 with no actionable defects noted at that time.²⁶⁸

²⁶³ *Id.* at 16.

²⁶⁴ Ex. 7 at 16 (Undeland Direct).

²⁶⁵ *Id.*

²⁶⁶ *Id.*

²⁶⁷ *Id.*

²⁶⁸ *Id.*

Piping experiences a combination of stresses due to internal pressure, weight loads, and bending/torsion caused by thermal expansion.²⁶⁹ In general, vertical pipe runs like the HRH line experience lower stress levels because they have lower weight loads than horizontal and hanging pipe.²⁷⁰ For horizontal runs, bending stresses are present in the unsupported sections between the hangers, and valves and protective insulation add to the weight and stress of those sections.²⁷¹ As a result, horizontal runs have much higher risk of failure than vertical runs, and Minnesota Power plans its inspection protocol to account for these different risk levels.

The vertical HRH line has been identified as a low stress area in all pipe inspections dating back to 1985, including in a Sargent & Lundy stress analysis performed in 2010.²⁷² Because the HRH line was last inspected in 2010, it was due for inspection in 2020. Since 2010, the Company observed no operational issues that would have caused BEC4's systems engineer to accelerate the inspection and testing schedule for the HRH line seam weld.²⁷³

Minnesota Power selected the 10-year inspection frequency for the HRH line based on input from its independent consulting engineer, the relative risk and stress in that section of the piping, and historic operating and metallurgical knowledge, among other sources.²⁷⁴ According to Thielsch, Minnesota Power's longest and most often used independent consulting engineer for HEP maintenance and inspection, over the past 30 years, none of the approximately 50 U.S. power companies they have worked for have inspected 100 percent of their low stress longitudinal seam welds on a five-year cycle.²⁷⁵ Thielsch confirmed that Minnesota Power's

²⁶⁹ *Id.* at 17.

²⁷⁰ Ex. 7 at 17 (Undeland Direct).

²⁷¹ *Id.*

²⁷² *Id.*

²⁷³ *Id.*

²⁷⁴ *Id.* at 18.

²⁷⁵ *Id.*

HRH inspection protocol is similar to those of the other power companies with which Thielsch has decades of experience.²⁷⁶

It is entirely consistent with good utility practice to focus more inspection resources on those areas that are most likely to have indications, which are visual or operational deviations from what is expected of the equipment.²⁷⁷ In the early years of pipe life, the most likely area to develop fatigue is at an attachment or discontinuity, which can include any equipment geometry besides that which is round or straight.²⁷⁸ As the pipe ages, the most common failure mechanism transitions from fatigue to creep. “Creep” is a function of operation at high temperatures, over time and with stress.²⁷⁹ Over time, the inspections begin to include replication and boat sample testing to detect creep in its earliest stages. A “boat sample” is a type of destructive testing where a sample is removed from the pipe with a precision cut and that sample is then subjected to various laboratory tests to evaluate the microstructure and condition of the pipe.²⁸⁰ Minnesota Power has continually adapted its HEP inspection protocol in order to focus on the areas of the system most likely to first show signs of damage to the overall system.

In sum, in order to ensure consistency with good utility practice, Minnesota Power develops inspection program scope and frequency protocols based upon many different sources of information including past results, known areas of risk, industry groups, insurance carrier recommendations, and third-party expert recommendations.²⁸¹ Additionally, Boswell employees meet every year with peers from Xcel Energy to discuss issues that have come up in

²⁷⁶ Ex. 7 at 18-19 (Undeland Direct); Exs. 14 and 15 at 26-27 (Undeland Rebuttal) (Public and Nonpublic).

²⁷⁷ *Id.*

²⁷⁸ *Id.* at 24-25.

²⁷⁹ *Id.* at 25.

²⁸⁰ *Id.*

²⁸¹ Exs. 14 and 15 at 31 (Undeland Rebuttal Public and Nonpublic).

the past year.²⁸² Minnesota Power's insurance carrier, FM Global, also shares industry issues with the Company and prompts changes to the protocol or frequency of inspections when applicable.²⁸³ The Company uses all of the above-described resources, as well the decades of experience of many of Boswell's employees, to ensure that its maintenance and inspection programs are, at a minimum, on par with other coal-fired power plants.

2. Minnesota Power's Handling of the HRH Steam Line Outage Was Consistent with Good Utility Practice

On February 6, 2019, the HRH steam line at BEC4 experienced a seam-weld failure, resulting in a steam release that required Minnesota Power to shut BEC4 down.²⁸⁴ The Company safely brought BEC4 offline within two hours of the failure to facilitate a detailed inspection.²⁸⁵ BEC4 personnel determined that the leak was caused by a two-foot failure of the welded seam of the HRH pipe.²⁸⁶ Due to the nature of the seam-weld failure, Boswell management and engineers decided to conduct a complete and thorough inspection of the HRH pipe.²⁸⁷

Minnesota Power had Thielsch mobilize to Boswell to conduct a comprehensive investigation of the HEP at BEC4 and help determine next steps.²⁸⁸ Thielsch took boat samples from above and below the HRH pipe that had failed.²⁸⁹ The results showed that there was

²⁸² *Id.*

²⁸³ *Id.*

²⁸⁴ Ex. 7 at 15 (Undeland Direct). A more detailed description of the HRH line outage is provided in Ex. 7, Schedule 3 (Undeland Direct).

²⁸⁵ *Id.* at 15.

²⁸⁶ *Id.*

²⁸⁷ *Id.*

²⁸⁸ *Id.*, Schedule 3 at 4.

²⁸⁹ *Id.*

substantial and widespread creep within the HRH piping, indicating that it was at the end of its usable life.²⁹⁰

The type of pipe used in power plant HEP is almost exclusively manufactured for specific jobs.²⁹¹ As a result, Minnesota Power had to order piping that would be manufactured to meet the specifications of the HRH line segment that needed to be immediately replaced. The pipe was ordered on February 15, 2019, and delivered to BEC4 on March 12, 2019.²⁹²

While the pipe was being manufactured, Minnesota Power decided to inspect 100 percent of the HEP system at BEC4 to determine if there was additional damage that would require repair.²⁹³ The inspection identified six additional areas that required repair.²⁹⁴ Additionally, Thielsch found transverse cracking in many pipe spools that was determined to not be service related, but rather were likely cracks from the manufacturing of the plate that would not likely create additional risk.²⁹⁵ In order to eliminate the possibility that the transverse cracks could cause a failure, however, Minnesota Power had Thielsch design patches that were installed by Moorhead Machinery & Boiler Company (“MMBCO”).²⁹⁶

During the analysis of the HRH system, Minnesota Power contacted EPRI to discuss the failure. EPRI suggested that Minnesota Power: (1) perform a 100 percent inspection of the system; (2) repair damaged areas discovered through the inspection; (3) hire a second inspection company to identify high risk locations in the piping system; and (4) have the second inspection

²⁹⁰ Ex. 7, Schedule 3 at 4 (Undeland Direct).

²⁹¹ *Id.*

²⁹² *Id.*

²⁹³ *Id.*, Schedule 3 at 4-5.

²⁹⁴ *Id.*, Schedule 3 at 5.

²⁹⁵ *Id.*

²⁹⁶ Ex. 7, Schedule 3 at 5 (Undeland Direct).

company verify Thielsch's results for high risk areas.²⁹⁷ Minnesota Power brought in Structural Integrity to identify and inspect high risk areas of the HEP.

Minnesota Power hired MMBCO to make the necessary repairs to the HRH system. Removal and replacement of very large HRH pipe is not a simple process, especially given that the three sections that required replacement were located near the top of the boiler building, 17 or more stories up, and were in difficult to access areas.²⁹⁸ MMBCO also installed 140 feet of reinforcement patches over areas with a lot of transverse cracking.²⁹⁹

The repairs were complete on March 25, 2019.³⁰⁰ A State of Minnesota High Pressure Piping Inspector reviewed the repairs and determined that it was safe to restart the facility.³⁰¹ Minnesota Power safely put the HRH system back in service seven weeks after the failure.³⁰²

Although the repairs made it safe to put BEC4's HRH system back in service, Boswell engineers concluded that a complete replacement of the piping system should be conducted during the next major planned outage in April 2020.³⁰³ Due to the COVID-19 pandemic, however, that outage was delayed until the spring of 2021. BEC4 completed the HEP system replacement in the spring of 2021.

3. Minnesota Power's Learning Team Provided Recommendations to Improve the HEP Maintenance and Inspection Program

Whenever a Minnesota Power facility experiences a significant failure or outage, the Company uses a learning team to analyze the causes and put measures into place to minimize

²⁹⁷ *Id.*, Schedule 3 at 7.

²⁹⁸ *Id.*

²⁹⁹ *Id.*

³⁰⁰ *Id.*, Schedule 3 at 10.

³⁰¹ *Id.* at 21.

³⁰² Ex. 7 at 15-16 (Undeland Direct).

³⁰³ *Id.*, Schedule 3 at 11.

risk of reoccurrence.³⁰⁴ The learning team is a collaborative approach using a group of individuals who are most familiar with the equipment and operations at issue. A trained coach or facilitator leads the learning team through a process that involves learning about the incident, reflection, and developing recommended solutions.³⁰⁵ When a high impact outage occurs, such as the HRH failure, the Company evaluates the PM and PdM programs to determine if improvements could be made in light of the information learned as a result of the outage.³⁰⁶ Minnesota Power established a learning team to review the HRH steam leak seam-weld failure and provide suggested changes to its operations, PM program, and PdM program.

Minnesota Power's learning team and its expert consultants concluded that the Company's PM and PdM programs and HEP inspection protocol were consistent with good utility practice.³⁰⁷ In light of the information learned through the steam leak investigation about the extent of creep in BEC4's HRH, Minnesota Power established four steps intended to reduce the risk of similar failure from occurring in the future: (1) inspect and repair the entire BEC4 HRH piping system; (2) accelerate inspections of the BEC3 HRH piping; (3) completely replace the BEC4 HRH piping system; and (4) revise BEC's HEP inspection program.³⁰⁸

Through an internal review of the HEP program, and consultation with third-party engineering firms, the Company elected to revisit the standardized test methods for specific areas of the pipes.³⁰⁹ The Company created a formalized HEP program document as a reference that

³⁰⁴ Exs. 14 and 15 at 32 (Undeland Rebuttal) (Public and Nonpublic).

³⁰⁵ *Id.*

³⁰⁶ *Id.*

³⁰⁷ *Id.*

³⁰⁸ *Id.*

³⁰⁹ Ex. 7 at 22 (Undeland Direct).

outlines the quality control procedures, inspection frequency, inspection methods, and required inspector qualifications.³¹⁰

4. The Department's Position Is Unsupported By Evidence

The Department, through its expert Mr. Polich, opined that Minnesota Power did not follow good utility practice with regard to its maintenance and inspection of the HRH steam line at BEC4, and that failure to do so caused the failure of the HRH and the unplanned outage in February 2019.³¹¹ But this contention is not supported by any evidence or even by the sources upon which Mr. Polich purports to rely.

Mr. Polich contends that Minnesota Power diverted from good utility practice in two ways. First, he suggests that Minnesota Power should have created a program that would inspect 100 percent of all seam welded pipe using phased array ultrasonic examination at least every five years, as recommended by EPRI.³¹² Second, Mr. Polich contends that Minnesota Power overly relied upon its vendor Thielsch in creating its HEP maintenance and inspection program, and should have questioned Thielsch's suggestions and been aware of the potential issues with seam-welded HEP pipe.³¹³ Neither of these assertions is supported by record evidence.

a. 100 Percent Phased Ultrasonic Inspection of HEP Every Five Years Was Not Common Utility Practice

At the time of the HRH steam line seam-weld failure and associated outage in February 2019, Minnesota Power was not aware of any other power companies that had implemented 100 percent inspections using phased array ultrasonic examination of all seam-welded HEP at least

³¹⁰ *Id.*

³¹¹ Exs. 14 and 15 at 17 (Undeland Rebuttal) (Public and Nonpublic).

³¹² Exs. 10 and 11 at 39-40 (Polich Direct). Notably, Mr. Polich did not list EPRI as one of the standard setting organizations in his definition of "good utility practice." *See id.* at 7.

³¹³ *Id.* at 40-41.

every five years.³¹⁴ Based on common practice in the industry and the information available to Minnesota Power at that time, the Company's inspection program for seam-welded HEP was on the upper end of the range of good utility practice.³¹⁵ Additionally, Minnesota Power utilized a detailed risk-based analysis to establish inspection frequency of all HEP. Minnesota Power's protocol of inspecting its low stress seam-welded HEP between every five to ten years depending on the level of risk for each area was considered good utility practice. The vertical section of HRH at BEC4 is one of the areas of least stress, so it was scheduled for inspection on a ten-year frequency.³¹⁶

In support of his position that good utility practice rigidly requires phased array ultrasonic examination of 100 percent of the HEP within a facility at least every five years, Mr. Polich indicated that he knew of two power plants that complied with that standard.³¹⁷ But he admitted that his knowledge regarding what HEP maintenance practices are employed by utilities across the country is limited to "the three power plants HEP inspection programs he has reviewed[.]"³¹⁸ Mr. Polich's definition of good utility practice requires that a "significant portion" of the electric utility industry must accept a practice or method. Thus, by his own standard, Mr. Polich's invocation of a grand total of two facilities falls immeasurably short of establishing the threshold for good utility practice.

³¹⁴ Exs. 14 and 15 at 18 (Undeland Rebuttal) (Public and Nonpublic).

³¹⁵ *Id.*

³¹⁶ *Id.*

³¹⁷ *Id.*, Rebuttal Schedule 1 at 5, response to MP IR 05(b). Although Mr. Polich states in testimony that he knows of three facilities that follow EPRI's guidelines, he clarified during the Hearing that only two of the three facilities have longitudinal seam-welded HEP for which EPRI's guidelines would be applicable. Ev. Hrg. Tr. at 59-60 (Polich). Thus, Mr. Polich's conclusions about industry practice are really based upon two facilities.

³¹⁸ Exs. 14 and 15 at 4, Rebuttal Schedule 1 at 2, response to MP IR 04(c) (Undeland Rebuttal) (Public and Nonpublic).

Rather than providing evidence of the common practices of a significant portion of utilities, Mr. Polich relies exclusively on the recommendations and guidelines set forth by the American Society of Mechanical Engineers (“ASME”) and EPRI to support his position.³¹⁹

Mr. Polich first cites to Appendix V, “Recommended Practice for Operation,” of the ASME Code for Pressure Piping, B31.1 (2016).³²⁰ Specifically, Mr. Polich quoted the following provision:

*V-8.5.2 Continued examination shall be made at intervals based upon the results of the initial inspection, but not to exceed 5 yr with corrective measures being taken each time that active corrosion is found.*³²¹

Section 8.1.1 of Appendix V (“V-8.1.1”) sets forth the types of piping systems to which that particular appendix applies:

V-8.1.1 This section pertains to the requirements for inspection of critical piping systems that may be subject to internal or external corrosion-erosion, such as buried pipe, piping in a corrosive atmosphere, or piping having corrosive or erosive contents. Requirements for inspection of piping systems to detect wall thinning of piping and piping components due to erosion/corrosion, or flow-assisted corrosion, are also included. Erosion/corrosion of carbon steel piping may occur at locations where high fluid velocity exists adjacent to the metal surface, either due to high velocity or the presence of some flow discontinuity (elbow, reducer, expander, tee, control valve, etc.) causing high levels of local turbulence. The erosion/corrosion process may be associated with wet steam or high purity, low oxygen content water systems. Damage may occur under both single and two phase flow conditions. Piping systems that may be damaged by erosion/corrosion include, but are not limited to, feedwater, condensate, heater drains, and wet steam extraction lines. Maintenance of corrosion control equipment and devices is

³¹⁹ *Id.* at 19. It is worth noting that Mr. Polich, in defining “good utility practice” did not cite to ASME’s standards or EPRI’s recommendations, but did include “acts generally accepted in the region in which the project is located.” See Exs. 10 and 11 at 6-7 (Polich Direct) (Public and Nonpublic).

³²⁰ Exs. 10 and 11 at 24 (Polich Direct) (Public and Nonpublic).

³²¹ *Id.* (emphasis in Polich Direct).

also part of this section. Measures in addition to those listed herein may be required.³²²

The BEC4 HRH seam-welded piping does not fall within any of the categories of piping systems set forth in V-8.1.1.³²³ The BEC4 HRH system is not buried, is not located in a corrosive atmosphere, and does not carry corrosive or erosive contents. Further, the BEC4 HRH system is not a part of the “feedwater, condensate, heater drains, and wet steam extraction lines” systems. Finally, the BEC4 HRH system does not carry wet steam; it carries dry superheated steam.³²⁴ Consequently, V-8.1.1 does not apply to the BEC4 HRH, and Mr. Polich’s reliance on this section is misplaced.

Importantly, none of the pre- or post-outage inspections of the HRH line indicated findings of any erosion or corrosion of the pipes (which is the subject of Section V-8), much less that it was the cause of the failure.³²⁵ This further demonstrates that the HRH pipes are not, by their nature, a corrosive or erosive environment that would be subject to V-8.

The cause of the HRH pipe failure was determined to be creep, not corrosion.³²⁶ In the 2016 version of the ASME Code for Pressure Piping, B31.1, which was applicable to active inspections and maintenance procedures developed ahead of the February 2019 unplanned HRH outage in question, section V-12, titled “Creep,” would have been the section of Appendix V that applied to BEC4’s HRH piping.³²⁷ V-12.1.1 indicates that operating companies “should

³²² Exs. 14 and 15 at 20 (Undeland Rebuttal) (Public and Nonpublic) (emphasis added); Ex. 15, Rebuttal Schedule 2 at 4 (Undeland Rebuttal) (Nonpublic) (emphasis added).

³²³ Exs. 14 and 15 at 21 (Undeland Rebuttal) (Public and Nonpublic).

³²⁴ *Id.*

³²⁵ *See, generally* Ex. 7, Schedule 3 (Undeland Direct) (discussing inspections of the welded seam failure of the HRH line).

³²⁶ Exs. 14 and 15 at 20-21, 32-33 (Undeland Rebuttal) (Public and Nonpublic); *see also* Ex. 7, Schedule 3 (Undeland Direct).

³²⁷ Exs. 14 and 15 at 21 (Undeland Rebuttal) (Public and Nonpublic); Ex. 15, Rebuttal Schedule 2 at 6 (Undeland Rebuttal) (Nonpublic).

periodically select high-priority creep damage areas for examination”³²⁸ V-12.2.2 states that a “procedure should be developed to select piping system areas more likely to have greater creep damage. . . . The procedure should establish a prioritized examination schedule based on the evaluation process.”³²⁹ Additionally, Section V-12 does not set forth a specific period for examinations. Instead, V-12.5 notes that “[t]he frequency of examination, determined by the Operating Company, should be based on previous evaluation results and industry experience. Particular consideration should be given to the selected high-priority weldments.”³³⁰

In other words, Section V-12 does not call for 100 percent inspection of all piping on a set schedule, but rather indicates that areas of high stress or that have a history of creep should be targeted for periodic evaluation and that the Company was responsible for determining the frequency based on facility experience and known conditions of the line.³³¹ This is consistent with Minnesota Power’s HEP maintenance and inspection program.

Minnesota Power worked with expert consultants to identify the amount of stress on all areas of the HEP systems at Boswell.³³² Minnesota Power’s system engineers used this information, along with past inspection results, known areas of concern, third-party expert recommendations, industry bulletins, and insurance carrier recommendations to identify the areas of the HEP system that were at a higher risk for creep, as laid out in Section V-12.5.³³³ Higher stress and risk areas were inspected every two to five years, while the areas of least stress, such

³²⁸ Ex. 15, Rebuttal Schedule 2 at 6 (Undeland Rebuttal) (Nonpublic).

³²⁹ *Id.*

³³⁰ Exs. 14 and 15 at 21 (Undeland Rebuttal) (Public and Nonpublic); Ex. 15, Rebuttal Schedule 2 at 7 (Undeland Rebuttal) (Nonpublic).

³³¹ Exs. 14 and 15 at 21 (Undeland Rebuttal) (Public and Nonpublic).

³³² *Id.* at 22.

³³³ *Id.*

as the vertical section of HRH at BEC4, were inspected on a ten-year frequency.³³⁴ This method of risk-based inspection scheduling is entirely consistent with the practices recommended in Section V-12 of the ASME standard.

Ultimately, Mr. Polich's reliance on the ASME standards to support a rigid five-year inspection frequency requirement is misplaced. Minnesota Power's maintenance and inspection program is consistent with Section V-12, which addresses creep damage inspections – the type of damage at issue in the BEC4 HRH. On the other hand, Section V-8 applies only to inspections for damage caused by erosion or corrosion, which was not identified as being present in any of the HRH inspection reports.

To support his opinion, Mr. Polich also cites to EPRI's "Guidelines for the Evaluation of Seam-Welded High-Energy Piping" to support his argument that phased array ultrasonic testing of 100 percent of seam-welded HEP every four to five years is required to comply with good utility practice.³³⁵ But EPRI is not a standard creating entity; it is a member utility organization that provides suggested practices and procedures to its members for a fee.³³⁶

Mr. Polich indicates that he relied upon the 2003 edition of this EPRI document. However, that version does not explicitly recommend phased array ultrasonic testing on 100 percent of seam-welded HEP on a four- to five-year cycle. Instead, the 2003 document cited by Mr. Polich recommends a risk-based analysis of HEP for purposes of establishing an inspection program for seam-welded piping, which Minnesota Power used in developing its HEP program, including increased inspections, like those performed as recently as 2018, on high-risk areas.³³⁷

³³⁴ *Id.*

³³⁵ Exs. 10 and 11 at 25 (Polich Direct) (Public and Nonpublic).

³³⁶ Ev. Hrg. Tr. at 75 (Polich).

³³⁷ *Id.* at 71-73.

Although Mr. Polich claims that compliance with good utility practice requires all seam-welded HEP inspection programs to include phased array ultrasonic testing of 100 percent of HEP at least every five years, he acknowledged that the EPRI recommendations do not state that conclusion with any clarity. Instead, after being unable to point to the places in the document supporting his position, Mr. Polich conceded that “It’s one of those things that’s a little bit convoluted throughout this document because there’s a lot of information contained in here . . .

.”³³⁸ Mr. Polich continued:

[I]t’s part of a decision tree that you go through to come to this conclusion. And so it’s not the type of thing where it just simply says 100 percent over five years. You actually have to follow the passes through the flow diagram and look at how the piping has performed and things like that. So there’s not a single specific place within this document you could find it, it’s related to the overall scope in which this document points out how you should address the evaluation of seam-welded high-energy piping.³³⁹

Mr. Polich further admitted that he did not inspect or conduct a decision tree analysis for the BEC4 HRH to determine what EPRI recommendations would apply.³⁴⁰ Thus, the EPRI recommendations are not nearly as straightforward as Mr. Polich initially claimed, and he has admittedly not performed the analysis necessary to determine what maintenance practices EPRI would suggest for BEC4’s HRH.

While EPRI is a very useful resource and Minnesota Power takes its guidelines and recommendations into consideration when creating and updating maintenance and inspection programs, EPRI recommendations do not alone set forth the range of programs that would be consistent with good utility practice.³⁴¹ Rather, EPRI’s recommendations often represent the

³³⁸ *Id.* at 66.

³³⁹ *Id.* at 67.

³⁴⁰ *Id.*

³⁴¹ Exs. 14 and 15 at 23 (Undeland Rebuttal) (Public and Nonpublic).

optimum utility practice. Some of EPRI's guidelines and recommendations are widely adopted within the industry, while others are not.³⁴²

In addition to taking into account any recommendations from trade groups such as EPRI, the range of maintenance and inspection programs that fall within good utility practice is also informed by OEM recommended practices and procedures, IEEE standards, historical experience, the common practices of other utilities and plant operators, continuing education and external training of personnel, and recommendations from independent engineering vendors and outside consultants, among other sources.³⁴³ Hence, EPRI recommendations are only one data point among many that must be taken into account in establishing the parameters of good utility practice.

As discussed above, Thielsch informed Minnesota Power that none of their approximately 50 utility clients, many of which have multiple coal-fired facilities, follow the EPRI recommendation for 100 percent ultrasonic inspection of seam-welded HEP at least every five years, including those clients that consistently subscribe to EPRI's applicable programs.

This is fairly consistent with EPRI's own survey results. In response to Minnesota Power's IR No. 04(c), which asked Mr. Polich to identify all utilities of which he is aware that have had a policy of 100 percent compliance with all EPRI guidelines and recommendations, the Department responded, in part:

EPRI has also conducted surveys of the utility industry on applying the recommendations contained in "Guidelines for the Evaluation of Seam-Welded High-Energy Piping." While the Department was not able to obtain a copy of EPRI's most recent survey due to cost-constraints, Mr. Polich was informed by EPRI that the most recent results are very similar to the 1993 survey, which are contained in

³⁴² *Id.*

³⁴³ *Id.*

the 2003 EPRI report, “Guidelines for the Evaluation of Seam-Welded High-Energy Piping,” page 1-47 through page 1-60³⁴⁴

The Department contended that EPRI’s survey, which included responses from 29 utilities, “concluded that 50% of the utilities responding to the 1993 survey were applying EPRI guidelines”³⁴⁵

In EPRI’s own words:

Although our survey indicated that only 2% of the utilities surveyed complied completely with the EPRI Guidelines, 50% of the utilities thought that they had followed the procedures completely, and another 17% believed that they were following the Guidelines procedures in part. EPRI review of these claims showed that in fact 41% had followed the Guidelines for the most part.³⁴⁶

Interestingly, two percent compliance means that, at most, only a couple of the power plants from the 29 utilities surveyed were actually following all of EPRI’s suggested procedures for HEP inspections. At best, 50 percent of respondents thought that they had followed EPRI’s guidelines. That means that at least half of respondents believed that they were not strictly following EPRI’s guidelines. Far more than half of the utility industry would need to adopt EPRI’s guidelines before they could be considered the only acceptable good utility practice.

More recently, EPRI has acknowledged that its five-year inspection interval recommendation is not generally followed within the industry and may be cost prohibitive. Specifically, in 2017 EPRI conceded that “the recommendation in [the Guidelines for the Evaluation of Seam-Welded High-Energy Piping] regarding a five-year inspection interval is

³⁴⁴ *Id.*, Rebuttal Schedule 1 at 2-3, response to MP IR 04(c).

³⁴⁵ *Id.*

³⁴⁶ *Id.*, Rebuttal Schedule 1 at 33 (emphasis in original).

viewed as cost-prohibitive with the estimated cost for a single HRH piping system to be on the order of \$5 million.”³⁴⁷

When asked about this conclusion in EPRI’s 2017 publication, Mr. Polich attempted to deflect by stating that “[t]his is not EPRI’s opinion” . . . “the view of being cost prohibitive is not by EPRI, but by the utilities.”³⁴⁸ However, the EPRI publication does not attribute the statement as the opinion of utilities or indicate that EPRI disagrees – that is solely how Mr. Polich has chosen to interpret the document. In any event, this is a distinction without a difference because good utility practice is established by the actual practices of utilities, not by EPRI recommended standards. The fact that utilities believe that a five-year inspection cycle is cost prohibitive demonstrates that a significant portion of the utility industry does not follow that EPRI recommendation.

In defending the potential cost of compliance with EPRI guidelines, Mr. Polich concludes that if Minnesota Power had undertaken an inspection of the vertical section of hot reheat pipe in 2013 at a cost \$35,000 “it is very likely that the flaws in the HRH pipe would have been found . . .”³⁴⁹ But Mr. Polich significantly misconstrues the cost of such an inspection as \$35,000. That was a bid from Thielsch for limited testing of the HRH, and did not include the costs of scaffolding, removing insulation, surface preparation, reinsulating, removing the scaffolding, and potentially extending an outage to complete the full inspection.³⁵⁰ Additionally, the scope of the Thielsch bid was for far less than the type of testing Mr. Polich claims Minnesota Power should have employed, which included 100 percent phased array ultrasonic testing of the entire HEP

³⁴⁷ Exs. 14 and 15 at 25, Rebuttal Schedule 1 at 427 (Undeland Rebuttal) (Public and Nonpublic).

³⁴⁸ Ev. Hrg. Tr. at 69-70 (Polich).

³⁴⁹ Exs. 10 and 11 at 15 (Polich Direct) (Public and Nonpublic).

³⁵⁰ Exs. 14 and 15 at 28 (Undeland Rebuttal) (Public and Nonpublic).

system and not just the HRH pipes.³⁵¹ Given the \$5 million estimate included in EPRI's 2017 publication, it is clear that Mr. Polich's claim that it would have cost Minnesota Power only \$35,000 to comply with EPRI's HEP inspection guidelines is meritless.

Minnesota Power has not specifically estimated the cost associated with such an inspection protocol because it would be significantly higher than the potential benefit.³⁵² Using EPRI's own estimate of \$5 million, however, the total cost from 2010 to 2020 would have been \$10 million for BEC3 (assuming two cycles of 100 percent inspection were completed over the two five-year periods), and another \$10 million for BEC4, for a total of \$20 million. That amount covers only the HRH piping systems of these two units, not those of Boswell Units 1 and 2, which were also in operation over this period, and would not include costs for the remainder of the HEP, which Mr. Polich concludes should also fall under this inspection protocol.³⁵³

In the approximately forty years of operation at BEC4, there has been only one outage caused by a high impact failure of the HRH piping; the 2019 outage at issue in this proceeding.³⁵⁴ The Department estimates an incremental cost increase of \$4,482,456 for the replacement power for the 2019 HRH steam line failure outage at BEC4. Based upon the estimate for implementing EPRI's inspection protocol that was included in its 2017 publication, the cost for BEC3 and BEC4 would have been approximately \$20 million over just the period from 2010 to 2020.³⁵⁵ During that same period, the actual costs to implement Minnesota Power's current program were approximately \$6.6 million.³⁵⁶ Even limiting the evaluation period to ten years and two facilities, the costs of implementing Mr. Polich's suggested

³⁵¹ *Id.*

³⁵² *Id.*

³⁵³ *Id.* at 29.

³⁵⁴ *Id.*

³⁵⁵ *Id.*

³⁵⁶ *Id.*

inspection protocol would be significantly more than the cost to ratepayers for the inspections actually performed plus the 2019 outage. If the comparison period was extended back to 2003 (the date of the EPRI report relied upon by Mr. Polich) and all of Minnesota Power's facilities that have HRH systems were included in the analysis, the costs of Mr. Polich's inspection protocol would dwarf the cost of the 2019 outage.

Ultimately, Mr. Polich's conclusion is not consistent with the common practice in the industry, which was to inspect seam-welded HEP between every five to ten years, with lower stress and lower risk areas such as the BEC4 HRH being inspected on the less frequent end of that range. But Mr. Polich does not really address, much less disprove, Minnesota Power's position that its HEP inspection program was consistent with the common practice in the industry at the time. Thus, while Mr. Polich's testimony addresses what EPRI suggests as the most optimal HEP inspection protocol, it does not establish the full range of good utility practices.

b. Minnesota Power Did Not Unreasonably Rely Upon Thielsch

Mr. Polich concludes that Minnesota Power "heavily relied upon Thielsch and essentially turned over the HEP inspection program to Thielsch."³⁵⁷ He concludes that Minnesota Power should have taken more control and questioned Thielsch's recommended inspection protocol.

Thielsch has provided independent consulting services for the HEP systems in Boswell facilities for decades, and has significant experience with coal fired power plants across the country.³⁵⁸ Minnesota Power values Thielsch's expertise within the industry and extensive knowledge of the Boswell facilities, including BEC4.³⁵⁹

³⁵⁷ Exs. 10 and 11 at 40-41 (Polich Direct) (Public and Nonpublic).

³⁵⁸ Exs. 14 and 15 at 30 (Undeland Rebuttal) (Public and Nonpublic).

³⁵⁹ *Id.*

There is significant value in having the same expert consultants inspect a HEP system over a long period. They gain valuable first-hand knowledge on the health of the system, have consistent access to the historical reports from past inspections, have the ability to trend findings throughout the years and predict potential future problem areas, and provide more informed recommendations for future inspections.³⁶⁰ Third-party experts also provide specialized knowledge in areas where it would be cost-prohibitive for Minnesota Power to train its employees and purchase the equipment necessary to perform the inspections and testing.³⁶¹

Mr. Polich's conclusion that Minnesota Power overly relied upon Thielsch's advice and counsel rings a little hollow considering he relies almost entirely on EPRI's recommended guidelines, which he admits are considered cost prohibitive by utilities. And while EPRI's guidelines are based upon its opinion about what the practices should be, Thielsch informed Minnesota Power regarding the practices actually employed by approximately 50 other utilities across the country.

In any event, Minnesota Power did not simply turn over the responsibility for the HEP inspection protocol to Thielsch, as suggested by Mr. Polich. Thielsch offers comprehensive and continuing oversight for piping and boiler inspection programs through a master services agreement relationship with some of its clients.³⁶² Minnesota Power does not have a master services agreement with Thielsch, but rather utilizes Thielsch and its expertise on more of a project by project basis.³⁶³

Although Minnesota Power certainly accepted and incorporated many of Thielsch's recommendations, they were one of many sources of information considered by the Company in

³⁶⁰ *Id.*

³⁶¹ *Id.*

³⁶² *Id.* at 31.

³⁶³ *Id.*

creating the final HEP maintenance and inspection program.³⁶⁴ Minnesota Power develops inspection program scope and frequency protocols based upon many different sources of information including past results, known areas of risk, industry groups, insurance carrier recommendations, and third-party expert recommendations.³⁶⁵ Inspection protocol development involves a collaborative process with several parties utilizing information from a variety of internal and external sources.³⁶⁶ While Thielsch has been a key contributor supporting development of Minnesota Power's HEP program over the years, the Company has also relied upon internal expertise and other third-party experts for additional inputs and recommendations for the program.³⁶⁷

In the end, it is good utility practice for a utility to consult with industry experts when developing an inspection and maintenance program.

c. Learning Team Recommendations Are Not Evidence that Past Practices Were Not Consistent with Good Utility Practice

Mr. Polich attempts to use the recommendation of Minnesota Power's learning team to improve its HEP inspection program as evidence that its historical program was not consistent with good utility practice.³⁶⁸ The fact that Minnesota Power chose to make changes to its PM and PdM programs related to HEP inspections in no way indicates that the prior programs fell short of good utility practice.³⁶⁹ To the contrary, it is good utility practice to learn from equipment failures and make improvements to prevent similar failures in the future.³⁷⁰ The term "continuous improvement" is often used in the industry as a means of expressing the desire to

³⁶⁴ Exs. 14 and 15 at 31 (Undeland Rebuttal) (Public and Nonpublic).

³⁶⁵ *Id.*

³⁶⁶ *Id.* at 32.

³⁶⁷ *Id.*

³⁶⁸ Exs. 10 and 11 at 39-40 (Polich Direct) (Public and Nonpublic).

³⁶⁹ Exs. 14 and 15 at 33 (Undeland Rebuttal) (Public and Nonpublic).

³⁷⁰ *Id.*

build upon the programs and systems already in place as a good utility practice.³⁷¹ The recommendations of the HRH learning team were aimed at continuous improvement and building additional defenses against recurrence of similar events. The recommendations do not mean there was fault or that good utility practices were not being followed.³⁷²

A number of inputs determines the level to which any particular topic, piece of equipment, or system is provided resources to maintain reliability.³⁷³ There is a spectrum, and good utility practice that thoughtfully plans additional maintenance, inspection, and testing falls appropriately in the middle. Balance between resources and the level of risk is never perfect, and adjustments are often needed to continuously improve.³⁷⁴

The ability to convene a learning team is very important for utilities, like Minnesota Power, to self-evaluate whether its programs require revisions.³⁷⁵ If these learning teams are used against utilities in the way Mr. Polich has used the HRH learning team analysis, such self-reflective and open discussion activities may be discouraged in the future.³⁷⁶

IV. REPLACEMENT POWER COSTS WERE REASONABLE AND PRUDENT

Replacement power costs are the costs incurred to purchase power to make up for the generation lost as a result of either a planned or unplanned outage at one of the Company's generation facilities.³⁷⁷ When an unplanned outage occurs or is imminent, Minnesota Power looks at multiple factors to determine whether to procure replacement energy during the outage timeframe. Those factors include projected load, MISO resource availability, renewable forecast, weather in MISO as well as in the Minnesota Power territory, Minnesota Power load

³⁷¹ *Id.*

³⁷² *Id.*

³⁷³ *Id.*

³⁷⁴ *Id.*

³⁷⁵ Exs. 14 and 15 at 34 (Undeland Rebuttal) (Public and Nonpublic).

³⁷⁶ *Id.*

³⁷⁷ Ex. 8 at 2 (Oehlerking-Boes Direct).

forecast, power supply expectation (both baseload and variable generation plus purchases and sales), and MISO market and bilateral market price expectations.³⁷⁸

If Minnesota Power determines that it needs additional power to meet customer needs during the unplanned outage, the Company purchases replacement power for the unplanned outage.³⁷⁹ The factors indicated above help the Company determine whether the least cost option would be to procure replacement energy bilaterally from a counterparty, to purchase the energy from the MISO Day-Ahead or Real-Time market, or to do both. For example, if the bilateral market is higher than the expected MISO market price, the decision may be made to purchase some or all of the energy needed from the MISO market.³⁸⁰

Whenever possible, Minnesota Power seeks to determine the best timing to take an unplanned outage in order to minimize replacement power costs. When an outage need is identified, the condition of the equipment is evaluated to determine whether the unit needs to immediately come down to avoid further damage to plant equipment or creates an unsafe environment. If the unplanned outage can be delayed, Minnesota Power arranges for the outage to occur during the next least cost time period for procuring replacement power.³⁸¹

The incremental replacement power costs for unplanned outages at Boswell included in Minnesota Power's FAC from July 1, 2018 through December 31, 2019, were \$7,728,000.³⁸² These are defined as incremental costs because they are the replacement power costs over and above Boswell's power costs.³⁸³ Using the process described above to utilize bilateral purchases and MISO market purchases to minimize replacement energy costs, Minnesota Power paid

³⁷⁸ *Id.*

³⁷⁹ *Id.* at 2-3.

³⁸⁰ *Id.* at 3.

³⁸¹ *Id.*

³⁸² *Id.* at 5.

³⁸³ Ex. 8 at 5 (Oehlerking-Boes Direct).

approximately \$606,000 less than it would have had it utilized only MISO Day-Ahead Market purchases.³⁸⁴

Overall, Minnesota Power's process to evaluate and procure replacement power for unplanned outages exhibited good utility practice. The Department has not provided any testimony or evidence challenging whether Minnesota Power's process for procuring replacement power is consistent with good utility practice.

V. MINNESOTA POWER'S PROPOSED REFUND METHODOLOGY SHOULD BE USED IF A REFUND IS ORDERED

Replacement power costs related to planned and unplanned outages are recovered from customers through the Rider for Fuel and Purchased Energy Charge. Minnesota Power included actual replacement power costs in its monthly FAC calculation, which was used to adjust rates monthly and in subsequently filed monthly and annual reports, which were reviewed for accuracy and prudence.³⁸⁵ The adjustments reflected, on a per kilowatt hour basis, deviations from the base cost of energy established in the utility's most recent general rate case.³⁸⁶

Minnesota Power's maintenance practices were consistent with good utility practice and no refund of replacement power costs for unplanned outages from July 1, 2018 through December 31, 2019 is appropriate. If the Commission finds that an adjustment is appropriate for the forced outage costs associated with BEC4's Hot Reheat Line steam leak and BEC3's Generator Bushing failure, however, Minnesota Power agrees that the Department's calculation of the adjustment amount is accurate for these two forced outages. Minnesota Power also agrees that it would be appropriate to include interest in the adjustment, and proposes to use the prime

³⁸⁴ *Id.* at 6.

³⁸⁵ *Id.*

³⁸⁶ *Id.*

interest rate in effect from the month the outage costs were charged to the customers until the month that customers would receive the refund.³⁸⁷

If the Commission orders a refund of forced outage costs to customers, the Company is proposing to calculate specific refund amounts for the eight Large Power customers and 17 Municipal customers based on their actual kilowatt hour usage to which the forced outage costs were applied.³⁸⁸ Minnesota Power proposes to calculate the specific refund amount for Large Power and Municipal customers by calculating what the applicable FAC rates would have been without the proposed disallowed outage costs (and interest), determining a reduction in the FAC rate, and applying that rate change to the actual usage for the months affected by the outage costs.³⁸⁹ If any of these Large Power customers or Municipal customers are in arrears, Minnesota Power will first apply this refund amount as a credit to the amount in arrears before issuing any refund.³⁹⁰

For the remaining customer classes, the potential refund amount (total potential refund plus interest less the amount to be refunded to the Large Power and Municipal customers) could be refunded in the month following receipt of a final order from the Commission.³⁹¹ Minnesota Power proposes to calculate the refund for these customers by taking the remaining refund amount divided by the forecasted sales for the applicable remaining customer classes. This rate would be applied to actual usage in the refund month.³⁹²

³⁸⁷ Exs. 16 and 17 at 2-3 (Oehlerking-Boes Rebuttal) (Public and Nonpublic). The applicable interest rates by month are included in Exs. 16 and 17, Rebuttal Schedule 1 at 2-4 (Oehlerking-Boes Rebuttal) (Public and Nonpublic).

³⁸⁸ *Id.* at 3.

³⁸⁹ *Id.* at 3-4.

³⁹⁰ *Id.* at 4.

³⁹¹ *Id.*

³⁹² *Id.*

The Company recognizes that there could be a difference in the forecasted versus actual usage in the refund month. Similar to the treatment of the “fuel cost reduction credit” issued by the Company in 2016, the Company will track the over or under refund amount.³⁹³ If the Company over refunds, that will become a shareholder expense; if the Company under refunds, the under refund amount will be donated to HeatShare.³⁹⁴

VI. CONCLUSION

Based on the record and the arguments presented in this proceeding, Minnesota Power requests that the ALJ find that Minnesota Power’s maintenance practices were consistent with good utility practice and replacement power costs for the unplanned outages that occurred during the AAA evaluation period of July 1, 2018 through December 31, 2019 were reasonably and prudently incurred for the benefit of Minnesota Power’s customers.

³⁹³ *In the Matter of Minnesota Power’s Petition for Approval of Credits to Customers*, MINNESOTA POWER’S REPLY COMMENTS at 1-2, Docket No. E015/M-15-875 (Feb. 15, 2016). The Commission approved the Company’s proposed refund methodology, aside from an offset for legal fees, in a May 26, 2016 Order Approving Refund and Requiring Filings.

³⁹⁴ Exs. 16 and 17 at 4 (Oehlerking-Boes Rebuttal) (Public and Nonpublic).

Dated: June 28, 2021

MINNESOTA POWER

David R. Moeller
Senior Attorney and
Director of Regulatory Compliance
30 West Superior Street
Duluth, MN 55802
Telephone: (218) 723-3963
dmoeller@allete.com

TAFT STETTINIUS & HOLLISTER LLP

/s/ Kodi J. Verhalen
Kodi J. Verhalen
Matthew R. Brodin
Elizabeth M. Brama
2200 IDS Center
80 South Eighth Street
Minneapolis, MN 55402
Telephone: (612) 977-8400
KVerhalen@Taftlaw.com
MBrodin@Taftlaw.com
EBrama@Taftlaw.com

Attorneys on behalf of Minnesota Power